

Bennie | 6/16/18 10394, Aha39

LKK: IMC

UJ CASE NUMBER

ASSIGNMENT

Surveyor: ADRIAN DOI: 5/6/18 Date/Time: 16/18

Registered in Merimen: 8/6/18
8016 733 8356

Pre-assign / CCU / FTE



Insured Vehicle No.: SLZ 6844M
 Name of Insured: KONG KOE CHEE
 Insured Tel No.: _____ HP: 97455759
 Excess Sec II :SS _____ D.O.A: 5/6/18
 Is driver the owner? YES / NO Nature of Accident: _____

Claim No.: _____
 Policy No.: 8000 52828
 Make / Model: Andi A4
 Place of Accident: Entrance of KPE from TPE

If NO, Driver Name / Age: _____
 Driver Tel No.: _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability: _____ % Final ? Yes / No

SJK 896E → SLZ 6844M → SJX 1034B → _____



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP: Leay Adm
 Tel:
 Liability:
 RMKS: TP



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

Date/Time	STAGE	DATE / PIC
<u>12/6/18</u>	Non-Reporting ltr (1st)	
<u>12/6/18</u>	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup)	
	Call OI:	<u>29/06/18-UC</u>
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
<u>29/06/18 @ 3:55PM</u>	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
<u>25/07/18</u>	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: LIS SS 4,900.00 (7 days) Reduction: 63 % Email Call

FINAL SETTLEMENT Date/Time: 25/07/18 Confirm with: MR UONG Email Call FAX

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 0%

Repair Cost: SS 4,900.00 (3 Veh. C.C.; OI 2ND)

Loss of Rental (LOR): SS _____ (_____ days)

Loss of Use (LOU): SS 120.00 (560 x 7 days)

Loss of Income (LOI): SS _____ (\$ x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS 7.45

Medical: SS _____

Disbursement: SS _____ (e.g. Tow/ Independent)

Legal Cost: SS _____

Total: SS 5,327.45 Global Sum SS: 5,320.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: SS 5,320.00 Name 1: LANG AUTOMOTIVE

Payee 2: (Strike if N.A.) SS _____ Name 2: _____

Payee 3: (Strike if N.A.) SS _____ Name 3: _____

COPY SENT
SJX 1034B

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$ 320.00

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SJX1034B Yr Regr: MY / 2010Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Swift 1.5 c.cColour: White A/C: Insured / Std / NI / NASp. Reading: 22562 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mm

D.O.A.

D.O.I.

05/06/18

Survey held at

LearyDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG.Lg \$4,900.00CRAB: \$3,678.70 (43%)MJ: \$18,000.00 (Cash)LTA: \$11,365.00 (Cash)NETT: \$6,635.00 (Cash)

Date/Time, File Pass to?

Prel. Report

Days Of Repair:

1)

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

Weekend (\$)

Report Format :

Lump Sum / L.B.I. (\$)

Survey Fee:

Transportation:

3 - Rd. \$

Photos:

Others:

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010394/Aha3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-06-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SLZ 6844M	Veh. Inspected	SIX 1034B
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	07/06/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 05/06/2018	Inspection Date	05/06/2018
	Survey held at LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TPA16
Vic

SJX1034B.
Suzuki Swift.

JSAI2G21S00561575.

Rear Number Plate. <i>crushed</i>	30(SN) ✓
Rear Number Plate Lamp x02 <i>damaged</i>	418x2=836.0 ✓
Rear Bumper <i>Distorted</i>	605 ✓
Rear Bumper Clips <i>new</i>	30 ✓
Rear Bumper Side Holder x02 <i>new</i>	35.1x2=70.2 ✓
Rear Bumper Impact Bracket x02 <i>rated</i>	47.2x2=94.4 ✓
Reverse Sensor <i>2nd</i>	280(SN) → 210(SN)
Rear End Panel <i>Distorted</i> <i>behind</i>	305 ✓ 73.40 ✓
Rear End Panel Top Garnish.	30.40 x 209.70.
Rear End Panel Air Vent. <i>HP</i> <i>new</i>	289.7x2=579.40
Taillamp x02 <i>LA ut</i>	580.20 ✓
Tailgate <i>dented</i>	149.50 ✓
Tailgate Lock <i>damaged</i>	76.60 ✓
Tailgate Weatherstripe. <i>ut</i>	172.20 x
Tailgate Inner Trim Board <i>HP</i> <i>new</i>	30 x
Tailgate Inner Trim Board Clips <i>HP</i> <i>new</i>	100.20 ✓ 60(SN) ✓
Tailgate Glass Moulding. } <i>new</i>	
Tailgate Glass Sealant. } <i>new</i>	

SJX1034B

Suzuki Logo. }
 Swift Wording. }
 Spare Tyre Panel ^{Backed}
 Spare Tyre Resuscitation Pads. ^{me}
 Spare Tyre Panel Top Cover ^{behind}
 Rees Exhaust Pipe. ^{Best}
 Rees Exhaust Mounting. ^{mp}
 3888.40 ^{me}
 3312.67 ^{SW: 480}

25.30 ✓
 25.90 ✓
 589.50 ✓
 280 (SW) 200 (SW)
 220.60 ✓
 579.30 ✓
 28 X

Panel Beating.
 Spray Painting.
 Wiring. 2390
 To undress
 To remove reverse sensor
 To remove exhaust pipe.
 To transfer tailgate fittings
 To remove tailgate g(s)

~~1500~~ 1200
~~1200~~ 800
~~500~~ 30
~~150~~ 60
~~100~~ 50
~~150~~ 50
~~150~~ 80
~~180~~ 120
0.578.70

total 6193.64
 L/S: 4.9K
 OT Pump

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7767A
Vehicle Details	
Vehicle No.:	SJX1034B
Vehicle to be Exported:	Yes
Intended De-registration Date:	29 Jun 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.5 GL 5DOOR AT
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	M15A1399517
Chassis No.:	JSAEZC21S00561575
Maximum Power Output:	74.0 kW (99 bhp)
Open Market Value:	\$11,786.00
Original Registration Date:	14 May 2010
First Registration Date:	14 May 2010
Transfer Count:	1
Actual ARF Paid:	\$11,786.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2020
PARF Rebate Amount:	\$6,482.00
Intended COE Rebate Details	
COE Expiry Date:	13 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$26,102.00
COE Rebate Amount:	\$4,883.00
Total Rebate Amount:	\$11,365.00

The information contained herein is correct as at 29 Jun 2018

OK



KM Service Done Requiring Change Of Automatic Transmission...

Posted: 15-May-2018 Tags: 2010 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift Sport 1.6A \$27,888 \$9,570 /yr 21-Jul-2010 1,586 cc 154,927 km Hatchback Available

Only 1 Owner! Meticulously Taken Care By Owner. Beautiful Exterior And Interior. Bluetooth Function Added By Owner. Bank/In House Loan Can Be Arranged, Trade In Welcome, Consignment Unit, Call/SMS/WA ...

Comment

Prem Roy Motoring

Posted: 12-May-2018 Tags: 2010 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Suzuki Swift, Suzuki Swift Singapore, used Suzuki Swift Singapore, used Suzuki Swift, used vehicles Singapore or even buy used Suzuki Swift Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Your Ref: SJX 10348
Our Ref: CC6/AIG18010394/Aha3

To: M/s LEANG AUTOMOTIVE

By Fax Only (69093046)

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES SLZ 6844M / SJX 10348 / OTHERS ON 05/06/2018

We refer to the above matter and we confirmed in receipt of your Letter of Demand.

On a without prejudice basis and purely for an amicable settlement and without admission of liability to our Insured's part, we proposed a global sum settlement of \$5,920.00 (all in) to settle your clients claim.

If agreeable, kindly chop and sign the attached DV then forward back a copy to us for our Principal to process the payment.

The above amount is to be made payable to LEANG AUTOMOTIVE.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or as the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,
Vic Alpeh | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4308
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18010394/Ahb3

29 JUNE 2018

**KONG KOK CHEE
BLOCK 318B ANCHORVALE LINK
#15-263
SINGAPORE 542318**

By Post and By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SLZ 6844M / SJX 1034B / OTHERS ON 05/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh

Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*e.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)
Kong.kc@portek.com
(Email)*

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Friday, 29 June, 2018 3:45 PM
To: Kong.kc@portek.com
Cc: Admin A; Vic (LKKAuto)
Subject: Your Ref: SLZ 6844M_ACCIDENT INVOLVING SLZ 6844M / SJX 1034B / OTHERS ON 05/06/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18010394/Ahb3

29 JUNE 2018

**KONG KOK CHEE
BLOCK 318B ANCHORVALE LINK
#15-263
SINGAPORE 542318**

By Post and By Email

Dear Sir/Madam,

ACCIDENT INVOLVING SLZ 6844M / SJX 1034B / OTHERS ON 05/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Date:

5/6/18

To: M/s Leang Automotive
No. 1 Kaki Bukit Avenue 6
#01-68
Singapore 417883

LETTER OF AUTHORITY & INDEMNITY


I/we FERNANDEZ COLIN BENEDICT NRIC No./ Co Registration No. S8537767A of (address) BLK SIRA PUNJAGOL DRIVE #11-787 (S) 821619 the registered owner (or his/her/their/agent) of motor vehicle registration no. SJX1034B hereby authorise M/s Leang Automotive ("the Repairer") to commence repairs to my/our vehicle and to forward the claim for inter alia the costs of repairs to the owner/insured of the Third Party responsible for the said accident on (date) 5-6-2018 involving motor vehicle nos SL26847M along ALONG KPE TUMBLE. I further authorise M/s Leang Automotive to sign and execute all documents in my name including but not limited to the Discharge Voucher in connection with the claim against the Third Party

However, if the third party rejects liability for whatever reasons and/or if the claim is reverted to my/our insurers and my/our insurers do not settle the repair costs and disbursements under my/our own insurance policy, I/we will be fully responsible for the repair costs and disbursements.

I also agree that if I do not fully co-operate in the Third Party claim, I will be responsible for any losses incurred by my Repairer.

My/our vehicle is repaired by the Repairer on my/our own free will and without any threat, inducement and/or promise.

In the event that the Repairer is compelled to enforce this undertaking, I/we agree that I/we shall pay for the legal costs incurred by the Repairer on a solicitor and client full indemnity basis.


Signature/ Co. Stamp

24/07/2018 22:55 67414188

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **LEANG AUTOMOTIVE** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,320.00** (Global Sum - all in) for vehicle no. **SJX 1034B** that was damaged pursuant to the accident which occurred on **05/06/2018** (date) along **ENTRANCE OF KPE FROM KPE** (location) involving vehicle no/s **SLZ 6844M**. This is pursuant to the inspection conducted on **05/06/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **FERNANDEZ COLIN BENEDICT** ("the third party claimant") of vehicle no. **SJX 1034B** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJX 1034B** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of 07 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2018 Edit Reg		05 Jun 2018 00:00 Edit Adj Rpt	\$44,900.00 Edit Estimates	\$44,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	KONG KOK CHEE , ID: S7135786D								
Main Claimant:	FERNANDEZ COLIN BENEDICT , ID: S8537767A								
Vehicle Reg. No.:	SJX1034B	Date of Loss:	05/06/2018 08:00 - :59 [96 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8016733783SG	Policy/Cover Note No.:	1800052828 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLZ6844M	Policy No. (Claimant):	V8008969						
		Excess:							
Repairer:	Leang Automotive - Kaki Bukit (HQ) AJTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/06/2018]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJX1034B (8016733783SG)**
[SLZ6844M]
TP
FERNANDEZ COLIN BENEDICT
Jun 5 2018 8:00AM
[KONG KOK CHEE]
Leang Automotive - Kaki Bukit

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											1			Edit				
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail			Print				
1	18/06/18 11:27	General View											1			Load JPG				
2	18/06/18 11:27	General View											1			Load JPG				
3	18/06/18 11:27	General View											1			Load JPG				
4	18/06/18 11:27	General View											1			Load JPG				
5	18/06/18 11:27	General View											1			Load JPG				
6	18/06/18 11:27	General View											1			Load JPG				
7	18/06/18 11:27	General View											1			Load JPG				
8	18/06/18 11:27	General View											1			Load JPG				
9	18/06/18 11:27	General View											1			Load JPG				
10	18/06/18 11:27	General View											1			Load JPG				
11	18/06/18 11:27	General View											1			Load JPG				
12	18/06/18 11:27	General View											1			Load JPG				
13	18/06/18 11:27	General View											1			Load JPG				
14	18/06/18 11:27	General View											1			Load JPG				
15	18/06/18 11:27	General View											1			Load JPG				
16	18/06/18 11:27	General View											1			Load JPG				
17	18/06/18 11:27	General View											1			Load JPG				
18	18/06/18 11:27	General View											1			Load JPG				
19	18/06/18 11:27	General View											1			Load JPG				
20	18/06/18 11:27	General View											1			Load JPG				
21	18/06/18 11:27	General View											1			Load JPG				
22	18/06/18 11:27	General View											1			Load JPG				
23	18/06/18 11:27	General View											1			Load JPG				
24	18/06/18 11:27	General View											1			Load JPG				
25	18/06/18 11:27	General View											1			Load JPG				
26	18/06/18 11:27	General View											1			Load JPG				
27	18/06/18 11:27	General View											1			Load JPG				
28	18/06/18 11:27	General View											1			Load JPG				
29	18/06/18 11:27	General View											1			Load JPG				
30	18/06/18 11:27	General View											1			Load JPG				
31	18/06/18 11:27	General View											1			Load JPG				
32	18/06/18 11:27	General View											1			Load JPG				
33	18/06/18 11:27	Reinspection Photo											1			Load JPG				
34	18/06/18 11:27	Reinspection Photo											1			Load JPG				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	18/06/18 11:27	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
71	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
72	18/06/18 11:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/06/18 13:16	TP GIA REPORT	Load PDF	
2	19/06/18 12:03	TP ESTIMATE - MARKED	Load PDF	
3	29/06/18 15:55	EMAIL TO OI	Load PDF	
4	29/06/18 15:55	LETTER TO OI	Load PDF	
5	27/07/18 08:57	WORKSHOP INVOICE	Load PDF	
6	27/07/18 08:57	AUTHORISATION TO ACT FORM	Load PDF	
7	27/07/18 08:57	Release Voucher	Load PDF	
8	27/07/18 08:57	LTA SEARCH	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/06/18 11:50	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 47px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLZ6844M (Insd veh)	Model:	SUZUKI SWIFT 1.5 GL (A)
	SJX1034B (TP veh)		
Date of Accident:	05/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	8,578.70	
Final Repair Cost	: \$	5,320.00	
Loss of Use	: \$	7.00 days at \$60.00 per day	
Rental (if any)	: \$	days	
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$	5,320.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Leang Automotive	: \$	5,320.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

27 Jul
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010394/AHA3Q2

Date: 27/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800052828
Claimant Vehicle No : SJX1034B	Insured Vehicle No :	SLZ6844M
Date of Loss: 05/06/2018	Nature of Claim:	TP Claim No: 8016733783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX1034B	Engine No:	M15A1399517
Make & Model:	SUZUKI SWIFT, 1.5 GL (A)	Chassis No:	JSAEZC21S00561575
Reg. Date:	14/05/2010 (Man. Year: 2009)	Odometer:	221562 km
Colour:	White		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,098.70	3,803.64	1,295.06	25.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	2,390.00	1,090.00	31.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,578.70	6,193.64	2,385.06	27.80
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	8,578.70	4,900.00	3,678.70	42.88
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,327.45		
Global Sum Settlement (S\$)		5,320.00		

INSPECTION

Date of Assignment:	05/06/2018	
Date Inspected:	05/06/2018 Inspected At:	Leang Automotive - Kaki Bukit (HQ) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68 Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Damaged	83.60 F	*83.60 FL
2	1		*REAR BUMPER	Distorted	605.00 F	*605.00 FL
3	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
4	2		*REAR BUMPER SIDE HOLDER	Necessary	70.20 F	*70.20 FL
5	2		*REAR BUMPER IMPACT BRACKET	Dented	94.40 F	*94.40 FL
6	1		*REAR END PANEL	Distorted	305.00 F	*305.00 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	73.40 F	*73.40 FL
8	1		*REAR END PANEL AIR VENT	Not Necessary	30.40 F	*- FL
9	1		*TAILLAMP	N/S Cut	579.40 F	*289.70 FL
10	1		*TAILGATE	Dented	580.20 F	*580.20 FL
11	1		*TAILGATE LOCK	Damaged	149.50 F	*149.50 FL
12	1		*TAILGATE WEATHERSTRIPE	Cut	76.60 F	*76.60 FL
13	1		*TAILGATE INNER TRIM BOARD	Not Necessary	172.20 F	*- FL
14	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 F	*- FL
15	1		*TAILGATE GLASS MOULDING	Necessary	100.20 F	*100.20 FL
16	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
18	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
19	1		*SPARE TYRE INSULATION PADS	Necessary	280.00 FS	*200.00 FS
20	1		*SUZUKI LOGO	Necessary	25.30 F	*25.30 FL
21	1		*SWIFT WORDING	Necessary	25.90 F	*25.90 FL
22	1		*SPARE TYRE PANEL	Buckled	589.50 F	*589.50 FL
23	1		*SPARE TYRE PANEL TOP COVER	Deformed	220.60 F	*220.60 FL
24	1		*REAR EXHAUST PIPE	Bent	579.30 F	*579.30 FL
25	1		*REAR EXHAUST MOUNTING	Not Necessary	28.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,098.70	4,388.40
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	584.76
Total Parts (\$\$)	5,098.70	3,803.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	1,200.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE EXHAUST PIPE	New	150.00	50.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
Gross Labour Cost (\$\$)			3,480.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >