

REF:

WORKSHOP

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
OO / TP / WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop no/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S		

Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Loss Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLK 3004 U Yr Regn: Jan 2017Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Hybrid C/C: 1798Colour: Silver A/C: Insured / Std / NI / NASp Reading: 94629 T/Radio: Insured / Std / NI / NAEng/No: 2ZRR986395C/No: JTOKB3FU1D3542463Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Fit / S/Rim / STD A/Rim orTyre Size: F: 195 / 65 R15R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Rowelo (Front), Giti (Rear)

Front

Rear

R/Bal: 6 mmR/Bal: 6 mmL/Bal: 6 mmL/Bal: 6 mmD.O.A: 4/6/2018D.O.I: 6/6/2018

Survey held at

World AutoDes. of Damages: FR / Rear / OB / N/S / UIC / Rooftop orO/S Front

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P 3,535.57

R(\$5,791.43/ 627-)

Date/Time, File Pass to/

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to/

2)

Add Fee:

☐

Site Insp: (\$

☐

Interview: (\$

☐

Tech Insp: (\$

☐

Total: (\$

Survey Fee:

Transportation:

) S + RC: \$1

) Petrol:

) Other:

Report Format :

Form No. H.D. 1.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18010436/Vja3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 07-06-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6621B	Veh. Inspected	SLK 3004U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/06/2018	Inspection Date	06/06/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000154

Date : 06/06/2018
 Vehicle Num. : SLK 3004U (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 04/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER ✓ Deform	550.00	450.80
2.	1	FRONT BUMPER RETAINER RH 2X NN	130.00	
3.	1	FRONT FENDER - RH ✓ Deform	960.00	685
4.	1	FRONT FENDER HYBRID EMBLEM RH ✓ NEL	100.00	86.50
5.	1	FRONT HEADLAMP - RH 2X ✓ CRK	2,550.00	2080
6.	1	FRONT FOG LAMP - RH 2X NN	980.00	
7.	1	FRONT WHEEL CAP - RH ✓ MB	250.00	195.80
8.	1	FRONT LOWER ARM RH 2X	300.00	
9.	1	FRONT ABSORBER RH 2X	400.00	
10.	1	FRONT LINKAGE - RH 2X	200.00	
11.	1	FRONT KNUCKLE - RH 2X	550.00	
12.	1	FRONT WHEEL HUB BEARING 2X } NN	580.00	
List Total S\$:			7,600.00	
25.00% Discount S\$:			1,900.00	
			5,700.00	

SPECIAL NETT ITEMS :				
1.	1	FRONT BUMPER CLIP	30.50.00	✓ NEL
2.	1	FRONT SPORT RIM - RH	2,100.00	8
Special Nett Total S\$:			2,150.00	

LABOUR :
 LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO
 REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

700.00 400

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000154

Date : 06/06/2018
 Vehicle Num. : SLK 3004U (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 04/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)		600.00 400
--	--	---	--	-----------------------

		PERFORM 4 WHEEL COMPUTERISED ALIGNMENT.		180.00 100
--	--	---	--	-----------------------

		Labour Total S\$:		1,480.00
--	--	--------------------	--	----------

Sathya Sai

6/6/2018

sebastianycang@lkkauto.com

- Part by Part repair
- Question mark item
- Photo before paint -

LKK Auto Consultants hence notify the Reparer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Reparer Signature: Date:

3 days

E. & O.E.

Total S\$: 9,330.00

for WORLD AUTO PTE LTD

3478.1
- 25%
<u>2608.58</u>
+ 30
+ 900
<u>3538.58</u>

COR : \$ 3538.58 @ 3 days
 confirmed.

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000154

Date : 06/06/2018
 Vehicle Num. : SLK 3004U (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 04/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

FRONT BUMPER ✓ Deform	550.00
FRONT BUMPER RETAINER RH 8 X	130.00
FRONT FENDER - RH ✓ Deform	950.00
FRONT FENDER HYBRID EMBLEM RH ✓ NGL	100.00
FRONT HEADLAMP - RH 8 ✓ CRK	2,550.00
FRONT FOG LAMP - RH 8 X	980.00
FRONT WHEEL CAP - RH ✓ NGL	250.00
FRONT LOWER ARM RH 8	380.00
FRONT ABSORBER RH 8 } X	400.00
FRONT LINKAGE - RH 8	200.00
FRONT KNUCKLE - RH 8	550.00
FRONT WHEEL HUB BEARING ?	560.00

List Total S\$:

7,600.00

25.00% Discount S\$:

1,900.00

5,700.00

SPECIAL NETT ITEMS :

FRONT BUMPER CLIP	50.00 ✓ NGL
FRONT SPORT RIM - RH	2,100.00 R

Special Nett Total S\$:

2,150.00

LABOUR :

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO
 REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

700.00 HCU

CONTINUE / ...

Photo after paint - Satya Sa
 14/6/2018

Print Received Message

This mail is associated with :

***SLK3004U (MCT18060146)**
[SH6621B]
TP
LCRF PTE LTD
Jun 4 2018 5:00PM
[-]
World Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/10/2018 16:51 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3966.27) - SLK3004U - Claim Handler: Zuhaidah Bte Samsuri

Approved:3966.27.

Motor Claims Discharge Voucher

Insured / Owner : ICRF Pte Ltd Vehicle No : SLK 3004U
Policy No : _____ NRIC : 201624597K
Address : _____
Tel : _____ H/P : _____

I am / We are the registered owners(s) of the above motor vehicle involved in the above captioned accident.

My / Our authorized repairs **WORLD AUTO PTE LTD** of **47 Jalan Pemimpin #01 - 02/03, Halcyon 2 S'pore 577200** Will be forwarding to you all the relevant documents. I / We undertake to pay all the legal costs incurred thereof.

I / We have authorized **WORLD AUTO PTE LTD** to represent me / us in all aspects of my claim against the driver of the other vehicle and you may take full instructions from them.

In the event, I am / We are successful in my / our claim againsts the other driver who was involved in the above accident. I / We hereby irrevocable instruct and authorize you to deduct from the proceeds recovered your legal costs and incidentals and thereafter to forward the balance to M/S **WORLD AUTO PTE LTD**.

I / We authorize M/S **WORLD AUTO PTE LTD** to sign all discharge voucher / indemnity forms and all necessary documents in connection with and arising out of the above claim.

I / We undertake to indemnify you and keep you indemnified in respect of any claim or action that may rise as a result of your complying with my / our request.

I confirm that I have taken delivery of vehicle registration no. SLK 3004U from the requires, M/S **WORLD AUTO PTE LTD** of **47 Jalan Pemimpin #01 - 02/03, Halcyon 2 s'pore 577200** and that all repairs necessary as a result of an accident in which the said vehicle was involves on or about the 04/06/2018 have been completed to my satisfaction and that i have no further claims whatsoever against the said repairs in respect hereof.

I hereby assign all monies arising from my claims, due under insurance policy to M/S **WORLD AUTO PTE LTD** of **47 Jalan Pemimpin #01 - 02/03, Halcyon 2 S'pore 577200**.

Kindly effect payment of all monies to M/S **WORLD AUTO PTE LTD** and only payment to them will constitute a good effective discharge of the debt.

Date : 18/06/2018

Signature of Insured / Owner : _____





WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

16/08/2018

Your Ref :

Our Ref : TP/2061/2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04/ #05 IOB BLDG

SINGAPORE 049711

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLK3004U / SH6621B ON 04/06/2018

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF)

Enclosed herewith are the following documents for your information and necessary actions only :-

- a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 3538.57 (already surveyed & finalised with your surveyor)
GST 7%	\$ 247.70
Loss of Use (\$60 x 3 days)	\$ 180.00
Amount	<u>\$ 3966.27</u>

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : **04/06/2018**

CLIENT'S VEHICLE NO : **SLK3004U**

PLACE OF ACCIDENT : **TURF CLUB ROAD**

THIRD PARTY VEHICLE NO : **SH6621B**

I/We, **LCRF PTE LTD**

ADDRESS: **NO.29, PAYA LEBAR ROAD, SINGAPORE 409005**

UEN/NRIC/FIN NO : **201624597K**

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 5TH DAY OF JUN YEAR 2018



Name: **LCRF PTE LTD**
NRIC No: **201624597K**

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III - Direct Settlement (PODS)

India Ref: MCT18060146
Claimant Ref: TP/2061/2018

We/I, WORLD AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,786.27 (repair cost), S\$ 180.00 (loss of use/~~rental~~) S\$ 0.00 (search fee), vehicle no. SLK 3004U that was damaged pursuant to the accident which occurred on 04.08.2018 (date) at TURF CLUB ROAD (location) involving vehicle no. SH 6621B (insured vehicle). This is pursuant to the inspection conducted on 06/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LCRF PTE LTD ("the third party claimant") of vehicle no. SLK 3004U to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLK 3004U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,966.27 to WORLD AUTO PTE LTD

Dated this 19 day of October 2018

CLAIMANT:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

Signed by "the workshop" (with chop)

Geraldine Teong

S2001848

42 Jalan Pemimpin #01-02/03 Halcyon 2

Singapore 577200

WITNESS:

Signature: _____

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

WORLD AUTO PTE LTD
47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
S'PORE 577200
Tel No. : 64513933 Fax No. : 64557576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

Tax Invoice : F188634

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04 / #05 IOB BUILDING
S'PORE 049711

Attention : Motor Claim Department
Contact : 63476100 63476139-LALITA Fax No. : 62244174

Date : 14/08/2018
Vehicle Num. : SLK 3004U
Make/Model : TOYOTA PRIUS, 1.8 HYBRID
Chassis/Eng# :
Accident Date : 04/06/2018
Claim No. : TP/2061/2018
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	FRONT BUMPER		450.80
2.	1	FRONT FENDER RH		685.00
3.	1	FRONT FENDER HYBRID EMBLEM RH		86.50
4.	1	HEADLAMP RH		2,080.00
5.	1	FRONT WHEEL CAP RH		175.80
		List TotalS\$:		3,478.10
		25.00% Discount S\$:		869.53
				2,608.57
1.	1 SET	SPECIAL NETT ITEMS : FRONT BUMPER CLIPS		30.00
		Special Nett Total S\$:		30.00
		LABOUR :		
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS INORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD, STRAIGHTENING WHERE NECESSARY AND REPLACE PARTS		400.00
		PUTTY & SPRAY PAINT ON ALL AFFECTED AREAS		400.00
		PERFORM 4 WHEEL COMPUTERISED ALIGNMENT		100.00
		Labour Total S\$:		900.00

Total S\$: 3,538.57
GST 7% S\$: 247.70
Amount Due S\$: 3,786.27
=====

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jun 2018 Edit Reg		06 Jun 2018 00:00 Edit Adj Rpt	S\$3,538.57 Edit Estimates	S\$3,538.57 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLK3004U	Date of Loss:	04/06/2018 17:00 - :59 [16 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060146	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH6621B	Policy No. (Claimant):	999995006						
		Excess:							
Repairer:	World Auto Pte Ltd (HQ) 47 Jln Pemimpin, #01-02/03 Halcyon 2, 577200 Bishan - Tel: 6451 3933								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 19/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (09/10/2018): Alert - Adj Mandate Approved (S\$3966.27) - SLK3004U - Claim Handler: Zuhaidah Bt... - III_SG (14/06/2018): Alert - Adj Mandate Approved (S\$0.00) - SLK3004U - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK3004U (MCT18060146)
[SH6621B]
TP
LCRF PTE LTD
Jun 4 2018 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/06/18 09:03	General View		Load JPG	☒
2	08/06/18 09:03	General View		Load JPG	☒
3	08/06/18 09:03	General View		Load JPG	☒
4	08/06/18 09:03	General View		Load JPG	☒
5	08/06/18 09:03	General View		Load JPG	☒
6	08/06/18 09:03	General View		Load JPG	☒
7	08/06/18 09:03	General View		Load JPG	☒
8	08/06/18 09:03	General View		Load JPG	☒
9	08/06/18 09:03	General View		Load JPG	☒
10	08/06/18 09:03	General View		Load JPG	☒
11	08/06/18 09:03	General View		Load JPG	☒
12	08/06/18 09:03	General View		Load JPG	☒
13	08/06/18 09:03	General View		Load JPG	☒
14	08/06/18 09:03	General View		Load JPG	☒
15	08/06/18 09:03	General View		Load JPG	☒
16	08/06/18 09:03	General View		Load JPG	☒
17	08/06/18 09:03	General View		Load JPG	☒
18	08/06/18 09:03	General View		Load JPG	☒
19	08/06/18 09:03	General View		Load JPG	☒
20	08/06/18 09:03	Chassis Number		Load JPG	☒
21	08/06/18 09:03	Odometer Reading		Load JPG	☒
22	08/06/18 09:03	General View		Load JPG	☒
23	08/06/18 09:03	General View		Load JPG	☒
24	08/06/18 09:03	General View		Load JPG	☒
25	08/06/18 09:03	General View		Load JPG	☒
26	19/06/18 09:06	Dismantled Parts		Load JPG	☒
27	19/06/18 09:06	Dismantled Parts		Load JPG	☒
28	19/06/18 09:06	Photo After Spray		Load JPG	☒
29	19/06/18 09:06	Photo After Spray		Load JPG	☒
30	19/06/18 09:06	Photo After Spray		Load JPG	☒
31	19/06/18 09:06	Photo After Spray		Load JPG	☒
32	19/06/18 09:06	Photo After Spray		Load JPG	☒
33	19/06/18 09:06	Photo After Spray		Load JPG	☒
34	19/06/18 09:06	Photo After Spray		Load JPG	☒
35	19/06/18 09:06	Photo After Spray		Load JPG	☒
Documentation				1 per page	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 19:35	ACKNOWLEDGEMENT EMAIL TO III DD 06.06.2018		Load PDF
2	09/06/18 17:38	TP ESTIMATE-MARKED		Load PDF
3	09/06/18 17:38	TP GIA REPORT		Load PDF
4	27/09/18 10:52	WORKSHOP INVOICE		Load PDF
5	27/09/18 10:52	LOD		Load PDF
6	01/11/18 09:03	AUTHORISATION TO ACT FORM		Load PDF
7	01/11/18 09:03	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 09:16	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18010436/VJA3Q2

Date: 01/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SLK3004U

Insured Vehicle No : SH6621B

Date of Loss: 04/06/2018

Nature of Claim:

TP

Claim No: MCT18060146

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK3004U

Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A)

Engine No: 2ZRR986395

Reg. Date: 12/01/2017 (Man. Year: 2016)

Chassis No: JTDKB3FU103542463

Colour: Silver

Odometer: 94629 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Rovel 6 mm

Rear Left Side:

Giti 6 mm

Front Right Side: Rovel 6 mm

Rear Right Side:

Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,850.00	2,638.57	5,211.43	66.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	900.00	580.00	39.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,330.00	3,538.57	5,791.43	62.07
+ GST 7.00/7.00% (S\$)	653.10	247.70	405.40	62.07
Nett Amount (S\$)	9,983.10	3,786.27	6,196.83	62.07
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		3,966.27		

INSPECTION

Date of Assignment: 06/06/2018

Date Inspected: 06/06/2018 Inspected At:

World Auto Pte Ltd (HQ)
47 Jln Pemimpin, #01-02/03 Halcyon 2
Singapore 577200

Estimated Period of Repair: 3.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2018)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3004U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	550.00 FL	*450.80 FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	130.00 FL	*- FL
3	1		*FRONT FENDER -RH	Deformed	950.00 FL	*685.00 FL
4	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	100.00 FL	*86.50 FL
5	1		*FRONT HEADLAMP-RH	Cracked	2,550.00 FL	*2,080.00 FL
6	1		*FRONT FOG LAMP-RH	Not Necessary	980.00 FL	*- FL
7	1		*FRONT WHEEL CAP -RH	Missing	250.00 FL	*175.80 FL
8	1		*FRONT LOWER ARM RH	Not Necessary	380.00 FL	*- FL
9	1		*FRONT ABSORBER RH	Not Necessary	400.00 FL	*- FL
10	1		*FRONT LINKAGE -RH	Not Necessary	200.00 FL	*- FL
11	1		*FRONT KNUCKLE-RH	Not Necessary	550.00 FL	*- FL
12	1		*FRONT WHEEL HUB BEARING	Not Necessary	560.00 FL	*- FL
13	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
14	1		*FRONT SPORT RIM -RH	Repair	2,100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,750.00	3,508.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,900.00	869.53
Total Parts (\$\$)	7,850.00	2,638.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,CUT/WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	700.00	400.00
2	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	600.00	400.00
3	PERFORM 4 WHEEL COMPUTERISED ALIGNMENT	New	180.00	100.00
Gross Labour Cost (S\$)			1,480.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >