

Police Report



SINGAPORE
POLICE FORCE



T/20180030/2140

Page 9

Police Station Of Origin
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No: T/20180030/2140

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /
Sgt 3 LIYANA BINTE MOHD RAZALI

Signature Of Informant

Signature Of Interpreter
Not applicable

Date/Time
30/05/2018 18:06

Officer In Charge Of Case.
TP / HRT /
Sr Staff Sgt TAN JEOK LENG
Contact No: 65478144

Classification Of Case

Authentication Stamp
NP120



SINGAPORE
POLICE FORCE

SIGNATURE

SN 051

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0241H
Vehicle Details	
Vehicle No.:	SGC8218M
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	CHZ515241
Chassis No.:	WAUZZZ8VXJ1008407
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,475.00
Original Registration Date:	14 Sep 2017
First Registration Date:	14 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$16,265.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2027
PARF Rebate Amount:	\$12,198.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$39,742.00
Total Rebate Amount:	\$51,940.00

The information contained herein is correct as at 08 Jun 2018

OK

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/649/2018/PH
Date : 4-Jun-18

Booked 07/06/18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Kim Huat
Address : Blk 289 Bishan St 24
#12-21
Singapore 570289
Telephone : HP +65 92278620
Type of Claim : Own Damage Claim
Policy No. : 1700047720
Vehicle No : **SGC 8218 M**
Model Code : Audi A3 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ 515241
Chassis No : WAUZZZ8VXJ1008407
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-May-18
Place of Accident : 39 Jurong West Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGC 8218 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00	✓ ✓
2	To dismantle and renew lhs front door, align to position. Reinstall all parts removed.	\$ 900.00	500 ✓
3	To respray lhs front door, door handle and lhs sill panel.	\$ 1,800.00	650 ✓
4	To carry out diagnostic checks.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 3,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 8218 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	DOOR - LH <i>Dented</i>	\$ 2,190.00	✓ 1752
2	OUTER DOOR SEAL - LH <i>new</i>	\$ 139.00	✓ 111.00
3	BONDING AGENT <i>new</i>	\$ 43.00	? X
4	CLEANING SOLUTION <i>new</i>	\$ 64.00	? X
5	DOOR CATCH <i>new</i>	\$ 92.00	X
6	DOOR HANDLE, EXTERIOR - LH <i>new Dented</i>	\$ 207.00	✓ 165.60
7	MOUNTING BAR <i>new</i>	\$ 143.00	+
8	WINDOW REGULATOR WITHOUT MOTOR <i>new</i>	\$ 232.00	+
9	SUNDRIES <i>new</i>	\$ 200.00	? X
SPARE PARTS		:	\$ 3,310.00
LABOUR CHARGES		:	\$ 3,172.00
GRAND TOTAL		:	\$ 6,482.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adnan King

Surveyed Date

:

07/06/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Authorised Repairs, 030 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0649/2018/PH
Date	:	4-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb -17 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr.Lim Kim Huat
Address	:	Blk 289 Bishan St 24 #12-21 Singapore 570289
Telephone	:	(HP) 922789620
Type of Claim	:	Own Damage Claims
Policy No.	:	1700047720
Vehicle No	:	SGC 8218 M
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Sep-17
Engine No	:	CHZ 515241
Chassis No	:	WAUZZZVXJ1008407
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	29-May-18
Place of Accident	:	39 Jurong West Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGC 8218 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00	\$ 280.00
2	To dismantle and renew lhs front door, align to position. Reinstall all parts removed.	\$ 900.00	\$ 500.00
3	To respray lhs front door, door handle and lhs sill panel.	\$ 1,800.00	\$ 650.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES - FRONT		: \$ 3,172.00	\$ 1,622.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 8218 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	DOOR - LH	\$ 2,190.00	\$ 1,752.00
2	OUTER DOOR SEAL - LH	\$ 139.00	\$ 111.20
3	BONDING AGENT	\$ 43.00	
4	CLEANING SOLUTION	\$ 64.00	
5	DOOR CATCH	\$ 92.00	
6	DOOR HANDLE, EXTERIOR - LH	\$ 207.00	\$ 165.60
7	MOUNTING BAR	\$ 143.00	
8	WINDOW REGULATOR WITHOUT MOTOR	\$ 232.00	
9	SUNDRIES	\$ 200.00	
	SPARE PARTS	\$ 3,310.00	\$ 2,028.80
	LABOUR CHARGES	\$ 3,172.00	\$ 1,622.00
	GRAND TOTAL	\$ 6,482.00	\$ 3,650.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 17 October 2018 4:37 PM
To: 'Boo seng yak'; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SGC8218M - OD AIG - SURVEYED 7 JUN 18

Dear Mr Boo,

Confirm repair cost of \$3650.80 before GST @ 3 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Wednesday, 17 October 2018 4:28 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SGC8218M - OD AIG - SURVEYED 7 JUN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3650.80 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGC 8218 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0649/2018/MAS

20 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SGC 8218 M, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no **SGC 8218 M**, claimant,
Mr. Lim Kim Huat, please find the related document per attached.

1. A copy of the Original invoice no. 85013120 – S\$3,906.36
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGC 8218 M

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

	PASS DATE
Class 2B Motorcycles not exceeding 200 cc	27 Apr 1987
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	08 Aug 1987
Class 4 Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	21 Feb 1989
Class 5 Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	25 Jul 1995

NP 428A

Licence No: S1800241H

5736973



HEIC No. S1800241H



Date of Issue
02-05-2017

Address
APT BLK 289 BISHAN STREET 24
#12-21
SINGAPORE 570289

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S1800241H

LIM KIM HUAT

Birth Date: 03 May 1967

Issue Date: 20 Mar 2003

000307810G



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1800241H

Name

LIM KIM HUAT

林金发

Race

CHINESE

Sex

M

Date of birth

03-05-1967

Country/Place of birth

SINGAPORE



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM KIM HUAT
Period of Insurance : 14 Sep 2018 To 13 Sep 2019
Engine No. : CHZ515241
Chassis No. : WAUZZZ8VXJ1008407

Vehicle No. : SGC8218M
Policy No. : 1700047720-01
Endorsement No. :
Issued Date : 20 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM KIM HUAT - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125262

PREMIUM LEASING -KTL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPSLT



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408899
Telephone 6388 1232
Telefax 6441 1232

Customer Service
Service Appointment 6366 2323
9818 1232
24 hour Breakdown Service
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:06

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013120 Date : 12/11/2018 Order : SGC8218M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGC8218M (V 34955) Regn Date: 14/09/2017 Mileage: 29970 WIP No.: 12332
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8VXJ1008407 Engine: CHZ 515241 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE AND RENEW LHS FRONT DOOR, ALIGN TO POSITION, REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY LHS FRONT DOOR AND DOOR HANDLE	650.00	1.00	650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A0V5831051B	DOOR Less 020%	1.00	2190.00	1,752.00
X	A0V5837911C	SEAL Less 020%	1.00	139.00	111.20
X	A0V0837205A GRU	HANDLE Less 020%	1.00	207.00	165.60

Parts 2,028.80
Labour 0.00
Sublet 1,622.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,650.80

7% GST 255.56

Grand Total 3,906.36



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGC 8218 M

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/0649/2018/GW
06 September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages


RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8VXJ1008407
Vehicle Regn No. : SGC 8218 M
Vehicle Mileage : 25708 KM
Vehicle Owner : Mr. Lim Kim Huat
Certificate No : 1700047720-01
Policy Excess : NIL (Inclusive GST)
Accident Date : 29 of May 2018
Place : 39 Jurong West Ave1
Repair Cost : \$ 3,906.36
WIP No. : 12332
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 6/9/18 @ 1700
Date : 1700

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018		08 Jun 2018 09:55 Edit Adj Rpt	S\$3,650.80 Edit Estimates	S\$3,650.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM KIM HUAT, ID: S1800241H, Tel: +6592278620, Email: NOEMAIL								
Vehicle Reg. No.:	SGC8218M	Date of Loss:	29/05/2018 14:00 - :59 [8 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4077391083SG	Policy/Cover Note No.:	1700047720 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/06/2018]								
Driver/Custodian:	LIM KIM HUAT (51 / Male), NRIC: S1800241H, Tel: +6592278620								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
- AIG_SG (15/08/2018): SGC8218M / OD / 29/05/2018 / Coverage & Excess update - AIG_SG (08/06/2018): SGC8218M / OD / 29/05/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGC8218M (4077391083SG)
OD
May 29 2018 2:20PM
[LIM KIM HUAT]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

3 per page

Photos/Images

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

08/06/18 14:24

General View

Load JPG

2

08/06/18 14:24

General View

Load JPG

3

08/06/18 14:24

General View

Load JPG

4

08/06/18 14:24

General View

Load JPG

5

08/06/18 14:24

General View

Load JPG

6

08/06/18 14:24

General View

Load JPG

7

08/06/18 14:24

General View

Load JPG

8

08/06/18 14:24

General View

Load JPG

9

08/06/18 14:24

General View

Load JPG

10

08/06/18 14:24

General View

Load JPG

11

08/06/18 14:24

General View

Load JPG

12

08/06/18 14:24

General View

Load JPG

13

08/06/18 14:24

General View

Load JPG

1 per page

Documentation

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

08/06/18 11:34

Singapore Accident Statement

Load PDF

2

08/06/18 11:34

Police Report

Load PDF

3

08/06/18 11:35

Insured's Driving License

Load PDF

4

08/06/18 11:35

MARK ESTIMATE

Load PDF

5

29/11/18 14:12

DISCHARGE VOUCHER

Load PDF

6

29/11/18 14:12

WORKSHOP INVOICE

Load PDF

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/06/18 12:01	Accident Statement	 Load HTM	☒

3 per page ☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/06/18 11:56	Police Report	 Load JPG	☒
2	02/06/18 11:56	Police Report	 Load JPG	☒
3	02/06/18 11:56	Police Report	 Load JPG	☒
4	02/06/18 12:00	Accident Photo	 Load JPG	☒
5	02/06/18 12:00	Accident Photo	 Load JPG	☒
6	02/06/18 12:00	Accident Photo	 Load JPG	☒
7	02/06/18 12:00	Accident Photo	 Load JPG	☒

Assessment Reports		1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
8	02/06/18 12:00	Accident Photo	 Load JPG	☒
9	02/06/18 12:00	Accident Photo	 Load JPG	☒
10	02/06/18 12:00	Accident Photo	 Load JPG	☒
11	02/06/18 12:00	Accident Photo	 Load JPG	☒
Documentation		1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/06/18 11:53	Sketch Plan	 Load JPG	☒
2	02/06/18 11:53	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18010447/AVBS2
Date: 29/11/2018

REFERENCE

Insured/Claimant: LIM KIM HUAT Policy No: 1700047720
Date of Loss: 29/05/2018 Nature of Claim: OD Claim No: 4077391083SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC8218M**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ515241
Reg. Date: 14/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8VXJ1008407
Colour: Red Odometer: 19330 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,310.00	2,028.80	1,281.20	38.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,172.00	1,622.00	1,550.00	48.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,482.00	3,650.80	2,831.20	43.68
+ GST 7.00/7.00% (S\$)	453.74	255.56	198.18	43.68
Nett Amount (S\$)	6,935.74	3,906.36	3,029.38	43.68

INSPECTION

Date of Assignment: 08/06/2018
Date Inspected: 07/06/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR - LH	Dented	2,190.00 FS	*1,752.00 FS
2	1		*OUTER DOOR SEAL - LH	Necessary	139.00 FS	*111.20 FS
3	1		*BONDING AGENT	Not Necessary	43.00 FS	*-FS
4	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*-FS
5	1		*DOOR CATCH	Not Necessary	92.00 FS	*-FS
6	1		*DOOR HANDLE, EXTERIOR - LH	Deformed	207.00 FS	*165.60 FS
7	1		*MOUNTING BAR	Not Necessary	143.00 FS	*-FS
8	1		*WINDOW REGULATOR WITHOUT MOTOR	Not Necessary	232.00 FS	*-FS
9	1		*SUNDRIES	Not Necessary	200.00 FS	*-FS
Total Parts (S\$)					3,310.00	2,028.80

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
2	TO DISMANTLE AND RENEW FRONT DOOR, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	New	900.00	500.00
3	TO RESPRAY LHS FRONT DOOR, DOOR HANDLE AND LHS SILL PANEL.	New	1,800.00	650.00
4	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (S\$)			3,172.00	1,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >