

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 7143J

DATE 6/7/2018 12:13

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ✓			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Clips 10 pcs ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover X			\$ 225.00	
	SUB TOTAL			\$ 1,858.35	
	LESS 20%			\$ 371.67	
	DISCOUNTED TOTAL			\$ 1,486.68	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge			200	
	Panel Beating (Repair)			\$ 380.00	
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 30.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	30
	TOTAL LABOUR			\$ 780.00	
	ESTIMATE TOTAL			\$ 2,452.38	
<i>Kehin, CLK/4</i> <i>7/6/18 1405hrs</i> <i>2 Days</i> <i>PIP</i> <i>Before Paint photo</i>					LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					