

Justin

cc 6, 601 180 10479, Upaz

Surveyor

mprens

DOI

ASSIGNMENT

8/1/8

Date / Time

8/1/8

Registered in Merimen

Pre-assign / CCU / FTE

645886M



Insured Vehicle No.

Name of Insured

A & J MAINTENANCE SERVICES

Insured Tel No.

HP

Excess See II :SS

D.O.A

21/6/2018

Is driver the owner?

(YES / NO)

Nature of Accident

If NO, Driver Name / Age

Heng Kai chom (Wang Kai Jun)

Driver Tel No.

93238585

(V/L: YES / NO)

Claim No.

Policy No.

0mcp17-004213

Make / Model

MAZDA URVAN

Place of Accident

Boon Lay Way > Commonwealth Ave West

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability

%

Final ? Yes / No

CLS 8380H



INSRS

WSP

Tel

Liability

RMKS

Fastech



INSRS

WSP

Tel

Liability

RMKS



INSRS

WSP

Tel

Liability

RMKS



INSRS

WSP

Tel

Liability

RMKS

Date / Time

19/6

01/7

CLS 8380H

645886M

NA/CL/001038/1/4

001A 21/6/18

(owner)

29/6/18 @ 4:45pm Called OIB, Mr Heng, Confirm 2veh cc. He was last car. Inam to claim. Agreed to settle cover NCD issue. To send letter by email & post.

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI

21/6/18 y. 29/6/18

After call Itr to OI

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time

26/7/18

Sent By

Ch

FINALIZATION

Date/Time

Confirm with

Confirm by

Repair Cost

S\$

(

days) Reduction

%

Email

Call

FINAL SETTLEMENT

Date/Time

26/10/18

Confirm with

Jason

Email

Call

Final Liability

%

100

(Agreed / Assessed)

BOLA S/N No. 28 (3veh cc. 013m)

NO or B 28, Ass. Lia: 100%

Repair Cost

S\$

7918.00

Loss of Rental (LOR)

S\$

(

days)

Loss of Use (LOU)

S\$

8w.w (\$50

x

16 days)

Loss of Income (LOI)

S\$

(

\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical

S\$

Disbursement

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total

S\$

8720.00

Global Sum S\$

FINAL PAYMENT

Date/Time

Confirm with

Email

Call

Payee 1

S\$

8720.00

Name 1

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2

Payee 3: (Strike if N.A.)

S\$

Name 3

1) Claim status: Normal/Reject/Private Settle

2) Report Format

3) Survey fee

4w.w

30/10/18

all over

RECEIVED 30 OCT 2018

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL58380Hat Workshop m/s L1

of _____

Insured: G45886M

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 12500

D/C Accident Report: _____ Consistent?: Yes or No

G/A / PR Seen: 9 Consistent?: Yes or NoEst. Repairs: 15 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL58380H Yr Regn: 29/4 09Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime MoverTruck / Trailer or CAMake: Kia Picanto C.C. 1088Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 137959 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNABA26338T753630Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 165/60R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal: 5 mm R/Bal: 5 mmL/Bal: 5 mm L/Bal: 5 mmD.O.A. 7/6/18 D.O.J. 8/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear & L1

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L14 5070next 743010 mth.26/6/18 confirmed L/S @ 7400 with Rm.(Ref # 15632/ 6071)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

3) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQI18010479/Upa3

Date: 26.07.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD
Attn : Justin

Dear Sirs,

PRELIMINARY ADVICE OF VEHICLE NO.

SLS 8380H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/06/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	23,032.00	
Revised Estimate Amount	: S\$	7,400.00	
"Check" Items Amount	: S\$		
Market Value	: S\$	12,500.00	(est)
LTA Reimbursement Value	: S\$	5,070.00	(est)
Nett Value	: S\$	7,430.00	(est)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 15.0 days

Yours faithfully,

Marcus Chua
Licensed Appraiser

FASTECH AUTO PTE LTD

VEHICLE NO: SLS 8380H

Qty Particular

List Item:

Not Allowed
L/S # 7400
8/6/18
Amount S\$ 1527.

1PCS	REAR WINDSCREEN MOULDING	nee	\$118.00	—
1PCS	TAILGATE	So. by 20	\$665.00	✓
1PCS	TAILGATE 'PICANTO' EMBLEM	nee	\$31.00	—
1PCS	TAILGATE 'KIA' LOGO	11	\$30.00	X
1PCS	TAILGATE C&C LOGO	nee	\$38.00	✓
1PCS	TAILGATE INNER LOCK	twi/gm	\$89.00	✓
1PCS	TAILGATE LOCK STRIKER	11	\$40.00	X
1PCS	TAILGATE INNER TRM	11	\$181.00	X
1PCS	TAILGATE WEATHERSTRIP	twi	\$108.00	—
1PCS	REAR BUMPER	7.5	\$289.00	—
1PCS	REAR BUMPER REINFORCEMENT	7.5	\$175.00	—
2PCS	REAR BUMPER SIDE RETAINERS @\$25.00	3ent	\$50.00	—
1SET	REAR BUMPER CLIPS	nee	\$42.00	—
2PCS	REAR BUMPER SPLASH SHIELDS @\$39.00	11	\$78.00	X
1PCS	REAR END PANEL	So. by 20	\$285.00	—
1PCS	REAR END PANEL TOP GARNISH	twi	\$115.00	✓
2PCS	TAILLAMPS @\$266.00	one	\$532.00	—
1PCS	REAR FLOOR PANEL	cramped/gu	\$782.00	✓
1PCS	REAR FLOOR PANEL INSULATOR	nee	\$190.00	505.2
1PCS	REAR FLOOR PANEL TOOLS SPONGE	11	\$195.00	X
2PCS	REAR FENDERS @\$655.00	1	\$1310.00	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$199.00	n/s de	\$398.00	116
1PCS	REAR WHEEL HOUSING PANEL N/S	1	\$685.00	X

107

FASTECH AUTO PTE LTD

VEHICLE NO:

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	REAR SHOCK ABSORBER N/S	11 \$125.00 X
1PCS	REAR AXLE BEAM	11 \$988.00 X
1PCS	BONNET	342 \$495.00 ✓
2PCS	BONNET HINGES @\$65.00	11 \$130.00 X
1PCS	BONNET LOCK	721 \$49.00 ✓
1PCS	FRONT BUMPER	703 \$322.00 ✓
1PCS	FRONT BUMPER CENTRE GRILLE	701 \$82.00 ✓
1PCS	FRONT BUMPER FOG LAMP COVER N/S	11 \$45.00 X
1PCS	FRONT BUMPER SPONGE	701 \$102.00 ✓
1PCS	FRONT BUMPER REINFORCEMENT	703 \$226.00 ✓
1PCS	FRONT GRILLE	341/one \$165.00 ✓
1PCS	FRONT GRILLE BASE	115 \$145.00 X
1PCS	FRONT GRILLE LOGO	112 \$35.00 ✓
2PCS	HEADLAMPS @\$305.00	one \$610.00 ✓
2PCS	FRONT FENDERS @\$366.00	11 \$732.00 X
2PCS	FRONT FENDER INNER SHIELDS @\$145.00	11 \$290.00 X
1SET	FRONT FENDER INNER SHIELD CLIPS	11 \$45.00 X
1PCS	FRONT SUPPORT PANEL	341/one \$562.00 ✓
1PCS	AIR CON CONDENSER	703 \$485.00 ✓
1PCS	AIR CON HOSE	11 \$185.00 X
1PCS	RADIATOR	341/one \$598.00 ✓

(107)

FASTECH AUTO PTE LTD

VEHICLE NO

Qty Particular

Amount S\$

List Item:

1PCS RADIATOR FAN MOTOR ASSY
1PCS FUSE BOX
1PCS AIR CLEANER BOX
1PCS BATTERY BOX
1PCS FRONT WHEEL HOUSING PANEL N/S

102
cns/ym \$395.00 ✓
11 \$195.00 x
11 \$320.00 x
11 \$105.00 x
1 \$620.00 x

List Item Total:

\$14,477.00

7644
6879-6

Special Nett Item:

1PCS REAR LICENCE PLATE W/HOLDER
1SET REAR BUMPER REVERSE SENSOR
1PCS REAR WINDSCREEN SEALANT
1PCS REAR END PANEL SEALANT
1PCS FRONT LICENCE PLATE W/HOLDER
1BOL RADIATOR COOLANT

Best \$50.00 40
shwd \$280.00 200
ner \$50.00 40
ner \$50.00 ✓
3no \$50.00 40
ner \$50.00 30

Special Nett Total:

\$530.00

Labour Charge:

TOWING CHARGE.
TO CHECK WIRING.
TO DISMANTLE & REPLACING REVERSE SENSOR.
TO DISMANTLE & REFIX REAR WINDSCREEN.
TO TRANFER TAILGATE COMPONENTS.
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.

\$65.00 50
\$100.00 30
\$100.00 50
\$150.00 120
\$100.00 60
\$180.00 80

FASTECH AUTO PTE LTD

VEHICLE NO:

Qty Particular

Amount S\$

Labour Charge:

TO CONDUCT CHASSIS ALIGNMENT.

11 \$380.00 X

TO REFILL AIR CON GAS.

\$150.00 100

LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN

& REPLACING PARTS.

\$3800.00 2000

TO PUTTY & SPRAY PAINTING.

\$3000.00 1680

Labour Charge Total:

\$8025.00

11649.6

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$23,032.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To replace Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	6341B

Vehicle Details

Vehicle No.:	SLS8380H
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jun 2018
Vehicle Make:	KIA
Vehicle Model:	PICANTO 1.1(A)
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4HG9557223
Chassis No.:	KNABA24339T753630
Maximum Power Output:	47.1 kW (63 bhp)
Open Market Value:	\$8,805.00
Original Registration Date:	29 Apr 2009
First Registration Date:	29 Apr 2009
Transfer Count:	3
Actual ARF Paid:	\$8,805.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2019
PARF Rebate Amount:	\$4,402.00

Intended COE Rebate Details

COE Expiry Date:	28 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,589.00
COE Rebate Amount:	\$668.00
Total Rebate Amount:	\$5,070.00

The information contained herein is correct as at 08 Jun 2018

OK

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Kia Picanto

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home > Used Cars > 786 Blitz Automobile LLP > Kia Picanto 1.1A

Resources

Car Buying

Car Selling


Car Ownership


Car Aftermarket

On The Move

Lifestyle

Car Tyres





Kia Picanto 1.1A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$11,786

Depreciation

\$9,540 /yr

View models with similar depreciation

Reg Date

16-Mar-2009

(9mths 7days COE left)

Manufactured

2009

Mileage

113,000 km (12.2k /yr)

Transmission

Auto

Engine Cap

1,086 cc

Road Tax

\$442 /yr

Power

47.1 kW (63 bhp)

View specs of the Kia Picanto (2005-2010)

Curb Weight

872 kg

Features

Fuel Efficient 4 Cylinders Inline 1.1L SOHC Engine, 63 BHP, Low Fuel Consumption, Knockdown Rear Seats.

Accessories

Audio System, Leather Seats, Remote Key, Solar Films, Reverse Sensors, Fog Lamps.

Description

New Road Tax, In-House Finance Available. 2 Free Standard Servicing By Our Own Workshop. Pristine Condition. Do Not Hesitate To Call For Appointment. Professional Grooming By Ceramic Works.

COE

\$1,020

OMV

\$8,933

ARF

\$8,933

Dereg Value

\$4,545 as of today (change)

No. of Owners

2

Type of Veh

Hatchback

Category

PAFF Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 25-Apr-2018 | Last Updated on: 25-Apr-2018

Tags: Kia Picanto, 2009 Kia Picanto, Kia, Picanto, Used Kia

Upfront Payment

> More Financial Info


Transfer Fee




\$25


Down Payment

\$3,536 (change)

Maximum 70% Loan







Location Map

Price Analysis

Seller Information

Company

786 Blitz Automobile LLP

» dealer's pricelist

» 1 vehs sold | 6 vehs available

Address

13 Kaki Bukit Road 4 #01-25

Search cars nearby this location

Location


Bartley Biz Centre

Contact Person(s)

Dan


93259171

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

http://www.sgcarmart.com/used_cars/info.php?ID=717012&DL=2784

08-Jun-18

Sharing
&
Serving

COME VOLUNTEER WITH US!
If you are 40 years old and above and are able to spend half a day every month to contribute your talents and skills in many meaningful ways, we want you!


RSVP
SINGAPORE
RSVP SINGAPORE
SINCE 1982

Kia Picanto

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Carz World Pte Ltd » Kia Picanto 1.1A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Rental

For Private & Commercial Vehicles
Rental From
\$50/Day





Plan Your Next Trip

\$81

KSL Hotel & Resort

Learn more

Robertson Quay Hotel

Learn more

The Ritz-Carlton, Millenia Singapore

Learn more

Kia Picanto 1.1A

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$10,288	
Depreciation	\$7,460 /yr	View models with similar depreciation
Reg Date	19-Mar-2009	(9mths 10days COE left)
Manufactured	2009	
Mileage	86,000 km (9.3k /yr)	
Transmission	Auto	
Engine Cap	1,086 cc	
Road Tax	\$442 /yr	
Power	47.1 kW (63 bhp)	View specs of the Kia Picanto (2005-2010)
Curb Weight	872 kg	
Features	Fuel Efficient 1.1L 4 Cylinder Inline SOHC Engine. 4 Speed Automatic Transmission. Power Steering. Knockdown Rear Seats. Leather Seats.	
Accessories	Remote Alarm. Audio System. Fog Lamps. Standard Wheels. Reverse Sensor. Well Kept Interior Condition. Original Exterior Still In Good Condition.	
Description	Road Tax Fully Paid Till Scrap! Mileage 93,000km Only. Regularly Serviced. No Repairs Needed. Just Changed 3 Belts (Timing Belt Included) For Peace Of Mind. Female Driver. Consignment Unit. Viewing Strictly By Appointment Only!	
COE	\$4,890	
OMV	\$9,009	
ARF	\$9,009	
Dereg Value	\$4,884 as of today (change)	
No. of Owners	3	
Type of Veh	Hatchback	
Category	PAPF Car, Premium Ad Car, Low Mileage Car	
Availability	Available	PREMIUM AD

Add to Shortlist Add to Compare Add a Note

Posted on: 17-Apr-2018 | Last Updated on: 28-May-2018
Tags: Kia Picanto, 2009 Kia Picanto, Kia, Picanto, Used Kia















Seller Information

Company

Carz World Pte Ltd

• dealer's pricelist

• 16 vehs sold | 13 vehs available

Address

33 Ubi Avenue 3 #01-09

Search cars nearby this location

Location

Vertex

Office No

65709482

Contact Person(s)

Gary

90928643

Edwin

96437773

Ben

87428218

Terry

98371577

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

Upfront Payment > more Financial info

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 26 July 2018 9:30 AM
To: 'justin.wong@eqinsurance.com.sg'
Cc: Joy Irene (LKKAuto); Asher Sng (LKKAuto); Admin A; Poh Kin (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018
Attachments: TP ESTIMATE_MARKED_.pdf; Preliminary Advice - SLS 8380H.pdf; PARF_COE REBATE.pdf; LKK Survey Photos.pdf

Your Ref: **TBA**
LKK REF: CC6/EQI18010479/Upa3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Francis Ng <francis.ng@eqinsurance.com.sg>
Sent: Monday, 18 June 2018 12:00 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

Dear Mei Kwan,

Our insured's report is attached.

Regards,
Francis Ng

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify I

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Monday, June 18, 2018 11:46 AM

To: Francis Ng <francis.ng@eqinsurance.com.sg>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

WITHOUT PREJUDICE

Your ref: TBA

LKK ref: CC6/EQI18010479/Upa3

Dear Francis,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SLS 8380H at M/s Fastech Auto Pte Ltd - Kaki Bukit.

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Enclosed for your perusal is:

- Photographs of TP vehicle in its damaged condition
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 2 July 2018 8:07 AM
To: 'ALVINHENG1985@GMAIL.COM'
Subject: ACCIDENT INVOLVING GY 5886M(EQ)/ SLS 8380H/ OTHERS ON 07/06/2018

03 JULY 2018

A & J MAINTENANCE SERVICES
ATTN: THE MANAGEMENT

Dear Sir/Madam,

Our Ref: CC6/EQI18010479/Upa3
ACCIDENT INVOLVING GY 5886M(EQ)/ SLS 8380H/ OTHERS ON 07/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from SLS 8380H against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

c.c. EQ INSURANCE COMPANY LIMITED
(Motor Claims Dept)

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DNECSH2037561700	Engine No : G4HG5557223 Chassis No: KHABA2433PT753630
1. Index Mark and Registration Number of Vehicle	EL38380H	
2. Name of Policy Holder	M/S SHARANI BINTE KHAMIS	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	23 DECEMBER 2017 (11:41 HOURS) 22 DECEMBER 2018	NAMED DRIVERS EX SECT. I.....\$8500.00 IN ADDITION TO NAMED DRIVERS EX: EX SECT. I - AGE <= 25.....\$80,000.00 EX SECT. I - AGE >= 26.....\$8500.00 + AGE AS AT DATE OF ACCIDENT EX ON WINDSCREEN.....\$8100.00
4. Date of Expiry of Insurance		
5. Persons or Classes of Persons entitled to drive *		

(A) THE POLICYHOLDER.
(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT RESPECT FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR RENTAL TUITION DRIVING TEST RACING RACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS - THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$8500 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF ONE DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : HONG LEONG FINANCE LTD AS RE OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse.
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:

Authorised Officer

Authorised Signatory

REPUBLIC OF SINGAPORE DRIVING LICENCE



Identification Number: S8136341B

Name: SHARANI BINTE KHAMIS

Birth Date: 07 Nov 1981

Issue Date: 05 Jan 2005



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8136341B



Name

SHARANI BINTE KHAMIS

Race

MALAY

Date of Birth

07-11-1981

Country of Birth

SINGAPORE

Sex

F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 1 Motor cars < 3000 kg with < 7 passengers, exclusive of the driver, and motor tractors / vehicles < 2000 kg

Issue Date

04 Nov 2002



License No. S8136341B

HP 425A



NRIC No. S8136341B



Registration

03-01-2005

AFT BLK 9 JALAN BATU POK-21
SINGAPORE 431000

NRIC No. S8136341B

Date: 25/03/2014

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 6341B

Vehicle Details

Vehicle No.: SL58380H
Vehicle to be Exported: No
Intended De-registration Date: 07 Jun 2018
Vehicle Make: KIA
Vehicle Model: PICANTO 1.1(A)
Primary Colour: Blue
Manufacturing Year: 2009
Engine No.: G4HG9557223
Chassis No.: KNABA24339T753630
Maximum Power Output: 47.1kW (63 bhp)
Open Market Value: \$8,805.00
Original Registration Date: 29 Apr 2009
First Registration Date: 29 Apr 2009
Transfer Count: 3
Actual ARF Paid: \$8,805.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Apr 2019
PARF Rebate Amount: \$4,402.00

Intended COE Rebate Details

COE Expiry Date: 28 Apr 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$7,589.00
COE Rebate Amount: \$676.00
Total Rebate Amount: \$5,078.00

The information contained herein is correct as at 07 Jun 2018

OK

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 13 October 2018 11:55 AM
To: 'Justin Wong'
Cc: Joy Irene (LKKAUTO); Asher Sng (LKKAUTO); Admin A; Poh Kin (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - DM18HO01463/JW) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018
Attachments: LKK Survey Report & Photos.pdf; TP LOD_SLS8380H.pdf

Your ref : **DM18HO01463/JW**
Our ref : CC6/EQI18010479/Upa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GY5886M(OI) / SLS8380H(TP) / OTHERS ON 07/06/2018

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "FASTECH AUTO PTE LTD" at **\$8,720.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 24,644.24	\$ 7,918.00
2. Loss of Use (17days x \$100.00)	\$ 1,700.00	\$ 800.00 (16days x \$50.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 26 346.24	<u>\$ 8,720.00</u>

Market Value	: \$12,500.00 (est)
LTA Rebate	: \$ 5,070.00 (est)
Nett Value	: <u>\$ 7,430.00 (est)</u>

**15days recommendation for repair

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 26 October 2018 5:45 PM
To: 'jason@fastechauto.com.sg'
Subject: RE: Your ref: SLS 8380H *Our Ref: CC6/EQI18010479/Upa3q2 [ACCIDENT INVOLVING GY 5886M(EQ) / SLS 8380H / OTHERS ON 07/06/2018]

Without Prejudice

Hi Jason,

As spoken earlier, we confirm settlement at a global sum of \$8,720.00(all-in).

We will proceed to close file.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Tuesday, 23 October 2018 10:05 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Your ref: SLS 8380H *Our Ref: CC6/EQI18010479/Upa3q2 [ACCIDENT INVOLVING GY 5886M(EQ) / SLS 8380H / OTHERS ON 07/06/2018]

Without Prejudice

Dear Hsiao Tong,

We are unable to accept your offer.

We are counter proposing at global sum \$9600 all in (Property claim only).

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Monday, October 22, 2018 10:50 AM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: Your ref: SLS 8380H *Our Ref: CC6/EQ18010479/Upa3q2 [ACCIDENT INVOLVING GY 5886M(EQ) / SLS 8380H / OTHERS ON 07/06/2018]

Your ref: **SLS 8380H**
Our Ref: CC6/EQ18010479/Upa3q2

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING GY 5886M(EQ) / SLS 8380H / OTHERS ON 07/06/2018

We refer to the above matter.

We propose settlement at a global sum of **\$8,700.00(all-in)**.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Date : 04.07.2018

EQ Insurance Company Limited

5 Maxwell Road

#17-00 Tower Block MND Complex

Singapore 069110

Attn: Motor Claims Department

ACCIDENT INVOLVING VEHICLE: SLS 8380H / GY 5886M ON 07.06.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SLS 8380H**, which was involved in the captioned accident with your insured vehicle no: **GY 5886M**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	7,918.00
2) Loss Of Use (15 days + 2 Sunday X \$100)	\$	1,700.00
3) GIA Search Result	\$	2.00
	\$	9,620.00

We enclosed herewith the following documents to support the claims:

- | | |
|-----------------------------------|------------------------------------|
| a) Final Repair Invoice | e) Vehicle Registration Log Card |
| b) I/C & Driving License | f) Letter of Authorisation, etc... |
| c) GIA Report / GIA Search Result | |
| d) Insurance Certificate | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,



Jason Tang (jason@fastechauto.com.sg)

FASTECH AUTO PTE LTD



Auto
Consultants
Pte Ltd

31 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQ118010479/Upa3

03 JULY 2018

A & J MAINTENANCE SERVICES
BLK 319A ANCHORVALE DRIVE
#08-76
SINGAPORE 541319
ATTN: THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GY 5886M/ SLS 8380H/ OTHERS ON 07/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from SLS 8380H against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

DATE : 07.06.2018

TO : EQ Insurance Company Limited

RE : ACCIDENT INVOLVING VEHICLE NO. SLS 8380H and
GY 5885M ONLY
ALONG BOON LAY WAY TWDS CLEMENTI
ON 07.06.2018

I/We, SHARANI BINTE KHAMIS
of (NRIC No./ROC No.) S6135341B
of BLK 9 JLN BATU #04-31 S-431009
owner of vehicle no. SLS 8380H in consideration of M/s FASTECH AUTO
PTE LTD repairing my/our vehicle SLS 8380H at my/our instruction and hereby
authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever
amount settled/payable by the Insurance Company and/or third party or to commence legal
proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use,
etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and
all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost
which may arisen therewith.

Signature of Owner : 

Name of Owner : SHARANI BINTE KHAMIS

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

EQ Insurance Company Limited

5 Maxwell Road

#17-00 Tower Block MND Complex

Singapore 069110

Attn: Motor Claims Department

Tax Invoice : 20338

Date : 04.07.2018

Vehicle No : SLS 8380H

Make/Model : KIA PICANTO

Chassis/Eng# :

Accident Date : 07.06.2018

Claim No : 0618- 20338

Reference :

Policy No :

Amount

To proceed on lump sum repair

S\$

7,400.00

E. & O. E.

Total : S\$ 7,400.00

GST @ 7% : S\$ 518.00

Amount Due : S\$ 7,918.00


FASTECH AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-087238
Date of Request: 07/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 07/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. GY5886M
Accident Date 07/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GY5886M	EQ Insurance Company Ltd	01/08/2017-31/07/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-087236
Date of Request: 07/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 07/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. GY5886M
Accident Date 07/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Hsiao Tong (LKKAUTO)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Monday, 15 October 2018 9:24 AM
To: Hsiao Tong (LKKAUTO)
Cc: Joy Irene (LKKAUTO); Asher Sng (LKKAUTO); Admin A; Poh Kin (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving GY5886M (OI : EQI - DM18HO01463/JW) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018
Attachments: LKK Survey Report & Photos.pdf; TP LOD_SLS8380H.pdf

Dear Hsiao Tong,


Please proceed to settle as per the revised amount of \$8,720.00 (all-in).

Thank you.

Regards,
Justin Wong
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, October 13, 2018 11:55 AM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Cc: Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - DM18HO01463/JW) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

Your ref : **DM18HO01463/JW**
Our ref : CC6/EQI18010479/Upa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GY5886M(OI) / SLS8380H(TP) / OTHERS ON 07/06/2018

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "FASTECH AUTO PTE LTD" at **\$8,720.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 24,644.24	\$ 7,918.00
2. Loss of Use (17days x \$100.00)	\$ 1,700.00	\$ 800.00 (16days x \$50.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 26 346.24	<u>\$ 8,720.00</u>

Market Value	: \$12,500.00 (est)
LTA Rebate	: \$ 5,070.00 (est)
Nett Value	: <u>\$ 7,430.00 (est)</u>

**15days recommendation for repair

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Justin Wong <justin.wong@eqinsurance.com.sg>

Sent: Friday, 27 July 2018 10:22 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

Dear Hsiao Tong,

Please be informed that our insured vehicle is GY5886M and our ref is :DM18HO01463/JW.

Thank you.

Regards,

Justin Wong

Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Thursday, July 26, 2018 9:30 AM

To: Justin Wong <justin.wong@eqinsurance.com.sg>

Cc: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

Your Ref: **TBA**

LKK REF: CC6/EQI18010479/Upa3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Francis Ng <francis.ng@eqinsurance.com.sg>

Sent: Monday, 18 June 2018 12:00 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

Dear Mei Kwan,

Our insured's report is attached.

Regards,
Francis Ng
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately by email.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Monday, June 18, 2018 11:46 AM

To: Francis Ng <francis.ng@eqinsurance.com.sg>

Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GY5886M (OI : EQI - TBA) AND SLS8380H (TP : LKK REF - CC6/EQI18010479/Upa3) on 07/06/2018

WITHOUT PREJUDICE

Your ref: TBA

LKK ref: CC6/EQI18010479/Upa3

Dear Francis,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SLS 8380H at M/s Fastech Auto Pte Ltd - Kaki Bukit.

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Enclosed for your perusal is:

- Photographs of TP vehicle in its damaged condition
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 09/11/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GY 5886M (Insd Veh)	Your Ref. No. : DM18HO01463/JW
	SLS 8380H (TP Veh)	Our Ref. No. : CC6/EQI18010479/Upa3q2
Date of Accident	7/6/2018	

Liability	100%	
Final Repair Cost	: \$ 7,918.00	
Loss of Use	: \$ 800.00	16 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	8,720.00	
Final Settlement Sum	: \$ 8,720.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	FASTECH AUTO PTE LTD	: \$ 8,720.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18010479/Upa3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 09-11-2018		
		Code : EQ1		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 5886M	Veh. Inspected	SLS 8380H	
Policy No.	DMCPHQ17-004213	Coverage (\$)	0.00	
Claim No.	DM18HO01463/JW	Excess (\$)	0.00	
Assign From		Assign Date	08/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA PICANTO (A)	c.c	1086	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KNABA24339T753630	Colour	BLUE	
Odometer	137959	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/60 R14	YOKOHAMA	5 mm	
L/H Front Tyre	165/60 R14	YOKOHAMA	5 mm	
R/H Rear Tyre	165/60 R14	YOKOHAMA	5 mm	
L/H Rear Tyre	165/60 R14	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/06/2018	Inspection Date	08/06/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8380H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	118.00	118.00
1	TAILGATE	BADLY DENTED	665.00	665.00
1	TAILGATE 'PICANTO' EMBLEM	NECESSARY	31.00	31.00
1	TAILGATE 'KIA' LOGO	NOT NECESSARY	30.00	-
1	TAILGATE C&C LOGO	NECESSARY	38.00	38.00
1	TAILGATE INNER LOCK	TWISTED / JAMMED	89.00	89.00
1	TAILGATE LOCK STRIKER	NOT NECESSARY	40.00	-
1	TAILGATE INNER TRIM	NOT NECESSARY	181.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	108.00	108.00
1	REAR BUMPER	DISTORTED	289.00	289.00
1	REAR BUMPER REINFORCEMENT	DISTORTED	175.00	175.00
2	REAR BUMPER SIDE RETAINERS @\$25.00	BENT	50.00	50.00
1	SET REAR BUMPER CLIPS	NECESSARY	42.00	42.00
2	REAR BUMPER SPLASH SHIELDS @\$39.00	NOT NECESSARY	78.00	-
1	REAR END PANEL	BADLY DENTED	285.00	285.00
1	REAR END PANEL TOP GARNISH	TWISTED	115.00	115.00
2	TAILLAMPS @\$266.00	CRACKED	532.00	532.00
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	782.00	782.00
1	REAR FLOOR PANEL TOOLS SPONGE	NOT NECESSARY	195.00	-
2	REAR FENDERS @\$655.00	TO REPAIR SEE LABOUR	1,310.00	-
2	REAR FENDER INNER TRIM BOARDS @\$199.00	N/S DEFORMED	398.00	199.00
1	REAR WHEEL HOUSING PANEL N/S	TO REPAIR SEE LABOUR	685.00	-
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	125.00	-
1	REAR AXLE BEAM	NOT NECESSARY	988.00	-
1	BONNET	BUCKLED	495.00	495.00
2	BONNET HINGES @\$65.00	NOT NECESSARY	130.00	-
1	BONNET LOCK	TWISTED	49.00	49.00
1	FRONT BUMPER	DISTORTED	322.00	322.00
1	FRONT BUMPER CENTRE GRILLE	TORN	82.00	82.00

Report Ref No. CC6/EQ18010479/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER FOG LAMP COVER N/S	NOT NECESSARY	45.00	-
1	FRONT BUMPER SPONGE	TORN	102.00	102.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	226.00	226.00
1	FRONT GRILLE	BENT / CRACKED	165.00	165.00
1	FRONT BUMPER BASE	NO SUCH PARTS	145.00	-
1	FRONT GRILLE LOGO	NECESSARY	35.00	35.00
2	HEADLAMPS @\$305.00	CRACKED	610.00	610.00
2	FRONT FENDERS @\$366.00	TO REPAIR SEE LABOUR	732.00	-
2	FRONT FENDER INNER SHIELDS @\$145.00	NOT NECESSARY	290.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	45.00	-
1	FRONT SUPPORT PANEL	BENT / CRACKED	562.00	562.00
1	AIR CON CONDENSER	DISTORTED	485.00	485.00
1	AIR CON HOSE	NOT NECESSARY	185.00	-
1	RADIATOR	BENT / PUNCTURE	598.00	598.00
1	RADIATOR FAN MOTOR ASSY	CRACKED / JAMMED	395.00	395.00
1	FUSE BOX	NOT NECESSARY	195.00	-
1	AIR CLEANER BOX	NOT NECESSARY	320.00	-
1	BATTERY BOX	NOT NECESSARY	105.00	-
1	FRONT WHEEL HOUSING PANEL N/S	TO REPAIR SEE LABOUR	620.00	-
	LESS 10% DISCOUNT		-	-764.40
			14,287.00	6,879.60
	SPECIAL NETT ITEMS			
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	190.00	50.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			720.00	450.00

Report Ref No. CC6/EQ18010479/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING CHARGE.		65.00	50.00
	TO CHECK WIRING .		100.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		100.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .		150.00	120.00
	TO TRANFER TAILGATE COMPONENTS .		100.00	60.00
	TO DISMANTLE & REFIX SEAT .CUSHION UPHOLSTERY.		180.00	80.00
	TO CONDUCT CHASSIS ALIGNMENT .	NOT NECESSARY	380.00	-
	TO REFILL AIR CON GAS.		150.00	100.00
	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS .INCLUSIVE OF THE REPAIR OF REAR FENDERS,REAR WHEEL HOUSING PANEL N/S,FRONT FENDERS AND FRONT WHEEL HOUSING PANEL N/S .		3,800.00	2,000.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,680.00
			8,025.00	4,170.00
	GRAND TOTAL		23,032.00	11,499.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,400.00

Report Ref No. CC6/EQ118010479/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.