

 $51~\mathrm{UBI~AVE~1}, \#02\text{-}25~\mathrm{PAYA~UBI~INDUSTRIAL~PARK}, \mathrm{SINGAPORE~408933~TEL:} \\ (065)~62563561~\mathrm{FAX:} \\ (065)~62564315$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 12/9/2018

Survey Details:

Date of loss	6-Jun-18
Date of appointment	8-Jun-18
Date of survey	8-Jun-18
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 3760J
Make and Model	HYUNDAI I40 1685cc
Date of registration	Aug-14
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 11	L,833.98
------------------	-------	----------

Proposed/Revised repair cost:

Parts	\$ 2,618.50
Check items (estimate)	\$0
Labour	\$ 1,350.00
Total	\$ 3,968.50
Lump Sum(if applicable)	\$ 3,150.00

Number of days for repair	<u>3 days</u>



 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\;\; FAX: (065)\; 6256415\;\; FAX: (065)\;\; FAX: (065$

Remarks:

We called OID Mr Md Izzudin and OI Mr Cheong but to no avail. It was reported that Insured Drvier had rear-ended TP. As such, a letter was sent out to the Insured to inform of liability and TP claim. No feedback from OI till date. BOLA 27 - OID rear-ended TP. TP LOD IN.

Mandate:

Liability(TP)	100%	
Proposed Repair Cost	\$ 3,370.50	w/gst
Loss of Use	\$ -	No. of days
Loss of Rental	\$ 596.40	\$119.28 x5 days
Loss of Income	\$ 250.00	\$50 x 5 days
GIA/LTA search fees	\$ 7.49	
Others	\$ -	
Proposed Total	\$ 4,224.39	
Global Sum	\$ 4,200.00	