

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg
GST:200712509E RCB NO:200712509E

not Arthur
link
2/58
11/6/18
Take photo after
rep.
5 day.

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, S068811

Email: motor.survey@axa.com.sg

TEL: 6880 4741(Hotline) FAX: 6880 4740/6880 4838

ATTN: Motor Claim Department

Your Ref No: SJV2931R

Claim Type: Third Party

Accident Date: 07-06-2018

TP Veh Reg No: SCK2437S

Estimate No: EST0000642

Date: 07 Jun 2018

Policy No: 5086594859-02

Veh Reg No: SJV2931R

Make/Model: TOYOTA ALTIS

Chassis No: MR053ZEE106164361

Engine No: 3ZZ4961964

Reg. Date: 20-01-2010

Estimate Repair Cost to Vehicle No :SJV2931R

Description	U/Price	Quantity	List Price S\$	Amount S\$
TOYOTA ALTIS 1.6				
List Price				
1 Front Fender RH <i>30-300</i>	655.1000	1 PC	655.10	—
2 Front Fender Dust Cover <i>70-1</i>	98.2000	1 PC	98.20	—
3 Front Fender Dust Cover Eclipse RH <i>neu</i>	5.5000	6 PC	33.00	—
4 Front Fender Emblem <i>neu</i>	28.4000	1 PC	28.40	—
5 Front Door RH <i>30-300</i>	1,138.900	1 PC	1,138.90	—
6 Front Door Pillar <i>neu</i>	689.2000	1 PC	689.20	X
7 Front Door Protector RH <i>neu</i>	198.4000	1 PC	198.40	—
8 Front Door Hinge Top RH <i>11</i>	48.6000	1 PC	48.60	+
9 Front Door Hinges Lower RH <i>neu</i>	48.6000	1 PC	48.60	—
10 Front Door Rubber RH <i>neu</i>	246.2000	1 PC	246.20	—
11 Front Door Check RH <i>neu</i>	58.4000	1 PC	58.40	—
12 RH Side Skirt RH <i>merged/70-1</i>	642.4000	1 PC	642.40	—
13 Front Shock Absorber	356.9000	2 PC	713.80	?
14 Front Knuckle Arm	456.4000	2 PC	912.80	?
15 Front Lower Arm	398.4000	2 PC	796.80	?
16 Front Hub Bearing	206.4000	2 PC	412.80	?
			6,721.60	
		Less 10%	672.16	6,049.44
Special Net				
17 Front Sport Rim <i>20/200 280 x 2 = 560</i>	650.0000	2 PC	1,300.00	560
18 Front Tyre LH <i>neu/200 2P 180</i>	250.0000	1 PC	250.00	600 @ 150
			1,550.00	1,550.00
Labour				
19 Towing	50.0000	1 PC	50.00	✓
20 Check Wiring	60.0000	1 PC	60.00	20
21 Rust Proofing	60.0000	1 PC	60.00	✓
22 To Remove & Replace Front Undercarriage	280.0000	1 PC	280.00	?
23 To Adjust Alignment	50.0000	1 PC	50.00	✓
24 To Remove & Replace Door Assy	80.0000	1 PC	80.00	60
25 Panel Beating	1,200.0000	1 PC	1,200.00	600
26 To Spray Painting	850.0000	1 PC	850.00	800
			2,630.00	2,630.00

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, S068811

Email: motor.survey@axa.com.sg

TEL: 6880 4741(Hotline) FAX: 6880 4740/6880 4838

ATTN: Motor Claim Department

Your Ref No: SJV2931R

Claim Type: Third Party

Accident Date: 07-06-2018

TP Veh Reg No: SCK2437S

Estimate No: EST0000642

Date: 07 Jun 2018

Policy No: 5086594859-02

Veh Reg No: **SJV2931R**

Make/Model: TOYOTA ALTIS

Chassis No: MR053ZEE106164361

Engine No: 3ZZ4961964

Reg. Date: 20-01-2010

Estimate Repair Cost to Vehicle No :SJV2931R

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 10,229.44

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED TWENTY NINE AND CENTS FORTY FOUR ONLY

For PROGRESSIVE AUTO PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: