

INS. CASE OWNER: Joel | CC 6 / EQ11801 0611, Ufb3 | LKK: 11/6/18
 IDAC: 11/6/18

Surveyor: Marius | DOI: ASSIGNMENT 11/6/18 | Date / Time: 11/6/18
 Registered in Meritum: —

Pre-assign / CCU / FTE



Insured Vehicle No.: SLR 1673P | Claim No.: DM LETH 18-011035
 Name of Insured: EMBI CAR LEASING & MARKETING | Policy No.: 7140211
 Insured Tel No.: — | HP: 8/6/18 | Make / Model: —
 Excess Sec II :SS | D.O.A: 8/6/18 | Place of Accident: DIE TUNGS NEAR LAMPANG 1
 Is driver the owner? (YES / (N)) | Nature of Accident: RA EXIT
 If NO, Driver Name / Age: U ANHUA 31YR | OI GIA REPORT: (Y) / NO : TP GIA REPORT: (N) / NO
 Driver Tel No.: — | (VA) (Y) / YES / NO | Insured Liability: — % Final ? Yes / No

SLX 5761G



INSRS: Quam
 WSP: bc.
 Tel: —
 Liability: —
 RMKS: —



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:



INSRS:
 WSP:
 Tel:
 Liability:
 RMKS:

Date / Time	STAGE	DATE / PIC
<u>11/6/18</u>	<u>SLX 5761G-X</u>	<u>SLR 1673P-X</u>
<u>11/6/18</u>	<u>pph kin</u>	
<u>11/11/18</u>	<u>Send letter to OI, email liability clear</u>	
	<u>kin led ✓</u>	
	<u>After repair photo ✓</u>	

PRELIMINARY ADVICE	Date/Time: <u>27/11/2018</u>	Sent By: <u>CFK</u>	Confirm with:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS <u>5,800.00</u>	(<u>18</u> days) Reduction: <u>51</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>30/11/2018</u>	Confirm with: <u>Seifiter</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	SS <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>27</u>	If NO or B 25, Ass. Lia:
Repair Cost:	SS <u>5,800.00</u>		
Loss of Rental (LOR):	SS <u>—</u>	(<u>—</u> days)	
Loss of Use (LOU):	SS <u>4,480.00</u>	(<u>500.00</u> x <u>9</u> days)	
Loss of Income (LOI):	SS <u>—</u>	(<u>—</u> x <u>—</u> days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	(Tick only one)	
GIA/LTA Search	SS <u>—</u>		
Medical:	SS <u>—</u>		
Disbursement:	SS <u>—</u>	(e.g. Tow/Independent)	
Legal Cost:	SS <u>—</u>		
Total:	SS <u>6,280.00</u>	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>6,280.00</u>	Name 1: <u>Quam De Motor Trading</u>	
Payee 2 (Strike if N.A.):	SS <u>—</u>	Name 2:	
Payee 3 (Strike if N.A.):	SS <u>—</u>	Name 3:	

COPY SENT

11/11/18
OK

08/11/13 wef

ASS. REC. BY: Marcus

REF:

EA/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLX5-361G

at Workshop mis: Quan De

of _____

Insured: SLR 1673P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 20k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

CA / FR Sean: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7577x

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLX5-361G Yr Regn: 17/4/09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1598

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 156828 T/Radio: Insured / Std / NI / NA

Engl No: _____

C/No: JHMF0462095200614

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop / Jammed / Leaked / Burnt or

Brake: Inop / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55-16

BS / DUN / EXNOVA / GY / FS / LIZ / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A. 8/6/18 D.O.I. 11/6/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ree

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10 min

LTA 13106

Rep 9500 net 6894

L/S: \$5,800.00 / Red: \$6,060.00 / 51%

Date/Time, File Pass to:

: Prel. Report

Days Of Repair: _____

1) _____

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to:

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportat: _____

\$ - RC, Bl

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18010611/Ufb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 11-06-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLR 1673P	Veh. Inspected	SLX 5361G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/06/2018	Inspection Date	11/06/2018
Survey held at	QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

f

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
 AUTOBAY, SINGAPORE 417883
 HP: 96709191 FAX: 66840767

EQ Insurance Co. Ltd
 5 Maxwell Road,
 #17-00 Tower Block
 MND Complex
 Singapore 069110.
 Attn: Motor Claims Department

Attn: Mr. Marcus (Buyer)
 Not Allowed
 L/S \$ 5800
 8/11

Date: 11 June 2018

Accident on 08/06/2018 involving vehicles SLX5361G & SLR1673P
along PIE towards Tuas

Estimate cost of repair to vehicle SLX5361G Honda Civic

1 pc.	rear bumper	20	\$	638.00	/
2 pcs.	rear bumper side retainers @\$20.50	set	\$	41.00	/
1 set	rear bumper clips	set	\$	45.00	/
1 pc.	bootlid	20/suc	\$	610.00	/
1 pc.	bootlid rear logo	set	\$	28.80	/
1 pc.	bootlid "CIVIC" emblem	set	\$	32.20	/
1 pc.	bootlid "IVTEC" emblem	set	\$	36.50	/
2 pcs.	bootlid reflectors @\$248.20	17	\$	496.40	X
1 pc.	bootlid inner lock	twl	\$	198.60	/
1 pc.	bootlid weatherstrip	twl	\$	101.00	/
1 pc.	bootlid inner trim	17	\$	282.30	X
2 pcs.	bootlid hinges @\$148.60	2	\$	297.20	X
2 pcs.	taillamps @\$282.50	one	\$	565.00	/
2 pcs.	taillamp housing panel @\$167.70	msd	\$	335.40	1pc
1 pc.	rear end panel	Bo byd	\$	296.60	/
1 pc.	rear end panel top garnish	tyl	\$	160.80	/
1 pc.	rear floor panel	crupha	\$	911.40	/
1 pc.	rear floor panel top board	wayd	\$	316.00	/
2 pcs.	rear fenders @\$741.50	ms de	\$	1,483.00	X
2 pcs.	rear fender inner trims @\$242.80	2	\$	485.60	1pc
1 pc.	rear exhaust	17	\$	494.00	X
2 pcs.	rear exhaust mountings @\$36.00	17	\$	72.00	X
1 pc.	rear splash shield	17	\$	42.50	X
1 pc.	rear windscreen moulding	17	\$	68.20	X
			\$	8,037.50	
			Less 20%	\$ 1,607.50	
				\$ 6,430.00	

4391.40
 3513.12

S. Nett Items:

1 set	rear bumper reverse sensor
1 pc.	rear end panel sealant
1 pc.	rear license plate w/holder
1 set	rear floor panel insulator
1 pc.	rear windscreen sealant

Bal c/f \$ 6,430.00

sluhl	\$ 300.00	200
ru	\$ 100.00	50
11	\$ 50.00	X
rec	\$ 300.00	200
11	\$ 60.00	X

Labour Charges:

To check wiring	\$ 80.00	30
To remove & refix reverse sensor	\$ 100.00	50
To remove & refix seat & cushion upholstery	\$ 150.00	100
To remove & refix rear exhaust	\$ 120.00	60
To remove & reinstall rear windscreen	\$ 150.00	X
To remove & refix petrol tank	\$ 120.00	80
To transfer bootlid components	\$ 100.00	60
To spray rust proofing	\$ 200.00	120
Labour for panel beating, welding & renew parts	\$ 2,000.00	1500
To putty & spray painting	\$ 1,600.00	1200

Total: \$ 11,860.00

7263.12
5810.

LKK Auto Components hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 31 August 2018 5:23 PM
To: 'Jennifer Pang'
Cc: Hsiao Tong (LKKAuto)
Subject: RE: offer: Our Ref: CC6/EQI18010611/Ufb3; Your Ref: SLX 5361G

Importance: High

Without Prejudice

Our Ref: CC6/EQI18010611/Ufb3
Your Ref: SLX 5361G

Dear Jennifer,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLR 1673P AND SLX 5361G ON 08/06/2018

We refer to the above matter.

Thank you for your acceptance.

Please note that no DV is required and kindly furnish us a copy of Authorization to Act for payment processing.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: Jennifer Pang <quanv3@yahoo.com.sg>
Sent: Thursday, 30 August 2018 7:15 PM
To: Poh Kin (LKKAuto)
Subject: Re: offer: Our Ref: CC6/EQI18010611/Ufb3; Your Ref: SLX 5361G

Dear Poh Kin,

We refer to your email as above.

We confirm acceptance of your offer settlement for the above matter. Kindly send us the DV or thru email if possible.

Thank you.

Regards,
Quan De Motor Trading
Jennifer

On Thursday, 30 August 2018, 8:39:39 AM GMT+8, Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

Without Prejudice

Our Ref: CC6/EQI18010611/Ufb3

Your Ref: SLX 5361G

Dear Sirs,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLR 1673P AND SLX 5361G ON 08/06/2018

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair	S\$ 5,800.00
2. Loss of Use (\$60.00 x 8 days)	S\$ 480.00
	S\$ 6,280.00

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 30 August 2018 8:40 AM
To: 'quanv3@yahoo.com.sg'
Cc: Hsiao Tong (LKKAuto)
Subject: offer: Our Ref: CC6/EQ18010611/Ufb3; Your Ref: SLX 5361G

Without Prejudice

Our Ref: CC6/EQ18010611/Ufb3
Your Ref: SLX 5361G

Dear Sirs,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLR 1673P AND SLX 5361G ON 08/06/2018

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair	S\$ 5,800.00
2. Loss of Use (\$60.00 x 8 days)	S\$ 480.00
	S\$ 6,280.00

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 27 July 2018 2:36 PM
To: 'quanv3@yahoo.com.sg'
Cc: Admin A; Marcus Chua (LKKAuto)
Subject: REQUEST DOC: Our Ref: CC6/EQI18010611/Ufb3; Your Ref: SLX 5361G

Importance: High

Without Prejudice

Our Ref: CC6/EQI18010611/Ufb3
Your Ref: SLX 5361G

Dear Sirs,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLR 1673P AND SLX 5361G ON 08/06/2018

We refer to the above matter.

For COR, our surveyor had recommended amount at **L/S \$5,800.00 (before GST) with 8 repair days.**

Please note that: All finalisation is subject to our Principal insurer's approval.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Tuesday, 19 June 2018 1:57 PM
To: 'quanv3@yahoo.com.sg'
Cc: Hsiao Tong (LKKAuto)
Subject: Our Ref: CC6/EQ118010611/Ufb3; Your Ref: SLX 5361G

Importance: High

Without Prejudice

Our Ref: CC6/EQ118010611/Ufb3
Your Ref: SLX 5361G

Dear Sirs,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLR 1673P AND SLX 5361G ON 08/06/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191 FAX: 66840767

f

EQ Insurance Co. Ltd.
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
Attn: Motor Claims Department

Date: 10 July 2018

**Accident on 08/06/2018 involving vehicles SLX5361G & SLR1673P
along PIE towards Tuas**

With regards to the above, we are writing on behalf of the registered owner of vehicle SLX 5361G which was involved in the abovementioned accident.

We are informed that the accident was caused solely by the negligence of your insured vehicle SLR1673P. As a result of the accident, our client's vehicle was damaged and our client has been put to great loss and expenses, particulars of which are as follows:

1) Cost of Repairs	\$5,800.00
2) Loss Of Use (8 days x @\$100.00)	\$800.00
Total:	<u>\$6,600.00</u>

We hereby enclosed herewith the following documents for your confirmation of the above claim.

- | | |
|-----------------------------|--|
| a) Original Invoice | b) GIA Accident Report |
| c) Certificate of Insurance | d) Owner/Driver NRIC & Driving License |
| e) Letter of Authorisation | |

Kindly acknowledge receipt of the above documents and your favourable reply is much appreciated.

Yours sincerely,
QUAN DE MOTOR TRADING


email: quanv8@yahoo.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/EQ118010611/Ufb3

19th June 2018

EAZI CAR LEASING AND MARKETING PTE LTD

1 Bukit Batok Crescent,
#02-43 Wcega Plaza,
Singapore 658064.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING SLR 1673P AND SLX 5361G ALONG
PIE TOWARDS TUAS ON 08.06.2018.**

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kim, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

Date:

To: EG Insurance Co. Ltd.

RE: ACCIDENT INVOLVING VEHICLES SLX 5361G & SLR 1673P

ALONG PIE TOWARDS TUAS

ON 08/06/2018

I/We, Ng Boon Kiat of (NRIC/ROE No.) S6927577/z


of 23 Rosewood Drive #17-12 S(737918)

owner of vehicle no. SLX 5361G in consideration of M/s. Quan De Motor Trading repairing my/our vehicle SLX 5361G at my/our instruction and hereby authorise

M/s. Quan De Motor Trading to demand claim settle receive whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I further agree and undertake to indemnify them against the abovementioned claims costs which may arisen therewith.

Signature of Owner :



Name of Owner :

Ng Boon Kiat

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
AUTOBAY, SINGAPORE 417883
HP: 96709191 FAX: 668F40767

EQ Insurance Co. Ltd.
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110.
Attn: Motor Claims Department

Date: 10 July 2018

Accident on 08/06/2018 involving vehicles SLX5361G & SLR1673P
along PIE towards Tuas
Invoice for cost of repair to vehicle SLX5361G Honda Civic

To supply spare parts, labour for panel
beating, welding and renew parts,
including spray painting.

Lump Sum: \$ 5,800.00

(S.DLS: FIVE THOUSAND EIGHT HUNDRED ONLY)





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 31/12/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLR 1673P (Insd Veh)	Your Ref. No. : DMCFHQ18-000035
	SLX 5361G (TP Veh)	Our Ref. No. : CC6/EQI18010611/Ufb3q2
Date of Accident	8/6/2018	

Liability	100%	
Final Repair Cost	: \$ 5,800.00	
Loss of Use	: \$ 480.00	8 days
Rental (If any)	: \$	days
Others:	: \$	
	: \$	
	6,280.00	
Final Settlement Sum	: \$ 6,280.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	QUAN DE MOTOR TRADING	: \$ 6,280.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ118010611/Ufb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 31-12-2018



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 1673P	Veh. Inspected	SLX 5361G
Policy No.	DMCFHQ18-000035	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/06/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMF46209S200654	Colour	RED
Odometer	156828	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/06/2018	Inspection Date	11/06/2018
Survey held at	QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 5361G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	638.00	638.00
2	REAR BUMPER SIDE RETAINERS @\$20.50	BENT	41.00	41.00
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	BOOTLID	DENTED / BUCKLED	610.00	610.00
1	BOOTLID REAR LOGO	NECESSARY	28.80	28.80
1	BOOTLID 'CIVIC' EMBLEM	NECESSARY	32.20	32.20
1	BOOTLID 'IVTEC' EMBLEM	NECESSARY	36.50	36.50
2	BOOTLID REFLECTORS @\$248.20	NOT NECESSARY	496.40	-
1	BOOTLID INNER LOCK	TWISTED	198.60	198.60
1	BOOTLID WEATHERSTRIP	TWISTED	101.00	101.00
1	BOOTLID INNER TRIM	NOT NECESSARY	282.30	-
2	BOOTLID HINGES @\$148.60	TO REPAIR SEE LABOUR	297.20	-
2	TAILLAMPS @\$282.50	CRACKED	565.00	565.00
2	TAILLAMP HOUSING PANEL @\$167.70	N/S DENTED	335.40	167.70
1	REAR END PANEL	BADLY DENTED	296.60	296.60
1	REAR END PANEL TOP GARNISH	TWISTED	160.80	160.80
1	REAR FLOOR PANEL	CRUMPLED	911.40	911.40
1	REAR FLOOR PANEL TOP BOARD	WARPED	316.00	316.00
2	REAR FENDERS @\$741.50	TO REPAIR SEE LABOUR	1,483.00	-
2	REAR FENDER INNER TRIMS @\$242.80	N/S DEFORMED	485.60	242.80
1	REAR EXHAUST	TO REPAIR SEE LABOUR	494.00	-
2	REAR EXHAUST MOUNTINGS @\$36.00	NOT NECESSARY	72.00	-
1	REAR SPLASH SHIELD	NOT NECESSARY	42.50	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	68.20	-
	LESS 20% DISCOUNT		-1,607.50	-878.28
			6,430.00	3,513.12
SPECIAL NETT ITEMS				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00

Report Ref No. CC6/EQ18010611/Ufb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. :2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR LICENSE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	300.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			810.00	450.00
	LABOUR			
	TO CHECK WIRING .		80.00	30.00
	TO REMOVE & REFIX REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIX SEAT & CUSHION UPHOLSTERY .		150.00	100.00
	TO REMOVE & REFIX REAR EXHAUST .		120.00	60.00
	TO REMOVE & REINSTALL REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX PETROL TANK.		120.00	80.00
	TO TRANSFER BOOTLID COMPONENTS .		100.00	60.00
	TO SPRAY PROOFING.		200.00	120.00
	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID HINGES,REAR FLOOR PANEL TOP BOARD AND REAR EXHAUST.		2,000.00	1,600.00
	TO PUTTY & SPRAY PAINTING.		1,600.00	1,200.00
			4,620.00	3,300.00
GRAND TOTAL			11,860.00	7,263.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CC6/EQ118010611/Ufb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.