

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

*25/6/2018
Survey of repair
need rental car*

*Account closed
on 14/6/2018
we still
follow up
third party
claim*



GST REG. NO : M2 - 0020081 - X

ESTIMATE

11 JUN 2018

Estimate No. : b1 47174	Page No. : 1 of 5
Date Estimated : 04/06/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Ng Aik Kwang (Huang Yiquan) 51 Kent Road #05-28 Singapore 210051	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP861E	G382738	30/08/2016	420iA GC	0

DESCRIPTION	VALUE
Replace front bumper and remove attachment etc and knock on accident dent	850 1,700.00
Spray painting front bumper	930 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	? 150.00
Total Labour 1:	3,065.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH BOTTOM MOUNTING SIDE PANEL	1	18.00	X 18.00
FRT RH BOTTOM MOUNTING SIDE PANEL	1	18.00	X 18.00
SUPPORT FOG LAMP RH	1	37.20	? 37.20
FRT LH TOP MOUNTING SIDE PANEL	1	18.00	X 18.00
FRT RH TOP MOUNTING SIDE PANEL	1	18.00	X 18.00
INSERT AIR INLET MIDDLE (LINE/SPORT MOUNTING SUPPORT	1	114.85	? 114.85
COVER LOWER PART CENTRE	1	13.25	? 13.25
FRT BUMPER PANEL PRIMED (SRA)	1	40.10	? 40.10
FLAP TOWING EYE PRIMED	1	1,031.90	see 1,031.90
RH COVER SPRAY NOZZLE PRIMED	1	42.20	cut 42.20
SET MOUNTING PDC/PMA SENSOR FRT	1	42.20	? 42.20
FRT RH GRILLE (SPORT)	1	84.10	? 84.10
GROMMET	1	115.65	? 115.65
PLAQUE 82MM	2	0.75	see 1.50
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	69.50	see 69.50
TELESCOPING NOZZLE RH	1	84.85	? 84.85
RH BI XENON HEADLIGHT	1	155.95	? 155.95
RH FOG LIGHT	1	2,135.85	? 2,135.85
DECOUPLING RING PDC TORQUE CONVERTER	1	276.40	? 276.40
PDC SENSOR MELBOURNEROT (A75)	4	5.05	? 20.20
	4	368.80	? 1,475.20
Total Parts :			5,812.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47174
Date Estimated : 04/06/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP861E	G382738	30/08/2016	420iA GC	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 25/06/18 @ 1250 Excess S\$ _____

Surveyor's Name Ram Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	3,065.00
Parts	:	5,812.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	621.45
Grand Total	:	9,499.35

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **