



SLG9690U

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 8-Jun-2018

Vehicle Reg. No. : SLG9690U
Vehicle Reg. Date: 19-Oct-2016
Make / Model : H. GRACE 1.5 HYBRID DX
Engine No. : LEB5254653
Chassis No. : GM41104641

COST OF CLAIMS

Parts Cost / List Items : \$ 13,892.30
Plus/Less 20% \$ 2,778.46
Total Cost / List : \$ 11,113.84
Special Nett Items : \$ 718.00
Total Parts Amount : \$ 11,831.84
Total Labour Amount : \$ 4,650.00
Gross Total : \$ 16,481.84
GST % : 7% \$ 1,153.73
Nett Amount : \$ 17,635.57

Surveyor Name and Company :

Tanpin 92495709
Date of survey : 4/6/18 @ 1430
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint WP
Authorize/Not Authorize/Without Prejudice
Email : suu@lkkauto.com
Fax No : _____
HP No : _____

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9690U**
 Vehicle Reg. Date: **10/19/2016**
 Make / Model : **H. GRACE 1.5 HYBRID DX CVT ABS D/AIRBAC**
 Engine No. : **LEB5254653**
 Chassis No. : **GM41104641**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	de ✓	\$ 937.00		
2	1	REAR BUMPER CLIP - SET	un ✓	\$ 50.00		
3	2	REAR BUMPER SIDE RETAINER LH/RH	rel ✓	\$ 114.00		
4	1	REAR BUMPER SPONGE	x	\$ 97.00		
5	2	REAR BUMPER REFLECTOR LH/RH	x	\$ 187.10		
6	1	REAR BUMPER ANTENNA SENSOR	✓	\$ 90.00		
7	1	REAR BUMPER LOWER COVER	de ✓	\$ 155.00		
8	1	REAR BUMPER TOW HOOK	✓	\$ 135.00		
9	2	REAR FENDER INNER SHIELD LH/RH	x	\$ 130.00		
10	2set	REAR FENDER INNER SHIELD CLIPS	x	\$ 60.00		
11	2	REAR FENDER INNER TRIM LH/RH	x	\$ 680.00		
12	2set	REAR FENDER INNER TRIM CLIPS	x	\$ 80.00		
13	1	REAR END PANEL	ht ✓	\$ 450.00		
14	1	REAR END PANEL TOP GARNISH	de ✓	\$ 180.00		
15	1	REAR END PANEL TOP GARNISH CLIP - SET	un ✓	\$ 50.00		
16	1	SPARE TYRE PANEL	Ry ✓	\$ 855.10		
17	1	SPARE TYRE PANEL TOOL TRAY	de ✓	\$ 225.10		
18	1	SPARE TYRE PANEL TOP BOARD	x	\$ 160.00		
19	1	EXHAUST MUFFLER	Ry ✓	\$ 485.00		
20	1	EXHAUST HEATSHIELD	x	\$ 85.00		
21	2	EXHAUST MOUNTING	y	\$ 40.00		
22	1	REAR BOOT	ht ✓	\$ 725.40		
23	2	REAR BOOT HINGE LH/RH	Ry ✓	\$ 190.00		
24	1	REAR BOOT LOCK	ht ✓	\$ 180.00		
25	1	REAR BOOT LOCK CATCH	ht ✓	\$ 30.00		
26	1	REAR BOOT INNER TRIM	x	\$ 100.00		
27	1	REAR BOOT INNER TRIM CLIP - SET	x	\$ 40.00		
28	1	REAR BOOT CHROME GARNISH	x	\$ 190.00		
29	2	REAR BOOT LAMP LH/RH	ant ✓	\$ 720.00		
30	1	REAR BOOT LOGO	un ✓	\$ 60.00		
31	1	REAR BOOT EMBLEM - GRACE	un ✓	\$ 56.00		
32	1	REAR BOOT EMBLEM - HYBRID	un ✓	\$ 60.00		
33	1	REAR BOOT SPOILER	x	\$ 490.80		
34	1	REAR BOOT HANDLE SWITCH	x	\$ 295.30		
35	1	REAR BOOT OPEN SMART SENSOR	?	\$ 187.00		
36	1	REAR BOOT WIRE HARNESS	?	\$ 1,025.00		
37	1	REAR BOOT WEATHERSTRIP	twi ✓	\$ 125.00		
38	2	REAR NUMBER PLATE LAMP	x	\$ 167.00		
39	2	TAILLAMP LH/RH	ant ✓	\$ 785.40		
40	2	REAR FENDER LH/RH	x	\$ 2,700.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9690U**
 Vehicle Reg. Date: **10/19/2016**
 Make / Model : **H. GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG**
 Engine No. : **LEB5254653**
 Chassis No. : **GM41104641**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	2	REAR AIR DUCT LH/RH	X	\$ 150.00		
42	2	TAILLAMP CLIPS	new	\$ 60.00		
43	2	TAIL LAMP PANEL LH/RH	Rp	\$ 310.10		
44	1	REVERSE SENSOR	new	200	\$ 300.00	
45	1	REAR NUMBER PLATE WITH FRAME	X		\$ 50.00	
46	1	REAR BOOT SEALANT	new	30	\$ 80.00	
47	1	REAR END PANEL SEALANT	new	30	\$ 80.00	
48	1	SPARE TYRE SEALANT	X		\$ 80.00	
49	3	EXHAUST RUBBER HOOK	X		\$ 60.00	
50	2	EXHAUST GASKET	X		\$ 45.00	
51	2	REAR BUMPER EXTENSION GROMMET SCREW	new		\$ 8.00	
52	2	REAR BYMPER EXTENSION FASTENER	new		\$ 7.00	
53	2	REAR BUMPER FASTENER	new		\$ 8.00	
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLG9690U
Vehicle Reg. Date:	10/19/2016
Make / Model :	H. GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG
Engine No. :	LEB5254653
Chassis No. :	GM41104641

Estimates on Labour

[illegible]