



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

FWD/AXA(YP5080E)
DOA: 03/06/2018@1400

AXA INSURANCE PTE LTD

8/6/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLN 362 P - KIA NIRO HYBRID 1.6 GDI DCT SUNROOF
CHASSIS NO: KNACC81CVH5062252 (2017)

Labour to repair and straighten front fender LH.

\$ 200.00 ¹⁵⁰

Putty and respray front fender LH.

\$ 250.00 ²⁰⁰

ADD 7% GST

\$ 450.00
\$ 31.50
\$ 481.50

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

Tan Jiah 17495749
'wp'
12/6/18 @ 115pm
• 2 days
Resurvey after repair
suw@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: