

COMFORTDELGRO ENGINEERING PTE LTD

AIG

REPAIR ESTIMATE*

VEHICLE NO : SHD4851T

MAKE : HYUNDAI

MODEL : i40

DJA: 08.06.18

Date: 11.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Bumper ✓			\$ 603.60
1	Rear Bumper Reinforcement ?			\$ 504.35
1	Rear Bumper Sponge ?			\$ 143.40
10	Rear Bumper clips @ \$2.20 ✓			\$ 22.00
1	Rear Bumper Under Cover ✓			\$ 225.00
1	Rear Bumper Stay - RH ?			\$ 180.00
1	Rear Bumper Stay - LH ?			\$ 180.00
1	Rear Panel ✕			\$ 592.30
1	Tail lamp Quarter Panel - RH ✕			\$ 97.90
1	Boot Lid ✓			\$ 1681.40
1	Boot Lid Rubber ✕			\$ 115.80
1	Boot Lid Upper Lock ✕			\$ 137.90
1	Boot Lid Lower Lock ✕			\$ 31.70
1	Boot Lid 'H' emblem ✓			\$ 27.20
1	Boot Lid CRDI plate ✓			\$ 41.00
1	Boot Lid i40 emblem ✓			\$ 41.00
1	Boot Lid Lamp - RH ✓			\$ 556.80
1	Exhaust Silencer - RH ✓			\$ 954.00
1	Exhaust Silencer - LH ✓			\$ 954.00
1	Exhaust Centre Pipe ?			\$ 1150.30
SUB TOTAL				\$ 8,239.65
LESS 20% DISCOUNT				\$ 1647.93
DISCOUNTED TOTAL				\$ 6,591.72
1	Boot Lid ComfortDelgro Sticker ✓			\$ 15.00
1	Boot Lid Tel no sticker ✓			\$ 15.00
Labour Charge				
1	Panel Beating			\$ 600.00
1	Spray Painting Charge			\$ 600.00
1	Wiring Charge			\$ 50.00
1	Tuff Kote			\$ 80.00
1	Remove/Refix Exhaust			\$ 150.00
TOTAL LABOUR				\$ 1600.00
ESTIMATE TOTAL				\$ 8,221.72

SUB TOTAL

LESS 20%

DISCOUNTED TOTAL

LKK Auto Consultants hence notify

the Repairer of the following:

• To be surveyed before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15.00

Nett

15.00

Nett

30.00

K. L. K. K.

11/6/18 1040h
3 Pgs.

4/3 After Repair 16

400

600.00

600.00

50.00

80.00

150.00

400

20

20

20

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.