

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE

SECTOR C #01-115

SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 2009175125K

Your Vehicle: SLV2538U

Our Vehicle: SJZ8694P

Date: 11/06/2018

M/s AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#07-16

Singapore 079120

WITHOUT PREJUDICE

BY FAX: 6415 3727 ONLY

Dear Sir,

**ACCIDENT INVOLVING SJZ8694P & SLV2538U ON 08/06/2018 ALONG TOA PAYOH
CENTRAL HUB CARPARK BESEMENT 3.**

We refer to the above matter.

Kindly let us have your list of ten surveyors for our consideration within the stipulated timeline under the NIMA protocol.

Please be informed that the said vehicle can be inspected at:

BLK 1 SIN MING INDUSTRIAL ESTATE

SECTOR C #01-115

SINGAPORE 575636

Please note that if you fail to conduct the pre-repair inspection within the next 2 DAYS excluding any intervening Saturday, Sunday and/or Public Holiday, we will commence repairs thereafter without any further notice or reference to you.

Yours Faithfully,

A handwritten signature in blue ink is written over a circular blue stamp. The stamp contains the text "BH AUTO SERVICES PTE LTD" around the perimeter. The signature is a stylized, cursive script.

BH Auto Services Pte Ltd / Jacelyn loh