

cc 4, lpc 180 10723, Kd/pa352

Surveyor:

Kenneth

DOI:

ASSIGNMENT


12/6/18

Date / Time:

11.6.18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGJ 8781R

Name of Insured:

Lim Chuan Qian

Insured Tel No.:

HP:

81337057

Excess Sec II :SS

D.O.A.:

8/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

12/18/18/VP05/020661

Policy No.:

217 VP05016593

Make / Model:

Honda Civic

Place of Accident:

Sigmon Rd 3 Potong Pasir

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

K Kim Hin



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date/ Time |           | STAGE                             | DATE / PIC     |
|------------|-----------|-----------------------------------|----------------|
| 15/6       | SGJ 8781R | Non-Reporting ltr (1st):          |                |
| 15/6       | SGJ 8781R | Non-Reporting ltr (2nd):          |                |
| 15/6       | SGJ 8781R | Non-Reporting ltr (Final):        |                |
| 15/6       | SGJ 8781R | Notification ltr (if non-pickup): |                |
| 15/6       | SGJ 8781R | Call OI:                          |                |
| 15/6       | SGJ 8781R | After call ltr to OI:             |                |
| 15/6       | SGJ 8781R | Documentation Check List:         | Handler Typist |
| 15/6       | SGJ 8781R | Notification ltr (if non-pickup)  |                |
| 15/6       | SGJ 8781R | After call ltr to OI:             |                |
| 15/6       | SGJ 8781R | Authorisation To Act:             |                |
| 15/6       | SGJ 8781R | Release Voucher:                  |                |
| 15/6       | SGJ 8781R | Final Repair Bill:                |                |
| 15/6       | SGJ 8781R | Car Rental Invoice:               |                |
| 15/6       | SGJ 8781R | Towing Invoice:                   |                |
| 15/6       | SGJ 8781R | LTA / GIA:                        |                |
| 15/6       | SGJ 8781R | Medical Bill:                     |                |
| 15/6       | SGJ 8781R | PIR:                              |                |
| 15/6       | SGJ 8781R | Mandate/Reject Instruction:       |                |
| 15/6       | SGJ 8781R | LOD:                              |                |
| 15/6       | SGJ 8781R | Payment Breakdown Form:           |                |
| 15/6       | SGJ 8781R | Post-Repair Photos:               |                |
| 15/6       | SGJ 8781R | Others:                           |                |

|                                                                     |                                                                       |                                   |                         |
|---------------------------------------------------------------------|-----------------------------------------------------------------------|-----------------------------------|-------------------------|
| <b>PRELIMINARY ADVICE</b>                                           |                                                                       | Date/Time: 14/6                   | Sent By: Kim            |
| <b>FINALIZATION</b>                                                 |                                                                       | Date/Time:                        | Confirm with: Margaret  |
| Repair Cost:                                                        | SS                                                                    | ( ) days Reduction:               | %                       |
| <b>FINAL SETTLEMENT</b>                                             |                                                                       | Date/Time: 11/8/19                | Confirm with: Margaret  |
| Final Liability:                                                    | % 100                                                                 | (Agreed / Assessed) BOLA S/N No.: | 28                      |
| Repair Cost:                                                        | SS 7329.50                                                            |                                   |                         |
| Loss of Rental (LOR):                                               | SS -                                                                  | ( ) days                          |                         |
| Loss of Use (LOU):                                                  | SS 900.00                                                             | (\$ 60 x 15 days)                 |                         |
| Loss of Income (LOI):                                               | SS -                                                                  | (\$ x days)                       |                         |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> | (Tick only one)                   |                         |
| GIA/LTA Search                                                      | SS 2.00                                                               |                                   |                         |
| Medical:                                                            | SS -                                                                  |                                   |                         |
| Disbursement:                                                       | SS -                                                                  | (e.g. Tow/ Independent)           |                         |
| Legal Cost                                                          | SS -                                                                  |                                   |                         |
| Total:                                                              | SS 8231.50                                                            | Global Sum SS:                    | 8200.00                 |
| <b>FINAL PAYMENT</b>                                                |                                                                       | Date/Time:                        | Confirm with:           |
| Payee 1:                                                            | SS 8200.00                                                            | Name 1:                           | K. Kim Hin Auto Pte Ltd |
| Payee 2: (Strike if N.A.)                                           | SS                                                                    | Name 2:                           |                         |
| Payee 3: (Strike if N.A.)                                           | SS                                                                    | Name 3:                           |                         |

ASS. REC. BY:

REF:

LPC1

10723/KP03

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

\$25,500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

9/22

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/8/16 next to Corbin

H/S \$ 6850 Cred \$ 398.45 / 3771.

Veh No:

SGY 7368D

Yr Regn:

10, 0, 7

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c.

1339

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

170840

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

THMG01850.7 9 228408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

8/6/18

D.O.I.

12/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &amp; 1st N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                  |                 |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                  |                 | Ref : CC4/LPC18010723/Kpa3 |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                  |                 | Date : 12-06-2018          |  |
|                                                                                                                                        |                                                                                  |                 | Code : LPC2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                  |                 |                            |                                                                                     |
| Insured Veh.                                                                                                                           | SGJ 8781R                                                                        | Veh. Inspected  | SGY 7368D                  |                                                                                     |
| Policy No.                                                                                                                             | Z17VP05016593                                                                    | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                                                                                              | 17/18/18/VP05/020661                                                             | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                                                                                            |                                                                                  | Assign Date     | 12/06/2018                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                  |                 |                            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                  | c.c             | 0                          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                           | Year of Reg.    |                            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                  | Colour          |                            |                                                                                     |
| Odometer                                                                                                                               | -                                                                                | Steering        |                            |                                                                                     |
| Brakes                                                                                                                                 |                                                                                  | Modification    |                            |                                                                                     |
| General                                                                                                                                |                                                                                  |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                  |                 |                            |                                                                                     |
|                                                                                                                                        | Size                                                                             | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                  |                 | mm                         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                  |                 | mm                         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                  |                 | mm                         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                  |                 | mm                         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                  |                 |                            |                                                                                     |
|                                                                                                                                        |                                                                                  |                 |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                  |                 |                            |                                                                                     |
| Accident Date                                                                                                                          | 08/06/2018                                                                       | Inspection Date | 12/06/2018                 |                                                                                     |
| Survey held at                                                                                                                         | K KIM HIN AUTO PTE LTD<br>BLK 34 SIN MING DRIVE,<br>#01-114,<br>SINGAPORE 575708 |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                  |                 |                            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                  |                 |                            |                                                                                     |

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SGJ 8781 R  
Accident Date : 08-Jun-2018

No. : 29832

Date : 12-Jun-2018

Our Ref : 180383 (LONPAC) / SHUMAN

PAGE : 1

DREAMZWORK WORK CREATION  
Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.4A (2007) SGY7368D

*Not withholder  
6/12/18 @ 8:00 AM  
After Paint 14 days*

|        |                                     |             |  |              |        |   |   |
|--------|-------------------------------------|-------------|--|--------------|--------|---|---|
| 1 pc   | front bumper                        |             |  | <i>As</i>    | 160.00 | c | ✓ |
| 1 pc   | n/s front bumper side retainer      |             |  | <i>DI</i>    | 9.00   | c | ✓ |
| 10 pcs | front bumper clips                  | @ S\$ 1.00  |  | <i>As</i>    | 10.00  | c | ✓ |
| 1 pc   | front bumper towing cover           |             |  | <i>As</i>    | 10.00  | c | ✓ |
| 1 pc   | front bumper centre lower grille    |             |  | <i>As</i>    | 95.00  | c | x |
| 1 pc   | front bumper lower side grille      |             |  | <i>As</i>    | 15.00  | c | x |
| 1 pc   | front bumper reinforcement          |             |  | <i>As</i>    | 85.00  | c | ✓ |
| 1 pc   | n/s headlamp assy                   |             |  | <i>As</i>    | 285.00 | c | ✓ |
| 1 pc   | n/s headlamp lower bracket          |             |  | <i>DI</i>    | 16.00  | c | ✓ |
| 1 pc   | front support panel                 |             |  | <i>As</i>    | 125.00 | c | ✓ |
| 1 pc   | front grille                        |             |  | <i>As</i>    | 100.00 | c | x |
| 1 pc   | front grille logo                   |             |  | <i>As</i>    | 20.00  | c | x |
| 1 pc   | aircon condenser                    |             |  | <i>77/As</i> | 270.00 | c | ✓ |
| 1 pc   | radiator                            |             |  | <i>As</i>    | 290.00 | c | ✓ |
| 1 pc   | n/s radiator air guide              |             |  | <i>As</i>    | 18.00  | c | ✓ |
| 1 pc   | radiator spare tank                 |             |  | <i>As</i>    | 25.00  | c | ✓ |
| 1 pc   | n/s front fender                    |             |  | <i>As</i>    | 115.00 | c | ✓ |
| 1 pc   | n/s front fender inner shield       |             |  | <i>DI</i>    | 35.00  | c | ✓ |
| 8 pcs  | n/s front fender inner shield clips | @ S\$ 1.00  |  | <i>As</i>    | 8.00   | c | ✓ |
| 1 pc   | air intake duct                     |             |  | <i>As</i>    | 28.00  | c | ✓ |
| 1 pc   | rear bumper                         |             |  | <i>As</i>    | 165.00 | c | ✓ |
| 2 pcs  | rear bumper side retainer (LH/RH)   | @ S\$ 12.00 |  | <i>DI</i>    | 24.00  | c | ✓ |
| 10 pcs | rear bumper clips                   | @ S\$ 1.00  |  | <i>As</i>    | 10.00  | c | ✓ |
| 1 pc   | tailgate                            |             |  | <i>As</i>    | 580.00 | c | ✓ |
| 1 pc   | tailgate lock                       |             |  | <i>As</i>    | 90.00  | c | ✓ |
| 1 pc   | tailgate lock catch                 |             |  | <i>As</i>    | 24.00  | c | x |
| 1 pc   | tailgate weatherstrip               |             |  | <i>DI/As</i> | 55.00  | c | ✓ |

2052

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: [service@kkimhin.com.sg](mailto:service@kkimhin.com.sg)

Vehicle Insured : SGJ 8781 R  
Our Ref : 180383

Page : 2  
No. : 29832

|       |                                    |                   |        |                                                     |    |                              |
|-------|------------------------------------|-------------------|--------|-----------------------------------------------------|----|------------------------------|
| 1 pc  | tailgate "JAZZ" emblem             |                   | Mt     | 20.00                                               | c  |                              |
| 1 pc  | tailgate glass moulding            |                   | m      | 30.00                                               | c  |                              |
| 1 pc  | tailgate inner trimboard           |                   | Bm     | 85.00                                               | c  |                              |
| 1 pc  | tailgate "H" logo                  |                   | n s m  | 18.00                                               | c  | X                            |
| 1 pc  | tailgate outer garnish             |                   | Su     | 75.00                                               | c  | X                            |
| 2 pcs | taillamp assy (LH/RH)              | n/s m @ S\$125.00 |        | 250.00                                              | c  | L + 2pcs                     |
| 2 pcs | taillamp panel (LH/RH)             | @ S\$ 60.00       | m      | 120.00                                              | c  | X                            |
| 1 pc  | rear exhaust muffler               |                   | Rx     | 265.00                                              | c  |                              |
| 1 pc  | rear exhaust head shield           |                   | Nd     | 45.00                                               | c  |                              |
| 2 pcs | rear exhaust mounting              | @ S\$ 15.00       | Jn     | x30.00                                              | c  | X                            |
| 1 pc  | rear end panel                     |                   | Rj     | 220.00                                              | c  |                              |
| 1 pc  | rear end panel top garnish         |                   | mt     | 40.00                                               | c  |                              |
| 1 pc  | spare tyre lock screw              |                   | Jn     | x15.00                                              | c  | X                            |
| 1 pc  | spare tyre top board               |                   | Return | 160.00                                              | c  |                              |
| 1 pc  | spare tyre panel                   |                   | Brl An | 395.00                                              | c  |                              |
| 2 pcs | spare tyre extension panel (LH/RH) | @ S\$195.00       | m      | 390.00                                              | c  | X                            |
| 1 pc  | n/s rear chassis member            |                   | R x    | 160.00                                              | c  | X                            |
| 2 pcs | rear fender inner shield (LH/RH)   | @ S\$ 75.00       | C M    | 150.00                                              | c  |                              |
| 8 pcs | rear fender inner shield clips     | @ S\$ 1.00        | m      | 8.00                                                | c  |                              |
| 1 pc  | n/s rear fender inner trimboard    |                   | Bm     | 120.00                                              | c  |                              |
|       |                                    |                   |        | -----<br>5,263.00<br>Add 15% :      789.45<br>----- |    |                              |
|       |                                    |                   |        |                                                     |    | 1788<br>+ 2052<br><hr/> 3840 |
|       |                                    |                   |        |                                                     |    | <b>6,052.45</b>              |
| 1 pc  | radiator coolant                   |                   | m      | 48.00                                               | sn |                              |
| 1 pc  | reverse sensor assy                |                   | Bm     | 220.00                                              | sn | 20052                        |
| 1 pc  | tailgate glass sealant             |                   | m      | 40.00                                               | sn |                              |
| 1 pc  | tailgate glass damping seal        |                   | m      | 20.00                                               | sn |                              |
| 1 pc  | spare tyre panel heat insulation   |                   | m      | 150.00                                              | sn | Parn                         |
|       |                                    |                   |        |                                                     |    | 288                          |
|       |                                    |                   |        |                                                     |    | <b>60.00</b>                 |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Con't Page 3 ...

## 金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SGJ 8781 R  
Our Ref : 180383

Page : 3  
No. : 29832

|                                                                                                                        |                 |                |          |
|------------------------------------------------------------------------------------------------------------------------|-----------------|----------------|----------|
| To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.                    |                 | 1500           | 1,600.00 |
| To remove and refit rear windscreen glass and conduct water leak test                                                  |                 | 120.00 ✓       |          |
| To remove and refit reverse sensor assy.                                                                               | 3840            | 60.00 50       |          |
| To apply undersealing                                                                                                  | + 15%           | 150.00 120     |          |
| To check and realignment on chassis member.                                                                            | 4416 (S/parts)  | 350.00 250     |          |
| To remove and renew exhaust silencer box                                                                               | 388 (S/parts)   | 80.00 60       |          |
| To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works | 3800 (labour)   | 180.00 100     |          |
| To remove aircon condenser, pipes and driers. Vaccum and recharge gas                                                  | \$8604          | 120.00 100     |          |
| To putty and respray on affected portions.                                                                             | -20%            | 1,500.00 1400  |          |
| To focus Headlamps and Taillamps.                                                                                      | 6883.20         | 80.00 40       |          |
| To check front and rear lighting operation and rewiring                                                                | L/Sum \$ 6850/✓ | 3800           |          |
|                                                                                                                        |                 | 80.00 40       |          |
|                                                                                                                        |                 | -----          |          |
|                                                                                                                        | Total :         | \$S\$10,830.45 | 3800     |
|                                                                                                                        |                 | =====          |          |

Singapore Dollars Ten Thousand Eight Hundred and Thirty and Cents Forty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                          |
| Owner ID Type:                                                                                                                                                                                                          | Business                 |
| Owner ID:                                                                                                                                                                                                               | 3734C                    |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                          |
| Vehicle No.:                                                                                                                                                                                                            | SGY7368D                 |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                       |
| Intended De-registration Date:                                                                                                                                                                                          | 11 Jun 2018              |
| Vehicle Make:                                                                                                                                                                                                           | HONDA                    |
| Vehicle Model:                                                                                                                                                                                                          | JAZZ 1.4A                |
| Primary Colour:                                                                                                                                                                                                         | White                    |
| Manufacturing Year:                                                                                                                                                                                                     | 2007                     |
| Engine No.:                                                                                                                                                                                                             | L13A54002992             |
| Chassis No.:                                                                                                                                                                                                            | JHMGD18507S228404        |
| Maximum Power Output:                                                                                                                                                                                                   | 60.0 kW (80 bhp)         |
| Open Market Value:                                                                                                                                                                                                      | \$13,611.00              |
| Original Registration Date:                                                                                                                                                                                             | 08 Oct 2007              |
| First Registration Date:                                                                                                                                                                                                | 08 Oct 2007              |
| Transfer Count:                                                                                                                                                                                                         | 3                        |
| Actual ARF Paid:                                                                                                                                                                                                        | \$14,973.00              |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                          |
| PARF Eligibility:                                                                                                                                                                                                       | Forfeited                |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                        |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00                   |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                          |
| COE Expiry Date:                                                                                                                                                                                                        | 30 Sep 2022              |
| COE Category:                                                                                                                                                                                                           | A - Car (1600cc & below) |
| COE Period(Years):                                                                                                                                                                                                      | 5                        |
| PQP Paid:                                                                                                                                                                                                               | \$22,041.00              |
| COE Rebate Amount:                                                                                                                                                                                                      | \$18,967.00              |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$18,967.00</b>       |
| <b>Message</b>                                                                                                                                                                                                          |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 11 Jun 2018

OK



6303 6303  
inchcapepreowned.com.sg





**DRIVE-AWAY LEASING PROGRAMME**  
LEARN MORE  
WIDE VARIETY OF VEHICLES



FROM \$1,600 PER MONTH

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2800 Downpayment Monthly  
From \$688 Onwards. Lowest  
3.68% P.A. 0% GV Cars Financing  
GV Credit Pte Ltd StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

**YONG LEE SENG MOTOR PTE LTD**

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Honda Jazz

Advanced Search

|                                                                                                                                                                                                              | Make       | Model                   | Price    | Depreciation | Reg Date         | Eng Cap  | Mileage    | Veh Type  | Status    |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------|----------|--------------|------------------|----------|------------|-----------|-----------|
| <b>Search Selection</b>                                                                                                                                                                                      | Honda Jazz |                         | Any      | Any          | > 10 year(s) old | Any      | Any        | Any       | Available |
|                                                                                                                             | Honda Jazz | 1.3A (COE till 11/2021) | \$21,000 | \$6,130 /yr  | 15-Nov-2006      | 1,339 cc | 149,000 km | Hatchback | Available |
| 11.5 Years Old, Coe Renewed 5 years, 3.5 Years Left. Mileage Low For The Age. Running Perfectly With No Repairs Needed. New Paintwork Done 1 Year Ago. Currently Used As 2nd Car Only For Commuting Betwe... |            |                         |          |              |                  |          |            |           |           |
| Posted: 12-Jun-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda                                                                                                                               |            |                         |          |              |                  |          |            |           |           |
|                                                                                                                            | Honda Jazz | 1.3A (COE till 06/2021) | \$19,800 | \$6,500 /yr  | 30-Jun-2006      | 1,339 cc | 148,288 km | Hatchback | Available |
| Selling Near Export Value! Bank And In House Loan Available, Peace Of Mind, Fully Refurbished, Wear And Tear Replaced, Accident Free, Free Oil Servicing, Free Grooming.                                     |            |                         |          |              |                  |          |            |           |           |
| Posted: 09-Jun-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda                                                                                                                               |            |                         |          |              |                  |          |            |           |           |
|                                                                                                                           | Honda Jazz | 1.3A (COE till 12/2021) | \$22,800 | \$6,510 /yr  | 13-Dec-2006      | 1,339 cc | 204,000 km | Hatchback | Available |
| Bank And In House Loan Available! Low Down Payment Available! Trade In Welcome! Excellent Condition! Don't Miss It, View To Believe! Consignment Unit! Contact Us Now To Arrange Viewing And Enjoy Spec...   |            |                         |          |              |                  |          |            |           |           |
| Car Search<br>Posted: 03-Jun-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda                                                                                                                 |            |                         |          |              |                  |          |            |           |           |
|                                                                                                                           | Honda Jazz | 1.3A (COE till 09/2022) | \$25,800 | \$6,040 /yr  | 19-Sep-2007      | 1,339 cc | -          | Hatchback | Available |
| Low Maintenance. Good Condition, In House Loan Available.                                                                                                                                                    |            |                         |          |              |                  |          |            |           |           |
| Posted: 29-May-2018 Tags: 2007 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda                                                                                                                               |            |                         |          |              |                  |          |            |           |           |

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but  
Unsure of its Condition?  
Get STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



Honda Jazz 1.3A (COE till 06/2021) \$20,900 \$6,880 /yr 26-Jun-2006 1,339 cc Hatchback Available

\$3k Down. Fast And Easy Approval, Low Mileage, Accident Free, Excellent Condition, Well Kept By Previous Owner, Call Us Now For Viewing, Trade In Welcome.

Posted: 28-May-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



Honda Jazz 1.3A (COE till 06/2021) \$18,500 \$6,070 /yr 11-Jul-2006 1,339 cc Hatchback Available

Direct Owner Sale, Prefer Dealing With Non Agents. Transact At LTA. Please Sms If No Replies.

Posted: 22-Apr-2018 Tags: 2006 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda



Honda Jazz 1.3A (COE till 05/2022) \$26,881 \$6,840 /yr 19-May-2007 1,339 cc Hatchback Available

1st Owner, Clean And Neat Interior, Very Well-Maintain, Lowest Mileage In Market, Supreme Condition, Servicing Just Done, No Repairs Needed, n Welcome, Viewing Straightly By Appointment Only, ...

Posted: 11-Apr-2018 Tags: 2007 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

No. : 29832

Vehicle Insured : SGJ 8781 R  
Accident Date : 08-Jun-2018

Date : 12-Jun-2018

Our Ref : 180383 (LONPAC) / SHUMAN

PAGE : 1

DREAMZWORK WORK CREATION  
Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.4A (2007) SGY7368D

*Not with a car*  
*U/Lump B?*  
*Running After Paint*  
*14 days*

|        |                                     |             |  |                 |        |   |   |
|--------|-------------------------------------|-------------|--|-----------------|--------|---|---|
| 1 pc   | front bumper                        |             |  | <i>B</i>        | 160.00 | c | ✓ |
| 1 pc   | n/s front bumper side retainer      |             |  | <i>Diy</i>      | 9.00   | c | ✓ |
| 10 pcs | front bumper clips                  | @ S\$ 1.00  |  | <i>na</i>       | 10.00  | c | ✓ |
| 1 pc   | front bumper towing cover           |             |  | <i>na</i>       | 10.00  | c | ✓ |
| 1 pc   | front bumper centre lower grille    |             |  | <i>sn</i>       | 95.00  | c | x |
| 1 pc   | front bumper lower side grille      |             |  | <i>sn</i>       | 15.00  | c | x |
| 1 pc   | front bumper reinforcement          |             |  |                 | 85.00  | c | ? |
| 1 pc   | n/s headlamp assy                   |             |  | <i>Bu</i>       | 285.00 | c | ✓ |
| 1 pc   | n/s headlamp lower bracket          |             |  | <i>Diy</i>      | 16.00  | c | ✓ |
| 1 pc   | front support panel                 |             |  | <i>Bu</i>       | 125.00 | c | ✓ |
| 1 pc   | front grille                        |             |  | <i>sn</i>       | 100.00 | c | x |
| 1 pc   | front grille logo                   |             |  | <i>na</i>       | 20.00  | c | x |
| 1 pc   | aircon condenser                    |             |  |                 | 270.00 | c | ? |
| 1 pc   | radiator                            |             |  |                 | 290.00 | c | ? |
| 1 pc   | n/s radiator air guide              |             |  |                 | 18.00  | c | ? |
| 1 pc   | radiator spare tank                 |             |  |                 | 25.00  | c | ? |
| 1 pc   | n/s front fender                    |             |  | <i>Bu</i>       | 115.00 | c | ✓ |
| 1 pc   | n/s front fender inner shield       |             |  | <i>Diy</i>      | 35.00  | c | ✓ |
| 8 pcs  | n/s front fender inner shield clips | @ S\$ 1.00  |  | <i>na</i>       | 8.00   | c | ✓ |
| 1 pc   | air intake duct                     |             |  | <i>B</i>        | 28.00  | c | ? |
| 1 pc   | rear bumper                         |             |  | <i>B</i>        | 165.00 | c | ✓ |
| 2 pcs  | rear bumper side retainer (LH/RH)   | @ S\$ 12.00 |  | <i>Diy</i>      | 24.00  | c | ✓ |
| 10 pcs | rear bumper clips                   | @ S\$ 1.00  |  | <i>na</i>       | 10.00  | c | ✓ |
| 1 pc   | tailgate                            |             |  | <i>B</i>        | 580.00 | c | ✓ |
| 1 pc   | tailgate lock                       |             |  | <i>Diy</i>      | 90.00  | c | ✓ |
| 1 pc   | tailgate lock catch                 |             |  | <i>n</i>        | 24.00  | c | x |
| 1 pc   | tailgate weatherstrip               |             |  | <i>Diy / LH</i> | 55.00  | c | ✓ |

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

Vehicle Insured : SGJ 8781 R  
Our Ref : 180383

Page : 2  
No. : 29832

|       |                                    |        |             |    |        |   |   |
|-------|------------------------------------|--------|-------------|----|--------|---|---|
| 1 pc  | tailgate "JAZZ" emblem             |        |             | Mr | 20.00  | c | ✓ |
| 1 pc  | tailgate glass moulding            |        |             | Mr | 30.00  | c | ✓ |
| 1 pc  | tailgate inner trimboard           |        |             | Mr | 85.00  | c | ✓ |
| 1 pc  | tailgate "H" logo                  |        |             | Mr | 18.00  | c | ✓ |
| 1 pc  | tailgate outer garnish             |        |             | Mr | 75.00  | c | X |
| 2 pcs | taillamp assy (LH/RH)              | n/s cm | @ S\$125.00 |    | 250.00 | c | ✓ |
| 2 pcs | taillamp panel (LH/RH)             |        | @ S\$ 60.00 | Mr | 120.00 | c | X |
| 1 pc  | rear exhaust muffler               |        |             | Mr | 265.00 | c | ✓ |
| 1 pc  | rear exhaust head shield           |        |             |    | 45.00  | c | ✓ |
| 2 pcs | rear exhaust mounting              |        | @ S\$ 15.00 |    | 30.00  | c | ✓ |
| 1 pc  | rear end panel                     |        |             | Mr | 220.00 | c | ✓ |
| 1 pc  | rear end panel top garnish         |        |             | Mr | 40.00  | c | ✓ |
| 1 pc  | spare tyre lock screw              |        |             |    | 15.00  | c | ✓ |
| 1 pc  | spare tyre top board               |        |             | Mr | 160.00 | c | ✓ |
| 1 pc  | spare tyre panel                   |        |             | Mr | 395.00 | c | ✓ |
| 2 pcs | spare tyre extension panel (LH/RH) |        | @ S\$195.00 | Mr | 390.00 | c | X |
| 1 pc  | n/s rear chassis member            |        |             |    | 160.00 | c | ✓ |
| 2 pcs | rear fender inner shield (LH/RH)   |        | @ S\$ 75.00 | Mr | 150.00 | c | ✓ |
| 8 pcs | rear fender inner shield clips     |        | @ S\$ 1.00  | Mr | 8.00   | c | ✓ |
| 1 pc  | n/s rear fender inner trimboard    |        |             | Mr | 120.00 | c | ✓ |

-----  
Add 15% : 5,263.00  
789.45  
-----

6,052.45

|      |                                  |  |
|------|----------------------------------|--|
| 1 pc | radiator coolant                 |  |
| 1 pc | reverse sensor assy              |  |
| 1 pc | tailgate glass sealant           |  |
| 1 pc | tailgate glass damping seal      |  |
| 1 pc | spare tyre panel heat insulation |  |

|    |        |    |      |
|----|--------|----|------|
| Mr | 48.00  | sn | ✓    |
| Mr | 220.00 | sn | 2005 |
| Mr | 40.00  | sn | ✓    |
| Mr | 20.00  | sn | ✓    |
| Mr | 150.00 | sn | 2005 |

To tow accident vehicle to workshop  
by normal towing

60.00 ✓

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 3 ...

R- 4200.25  
? - 1110.90  
L- 3800

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

Vehicle Insured : SGJ 8781 R  
Our Ref : 180383

Page : 3  
No. : 29832

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

1500  
1,600.00

To remove and refit rear windscreen  
glass and conduct water leak test

120.00 ✓

To remove and refit reverse sensor  
assy.

60.00 50

To apply undersealing

150.00 120

To check and realignment on chassis  
member.

350.00 250

To remove and renew exhaust  
silencer box

80.00 60

To remove and refit rear upholstery  
trimming, roof lining, seats,  
speaker board in order to  
facilitate repairing works

180.00 100

To remove aircon condenser, pipes  
and driers. Vaccum and recharge gas

120.00 100

To putty and respray on affected  
portions.

1,500.00 1400

To focus Headlamps and Taillamps.

nn

To check front and rear lighting  
operation and rewiring

80.00 40

Total : S\$10,830.45  
=====

Singapore Dollars Ten Thousand Eight Hundred  
and Thirty and Cents Forty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020661  
Our ref: CC4/LPC18010723/Kpa3

Date: 14.06.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SGY 7368D**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.06.2018 at the premises of M/s Kim Hin Auto Pte Ltd have the following to report:-

|                               |       |           |        |
|-------------------------------|-------|-----------|--------|
| Workshop Estimate Amount      | : S\$ | 10,830.45 |        |
| Revised Estimate Amount       | : S\$ | 8,000.25  |        |
| "Check" Items Amount          | : S\$ | 1,110.90  |        |
| Total (Including Check Items) | : S\$ | 9,111.15  |        |
| Market Value                  | : S\$ | 25,500.00 | (est.) |
| LTA Reimbursement Value       | : S\$ | 18,967.00 | (est.) |
| Nett Value                    | : S\$ | 6,533.00  | (est.) |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion and Front N/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 14.0 day

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

**Catherine Chong (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 11 June, 2018 1:39 PM  
**To:** admin1@kkimhin.com.sg  
**Cc:** MT\_Claim\_SG; assignments@lkkauto.com  
**Subject:** RE: Accident involving SGY 7368 D and SGJ 8781 R on 8/6/2018

WITHOUT PREJUDICE

Our Ref : 17/18/18/VP05/020661

11.06.2018 @ 1.44pm

Shuman veh in.

Kenneth

Dear Shuman,

Our insured has yet to lodge a report and we are unable to comment on liability.

We shall proceed to appoint LKK Auto Consultants Pte Ltd for the survey.

Aside to LKK - Attn :Catherine

Kindly proceed to conduct the survey.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]

**Sent:** Monday, 11 June, 2018 12:14 PM

**To:** MT\_Claim\_SG

**Cc:** service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg

**Subject:** Accident involving SGY 7368 D and SGJ 8781 R on 8/6/2018

Your ref: SGJ 8781 R

Our ref: SGY 7368 D

Dear all,

Enclosed the GIA report of our client SGY 7368 D, who was hit by your insured SGJ 8781 R, on 8/6/2018.

Vehicle is in and working on the estimate, we will arrange for survey once ready.

Kindly advise liability.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895

**Mei Kwan (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 18 June, 2018 2:21 PM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Accident involving SGY 7368 D and SGJ 8781 R on 8/6/2018  
**Attachments:** 18062018141754.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

**Categories:** HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

**Sent:** Monday, 18 June, 2018 1:47 PM

**To:** GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG; ONG LI LI; ERIC WOO JUN KIAT; Hsiao Tong (LKKAUTO); Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A

**Subject:** RE: Accident involving SGY 7368 D and SGJ 8781 R on 8/6/2018

**EQI ref:** 17/18/18/VP05/020661

**LKK REF:** CC4/LPC18010723/Kpa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SGY 7368D

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- TP GIA report
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

---

**From:** [admin1@kkimhin.com.sg](mailto:admin1@kkimhin.com.sg) [mailto:[admin1@kkimhin.com.sg](mailto:admin1@kkimhin.com.sg)]

**Sent:** Monday, 11 June, 2018 12:14 PM

**To:** MT\_Claim\_SG

**Cc:** [service@kkimhin.com.sg](mailto:service@kkimhin.com.sg); [sandrakhong@gmail.com](mailto:sandrakhong@gmail.com); [simon@kkimhin.com.sg](mailto:simon@kkimhin.com.sg); [survey@kkimhin.com.sg](mailto:survey@kkimhin.com.sg)

**Subject:** Accident involving SGY 7368 D and SGJ 8781 R on 8/6/2018

Your ref: SGJ 8781 R

Our ref: SGY 7368 D

Dear all,

Enclosed the GIA report of our client SGY 7368 D, who was hit by your insured SGJ 8781 R, on 8/6/2018.

Vehicle is in and working on the estimate, we will arrange for survey once ready.

Kindly advise liability.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18010723/Kda3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-09-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SGJ 8781R            | Veh. Inspected | SGY 7368D  |
| Policy No.   | Z17VP05016593        | Coverage (\$)  | 0.00       |
| Claim No.    | 17/18/18/VP05/020661 | Excess (\$)    | 0.00       |
| Assign From  | GERALD POH           | Assign Date    | 11/06/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HONDA JAZZ (A)    | c.c          | 1339       |
| Engine No.   | HIDDEN            | Year of Reg. | 2007       |
| Chassis No.  | JHMGD18507S228404 | Colour       | WHITE      |
| Odometer     | 170840            | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

## 3. Conditions of Tyres

|                | Size      | Make  | Balance |
|----------------|-----------|-------|---------|
| R/H Front Tyre | 195/50R15 | NEXEN | 7 mm    |
| L/H Front Tyre | 195/50R15 | NEXEN | 7 mm    |
| R/H Rear Tyre  | 195/50R15 | NEXEN | 5 mm    |
| L/H Rear Tyre  | 195/50R15 | NEXEN | 5 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                                  |                 |            |
|----------------|----------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 08/06/2018                                                                       | Inspection Date | 12/06/2018 |
| Survey held at | K KIM HIN AUTO PTE LTD<br>BLK 34 SIN MING DRIVE,<br>#01-114,<br>SINGAPORE 575708 |                 |            |

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 7368D

| Qty                         | Description of Parts                               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                    |                      |                           |                   |
| 1                           | FRONT BUMPER (WCP)                                 | BENT                 | 160.00                    | 160.00            |
| 1                           | N/S FRONT BUMPER SIDE RETAINER (WCP)               | DISTORTED            | 9.00                      | 9.00              |
| 10                          | FRONT BUMPER CLIPS @ \$1.00 (WCP)                  | NECESSARY            | 10.00                     | 10.00             |
| 1                           | FRONT BUMPER TOWING COVER (WCP)                    | DENTED               | 10.00                     | 10.00             |
| 1                           | FRONT BUMPER CENTRE LOWER GRILLE (WCP)             | SERVICEABLE          | 95.00                     | -                 |
| 1                           | FRONT BUMPER LOWER SIDE GRILLE (WCP)               | SERVICEABLE          | 15.00                     | -                 |
| 1                           | FRONT BUMPER REINFORCEMENT (WCP)                   | BENT                 | 85.00                     | 85.00             |
| 1                           | N/S HEADLAMP ASSY (WCP)                            | BROKEN               | 285.00                    | 285.00            |
| 1                           | N/S HEADLAMP LOWER BRACKET (WCP)                   | DISTORTED            | 16.00                     | 16.00             |
| 1                           | FRONT SUPPORT PANEL (WCP)                          | BUCKLED              | 125.00                    | 125.00            |
| 1                           | FRONT GRILLE (WCP)                                 | SERVICEABLE          | 100.00                    | -                 |
| 1                           | FRONT GRILLE LOGO (WCP)                            | NOT NECESSARY        | 20.00                     | -                 |
| 1                           | AIRCON CONDENSER (WCP)                             | TWISTED / PUNCTURE   | 270.00                    | 270.00            |
| 1                           | RADIATOR (WCP)                                     | SERVICEABLE          | 290.00                    | -                 |
| 1                           | N/S RADIATOR AIR GUIDE (WCP)                       | SERVICEABLE          | 18.00                     | -                 |
| 1                           | RADIATOR SPARE TANK (WCP)                          | SERVICEABLE          | 25.00                     | -                 |
| 1                           | N/S FRONT FENDER (WCP)                             | BUCKLED              | 115.00                    | 115.00            |
| 1                           | N/S FRONT FENDER INNER SHIELD (WCP)                | DISTORTED            | 35.00                     | 35.00             |
| 8                           | N/S FRONT FENDER INNER SHIELD CLIPS @ \$1.00 (WCP) | NECESSARY            | 8.00                      | 8.00              |
| 1                           | AIR INTAKE DUCT (WCP)                              | SERVICEABLE          | 28.00                     | -                 |
| 1                           | REAR BUMPER                                        | BENT                 | 165.00                    | 165.00            |
| 2                           | REAR BUMPER SIDE RETAINER (LH/RH) @ \$12.00 (WCP)  | DISTORTED            | 24.00                     | 24.00             |
| 10                          | REAR BUMPER CLIPS @ \$1.00 (WCP)                   | NECESSARY            | 10.00                     | 10.00             |
| 1                           | TAILGATE (WCP)                                     | BENT                 | 580.00                    | 580.00            |
| 1                           | TAILGATE LOCK (WCP)                                | DENTED               | 90.00                     | 90.00             |
| 1                           | TAILGATE LOCK CATCH (WCP)                          | TO REPAIR SEE LABOUR | 24.00                     | -                 |
| 1                           | TAILGATE WEATHERSTRIP (WCP)                        | DISTORTED / CUT      | 55.00                     | 55.00             |
| 1                           | TAILGATE "JAZZ" EMBLEM (WCP)                       | NECESSARY            | 20.00                     | 20.00             |
| 1                           | TAILGATE GLASS MOULDING (WCP)                      | NECESSARY            | 30.00                     | 30.00             |

Report Ref No. CC4/LPC18010723/Kda3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | TAILGATE INNER TRIMBOARD (WCP)                        | BUCKLED              | 85.00                     | 85.00             |
| 1   | TAILGATE "H" LOGO (WCP)                               | NOT NECESSARY        | 18.00                     | -                 |
| 1   | TAILGATE OUTER GARNISH (WCP)                          | SERVICEABLE          | 75.00                     | -                 |
| 2   | TAILLAMP ASSY (LH/RH) @ \$125.00 (WCP)                | CRACKED              | 250.00                    | 250.00            |
| 2   | TAILLAMP PANEL (LH/RH) @ \$60.00 (WCP)                | TO REPAIR SEE LABOUR | 120.00                    | -                 |
| 1   | REAR EXHAUST MUFFLER (WCP)                            | BENT                 | 265.00                    | 265.00            |
| 1   | REAR EXHAUST HEAD SHIELD (WCP)                        | DENTED               | 45.00                     | 45.00             |
| 2   | REAR EXHAUST MOUNTING @ \$15.00 (WCP)                 | SERVICEABLE          | 30.00                     | -                 |
| 1   | REAR END PANEL (WCP)                                  | BENT                 | 220.00                    | 220.00            |
| 1   | REAR END PANEL TOP GARNISH (WCP)                      | DENTED               | 40.00                     | 40.00             |
| 1   | SPARE TYRE LOCK SCREW (WCP)                           | SERVICEABLE          | 15.00                     | -                 |
| 1   | SPARE TYRE TOP BOARD (WCP)                            | DEFORMED             | 160.00                    | 160.00            |
| 1   | SPARE TYRE PANEL (WCP)                                | BENT / BUCKLED       | 395.00                    | 395.00            |
| 2   | SPARE TYRE EXTENSION PANEL (LH/RH) @ \$195.00 (WCP)   | TO REPAIR SEE LABOUR | 390.00                    | -                 |
| 1   | N/S REAR CHASSIS MEMBER (WCP)                         | TO REPAIR SEE LABOUR | 160.00                    | -                 |
| 2   | REAR FENDER INNER SHIELD (LH/RH) @ \$75.00 (WCP)      | CRACKED              | 150.00                    | 150.00            |
| 8   | REAR FENDER INNER SHIELD CLIPS @ \$1.00 (WCP)         | NECESSARY            | 8.00                      | 8.00              |
| 1   | N/S REAR FENDER INNER TRIMBOARD (WCP)                 | BUCKLED              | 120.00                    | 120.00            |
|     | COST PLUS 15%                                         |                      | 789.45                    | 576.00            |
|     |                                                       |                      | 6,052.45                  | 4,416.00          |
|     | <b>SPECIAL NETT ITEMS</b>                             |                      |                           |                   |
| 1   | RADIATOR COOLANT (SN)                                 | NECESSARY            | 48.00                     | 48.00             |
| 1   | REVERSE SENSOR ASSY (SN)                              | DENTED               | 220.00                    | 200.00            |
| 1   | TAILGATE GLASS SEALANT (SN)                           | NECESSARY            | 40.00                     | 40.00             |
| 1   | TAILGATE GLASS DAMPING SEAL (SN)                      | NECESSARY            | 20.00                     | 20.00             |
| 1   | SPARE TYRE PANEL HEAT INSULATION (SN)                 | NECESSARY            | 150.00                    | 80.00             |
|     |                                                       |                      | 478.00                    | 388.00            |
|     | <b>LABOUR</b>                                         |                      |                           |                   |
|     | TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING. |                      | 60.00                     | 60.00             |

Report Ref No. CC4/LPC18010723/Kda3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                                                                                                                                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE LOCK CATCH, TAILLAMP PANEL (LH/RH), SPARE TYRE EXTENSION PANEL (LH/RH) AND N/S REAR CHASSIS MEMBER. |               | 1,600.00                  | 1,500.00          |
|                                                                             | TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.                                                                                                                                                                      |               | 120.00                    | 120.00            |
|                                                                             | TO REMOVE AND REFIT REVERSE SENSOR ASSY.                                                                                                                                                                                                    |               | 60.00                     | 50.00             |
|                                                                             | TO APPLY UNDERSEALING.                                                                                                                                                                                                                      |               | 150.00                    | 120.00            |
|                                                                             | TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.                                                                                                                                                                                                 |               | 350.00                    | 250.00            |
|                                                                             | TO REMOVE AND RENEW EXHAUST SILENCER BOX.                                                                                                                                                                                                   |               | 80.00                     | 60.00             |
|                                                                             | TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.                                                                                                                     |               | 180.00                    | 100.00            |
|                                                                             | TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.                                                                                                                                                                      |               | 120.00                    | 100.00            |
|                                                                             | TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.                                                                                                                                                                                                  |               | 1,500.00                  | 1,400.00          |
|                                                                             | TO FOCUS HEADLAMPS AND TAILLAMPS. (NPA)                                                                                                                                                                                                     | NOT NECESSARY | -                         | -                 |
|                                                                             | TO CHECK FRONT AND REAR LIGHTING OPERATION AND REWIRING.                                                                                                                                                                                    |               | 80.00                     | 40.00             |
|                                                                             |                                                                                                                                                                                                                                             |               | 4,300.00                  | 3,800.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                                                                                             |               | <b>10,830.45</b>          | <b>8,604.00</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                                                                             |               |                           | <b>6,850.00</b>   |

Report Ref No. CC4/LPC18010723/Kda3s2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.