

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7191T

MAKE : TOYOTA

MODEL : PRIUS

CHINA

DOA: 09.06.18

Date : 11.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>X repair</i>			458.60
1	REAR BUMPER SIDE RETAINER <i>?</i>			225.40
1	REAR BUMPER SPONGE <i>X</i>			143.40
1	REAR BUMPER UNDER SIDE COVER - RH <i>X</i>			167.60
1	REAR BUMPER UNDER COVER <i>✓</i>			552.60
10	REAR BUMPER CLIPS <i>X</i>			22.00
SUB TOTAL				\$ 1,569.60
LESS 25%				514.60
DISCOUNTED TOTAL				\$ 1,055.00
1	Reverse Sensor <i>X</i>			135.70
				\$ 135.70
Labour Charge				200
1	Panel Beating			\$ 300.00
1	Spray Painting Charge			\$ 300.00 200
1	Wiring Charge			\$ 50.00 X
1	Remove/refix reverse sensor			\$ 80.00 X
TOTAL LABOUR				\$ 730.00
ESTIMATE TOTAL				\$ 1,920.70

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kahar 16/6/18

Page 1 of 1

11/6/18 1105hr.
200

VIP
After Repair photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: