

KIM CHWEE AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHICLE NO: SLJ 9329Z

QTY	PARTICULAR	AMOUNT
1 PCS	BOOTLID <i>11</i>	\$2,048.10 <i>X</i>
1 PCS	BOOTLID WEATHERSTRIP <i>11</i>	\$399.20 <i>X</i>
1 PCS	REAR BUMPER <i>10/02 1451.20</i>	\$2,166.20 <i>—</i>
1 PCS	REAR BUMPER REINFORCEMENT <i>but 866.01</i>	\$1,065.10 <i>—</i>
1 PCS	REAR BUMPER SPONGE <i>10.11 266.05</i>	\$342.20 <i>—</i>
2 PCS	REAR BUMPER REVERSE ULTRASON SENSORS @\$325.20 <i>8600</i>	\$650.40 <i>✓</i>
1 PCS	REAR BUMPER SIDE REATINER N/S <i>but</i>	\$89.20 <i>—</i>
1 SET	REAR BUMPER CLIPS <i>11</i>	\$50.00 <i>—</i>
2 PCS	TAILLAMPS @\$765.10 <i>11/10/11</i>	\$1,530.20 <i>120</i>
1 PCS	TAILLAMP LOWER BRACKET N/S <i>NS</i>	\$45.30 <i>X</i>
1 PCS	REAR END PANEL <i>11</i>	\$966.01 <i>X</i>
1 PCS	REAR BUMPER LOWER SKIRTING <i>10/11/11</i>	\$766.20 <i>—</i>
1 PCS	REAR BUMPER REFLECTOR N/S <i>11</i>	\$85.50 <i>X</i>
1 PCS	REAR EXHAUST <i>11</i>	\$1,655.10 <i>X</i>
1 PCS	REAR EXHAUST CHROME N/S <i>but 195</i>	\$385.00 <i>—</i>
		\$12,243.71

*(102
x 099.86
4588.24)*

LABOUR CHARGES:

TO CHECK WIRING	\$80.00 <i>20</i>
TO DISMENTLE & REPLACING REVERSE SENSOR	\$120.00 <i>50</i>
TO TRANSFER BOOTLID MECHANISM	<i>11</i> \$100.00 <i>X</i>
TO DISMENTLE & REFIX REAR EXHAUST	<i>11</i> \$180.00 <i>X</i>
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$180.00 <i>60</i>
TO SPRAY RUST PROOFING	<i>11</i> \$80.00 <i>X</i>
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$850.00 <i>480</i>
TO PUTTY & SPRAY PAINTING	\$1,080.00 <i>600</i>

TOTAL \$14,913.71

2798.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: