

Tanpin 97495749
WP'

13/6/18 @ 4pm

Resurvey before paint.

10-11 days.

sure 1/18/18

PDI TUAS

Phone No.

Fax No.

E-Mail

PDI TUAS

KATHERINE CHONG SIEW KOON

22 FARRER ROAD

#05-02

Singapore, 268828

Singapore

VAT Registration No. M20098505-2

Tax No. 199101494Z

Service Quote

Customer No. CV032196
Quote No. SER/QUO/1800910
QuoteDate 05/06/18
Salesperson Michelle Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

LKK Auto Consultants nence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)	13,808	
License No.	VIN	Initial Registration	Sales Advisor
SLB3035C	WVWZZZAUZGW075502	31/03/16	Michelle Lee
Engine Code	Labor Type	Engine No.	Model Code
	1T	CYV 358115	5G12BZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	9	UNIT		4200 5040. 7,560.00
P B&P ALEX LABOUR	LABOURTRANSFER DOOR MEC	1	UNIT		420 840.00
P B&P ALEX LABOUR	R&R REAR LUGGAGE TRIM	1	UNIT		420 840.00
P B&P ALEX PAINT	SPRAY PAINT	5	UNIT		2400 4,000.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		? 400.00
P CINTURATO 205/55R16	Pirelli Cinturato P7 205/55R16	1	pcs		? 680.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		✓ 480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		✓ 280.00
	Nett				photo
P B&P MECH	R&R REAR AXLE BEAM	3	Time Un		1260 ? 2,520.00
	Nett				
P B&P MECH	R&R RIM & BALANCE	1	Time Un		✓ 50.00
	Nett				
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT	1	Time Un		✓ 360.00
	Sum Labor				17,710.00
P 311601361	RUBBER VALVE	1	Pieces		all 1.72
	Use Predecessor 281601361				
P 5G0073146 8Z8	ALLOY WHEEL 16" ASPEN	1	Pieces		cut 994.14
P 5G0810971D	LHS REAR FENDER LINER	1	Pieces		de 190.83
	Use Predecessor 5G0810971C				
P 5G0837205N GRU	LHS REAR DOOR HANDLE	1	Pieces		cut 96.39
P 5G0839167D GRU	LHS REAR DOOR HANDLE COVE	1	Pieces		RY 19.83
	Use Predecessor 5G0839167 GR				
P 5G0945093AD	TAILLIGHT INNER LH	1	Pieces		X 179.56
	Use Predecessor 5G0945093S				

Sum carried forward

19,192.47

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

KATHERINE CHONG SIEW KOON
22 FARRER ROAD
#05-02
Singapore, 268828
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032196
Quote No. SER/QUO/1800910
QuoteDate 05/06/18
Salesperson Michelle Lee
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)	13,808	
License No.	VIN	Initial Registration	Sales Advisor
SLB3035C	WVWZZZAUZGW075502	31/03/16	Michelle Lee
Engine Code	Labor Type	Engine No.	Model Code
	1T	CYV 358115	5G12BZ
Continued			19,192.47
P 5G0945095M	TAILLIGHT OUTER LH Use Predecessor 5G0945095F	1 Pieces	X 198.39
P 5G0945105	REFELCTOR LH	1 Pieces	X 87.43
P 5G4809843	LHS REAR FENDER	1 Pieces	H 1,394.07
P 5G4833055AB	LHS REAR DOOR Use Predecessor 5G4833055AA	1 Pieces	bt 1,523.88
P 5G6807393	BUMPER SIDE BRACKET LH	1 Pieces	nel 36.45
P 5G6807393A	TAILLIGHT LOWER BRACKET LH	1 Pieces	? 36.45
P 5G6807394	BUMPER SIDE BRACKET RH	1 Pieces	X 36.45
P 5G6807394A	TAILLIGHT LOWER BRACKET RH	1 Pieces	X 36.45
P 5G6807417APGRU	REAR BUMPER Predecessor 5G6807417ARGRU	1 Pieces	dis 1,149.75
P 5G6839699D	DOOR SEAL Use Predecessor 5G6839699C	1 Pieces	nel 114.40
P 5N0839885H	SUPPORT DOOR HANDLE	1 Pieces	? 79.26
P 5Q0501049BH	REAR AXLE BEAM	1 Pieces	? 2,412.16
P 5Q0501117A	STUB AXLE Use Predecessor 5Q0501117	1 Pieces	? 242.29
P 7N0819465E	AIR DUCT LH	1 Pieces	? 62.16
P 8V0598611A	WHEEL BEARING Use Predecessor 8V0598611	1 Pieces	? 795.12
P D 007600A1	INOXSPRAY	1 Pieces	nel 78.43
P D 180003M2	2KADHESIV	1 Pieces	nel 330.24
P D 378500A2	DOOR INSULATOR	1 Pieces	nel 53.34
P D 476KD1M2	SEALANT	1 Pieces	nel 89.29
P D 506KD1A3	2K FOAM	1 Pieces	nel 182.26
Sum carried forward			28,130.74

Payments to:

- BBN: - Acc. -No...:

PDI TUAS

PDI TUAS

KATHERINE CHONG SIEW KOON
22 FARRER ROAD
#05-02
Singapore, 268828
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV032196
Quote No. SER/QUO/1800910
QuoteDate 05/06/18
Salesperson Michelle Lee
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)	13,808	
License No.	VIN	Initial Registration	Sales Advisor
SLB3035C	WVWZZZAUZGW075502	31/03/16	Michelle Lee
Engine Code	Labor Type	Engine No.	Model Code
	1T	CYV 358115	5G12BZ
Continued			28,130.74
Sum Item			10,420.74
Sum Labor			17,710.00
Sum Item			10,420.74
Total SGD			28,130.74
7% GST			28,130.74 1,969.15
Total SGD Incl. GST			30,099.89

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No..: