1	ASS, REC. BY	1.0	ASSIGNMENT (Office)			ds Special learnaction:			
	Zanavion -		ASS		Office)			٥ سماه ام	
		ten Lee Fong	AVQA		Dute/Time: 13 6 2018				
	Estimated Cost	ں		Bill to	У				
	OD TH WS/TP RES/OD RES/EVA/INV/MV/CS								
	To Inspect Vehic	1000	0813D			Insured:	_GBF	4655D	
	nt Workshop m/s	Mova Auto).			Tel			
	of		7.50				-		
	Policy No. A	1009009000	HOO	Cl	im No:	NSY 1	800358	TKL	
	Sum Insured:				lxoess:				
	Make of Veh: (Client's Record)						D.O.A	elebore	
	CA / REV / I	REP. / REV 24 HI	RS				H.O.D. End	lorsement:	
	Date/Time:		Person Co	intacted:		v	chicle IN/	OUT	
	Date/Time	K MATERIA WATER TO A CONTROL OF THE PARTY OF	· \	Service Re		-			
		Action/Instruction (1	Shiring		water	u	TIL DANK III	
	14/11/19	144M NHVA	smd.	they have	L Wat I	regions	THE VIEW	itch. wark w	
		close the	case.		C. M.	0			
		tempora	why clas	y choe -	- (1)	>1 u	19 -		
	Participant which		1						
11.4									
6. 10					_				

Nivitha (LKK Auto)

From:

Hew, LeeFong <LeeFong.Hew@awac.com> on behalf of Motorsurvey

<Motorsurvey@awac.com>

Sent:

Wednesday, 13 June 2018 1:12 PM

To:

'assignments' 'SUR'; 'nitha'

Subject:

TP Survey assignment for YK 2813D - DOA: 06/06/2018 Our ref: NSV1800355/TKL

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Mohamad Taufikh / Mr Mohammed Rasul as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	1	YK 2813 D
Insured Vehicle		GBF 4655 D
Policy Number		AVCPSB0090001700
Name of Workshop	1	Mova Automotive Pte Ltd
Contact Number		6272 3892
Person to Contact		Nitha
Estimated Cost of repairs		\$ 16,461.42

Regards, Claims Division

Copy to Mova Automotive Pte Ltd via Email

Note -

(x)

- This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
- Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.
- Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
- Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail

in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Summer Lee (LKK Auto)

From:

Summer Lee (LKK Auto) <admin-d@lkkauto.com>

Sent:

Wednesday, 20 November, 2019 3:12 PM

To:

'Motorsurvey'; 'assignments'

Cc:

'SUR'

Subject:

RE: TP Survey assignment for YK 2813D - DOA: 06/06/2018 Our re-

NSV1800355/TKL

Dear Sir/Mdm.

Please be informed that we are unable to conduct the inspection for YK 2813D after some attempts to inform the workshop to present the vehicle.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

Best Regards,

Shiau Chan on behalf of Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Sent: Wednesday, 13 June, 2018 1:20 PM

To: 'Motorsurvey' <Motorsurvey@awac.com>; 'assignments' <assignments@lkkauto.com>

Cc: 'SUR' <sur@lkkauto.com>

Subject: RE: TP Survey assignment for YK 2813D - DOA: 06/06/2018 Our ref: NSV1800355/TKL

Dear Lee Fong,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 [S(408933)

From: Hew, LeeFong [mailto:LeeFong.Hew@awac.com] On Behalf Of Motorsurvey

Sent: Wednesday, 13 June, 2018 1:12 PM

To: 'assignments' < assignments@lkkauto.com>

Cc: 'SUR' <sur@lkkauto.com>; 'nitha' <nitha@mova.com.sg>

Subject: TP Survey assignment for YK 2813D - DOA: 06/06/2018 Our ref: NSV1800355/TKL

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of <u>Mr Mohamad Taufikh / Mr</u>

<u>Mohammed Rasul</u> as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	YK 2813 D
Insured Vehicle	9	GBF 4655 D
Policy Number		AVCPSB0090001700
Name of Workshop		Mova Automotive Pte Ltd
Contact Number		6272 3892
Person to Contact		Nitha
Estimated Cost of repairs		\$ 16,461.42

Regards, Claims Division

Copy to Mova Automotive Pte Ltd via Email

Note -

 This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.

Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.

Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.

 Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Yvonne Wong (LKK Auto)

From:

Nitha <nitha@mova.com.sg>

Sent:

Thursday, July 11, 2019 5:19 PM

To:

Yvonne Wong (LKK Auto)

Subject:

RE: VEHICLE NO: YK2813D DOA: 06/06/2018

Dear Yvonne,

This vehicle not yet repair, as for now please close this case.

Thank you,

Best Regards,
Nitha
Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



From: Yvonne Wong (LKK Auto) [mailto:yvonnewong@lkkauto.com]

Sent: Thursday, 11 July 2019 9:50 AM

To: nitha@mova.com.sg

Subject: VEHICLE NO: YK2813D DOA: 06/06/2018

Hi

Please reply my email for the above vehicle for not repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: vvonnewong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)