LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd 5 Temasek Boulevard 51 Ubi Ave 1 #01-25 #04-01 Suntec Tower Five Singapore 038985 Paya Ubi Industrial Park Singapore 408933

Attn: Steve Lim Date: 14 Jun 2018

Preliminary Advice

Vehicle No : SKX1225E Accident Date : 08/06/2018

Make : HONDA CIVIC Policy No. : DMPC17SO12092

Assignment Date : 13/06/2018 Excess : \$\$700.00 Date of Inspection : 13/06/2018 Est. Duration of Repair : 4 days

Inspection At : Lee Kuan Hwa Motor Service (Sungei Kadut)

24 Sungei Kadut Street 4 Singapore 729050

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,379.45
Revised Amount	:S\$	3,830.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,830.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 24,000.00

 COE / PARF Rebate
 :S\$ 13,641.00

Salvage Value :S\$

Margin for Repair :S\$ 10,359.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments: