

# LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645  
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721  
 Tel: 6453 4177 Fax: 6459 3724  
 Email: limyewboo@singnet.com.sg  
 Company Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD  
 8 SHENTON WAY #27-01  
 AXA TOWER SINGAPORE 068811

Estimate : TP18/036

Date : 22/06/2018  
 Vehicle Num. : SGB 3470M  
 Make/Model : NISSAN SUNNY EX-2005  
 Chassis/Eng# : JN1CFAN16Z0516252/QG16391434  
 Accident Date : 08/06/2018  
 Claim No. :  
 Reference : LYB/SGB3470M/AXA/tp  
 Policy No. :

Attention : Motor Claim Department  
 Contact : 63387288 Fax No. : 68804838

*Not Authorised*  
*LYB & 4700*  
*Sunny After Paint*  
*Subject to AXA approval*

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|     |   |                                      |        |          |
|-----|---|--------------------------------------|--------|----------|
|     |   | NETT ITEMS :                         |        |          |
| 1.  | 1 | REAR BOOT LID                        |        | 679.00   |
| 2.  | 1 | REAR BOOT LID BADGE - LOGO           |        | 39.20    |
| 3.  | 1 | REAR EMBLEM 'EX-SALOON'              |        | 35.10    |
| 4.  | 1 | REAR EMBLEM 'CVTC'                   |        | 76.80    |
| 5.  | 1 | REAR BOOT LID WEATHERSTRIP           |        | 218.10   |
| 6.  | 2 | REAR BOOT LID HINGES                 | 67.90  | 135.80   |
| 7.  | 1 | REAR BOOT LID UPPER LOCK             |        | 52.90    |
| 8.  | 1 | REAR BOOT LID LOWER LOCK             |        | 49.10    |
| 9.  | 2 | REAR TAILAMPS                        |        | 716.54   |
| 10. | 2 | REAR TAILAMP LOWER PANEL             | 185.10 | 370.20   |
| 11. | 1 | REAR TAILEND PANEL                   |        | 458.90   |
| 12. | 1 | REAR TAILEND PANEL THEROSTAT SEALANT |        | 54.20    |
| 13. | 1 | REAR TAILEND PANEL INNER GARNISH     |        | 158.10   |
| 14. | 1 | REAR BUMPER                          |        | 476.85   |
| 15. | 2 | REAR BUMPER RETAINER                 | 38.00  | 76.00    |
| 16. | 2 | REAR BUMPER BRACKET                  | 31.14  | 62.28    |
| 17. | 1 | REAR BUMPER CHROME                   |        | 184.80   |
| 18. | 1 | REAR FENDER/LH                       |        | 983.40   |
| 19. | 1 | REAR FENDER INNER SHIELD             |        | 176.10   |
| 20. | 1 | REAR W/SCREEN MLDG                   |        | 98.56    |
|     |   | Nett Total S\$ :                     |        | 5,101.93 |
|     |   | 10.00% Discount S\$ :                |        | 510.19   |
|     |   |                                      |        | 4,591.74 |

LKK Auto Consultant  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplemental charges must be resurveyed and is subject to approval from Insurance Company


Acknowledged by Repairer  
 Signature:  
 Date:

CONTINUE / ...

All cheques should be crossed and made payable to  
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



# LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645  
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721  
 Tel: 6453 4177 Fax: 6459 3724  
 Email: limyewboo@singnet.com.sg  
 Company Reg. No. : 200514/001.

AXA INSURANCE SINGAPORE PTE LTD  
 8 SHENTON WAY #27-01  
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department  
 Contact : 63387288 Fax No. : 68804838

## Estimate : TP18/036

Date : 22/06/2018  
 Vehicle Num. : SGB 3470M  
 Make/Model : NISSAN SUNNY EX-2005  
 Chassis/Eng# : JN1CFAN16Z0516252/QG516391434  
 Accident Date : 08/06/2018  
 Claim No. :  
 Reference : LYB/SGB3470M/AXA/tp  
 Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                                 |      |  |        |                  |
|---------------------------------|------|--|--------|------------------|
| <b>SPECIAL NETT ITEMS :</b>     |      |  |        |                  |
| 1.                              | 10   | REAR TAILEND PANEL INNER GARNISH CLIP  | 2.50   | 25.00 X          |
| 2.                              | 1SET | REAR REVERSE SENSOR  | 200.00 | 200.00           |
| 3.                              | 1    | REAR W/SCREEN SEALANT  | 60.00  | 60.00 40.00      |
| 4.                              | 1    | REAR W/SCREEN INNER SEAL   | 50.00  | 50.00 30.00      |
| <b>Special Nett Total S\$ :</b> |      |  |        | <b>385.00</b>    |
| <b>LABOUR :</b>                 |      |  |        |                  |
| 1                               |      | TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS  | 180.00 | 180.00 90.00     |
| 1                               |      | TO CHECK REAR WIRING FUNCTION  | 80.00  | 80.00 20.00      |
| 1                               |      | TO CHECK WATER SEEPAGE   | 80.00  | 80.00 30.00      |
| 1                               |      | TO REPAIR,RE-ALIGN ON REAR EXHAUST SILENCER  | 120.00 | 120.00 X         |
| 1                               |      | TO REPLACE REVERSE SENSOR  | 120.00 | 120.00 50.00     |
| 1                               |      | TO COMPUTER ALIGNMENT  | 120.00 | 120.00 X         |
| 1                               |      | TO REMOVE/RE-INSTALL REAR W/SCREEN TO FACILITATE REPAIR  | 150.00 | 150.00 120.00    |
|                                 |      | TO REMOVE/REFIT CUSHION/UPHOLSTERY TO REPAIRS  |        | 180.00 100.00    |
|                                 |      | TO HEAT,CUT/WELD REAR PANEL INCLUDING TO HEAT,KNOCK OUT  |        |                  |
|                                 |      | LABOUR CHARGE FOR REPLACE THE ABOVE-MENTIONED PARTS  |        | 1200.00 1,500.00 |
|                                 |      | TO PUTTY,PRIMER TO SPRAY ON REAR BOOT LID,END PANEL,<br>BUMPER,BRACKET, LHS FENDER, TO TOUCH UP ON PAINT JOB<br>USING 2K PAINTS. |        | 900.00 1,200.00  |
| <b>Labour Total S\$ :</b>       |      |  |        | <b>3,730.00</b>  |

E. & O.E.

Total S\$ : 8,706.74

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to  
 Lim Yew Boo Spray Paint Co.

Customer

E. & O.E.