

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

11-Jun-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8069 U

1 pc	n/s tail lamp	\$	321.30 X <i>old damage</i>
1 pc	reflector	\$	295.10 X
1 pc	Tailgate lower garnish	\$	362.61 ?
1 pc	Tailgate weatherstrip	\$	276.98 X
1 pc	Emblem I30	\$	27.80 <i>new</i>
1 pc	Emblem CRDI	\$	29.40 <i>new</i>
1 pc	Emblem Hyundai	\$	29.40 <i>new</i>
1 pc	Rear bumper	\$	811.11 <i>del</i>
1 pc	Rear bumper sponge	\$	79.20 ?
1 pc	Rear bumper reinforcement	\$	815.64 ?
1 pc	Rear bumper reinforcement centre	\$	79.20 ?
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 ?
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00 X

\$ 3,447.14

Less 20%

\$ 689.43

\$ 2,757.71

S/NETT

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear no. plate
1 set	Tailgate sticker
1 set	Tailgate lower garnish clips

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sundry

Towing Fee

To dismantle and replace reverse sensor and test system

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate etc

To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel

To apply rustproofing on the repaired and replaced panels

\$ 48.00 *new*

\$ 280.00 *200 new*

\$ 50.00 X

\$ 100.00 *new*

\$ 38.00 *new*

\$ 50.00 *20-*

\$ 50.00 ✓

\$ 80.00 *30*

\$ 180.00 *40*

\$ 850.00 *400*

\$ 800.00 *400*

\$ 120.00 X

\$ 5,403.71

Total

Tan Kah 97495749
- WP
3-4 days
12/6/18 @ 1420
Resurvey before paint
sur@lkkauto.com
da

