

INSURANCE

INS. CASE OWNER

Richard
marcus

CC4/AXA1801

01/3, 4 p63/9

LKK:

IDAC:

Surveyor:

DOE

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$S

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

SHC 5094K

TRANS - LAB SERVICES PH

HP:

D.O.A.:

Nature of Accident:

TP KIA REPORT

Final ? Yes / No

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Insured Liability:

Final ? Yes / No

10473881

VRK / 1680520

RENAULT

SIGLAP RD TWO S LHM1

11/6/18

TP KIA REPORT

Final ? Yes / No

SW 2677



INSRS:
WSP:
Tel:
Liability:
RMKS:

KAN MOTOR



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

18/6/18

19/6/18

28/7/18

3/9/18

SW 2677 - X SHC 5094K - Y
TP ✓ video
Old came out from motor wack
hit TP who was during straight.
File pass to type mandate
* Final bill different 1 cent due to GST.
File pass to Shu Pei to close
RECEIVED 4 SEP 2018

STAGE	DATE / PIC
Non-Reporting 1st	
Non-Reporting 2nd	
Non-Reporting 3rd	
Notification 1st (if non-pickup)	
Call OT	18/6/18
After call 1st to OT	19/6/18
Documentation Check List	Handler
Notification 1st (if non-pickup)	
After call 1st to OT	
Authorization To Act	
Release Voucher	
Final Repair Bill	
Car Rental Invoice	
Towing Invoice	
LTA / GIA	
Medical Bill	
PIR	
Mandate/Reject Instruction	
LOD	
Payment Breakdown Form	
Post-Repair Photos	
Others	

PRELIMINARY ADVICE Date/Time: 18/6/18 Sent By: DM

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$S	days / Reduction:	%
FINAL SETTLEMENT	Date/Time: 11/9/18	Confirm with: Emilin	Email: ☒ Call: ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	9
Repair Cost:	\$S 11555.81		
Loss of Rental (LOR):	\$S	(days)	
Loss of Use (LOU):	\$S 900.00	(560 x 15 days)	
Loss of Income (LOI):	\$S	(days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOU ☐		(Tick only one)	
GIA/LTA Search	\$S		
Medical:	\$S		
Disbursement:	\$S	(e.g. Tow / Independent)	
Legal Cost:	\$S		
Total:	\$S 12455.81	Global Sum \$S:	
FINAL PAYMENT	Date/Time: 11/9/18	Confirm with: Emilin	Email: ☒ Call: ☐
Payee 1:	\$S 12455.81	Name 1:	Kan Motor Co. Sdn. Bhd.
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA18010873/Upb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 14-06-2018



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5094K	Veh. Inspected	SLU 2757J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	10/06/2018	Inspection Date	14/06/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No :
Date of Accident : 10/6/2018

Document No. : SQT18002419
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SITI						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 10/6/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SHC5094K						
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR <i>DO/Bent</i>	1	761.40	✓ 25	571.05	39.97	611.02
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH <i>neu</i>	1	25.80	✓ 25	19.35	1.35	20.70
67510-TEA-T00ZZ	PANELR.RR.DOOR <i>R. d. 500</i>	1	696.60	✓ 25	522.45	36.57	559.02
72925-TEA-T01	MOLDING ASSYR.RR.DRINNER <i>neu</i>	1	28.30	✓ 25	21.22	1.49	22.71
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR <i>neu</i>	1	96.40	✓ 25	72.30	5.06	77.36
72828-TEA-T01	SEALRR.DOOR LOWER <i>neu</i>	1	6.10	✓ 25	4.57	0.32	4.89
72135-SDA-A01	STRIKER ASSYDOOR LOCK <i>11</i>	1	15.10	X 25	11.32	0.79	12.11
72610-TEX-Y01	LATCH ASSYR.RR.DOOR POWER <i>11</i>	1	69.90	X 25	52.42	3.67	56.09
71800-TEA-T01ZB	GARNISH ASSYR.SIDE SILL <i>Deep out/20.1</i>	1	114.40	✓ 25	85.80	6.01	91.81
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL <i>neu</i>	1	132.60	✓ 25	99.45	6.96	106.41
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE <i>R. d. 500</i>	1	691.00	✓ 25	518.25	36.28	554.53
73227-TEA-003	RUBBER CWINDSHIELD DAM <i>neu</i>	1	16.70	✓ 25	12.52	0.88	13.40
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>neu</i>	3	9.50	✓ 25	21.37	1.50	22.87
91501-S70-003	FASTENER BW/SHIELD <i>neu</i>	2	3.20	✓ 25	4.80	0.34	5.14
91536-SS0-J01	FASTENER AW/SHIELD <i>neu</i>	2	3.50	✓ 25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD UPPER <i>neu</i>	2	2.80	✓ 25	4.20	0.29	4.49
73125-SR3-000	RUBBER, W/SHIELD <i>neu</i>	1	12.40	✓ 25	9.30	0.65	9.95
73126-SR3-000	RUBBER, W/SHIELD <i>neu</i>	1	14.10	✓ 25	10.57	0.74	11.31
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	3	60.00	✓ 25	180.00	12.60	192.60
71500-TEC-Q00ZZ	FACE ASSYR.RR.BUMPER <i>R</i>	1	617.20	X 25	462.90	32.40	495.30



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No. :
Date of Accident : 10/6/2018

Document No. : SQT18002419
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
42700-TEA-T61	DISKALUMINIUM WHEEL	3	289.10	25	650.47	45.53	696.00
HK-215/55R16H452	HANKOOK TYRE	3	148.00	25	444.00	31.08	475.08
Sum Item					3802.88	266.19	4069.07
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR R QTR GLASS	1	250.00		250.00	17.50	267.50
Sum Ext. Service					430.00	30.10	460.10
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BML021	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00		250.00	17.50	267.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	280.00		280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00		320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	350.00		350.00	24.50	374.50
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	380.00		380.00	26.60	406.60
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	380.00		380.00	26.60	406.60
BKFE22R	CUT OFF & RENEW RR R FENDER. REPLACE R SIDE STILL	1	2600.00		2600.00	182.00	2782.00
BP06R	SPRAY PAINTING ON FR BUMPER, RR BUMPER, FR R DOOR.	1	3300.00		3300.00	231.00	3531.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
Sum Labor					8580.00	600.60	9180.60

Survey By

Printed on 12/6/2018 6:26:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: 560FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No. :
Date of Accident : 10/6/2018

Document No. : SQT18002419
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	14/6/18 @ 1pm. C S Lim				Total Amount	12,812.68	896.89
Excess	81006303 (40)				Total (Inclusive of GST)		13,709.57
Status	Not authorized						
Signature	Take photo before repair.						

marcus xblu
8-9 day.

KY Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/6/2018 6:26:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

③

29/6/2018 Page 1/2
SERVICE PRE-INVOICE

Attn: Marcus (L.K.K.)

GST Reg No.: M200050223
Company Ref. No.: S80FC1380G

9 days.

Customer: WZA006 / AXA INSURANCE
Chassis No: MRHFC5650HT000832
License No: SLU2757J
Mileage: 7025
Engine No: R16B22001064

Document No: SVO18035414
Printed By: CSLIM
Order Date: 19. June 2018
Order Time: 2:27:48 PM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO: 70683)						
	OWNER: SITI						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 10/6/2018						
	SURVEYED BY: MARCUS (L.K.K.)						
	DATE: 14/06/2018 @ 13:00PM						
	REF NO: LKK REF: CC4/AXA18010873/Upb3						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SHC5094K						
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR	1	761.40	25	571.05	39.97	611.02
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH	1	25.80	25	19.35	1.35	20.70
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	696.60	25	522.45	36.57	559.02
72925-TEA-T01	MOLDING ASSYR.R.RR.DRINNER	1	28.30	25	21.22	1.49	22.71
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR	1	96.40	25	72.30	5.06	77.36
72628-TEA-T01	SEALRR.DOOR LOWER	1	6.10	25	4.57	0.32	4.89
71800-TEA-T01ZB	GARNISH ASSYR.SIDE SILL	1	114.40	25	85.80	6.01	91.81
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL	1	132.80	25	99.45	6.96	106.41
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	691.00	25	518.25	36.28	554.53
73227-TEA-003	RUBBER CWINDOWSHIELD DAM	1	16.70	25	12.52	0.88	13.40
73626-SYY-000	RUBBERRR QTR W/SHIELD	3	9.60	25	21.37	1.50	22.87
91501-S70-003	FASTENER BW/SHIELD	2	3.20	25	4.80	0.34	5.14
91836-S80-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD UPPER	2	2.80	25	4.20	0.29	4.49
73125-SR3-000	RUBBER, W/SHIELD	1	12.40	25	9.30	0.65	9.95
73128-SR3-000	RUBBER, W/SHIELD	1	14.10	25	10.57	0.74	11.31
BO-W8-SEALANT	WINDSCREEN SEALANT (N)	3	60.00		180.00	12.60	192.60
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
42700-TEA-T81	DISKALUMINIUM WHEEL	3	289.10	25	650.47	45.53	696.00
HK-215/55R16H452	HANKOOK TYRE	2	148.00	10	266.40	18.65	285.05
	SUM PARTS:				3,089.82	216.30	3,306.12
BOSUN	0672	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BML021	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BOBC	0672	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BA02R	EXT-YJ	1	80.00		80.00	5.60	85.60
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BG52R	EXT-YJ	1	280.00		280.00	19.60	299.60
	REPLACE RR. R QTR GLASS.(N)						
BG02D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN.						
	(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	WZA006 / AXA INSURANCE	Document No:	SVO18035414			
Chassis No:	MRHFC5650HT000632	Printed By:	CSLIM			
License No:	SLU2757J	Order Date:	19. June 2018			
Mileage:	7025	Order Time:	2:27:48 PM			
Engine No:	R16B22001064	Service Advisor:	LIM CHOU SIONG			
BOMISC1	0626 RESET SMART ENTRY SYSTEM & REMOVE NECESSARY COMPONENT.(N)	1	320.00	320.00	22.40	342.40
BMI02D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)	1	250.00	250.00	17.50	267.50
BKDR12R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST & ALIGN FR R DR.(N)	1	380.00	380.00	26.60	406.60
BKDR22R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN RR R DR.(N)	1	380.00	380.00	26.60	406.60
BKFE22R	EXT-YJ CUT OFF & RENEW RR R FENDER, REPLACE R SIDE STILL PANEL GARNISH, REPAIR RR BUMPER, FR BUMPER & OTHER	1	2,240.00	2,240.00	156.80	2,396.80
BP06R	EXT-YBH SPRAY PAINTING ON FR BUMPER, RR BUMPER, FR R DOOR, RR R DOOR, RR R FENDER, R SIDE STILL PANEL & R SID	1	2,700.00	2,700.00	189.00	2,889.00
BOJSE	0672 BODY JOINT SEALANT.	1	80.00	80.00	5.60	85.60
		SUM LABOUR:		7,380.00	516.60	7,896.60
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.80	192.80
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR R QTR GLASS.	1	150.00	150.00	10.50	160.50
		SUM EXT SERVICE:		330.00	23.10	353.10
TOTAL SGD				10,799.82	756.00	11,555.82
Total Payable (SGD)				11,555.82		

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle Thanks

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No :
Date of Accident : 10/6/2018

Document No. : SQT18002419
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SITI						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 10/6/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SHC5094K						
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR <i>DP/Bent</i>	1	761.40	✓ 25	571.05	39.97	611.02
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH <i>neu</i>	1	25.80	✓ 25	19.35	1.35	20.70
67510-TEA-T00ZZ	PANELR.RR.DOOR <i>B. 1.5.0</i>	1	696.60	✓ 25	522.45	36.57	559.02
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER <i>neu</i>	1	28.30	✓ 25	21.22	1.49	22.71
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR <i>neu</i>	1	96.40	✓ 25	72.30	5.06	77.36
72828-TEA-T01	SEALRR.DOOR LOWER <i>neu</i>	1	6.10	✓ 25	4.57	0.32	4.89
72135-SDA-A01	STRIKER ASSYDOOR LOCK <i>1.1</i>	1	15.10	X 25	11.32	0.79	12.11
72610-TEX-Y01	LATCH ASSYR.RR.DOOR POWER	1	69.90	? 25	52.42	3.67	56.09
71800-TEA-T01ZB	GARNISH ASSYR.SIDE SILL <i>Deep cut/To. 1</i>	1	114.40	✓ 25	85.80	6.01	91.81
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL <i>neu</i>	1	132.60	✓ 25	99.45	6.96	106.41
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE <i>B. 1.5.0</i>	1	691.00	✓ 25	518.25	36.28	554.53
73227-TEA-003	RUBBER CWINDSHIELD DAM <i>neu</i>	1	16.70	✓ 25	12.52	0.88	13.40
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>neu</i>	3	9.50	✓ 25	21.37	1.50	22.87
91501-S70-003	FASTENER BW/SHIELD <i>neu</i>	2	3.20	✓ 25	4.80	0.34	5.14
91536-SS0-J01	FASTENER AW/SHIELD <i>neu</i>	2	3.50	✓ 25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD.UPPER. <i>neu</i>	2	2.80	✓ 25	4.20	0.29	4.49
73125-SR3-000	RUBBER, W/SHIELD <i>neu</i>	1	12.40	✓ 25	9.30	0.65	9.95
73126-SR3-000	RUBBER, W/SHIELD <i>neu</i>	1	14.10	✓ 25	10.57	0.74	11.31
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	3	60.00	✓ 25	180.00	12.60	192.60
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>R</i>	1	617.20	X 25	462.90	32.40	495.30

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLU2757J

Chassis No : MRHFC5650HT000632

Model : CIVIC 1.6 VTI YM2017

Owner's Name : SITI

Ins Policy No. :

Date of Accident : 10/6/2018

Document No. : SQT18002419

Date : 11. Jun 2018

Customer No. : WZA006

Svc Advisor : LIM CHOU SIONG

Engine No : R16B22001064

Date | Time : 11. Jun 2018 8:02:20 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>11</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER <i>nu</i>	7	2.00	25	10.50	0.74	11.24
42700-TEA-T61	DISKALUMINIUM WHEEL <i>cut/20</i>	3	289.10	25	650.47	45.53	696.00
HK-215/55R16H452	HANKOOK TYRE <i>nu/5 cut 215 o/s?</i>	3	148.00	25	444.00	31.08	475.08
<i>Amk 40</i> Sum Item					3802.68	266.19	4,068.87
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR R QTR GLASS.	1	250.00	150	250.00	17.50	267.50
Sum Ext. Service					430.00	30.10	460.10
BOSUN	SUNDRIES <i>nu</i>	1	30.00	10	30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00	✓	80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00	80	130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	280.00	✓	280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00	✓	300.00	21.00	321.00
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00	✓	320.00	22.40	342.40
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	350.00	250	350.00	24.50	374.50
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	380.00	✓	380.00	26.60	406.60
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	380.00	✓	380.00	26.60	406.60
BKFE22R	CUT OFF & RENEW RR R FENDER, REPLACE R SIDE STILL	1	2600.00	2240	2600.00	182.00	2782.00
BP06R	SPRAY PAINTING ON FR BUMPER, RR BUMPER, FR R DOOR.	1	3300.00	2700	3300.00	231.00	3531.00
BOJSE	BODY JOINT SEALANT.	1	80.00	✓	80.00	5.60	85.60
<i>nu</i> Sum Labor					8580.00	600.60	9,180.60

Survey By

Printed on 12/6/2018 6:26:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU2757J
Chassis No : MRHFC5650HT000632
Model : CIVIC 1.6 VTI YM2017
Owner's Name : SITI
Ins Policy No. :
Date of Accident : 10/6/2018

Document No. : SQT18002419 Page 3
Date : 11. Jun 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : R16B22001064
Date | Time : 11. Jun 2018 8:02:20 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Date & Time	14/6/18 @ 1pm. C S Lim				Total Amount	12,812.68	13,709.57
Excess					Total (Inclusive of GST)		13,709.57
Status	Not followed						
Signature	Take photo before repair.						

marcus 2/18

8-9 day.

LIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/6/2018 6:26:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3280J
Vehicle Details	
Vehicle No.:	SLU2757J
Vehicle to be Exported:	No
Intended De-registration Date:	14 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	R16B22001064
Chassis No.:	MRHFC5650HT000632
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,726.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$19,726.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2027
PARF Rebate Amount:	\$14,794.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$34,030.00
Total Rebate Amount:	\$48,824.00

The information contained herein is correct as at 14 Jun 2018

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 19 June 2018 2:01 PM
To: 'Lim Chou Siong'
Cc: Jeshurueben Rao Thomas; Admin A
Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SLU2757J AGAINST SHC5094K *LKK REF: CC4/AXA18010873/Upb3

Without Prejudice

Hi Sirs,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

**LOU: \$60/day
**LOR: \$100/day

Please note that all finalisation subject to AXA approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong [mailto:cslim@honda.com.sg]
Sent: Tuesday, 19 June 2018 9:42 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Jeshurueben Rao Thomas <jeshurueben@honda.com.sg>
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SLU2757J AGAINST SHC5094K

Hi Hsiao Tong,

Your Surveyor Has Survey This Vehicle SLU2757J On 14/06/18 At 13:00PM,
May I Know Is The Liability Clear, How Much Is The Rental Or LOU Per Day,
Your Insure Vehicle Number Is SHC5094K, Accident Date 10/06/18, Thanks

Best Regards,

Lim Chou Siong
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : cslim@honda.com.sg
Fax : 67480770 DID : 68465671 H/P : 81006303

From: Lim Chou Siong
Sent: Wednesday, 13 June, 2018 4:12 PM
To: motor.survey@axa.com.sg
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SLU2757J AGAINST SHC5094K

To Officer In Charge,

The Above Attachment For Your Reference,

Kindly Help To Arrange Surveyor To Survey This Vehicle SLU2757J,

Your Insure Vehicle Number SHC5094K, Accident Date 10/06/18,

Thank for your help.

Best Regards,

Lim Chou Siong
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : cslim@honda.com.sg
Fax : 67480770 DID : 68465671 H/P : 81006303

From: Lim Chou Siong
Sent: Tuesday, 12 June, 2018 6:36 PM
To: 'motor.survey@axa.com.sg' <motor.survey@axa.com.sg>
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SLU2757J AGAINST SHC5094K

To Officer In Charge,

The Above Attachment For Your Reference,

Kindly Help To Arrange Surveyor To Survey This Vehicle SLU2757J,

Your Insure Vehicle Number SHC5094K, Accident Date 10/06/18,

Thank for your help.

Best Regards,

Lim Chou Siong
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : cslim@honda.com.sg
Fax : 67480770 DID : 68465671 H/P : 81006303

From: Printer Service
Sent: Tuesday, 12 June, 2018 6:30 PM
To: Lim Chou Siong <cslim@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAUTO)

From: Emillin Liew <emillinliew@honda.com.sg>
Sent: Tuesday, 3 July 2018 8:44 AM
To: Hsiao Tong (LKKAUTO); Admin A
Cc: SUR; Faeaz
Subject: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU5757J
Attachments: AXA-LKK SLU2757J.pdf

Dear Hsiao Tong,

RE: ACCIDENT INVOLVING SLU2757J AND SHC5094K ON 10.06.18

Attached please find our repair invoice and other relevant documents for the above direct settlement claim.

Kindly email me the DV as soon as possible.

Warmest Regards,

Emillin Liew
DID: +65 6514 5684
Email: emillinliew@honda.com.sg

KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
15 Ubi Road 4 Singapore 408610
Tel: +65 6743 4333 Fax: +65 6748 0770



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Print Sent Message

This mail is associated with :

***SLU2757J (C0473881)**
[SHC5094K]

TP
SITI

Jun 10 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Kah Motor Co Sdn Bhd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 26/07/2018 08:34 AM.
To richard.angbs@axa.com.sg
CC AXA_SG; chewht@lkkauto.com
Subject <Seek Mandate> C0473881

Hi,

We refer to the above matter.

Liability: 100%. OID came out from minor road and colloded with third party who was on main road. Third party video had been uplaoded in Merimen.

We seek your approval to offer third party up to \$12,455.81(all-in). IA with mandate had been uploaded in Merimen for your perusal.

Kindly let us have your instruction/ approval please.

Hsiao Tong
DID: 6742 3197

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Jun 2018 09:15	Cim Veh Model Changed	(202493) RENAULT LATITUDE 2.0 CVT ABS (A),	[I] Shekhar Vishnu Batham
2	13 Jun 2018 09:15	Cim Created	Reg No: SLU2757J, Policy No: P1680520, Acct Date: 2018/06/10, Claim Type: TP, Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Kah Motor Co Sdn Bhd (Ubi), Ins.S tatus => Incoming Claim	[I] Shekhar Vishnu Batham
3	13 Jun 2018 15:25	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: AXA 6 Month Rotation LBS/RT, Sug gested Adj, : RT Appraisal Pte Ltd.	[I] Richard Ang
4	13 Jun 2018 15:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/25	[I] Richard Ang
5	13 Jun 2018 15:25	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[I] Richard Ang
6	13 Jun 2018 16:02	Assignment 1st Accessed		[A] Nivitha Govindasamy
7	13 Jun 2018 16:14	Label Added	(469):VNI.	[A] Nivitha Govindasamy
8	14 Jun 2018 14:27	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
9	18 Jun 2018 16:16	Label Removed	(469):VNI.	[A] Lau Shu Pei
10	26 Jul 2018 08:35	Adj Mandate Request	Cur.Req:12455.81:Liability: 100% IA with mandate uploaded in Merimen	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None



Go

ACTIVITY

[13/06/2018 16:14] Nivitha Govindasamy:
Vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1870041	26/07/2018 08:32	Motor	AXA Insurance Pte Ltd (HQ)	AXA Insurance Pte Ltd (HQ)	SLU2757J	CHEW HSIAO TONG	xx.xx
1870042	26/07/2018 08:32	Motor	AXA Insurance Pte Ltd (HQ)	AXA Insurance Pte Ltd (HQ)	SLU2757J	CHEW HSIAO TONG	xx.xx



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 URBANE L, #02-25 PAYA URBAN INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26.07.2018

Survey Details:

Date of loss	10.06.2018
Date of appointment	14.06.2018
Date of survey	14.06.2018
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLU 2757J
Make and Model	Handa Civic (1597cc)
Date of registration	28.11.2017
Excess	
Market Value	\$ 90,000.00
Parf/COE Rebate	\$ 48,824.00
Nett Loss	\$ 41,176.00

Repair details:

Initial Estimate	\$ 12,812.68
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,419.82
Check items (estimate)	.
Labour	\$ 7,380.00
Total	\$ 10,799.82
Lump Sum(if applicable)	

Number of days for repair	<u>9</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 189607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (865) 62563561 FAX : (865) 62564312

Date: 26.07.2018

Remarks:

*The breakdown of no. of days is as follows: - 9repair days +
2Saturday + 2Sunday + 1PH + 1PRS = 15days*

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 11,555.81	
Loss of use	\$ 900.00	(15days x \$60.00)
Loss of rental (w/GST)		
Loss of income		
LTA search fees		
Others		
Proposed Total	\$ 12,455.81	

Print Received Message

This mail is associated with :

***SLU2757J (C0473881)**

[SHC5094K]

TP

SITI

Jun 10 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

Kah Motor Co Sdn Bhd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 06/08/2018 15:59 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12455.81) - SLU2757J - Claim Handler: Richard Ang

Approved:12455.81.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 18 August 2018 12:57 PM
To: 'Faeaz'
Cc: Emillin Liew; Admin A; CS A Team
Subject: RE: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU2757J
Attachments: DV_SLU 2757J.pdf

Without Prejudice

Hi Faeaz,

Apologise for late reply.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$11,555.81
2. Loss of Use (15days x \$60.00)	\$ 900.00
TOTAL	<u>\$12,455.81</u>

If our offer is acceptable by your client, please duly sign the **DV** enclosed and return to us(LKK) for our necessary action.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Faeaz <faeaz@honda.com.sg>
Sent: Tuesday, 14 August 2018 2:09 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: Emillin Liew <emillinliew@honda.com.sg>
Subject: FW: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU5757J

Dear Hsiao Tong,

Refer to our below email dated 3/7/18.

To date we still have yet to receive your response on the above claim settlement.

We appreciate if you could kindly expedite the process and let us have your settlement Offer soonest possible.

Hsiao Tong (LKKAuto)

From: Emillin Liew <emillinliew@honda.com.sg>
Sent: Monday, 3 September 2018 10:05 AM
To: Hsiao Tong (LKKAuto); Faeaz
Cc: Admin A; CS A Team
Subject: RE: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU2757J
Attachments: AXA-LKK SLU2757J DV.pdf

Dear Hsiao Tong,

Attached signed DV for your retention.

We would appreciate if you could process payment for our claim soonest possible.

Regards,
Emillin

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Saturday, 18 August, 2018 12:57 PM
To: Faeaz <faeaz@honda.com.sg>
Cc: Emillin Liew <emillinliew@honda.com.sg>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: RE: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU2757J

Without Prejudice

Hi Faeaz,

Apologise for late reply.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$11,555.81
2. Loss of Use (15days x \$60.00)	\$ 900.00
TOTAL	<u>\$12,455.81</u>

If our offer is acceptable by your client, please duly sign the DV enclosed and return to us(LKK) for our necessary action.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Faeaz <faeaz@honda.com.sg>

Sent: Tuesday, 14 August 2018 2:09 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Cc: Emillin Liew <emillinliew@honda.com.sg>

Subject: FW: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU5757J

Dear Hsiao Tong,

Refer to our below email dated 3/7/18.

To date we still have yet to receive your response on the above claim settlement.

We appreciate if you could kindly expedite the process and let us have your settlement Offer soonest possible.

Best Regards

Mohd Faeaz Bin Yaacob
Senior Executive
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465678
Hp : 82886304

From: Emillin Liew

Sent: Tuesday, 3 July, 2018 8:44 AM

To: chewht@lkkauto.com; Admin A <admin-a@lkkauto.com>

Cc: sur@lkkauto.com; Faeaz <faeaz@honda.com.sg>

Subject: LKK C/O AXA- Submission of Third Party Direct Settlement, Y/R: CC4/AXA18010873/Upb3 : O/R: SLU5757J

Dear Hsiao Tong,

RE: ACCIDENT INVOLVING SLU2757J AND SHC5094K ON 10.06.18

Attached please find our repair invoice and other relevant documents for the above direct settlement claim.

Kindly email me the DV as soon as possible.

Warmest Regards,

Emillin Liew

DID: +65 6514 5684

Email: emillinliew@honda.com.sg

KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
15 Ubi Road 4 Singapore 408610
Tel: +65 6743 4333 Fax: +65 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
15 Ubi Road 4
Singapore 408610
Tel : +65 6841 3838
Fax : +65 6748 0770
www.honda.com.sg

M/s **AXA Insurance Singapore Pte Ltd**
C/o LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

Date: 03/7/18

Your ref: CC4/AXA18010873/1p3

Our ref: SLU27571

Attn: Motor Claims Department

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLU27571 AND SHC5094K ON 10.06.18

We refer to the items(s) marked (✓) below:

- (✓) We refer to LKK-Hsiao Tong's email dated 19.06.18
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- (✓) Kindly forward the discharge voucher for our client's signature within 2 weeks via email to emillinliew@honda.com.sg or faeaz@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following:-

Repair Cost	S\$11,555.82 payable to Kah Motor Co Sdn Bhd
Loss of Use	S\$60.00 x 15 Days = S\$900.00 payable to
	Siti
Rental	NIL
TP Search Bill	NIL
LTA Search Bill	NIL
- (✓) Kindly let us have your cheque made in favour of the above mentioned names(s) for our transmission as soon as possible.
- (✓) Letter of Authority

Thank you.

Yours faithfully,

.....
Lim Chou Siong

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 19 June 2018 1:57 PM
To: claims@transcab.com.sg
Cc: 'carrisaalee@ava-ins.com'; 'icewong@ava-ins.com'; 'foonghon@ava-ins.com'; 'ireneng@ava-ins.com'
Subject: ACCIDENT INVOLVING SHC 5094K & SLU 2757J ALONG/AT SIGLAP ROAD TOWARDS CHAI CHEE DRIVE ON 10/06/2018

19 JUNE 2018

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA18010873/Upb3

YOUR REF : P1680520 (SHC 5094K)

ACCIDENT INVOLVING SHC 5094K & SLU 2757J ALONG/AT SIGLAP ROAD TOWARDS CHAI CHEE DRIVE ON 10/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from KAH MOTOR CO SDN BERHAD acting on behalf of the owner of SLU 2757J against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior

knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / chewht@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SLU 2757J
& (THIRD PARTY'S VEHICLE NO.) SHL 5094K
ON 10/6/2018 ALONG 91 Siglap Road

- I hereby authorize Kah Motor Co Sdn Bhd and its agents or any person authorized by Kah Motor to do all or any of the following.
- To submit, resolve and make any claims(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher / indemnity forms and all necessary documents in connection with and arising out of the above claim

Any payment should be made in favour of my name / Kah Motor Co Sdn Bhd



Owner Signature

(Co stamp & authorized signature if it's Co. registered vehicle)

Name : SITI
NRIC No : S2223280J
Vehicle No : SLU 2757J
Date : 11/6/2018



redefining / insurance

CLAIM REF : C0473881
INSURED : TRANS-CAB SERVICES PTE LTD

WITHOUT PREJUDICE IS

Only For use, Once Only

DISCHARGE VOUCHER

We/I, SITI, NRIC NO. S2223280J hereby agree to accept the sum of dollars TWELVE THOUSAND FOUR HUNDRED FIFTY FIVE AND CENTS EIGHTY ONE ONLY (\$\$12,455.81) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. SHC 5094K as a result of an accident along 91 SIGLAP ROAD on 10/06/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLU 2757J.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SHC 5094K in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SHC 5094K.

Dated this 01st day of Sept 2018

Claimant's Signature



NRIC no./ Company Stamp

S2223280J

Occupation/ Business

Address

63 Chai Chee Road #09-09 Singapore 460063

Telephone No.

96343595

Witness's Name

KAH MOTOR CO. SDN. BHD.

Witness's Signature

15, UBI ROAD 4
SINGAPORE 408610

Witness's NRIC No.

TEL: 6841 3838 FAX: 6748 0770



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, 408610 SINGAPORE

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S60FC1380G

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Invoice No. : SINV-BS18001124
 Invoice Date : 30/06/18
 Order No. : SVO18035414
 Reference :
 Job Card No. : 70683
 Date/Time Received : 11/06/18 / 8:02:20 PM
 Licence No. : SLU2757J
 Model : CIVIC 1.6 VTI YM2017
 Car Chassis No. : MRHFC5650HT000632
 Car Engine No. : R16B22001064
 Mileage : 7025
 Service Advisor : LIM CHOU SIONG 0427A
 Served By : CSLIM
 Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	Amount	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO: 70683)							
	OWNER: SITI							
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L							
	ACC DATE: 10/6/2018							
	SURVEYED BY: MARCUS (L.K.K.)							
	DATE: 14/06/2018 @ 13:00PM							
	REF NO: LKK REF: CC4/AXA18010873/Upb3							
	TP INSURER: AXA INSURANCE S'PORE PTE LTD							
	TP VEH: SHC5094K							
BOSUN	0672 SUNDRIES	1	Hours	10.00		10.00	0.70	10.70
BML02I	EXT- INSPECT RR LIGHTING MECHANISMS.	1	Hours	80.00		80.00	5.60	85.60
	YJ PERFORM WATER TEST.(N)							
BOBC	0672 BODY UNDERSIDE COATING (N)	1	Hours	100.00		100.00	7.00	107.00
BA02R	EXT- REMOVE & RENEW REVERSE SENSORS-4	1	Hours	80.00		80.00	5.60	85.60
	YJ PCS (N)							
BP00R	EXT- APPLY BODY UNDERSIDE COATING (N).	1	Hours	180.00		180.00	12.60	192.60
	YBH							
BG52R	EXT- REPLACE RR. R QTR GLASS.(N)	1	Hours	280.00		280.00	19.60	299.60
	YJ							
BG02D	EXT- REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	300.00		300.00	21.00	321.00
	YJ							
BOMISC1	0626 RESET SMART ENTRY SYSTEM & REMOVE NECESSARY COMPONENT.(N)	1	Hours	320.00		320.00	22.40	342.40
BM102D	EXT- REMOVE & INSTALL REAR COMPARTMENT LININGS, RR	1	Hours	250.00		250.00	17.50	267.50
	YJ SEATS, TRUNK LININGS, GARNISHES & ETC.(N)							
BKDR12R	EXT- REMOVE & TRANSFER ITEMS TO NEW FR R	1	Hours	380.00		380.00	26.60	406.60
	YJ DR. ADJUST & ALIGN FR R DR.(N)							
BKDR22R	EXT- REMOVE & TRANSFER ITEMS TO NEW RR R	1	Hours	380.00		380.00	26.60	406.60
	YJ DR. ADJUST & ALIGN RR R DR.(N)							
BKFE22R	EXT- CUT OFF & RENEW RR R FENDER, REPLACE R SIDE STILL	1	Hours	2,240.00		2,240.00	156.80	2,396.80
	YJ PANEL GARNISH, REPAIR RR BUMPER, FR BUMPER & OTHER							
BP06R	EXT- SPRAY PAINTING ON FR BUMPER, RR	1	Hours	2,700.00		2,700.00	189.00	2,889.00
	YBH BUMPER, FR R DOOR, RR R DOOR, RR R FENDER, R SIDE STILL PANEL & R SID							
BOJSE	0672 BODY JOINT SEALANT.	1	Hours	80.00		80.00	5.60	85.60
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR	1	Each	761.40	25	571.05	39.97	611.02

Printed by CSLIM on 30 Jun 2018 at 2:18:48 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your feedback by scanning the QR Code using mobile device.



**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4, 408610 SINGAPORE

Ubi Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BS18001124
Invoice Date : 30/06/18
Order No. : SVO18035414
Reference :
Job Card No. : 70683
Date/Time Received : 11/06/18 / 8:02:20 PM
Licence No. : SLU2757J
Model : CIVIC 1.6 VTI YM2017
Car Chassis No. : MRHFC5650HT000632
Car Engine No. : R16B22001064
Mileage : 7025
Service Advisor : LIM CHOU SIONG 0427A
Served By : CSLM
Page : 2

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount Incl		
						Amount	Amount	GST
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH	1	Each	25.80	25	19.35	1.35	20.70
67510-TEA-T00ZZ	PANELR.RR.DOOR	1	Each	696.80	25	522.45	36.57	559.02
72925-TEA-T01	MOLDING ASSYR.RR.DRINNER	1	Each	28.30	25	21.22	1.49	22.71
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR	1	Each	96.40	25	72.30	5.06	77.36
72828-TEA-T01	SEALRR.DOOR LOWER	1	Each	6.10	25	4.57	0.32	4.89
71800-TEA-T01ZB	GARNISH ASSYR.SIDE SILL	1	Each	114.40	25	85.80	6.01	91.81
73500-TEA-T01	GLASS ASSYR.QUARTER WINDSHIEL	1	Each	132.60	25	99.45	6.96	106.41
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	Each	691.00	25	518.25	36.28	554.53
73227-TEA-003	RUBBER CWINDOWSHIELD DAM	1	Each	16.70	25	12.52	0.88	13.40
73525-SYY-000	RUBBERRR QTR W/SHIELD	3	Each	9.50	25	21.37	1.50	22.87
91501-S70-003	FASTENER BW/SHIELD	2	Each	3.20	25	4.80	0.34	5.14
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.50	25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD.UPPER.	2	Each	2.80	25	4.20	0.29	4.49
73125-SR3-000	RUBBER, W/SHIELD	1	Each	12.40	25	9.30	0.65	9.95
73126-SR3-000	RUBBER, W/SHIELD	1	Each	14.10	25	10.57	0.74	11.31
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	3	Each	60.00		180.00	12.60	192.60
91505-TM8-003	CLIPBUMPER	7	Each	2.00	25	10.50	0.74	11.24
42700-TEA-T61	DISKALUMINIUM WHEEL	3	Each	289.10	25	650.47	45.53	696.00
HK-215/55R16H452	HANKOOK TYRE	2	Each	148.00	10	266.40	18.65	285.05
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	Labor	180.00		180.00	12.60	192.60
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR R QTR GLASS.	1	Each	150.00		150.00	10.50	160.50

Sum Labor	7,380.00	516.60	7,896.60
Sum Item	3,089.82	216.30	3,306.12
Sum External Services	330.00	23.10	353.10
Total SGD	10,799.82	756.00	11,555.82
Total Payable (SGD)			11,555.82

Printed by CSLM on 30 Jun 2018 at 2:18:48 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

(GST Amount is calculated from individual line(s))

Please give us your
feedback by scanning
the QR Code using
mobile device



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2018		13 Jun 2018 15:25 Edit Adj Rpt	S\$10,799.82 Edit Estimates	S\$10,799.82 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878X									
Main Claimant: SITI , ID: S2223280J									
Vehicle Reg. No.: SLU2757J		Date of Loss: 10/06/2018 00:00 - :59 [6 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / C0473881		Policy/Cover Note No.: P1680520 (Third Party Only)							
Vehicle Reg. No. (Insured): SHC5094K		Policy No. (Claimant): 17-MUD12115-R00							
		Excess: S\$5,000.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Richard Ang]									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/06/2018]									
Driver/Custodian (Insured): TEO KIAN KIM (52 / Male) , NRIC: S1720003H, Tel: +6596428733									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (06/08/2018): Alert - Adj Mandate Approved (S\$12455.81) - SLU2757J - Claim Handler: Richard An... - AXA_SG (13/06/2018): New TP Assignment - C0473881/P1680520									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU2757J (C0473881)
[SHC5094K]
TP
SITI
Jun 10 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	26/07/18 08:32	TP VIDEO_PART 1												1	Load AVI					
2	26/07/18 08:32	TP VIDEO_PART 2												1	Load AVI					
Letters/Correspondences															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
Documentation															1 per page		v	☒		
No	Finalized On	AXA Insurance Pte Ltd (HQ)												Thumbnail		Print				
1	13/06/18 09:20	ESTIMATE												1	Load PDF					
2	13/06/18 09:20	GIA SHC5094K INSD												1	Load PDF					
3	13/06/18 09:20	GIA SLU2757J TP												1	Load PDF					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	18/06/18 14:43	Immediate Advice												1	Load PDF					
2	18/06/18 16:16	TP ESTIMATE- MARKED												1	Load PDF					
3	26/07/18 08:24	LKK Survey Photos												1	Load PDF					
4	26/07/18 08:24	LKK Resurvey Photos												1	Load PDF					
5	26/07/18 08:30	Immediate Advice (with mandate) dd 260718												1	Load PDF					
6	19/09/18 15:40	WORKSHOP INVOICE												1	Load PDF					
7	19/09/18 15:40	AUTHORISATION TO ACT FORM												1	Load PDF					
8	19/09/18 15:40	DISCHARGE VOUCHER												1	Load PDF					
9	19/09/18 15:40	LETTER TO OI												1	Load PDF					
10	19/09/18 15:40	LOD												1	Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5094K (Insd veh)	Model:	RENAULT LATITUDE 2.0 CVT
	SLU2757J (TP veh)		ABS (A)
Date of Accident:	10/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		13,709.57
Final Repair Cost	:	\$		11,555.81
Loss of Use	:	\$		900.00
				15.00 days at \$60.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		0.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		12,455.81

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kah Motor Co.Sdn.Bhd.	:	\$ 12,455.81
2)		:	\$

JOANNE LEE KHANG MIN

19 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18010873/UPB3Q2
Date: 19/09/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SLU2757J	Insured Vehicle No :	SHC5094K
Date of Loss:	10/06/2018	Nature of Claim:	TP
		Claim No:	C0473881

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU2757J	Engine No:	R16B22001064
Make & Model:	RENAULT LATITUDE, 2.0 CVT ABS (A)	Chassis No:	MRHFC5650HT000632
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	7025 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,912.68	3,179.82	732.86	18.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,900.00	7,620.00	1,280.00	14.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,812.68	10,799.82	2,012.86	15.71
+ GST 7.00/7.00% (S\$)	896.89	755.99	140.90	15.71
Nett Amount (S\$)	13,709.57	11,555.81	2,153.76	15.71
+ Loss of Use (15.0 x S\$60.00/day) (S\$)		900.00		
Nett Liability (S\$)		12,455.81		

INSPECTION

Date of Assignment:	13/06/2018		
Date Inspected:	14/06/2018	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	9.0 days		

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2018)
Parts:	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU2757J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMPR.FR.DOOR (CONSISTENT)	Dented / Bent	571.05 FS	*571.05 FS
2	1		*MOLDING ASSYR.FR.DOOR SASH (CONSISTENT)	Necessary	19.35 FS	*19.35 FS
3	1		*PANEL.RR.DOOR (CONSISTENT)	Badly Dented	522.45 FS	*522.45 FS
4	1		*MOLDING ASSY,R.RR.DRINNER (CONSISTENT)	Necessary	21.22 FS	*21.22 FS
5	1		*WEATHERSTRIP.R.DOOR (CONSISTENT)	Necessary	72.30 FS	*72.30 FS
6	1		*SEALRR.DOOR LOWER (CONSISTENT)	Necessary	4.57 FS	*4.57 FS
7	1		*STRIKER ASSYDOOR LOCK (CONSISTENT)	Not Necessary	11.32 FS	*- FS
8	1		*LATCH ASSYR.RR.DOOR POWER (CONSISTENT)	Not Necessary	52.42 FS	*- FS
9	1		*GARNISH ASSYR.SIDE SILL (CONSISTENT)	Deep Cut / Torn	85.80 FS	*85.80 FS
10	1		*GLASS ASSYR.QUARTER WINDSHIEL (CONSISTENT)	Necessary	99.45 FS	*99.45 FS
11	1		*PANEL SETR.RR.OUTSIDE (CONSISTENT)	Badly Dented	518.25 FS	*518.25 FS
12	1		*RUBBER C WINDSHIELD DAM (CONSISTENT)	Necessary	12.52 FS	*12.52 FS
13	1		*RUBBERRR QTR W/SHIELD (3 PCS) (CONSISTENT)	Necessary	21.37 FS	*21.37 FS
14	2		*FASTENER BW/SHIELD (CONSISTENT)	Necessary	4.80 FS	*4.80 FS
15	1		*FASTENER AW/SHIELD (CONSISTENT) (2 PCS)	Necessary	5.25 FS	*5.25 FS
16	2		*CLIPFR.WINDSHIELD,UPPER (CONSISTENT)	Necessary	4.20 FS	*4.20 FS
17	1		*RUBBER ,W/SHIELD (CONSISTENT)	Necessary	9.30 FS	*9.30 FS
18	1		*RUBBER ,W/SHIELD (CONSISTENT)	Necessary	10.57 FS	*10.57 FS
19	3		*WINDSCREEN SEALANT (CONSISTENT)	Necessary	180.00 FS	*180.00 FS
20	1		*FACE ASSY ,RR.BUMPER (CONSISTENT)	Repair	462.90 FS	*- FS
21	1		*SPACERR.RR.BUMPER SIDE (CONSISTENT)	Not Necessary	8.62 FS	*- FS
22	7		*CLIPBUMPER (CONSISTENT)	Necessary	10.50 FS	*10.50 FS
23	1		*DISKALUMINIUM WHEEL (CONSISTENT) (3 PCS)	Cut / Dented	650.47 FS	*650.47 FS
24	1		*HANKOOK TYRE (CONSISTENT) (90%) (3 PCS)	N/S Cut / O/S Not Necessary	444.00 FS	*266.40 FS
25	1		*SUNDRIES (CONSISTENT)	Necessary	30.00 FS	*10.00 FS
26	1		*BODY JOINT SEALANT (CONSISTENT)	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 3,912.68 3,179.82

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	80.00	80.00
2	BODY UNDERSIDE COATING	New	100.00	100.00
3	REMOVE & RENEW REVERSE SENSORS	New	130.00	80.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REPLACE RR.R QTR GLASS	New	280.00	280.00
6	REMOVE & INSTALL RR .WINDSCREEN	New	300.00	300.00
7	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	New	320.00	320.00
8	REMOVE & INSTALL REAR COMPARTMENT LININGS,RR	New	350.00	250.00
9	REMOVE & TRANSFER ITEMS TO NEW FR R DR ADJUST	New	380.00	380.00
10	REMOVE & TRANSFER ITEMS TO NEW RR R DR ADJUST	New	380.00	380.00
11	CUT OFF & RENEW RR R FENDER ,REPLACE R SIDE STILL	New	2,600.00	2,240.00
12	SPRAY PAINTING ON FR BUMPER ,RR BUMPER ,FR R DOOR	New	3,300.00	2,700.00
13	WHEEL ALIGNMENT	New	180.00	180.00
14	SUPPLY & INSTALL SOLAR FILM ON REAR R QTR GLASS	New	250.00	150.00
Gross Labour Cost (S\$)			8,900.00	7,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >