

# ESTIMATE TO REPAIR

VEHICLE NO. : QX 1132 T  
 MAKE : TOYOTA  
 MODEL : WISH 1.8 CVT  
 YEAR : 2016  
 CHASSIS NO : JTDGG20W00J003663

SURVEYOR NAME	:	
DATE OF SURVEY	:	18.06.2018
TIME OF SURVEY	:	

DATE : 13-Jun-18  
 DATE OF ACCIDENT : 6-Jun-18  
 THIRD PARTY REF : SKQ 9998 S / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
	To putty and spray painting.			2008 \$	250.00
	To repair rear bumper			\$61	120.00
<div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer            Signature:            Date:</p> </div> <p style="text-align: center; margin-top: 20px;"><i>Not Authorized</i> 1 day</p>					
TG-RA/-	<b>TOTAL</b>				<b>\$ 370.00</b>

Lim Tan Motor Pte Ltd  
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel: 65-64520893 Fax 65-64589127 Website : www.LTM.sg  
 Co.Reg No.199307277D GST Reg No.M2-0019086-0