

REF:

CC3/ALH18010899/Aqbar

ASS: REC BY: Adrian Ling

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

170087591

Claims No.

246374759056

Sum Insured:

Excess:

600 20/6/18

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

145K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16 days

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKQ3666P

Yr Regn:

2017 Dec

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

cc 1395

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

10101

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAV222F4XJA041949

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SiRim / STD A/Rim or

Tyre Size:

F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/06/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

SKQ 3666P - NA/ALH18010899/A4

DCA: 11-06-18

15/6/18 @ 2:30pm revert to Victor via message.

19/6/18 @ 2:30pm Victor informed via message.

20/6/18 @ 12pm Informed Tony C/A to be \$600 by email.

12/4/18 @ 11:14am confirmed with Mr BOD final fig \$2443.52, 16 days by email.
(Red \$12558.48, 44%.)

Date/Time: File Pass to:

☐

: Prel. Report

12/5/19 11:55

☐

: Final Report

Date/Time: File Return to:

2)

Report Format

per-OD

Lump Sum / L.B.J. (\$) :

22443.52

RECEIVED 25 SEP 2018

Days Of Repair:

16

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$4

Photos:

Other:

TOTAL

200

10

210

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 12 September 2018 11:14 AM
To: Boo seng yak; SUR; Carrine Leong; jayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SKQ3666P - OD AIG - SURVEYED 14 JUN 18

Dear Mr Boo,

WITOUT PREJUDISE

Confirm final fig \$22,443.52 before excess \$600.00 & GST and 16 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 13 August 2018 10:39 AM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKQ3666P - OD AIG - SURVEYED 14 JUN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$22,443.52 @ 16 days of repairs exclude 3 Sundays.

Your early closure is well appreciated.

Best regards - jb

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	14 Jun 2018 16:32	Cim Dtl Modified	Insured Name: -> QUAH TUANG KIT @ LEE TUANG KIT.	[A] CATHERINE CHONG KAI LING
2	14 Jun 2018 16:32	Cim Dtl Modified	Claimant's Name: -> QUAH TUANG KIT @ LEE TUANG KIT. Claimant's ID: -> S016 4076C.	[A] CATHERINE CHONG KAI LING
3	14 Jun 2018 16:32	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
4	14 Jun 2018 16:32	Cim Created	Reg No: SKQ3666P, Policy No: 1700087591, Acct Date: 2018/06/11, Claim Type: O D, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Premium Automobiles Pte Ltd (UBI)	[A] CATHERINE CHONG KAI LING
5	14 Jun 2018 16:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); Suggested Adj. : LKK Auto Consultants Pte Ltd.	[A] CATHERINE CHONG KAI LING
6	14 Jun 2018 16:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/26	[A] CATHERINE CHONG KAI LING
7	14 Jun 2018 16:32	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	14 Jun 2018 16:32	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
9	14 Jun 2018 16:32	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
10	18 Jun 2018 14:05	Adj Rpt Initiated		[A] SHIAU CHAN
11	18 Jun 2018 14:05	Insured Phone No Updated	[None] -> [+6590628793]	[A] SHIAU CHAN
12	18 Jun 2018 14:05	Cim Dtl Modified	Driver Name: -> TIANG LENG ING.	[A] SHIAU CHAN
13	18 Jun 2018 14:05	Cim Dtl Modified	JPJ Reg. Date: -> 2017/12/11.	[A] SHIAU CHAN
14	18 Jun 2018 14:05	Cim Details Notified		[A] SHIAU CHAN
15	18 Jun 2018 14:34	Cim Registration Modified	Excess: -> 600.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Tr, Tinesh
16	18 Jun 2018 14:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/26	[A] SHIAU CHAN
17	18 Jun 2018 14:35	Adj Mandate Request	Cur.Req:24351.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	19 Jun 2018 14:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/26, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	19 Jun 2018 14:32	Adj Mandate Set	Approved:22251.00:Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK
20	17 Aug 2018 16:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/26	[A] SHIAU CHAN
21	17 Aug 2018 16:57	Adj Mandate Request	Cur.Req:22443.52:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY APPROVE ON CHECK ITEMS.	[A] SHIAU CHAN
22	11 Sep 2018 14:59	Adj Mandate Set	Approved:22443.52.Reinsp:Adj decides.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1834669	18/06/2018 14:05	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKQ3666P		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 17 Aug 2018

Preliminary Advice

Vehicle No	: SKQ3666P	Accident Date	: 11/06/2018
Make	: AUDI A4	Policy No.	: 1700087591
Assignment Date	: 14/06/2018	Excess	: S\$600.00
Date of Inspection	: 14/06/2018	Est. Duration of Repair	: 16.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,002.00
Revised Amount	:S\$	22,443.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	22,443.52

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	75,249.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,751.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON CHECK ITEMS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 20 June 2018 12:00 PM
To: 'Claims'
Cc: SUR
Subject: RE: VEHICLE SJQ 3666P (DOA: 11/06/2018)

Dear Tony,

As instructed by our client AIG Insurance, please proceed to repair the insured vehicle **SKQ 3666P (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Tuesday, 19 June 2018 9:51 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: VEHICLE SJQ 3666P (DOA: 11/06/2018)

Dear Shiau Chan,

The video footage has over write.

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	14 Jun 2018 16:32	Cim Dtl Modified	Insured Name: -> QUAH TUANG KIT @ LEE TUANG KIT.	[A] CATHERINE CHONG KAI LING
2	14 Jun 2018 16:32	Cim Dtl Modified	Claimant's Name: -> QUAH TUANG KIT @ LEE TUANG KIT, Claimant's ID: -> S016 4076C.	[A] CATHERINE CHONG KAI LING
3	14 Jun 2018 16:32	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
4	14 Jun 2018 16:32	Cim Created	Reg No: SKQ3666P, Policy No: 1700087591, Acct Date: 2018/06/11, Claim Type: O D, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Premium Automobiles Pte Ltd (UBI)	[A] CATHERINE CHONG KAI LING
5	14 Jun 2018 16:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); Suggested Adj. : LKK Auto Consultants Pte Ltd.	[A] CATHERINE CHONG KAI LING
6	14 Jun 2018 16:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/26	[A] CATHERINE CHONG KAI LING
7	14 Jun 2018 16:32	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	14 Jun 2018 16:32	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
9	14 Jun 2018 16:32	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
10	18 Jun 2018 14:05	Adj Rpt Initiated		[A] SHIAU CHAN
11	18 Jun 2018 14:05	Insured Phone No Updated	[None] -> [+6590628793]	[A] SHIAU CHAN
12	18 Jun 2018 14:05	Cim Dtl Modified	Driver Name: -> TIANG LENG ING.	[A] SHIAU CHAN
13	18 Jun 2018 14:05	Cim Dtl Modified	JPJ Reg. Date: -> 2017/12/11.	[A] SHIAU CHAN
14	18 Jun 2018 14:05	Cim Details Notified		[A] SHIAU CHAN
15	18 Jun 2018 14:34	Cim Registration Modified	Excess: -> 600.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Tr, Tinesh
16	18 Jun 2018 14:35	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/26	[A] SHIAU CHAN
17	18 Jun 2018 14:35	Adj Mandate Request	Cur,Req:24351.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	19 Jun 2018 14:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/26. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	19 Jun 2018 14:32	Adj Mandate Set	Approved:22251.00:Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Cl Name (Branch)	Ref 1	Ref 2	Amount
1834669	18/06/2018 14:05	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKQ3666P		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 18 Jun 2018

Preliminary Advice

Vehicle No	: SKQ3666P	Accident Date	: 11/06/2018
Make	: AUDI A4	Policy No.	: 1700087591
Assignment Date	: 14/06/2018	Excess	: S\$0.00
Date of Inspection	: 14/06/2018	Est. Duration of Repair	: 16.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,002.00
Revised Amount	:S\$	22,251.00
Check Items (Estimated)	:S\$	2,100.00
Total	:S\$	24,351.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	75,249.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,751.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4076C
Vehicle Details	
Vehicle No.:	SKQ3666P
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	CVN049863
Chassis No.:	WAUZZZF4XJA041949
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,726.00
Original Registration Date:	11 Dec 2017
First Registration Date:	11 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$27,817.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2027
PARF Rebate Amount:	\$20,862.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$54,387.00
Total Rebate Amount:	\$75,249.00

The information contained herein is correct as at 18 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/06/2018 14:27
Date Of Accident	11/06/2018 12:30
Exact Location Of Accident	UPPER SERANGOON VIADUCT TWDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ3666P
Insured/Policyholder	
Name Of Registered Owner	QUAH TUANG KIT @LEE TUANG KIT
NRIC No	S0164076C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90628793
Alternative Phone No	OFFICE-90628793

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.4 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700087591
Cover Note Number	-

Driver

Name of Driver	TIANG LENG ING
NRIC No	S0197402E
Date Of Birth	05/05/1950
Occupation	INDOOR
Date Of Driving Pass	22/07/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97609837
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 234 HOUGANG AVE 1 #04-262
Postcode	530234
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG UPPER SERANGOON VIADUCT TWDS CITY, WHEN I WAS DRIVING ON THE RIGHT LANE, SUDDENLY I NOTICED AN UNKNOWN OBJECT APPEAR ON THE ROAD WHICH WAS ON MY LANE, I PANIC THEN SWERVED TO THE RIGHT, UNFORTUNATELY MY VEH RIGHT SIDE HIT ONTO THE WALL. NO DAMAGE ON THE WALL.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	HAVENT RETRIEVE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WALL
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MNA 118075524. Vehicle Registration No: SKQ 3666P
Name (as shown in NRIC) : Quah Tuang Kit NRIC/FIN/Passport No : S 0164076C
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : 90628793.
Email Address : _____
Date of Accident : 11/6/18 Time of Accident : 12:30.
Place of Accident : Upper Serangoon viaduct twds City
Insurance Company: AIG.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

* Amend to change the Insurance company to
AIG instead of China taiping.

Policyholder / Driver's Signature

Date:

13/6/18

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date: 13/6/18.



Name of Policyholder : QUAH TUANG KIT @ LEE TUANG KIT
Period of Insurance : 11 Dec 2017 To 10 Dec 2018
Engine No. : CVN049863
Chassis No. : WAIJZZZF4XJA041949

Vehicle No. : SKQ3686P
Policy No. : 1700087591
Endorsement No. :
Issued Date : 21 Dec 2017

Make/Model	AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage	1,395.00 CC
Driver Restriction	NA

Sum Insured	Market Value
Off Peak Car	No

First Year of Registration	2017
Insuring with COE/PARE	Yes

The Policy will indemnify the Policyholder or any authorized driver only if both of the specified age conditions

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDE") if you are in your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition	All Age Condition
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

Limitation as to use*

Use only for small, domestic and pleasure purposes and for the Folklifeholder's pleasure

This Policy may not cover use by hire or reward, driving tuition, driving HQ, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 9 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 9C of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 4

Fire - \$0 Claim Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 1

Property Damage - \$0

Wintergreen : \$1.00

Named Driver and Excess (where applicable)

QUAN TUANGS HIT @ LEE TUANGS HIT ... \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

† Asia Customer Service Center, A-01, 10th Floor, 1 Singapore 408600 C3602325

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at 465-8338/8200. Alternatively, you may refer to AIG website www.aig.com to use AIG SOS Mobile App. Simply search and download "AIG SOS" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1988 (Malaysia).

D5D4125256

PREMIUM LEASING -LSYA

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 26

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing services (accidents or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and witnesses
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairer's within 24 hours or the next working day of the accident

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and witnesses, if applicable
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairer's within 24 hours or the next working day of the accident

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other parties.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairer's within 24 hours or the next working day of the accident.
- Submit AIG(Singapore)/Correspondence form (first page) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S0197402E

Name: TIANG LENG ING

Birth Date: 05 May 1950

Issue Date: 23 May 2003



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0197402E



Name

TIANG LENG ING

程蓮英

Race

CHINESE

Date of Birth

05-05-1950

Sex

F

Country of Birth

SINGAPORE



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms

22 Jul 1977



Licence No: S0197402E

NP 438A



1701056

NRIC No: S0197402E



Blood Group

B+

Date of issue

19-02-1994

APT BLK 234 HOUGANG AVENUE 1 #04-262
SINGAPORE 530234

NRIC No: S0197402E

Date: 23/12/2012

No: 7154040

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0680/2018/GW
Date : 12-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

YOUR INSURED VEH NO : SKQ3666P

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Ally

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Quah Tuang Kit@Lee Tuang Kit
Address : Blk 234 Hougang Avenue 1
#04-262
Singapore 530234
Telephone : HP +65-90628793
Type of Claim : Own damage claims
Policy No. : DMPCSN1680851701
Vehicle No : **SKQ 3666 P**
Model Code : Audi A4 1.4 TFSI S Tronic
Model / Year : Dec-17
Engine No : CVN 049863
Chassis No : WAUZZZF4XJA041949
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Jun-18
Place of Accident : Upper Serangoon Viaduct Twds City

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 3666 P.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer rhs front and rear door's multi-lock system and power window devices.	S/N \$ 560.00 ✗	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment .	S/N \$ 1,400.00 ✓	
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
5	To remove and renew rhs rear 1/4 glass and rear windscreen.	S/N \$ 600.00 ✓	
SUB-TOTAL LABOUR CHARGES		: \$ 4,320.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 3666 P.

S/N	Nature of Jobs	Estimated Charges
6	To dismantle front bumper front, rhs front fender, rhs front and rear doors, rear bumper and rear lid. Cut out and weld rhs rear fender. Renew damaged panels. Reinstall all parts removed.	\$ 7,200.00 4500 ✓
7	To respray front bumper, rhs front fender, sill panel, door panel, door entranc, drain panel, roof channel, end panelling and rear bumper. To carry out joint sealer works and stone chip treatment. Rear Fenders ✓	\$ 7,300.00 3850 4100 ✓
8	To renew rhs front fender and rear rims with tyres. Carry out wheel alignment.	S/N \$ 320.00 ✓
9	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>19,332.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3666 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>rehd</i>	\$ 1,849.00	✓ 1499.20
2	FRONT BUMPER FIXING PARTS <i>men</i>	\$ 245.00	x
3	FRONT BUMPER SECURING STRIP <i>2 men</i>	2 \$ 60.00	✓
4	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	x
5	FRONT BUMPER GUDIE SECTION-RH	\$ 32.00	x
6	FRONT FENDER-RH <i>Defud</i>	\$ 665.00	✓ 537.00
7	FENDER ATTACHEMENT PARTS <i>Not New</i>	\$ 45.00	?X
8	FRONT FENDER CLOSING ELEMENT-RH <i>men</i>	\$ 44.00	x
9	FRONT FENDER BRACKET-RH <i>men</i>	\$ 31.00	x
10	FRONT FENDER BRACKET DEFORMATION-RH <i>men</i>	\$ 43.00	✓ 34.16
11	FRONT FENDER BRACE-RH <i>men</i>	\$ 103.00	✓ 82.40
12	FRONT FENDER LEDGE COVER-RH <i>men</i>	\$ 20.00	✓ 15.36
13	FRONT FENDER COVER-RH <i>men</i>	\$ 27.00	✓ 21.04
14	FRONT WHEEL HOUSING LINER-RH <i>men</i>	\$ 209.00	x
15	WHEEL HOSUING LINER ATTACHMENT PARTS <i>men</i>	\$ 78.00	x
16	FRONT SPEEL SPOILER -RH <i>men</i>	\$ 63.00	x
17	FRONT STONE CHIP GUARD-RH <i>men</i>	\$ 44.00	✓ 34.56
18	FRONT DOOR-RH <i>men</i>	\$ 1,860.00	x
19	FRONT OUTER DOOR SEAL-RH <i>men</i>	\$ 176.00	x
20	BONDING AGENT	\$ 43.00	x
SUB- TOTAL SPARE PARTS		\$ 5,710.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3666 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CLEANING SOLUTION	\$	64.00 ✓
22	DOOR ATTACHMENT PARTS <i>2 New</i>	\$	462.00 ✓
23	FRONT DOOR CATCH-RH	\$	92.00 ✗
24	FRONT EXTERIOR MIRROR-RH <i>new</i>	\$	790.00 ✗
25	FRONT MIRROR CAP-RH <i>ct</i>	\$	217.00 ✓ 173.60
26	TURN SIGNAL INDICATOR-RH <i>new</i>	\$	93.00 ✗
27	FRONT MIRROR GLASS-RH <i>new</i>	\$	1,506.00 ✗
28	REAR DOOR-RH <i>Repis</i>	\$	1,928.00 ✗
29	REAR OUTER DOOR SEAL-RH <i>2</i>	\$	176.00 ✗
30	BONDING AGENT	\$	43.00 ✗
31	CLEANING SOLUTION	\$	64.00 ✓
32	DOOR ATTACHMENT PARTS <i>new</i>	\$	488.00 ✗
33	REAR DOOR CATCH-RH	\$	105.00 ✗
34	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$	33.00 ✗
35	REAR SECTIONAL PARTS <i>Disturbed</i>	\$	2,347.00 ✓ 1877.60
36	REAR BUMPER UPPER GUIDE-RH <i>2 new</i>	\$	38.00 ✓
37	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	38.00 ✓
38	SIDE WINDOW-RH <i>new</i>	\$	541.00 ? 457.40 ✓
39	REAR WINDOW <i>new</i>	\$	1,014.00 ? 811.20 ✓
40	PRIMER <i>new</i>	2 \$	37.00 ✓ 29.12
SUB-TOTAL SPARE PARTS		\$	10,076.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3666 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	REAR GUIDE SECTION-RH <i>new</i>	\$ 38.00	+
42	REAR BUMPER COVER <i>del</i>	\$ 1,907.00	✓ 1525.60
43	REAR BUMPER FIXING PARTS <i>new</i>	\$ 63.00	✓
44	ALUMINIUM RIM <i>cut</i>	2 \$ 1,290.00	✓ 1032
45	RUBBER VALVE <i>new</i>	2 \$ 6.00	✓
46	PIRELLI P7 TYRES X 2 <i>new</i>	S/N TBC	7.5
47	1/4 GLASS SEALANT <i>2</i>	S/N \$ 100.00	✓
48	REAR WINDSCREEN SEALANT <i>2</i>	S/N \$ 200.00	✓
49	ACYLIC SEALER <i>2</i>	S/N \$ 180.00	✓
50	CAVITY WAX <i>new</i>	S/N \$ 140.00	✓
51	STONE CHIP GUARD	S/N \$ 180.00	✓
52	METAL FILLER POWDER	S/N \$ 280.00	✓
53	SUNDRIES <i>new</i>	\$ 500.00	? 111.28 ✓
TOTAL SPARE PARTS		\$ 20,670.00	
TOTAL LABOUR CHARGES		\$ 19,332.00	
GRAND TOTAL		\$ 40,002.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 14/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 16 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0680/2018/GW
Date : 12-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

YOUR INSURED VEH NO : SKQ3666P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

16 days exclude 3 Sundays - ok

jb 13 Aug 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Quah Tuang Kit@Lee Tuang Kit
Address : Blk 234 Hougang Avenue 1
#04-262
Singapore 530234
Telephone : HP +65-90628793
Type of Claim : Own damage claims
Policy No. : DMPCSN1680851701
Vehicle No : **SKQ 3666 P**
Model Code : Audi A4 1.4 TFSI S Tronic
Model / Year : Dec-17
Engine No : CVN 049863
Chassis No : WAUZZZF4XJA041949
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Jun-18
Place of Accident : Upper Serangoon Viaduct Twds City

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 3666 P.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To remove and transfer rhs front and rear door's multi-lock system and power window devices.	S/N \$	560.00	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment .	S/N \$	1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	\$ 1,400.00
5	To remove and renew rhs rear 1/4 glass and rear windscreen.	S/N \$	600.00	\$ 600.00
SUB-TOTAL LABOUR CHARGES		:	\$ 4,320.00	\$ 3,760.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 3666 P.

S/N	Nature of Jobs	Estimated Charges
	<i>c/f</i>	
6	To dismantle front bumper front, rhs front fender, rhs front and rear doors, rear bumper and rear lid. Cut out and weld rhs rear fender. Renew damaged panels. Reinstall all parts removed.	\$ 7,200.00
7	To respray front bumper, rhs front fender, sill panel, door panel, door entranc, drain panel, roof channel, end panelling and rear bumper. To carry out joint sealer works and stone chip treatment.	\$ 7,300.00
8	To renew rhs front fender and rear rims with tyres. Carry out wheel alignment.	S/N \$ 320.00
9	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: \$ 19,332.00

*Surveyor's
Recommendation*

\$ 3,760.00

\$ 4,500.00

\$ 4,400.00

\$ 320.00

\$ 192.00

\$ 13,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3666 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 60.00	
4	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	
5	FRONT BUMPER GUDIE SECTION-RH	\$ 32.00	
6	FRONT FENDER-RH	\$ 665.00	\$ 532.00
7	FENDER ATTACHEMENT PARTS	\$ 45.00	
8	FRONT FENDER CLOSING ELEMENT-RH	\$ 44.00	
9	FRONT FENDER BRACKET-RH	\$ 31.00	
10	FRONT FENDER BRACKET DEFORMATION-RH	\$ 43.00	\$ 34.16
11	FRONT FENDER BRACE-RH	\$ 103.00	\$ 82.40
12	FRONT FENDER LEDGE COVER-RH	\$ 20.00	\$ 15.36
13	FRONT FENDER COVER-RH	\$ 27.00	\$ 21.04
14	FRONT WHEEL HOUSING LINER-RH	\$ 209.00	
15	WHEEL HOSUING LINER ATTACHMENT PARTS	\$ 78.00	
16	FRONT SPEEL SPOILER -RH	\$ 63.00	
17	FRONT STONE CHIP GUARD-RH	\$ 44.00	\$ 34.56
18	FRONT DOOR-RH	\$ 1,860.00	
19	FRONT OUTER DOOR SEAL-RH	\$ 176.00	
20	BONDING AGENT	\$ 43.00	
SUB- TOTAL SPARE PARTS		\$ 5,710.00	\$ 2,198.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3666 P.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		c/f	\$	2,198.72
21	CLEANING SOLUTION	\$	64.00	
22	DOOR ATTACHMENT PARTS	\$	462.00	
23	FRONT DOOR CATCH-RH	\$	92.00	
24	FRONT EXTERIOR MIRROR-RH	\$	790.00	
25	FRONT MIRROR CAP[-RH	\$	217.00	\$ 173.60
26	TURN SIGNAL INDICATOR-RH	\$	93.00	
27	FRONT MIRROR GLASS-RH	\$	1,506.00	
28	REAR DOOR-RH	\$	1,928.00	
29	REAR OUTER DOOR SEAL-RH	\$	176.00	
30	BONDING AGENT	\$	43.00	
31	CLEANING SOLUTION	\$	64.00	
32	DOOR ATTACHMENT PARTS	\$	488.00	
33	REAR DOOR CATCH-RH	\$	105.00	
34	DATA PLATE FOR TYRE PRESSURE	\$	33.00	
35	REAR SECTIONAL PARTS	\$	2,347.00	\$ 1,877.60
36	REAR BUMPER UPPER GUIDE-RH	\$	38.00	
37	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	38.00	
38	SIDE WINDOW-RH	\$	541.00	\$ 432.40
39	REAR WINDOW	\$	1,014.00	\$ 811.20
40	PRIMER	2 \$	37.00	\$ 29.12
SUB-TOTAL SPARE PARTS		:	\$ 10,076.00	\$ 5,522.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 3666 P.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	5,522.64
41	REAR GUIDE SECTION-RH	\$	38.00	
42	REAR BUMPER COVER	\$	1,907.00	\$ 1,525.60
43	REAR BUMPER FIXING PARTS	\$	63.00	
44	ALUMINIUM RIM	2 \$	1,290.00	\$ 1,032.00
45	RUBBER VALVE	2 \$	6.00	
46	PIRELLI P7 TYRES X 2	S/N	TBC	
47	1/4 GLASS SEALANT	S/N \$	100.00	\$ 100.00
48	REAR WINDSCREEN SEALANT	S/N \$	200.00	\$ 200.00
49	ACYLIC SEALER	S/N \$	180.00	\$ 180.00
50	CAVITY WAX	S/N \$	140.00	\$ 140.00
51	STONE CHIP GUARD	S/N \$	180.00	\$ 180.00
52	METAL FILLER POWDER	S/N \$	280.00	\$ 280.00
54	SUNDRIES	\$	500.00	\$ 111.28
	TOTAL SPARE PARTS	:	\$ 20,670.00	\$ 9,271.52
	TOTAL LABOUR CHARGES	:	\$ 19,332.00	\$ 13,172.00
	GRAND TOTAL	:	\$ 40,002.00	\$ 22,443.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKQ 3666 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0680/2018/MAS

22 Sept 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKQ 3666 P, Audi A4 Sedan 1.4 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no **SKQ 3666 P**, claimant,
Mr. Quah Tuang Kit, please find the related document per attached.

1. A copy of the Original invoice no. 85012952 – S\$23,372.57
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the
payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at
6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKQ 3666 P



Premium Automobiles Pte Ltd

Audi Centre Singapore
201 Alexandra Road
Singapore 159938
Main Telephone 8336 2223
Main Telefax 8471 3233

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

UBi Service Centre
35 Ubi Road 1
Singapore 408723
Telephone 8388 2223
Telefax 8475 1023

Customer Service
Service Appointment
Hour Breakdown Service
Email customer.care@premiumauto.com.sg
6386 2223
9628 1233

Page 1 15:35

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012952 Date : 18/09/2016 Order : SK03666P Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SK03666P (V 35361) Regn Date: 11/12/2017 Mileage: 10110 WIP No.: 13377
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUJZZF4XJA041949 Engine: CVN 049863 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	N: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	N: TO REMOVE AND REINSTALL FRONT HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	N: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	N: TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG	1400.00	1.00	1,400.00
S	BODYWORK	N: TO REMOVE AND RENEW RHS REAR 1/4 GLASS AND REAR WINDSCREEN	600.00	1.00	600.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone 6388 2223
Main Telefax 6471 3733
Page 2 15:35

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone 6388 2223
Telefax 6475 1023

UBi Service Centre
55 Ubi Road 1
Singapore 408822
Telephone 6388 1333
Telefax 6388 1333

Customer Service
Service Appointment 6366 2323
Hour Breakdown Service 6828 1233
Email customer.care@premiumauto.com.sg

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012952 Date : 18/09/2018 Order : SK03666P Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SK03666P (V 35361) Regn Date: 11/12/2017 Mileage: 10110 WTP No.: 13377
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XJA041949 Engine: CVN 049063 Dept: U
USB No.:
You have been assisted by :- UB-Jlaxee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT AND REAR DOORS, REAR BUMPER AND REAR LTD. CUT OUT AND WELD RHS REAR FENDER, RENEW DAMAGED PANELS, REINSTALL ALL PARTS REMOVED	4500.00	1.00	4,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS MIRROR COVER, RHS REAR FENDER, SILL PANEL, END PANNELLING, REAR BUMPER, RHS FRONT AND REAR DOORS. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	4400.00	1.00	4,400.00
S	BODYWORK	M: TO RENEW RHS FRONT FENDER AND REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	320.00	1.00	320.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO SUPPLY 1/4 GLASS SEALANT, REAR WINDSCREEN	1000.00	1.00	1,000.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6836 2223
Main Telefax: 6471 5733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6888 2223
Telefax: 6475 1025

Ubi Service Centre
55 Ubi Road 1
Singapore 408979
Telephone: 6388 1231

Customer Service
Service Appointment: 6886 2223
24-hour Breakdown Service: 9628 1231
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 15:35

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85812952 Date : 18/09/2018 Order : SKQ3666P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKQ3666P (V 35361) Regn Date: 11/12/2017 Mileage: 10110 WIP No.: 13377

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XJA041949 Engine: CVN 049863 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
		SEALANT, ACRYLIC SEALER, CAVITY WAX, STONE CHIP GUARD AND METAL FILLER POWDER				
X	ABW0601025EF	RIM 16" CX1	Less 020%	2.00	645.00	1,032.00
X	ABW5809838	SUBPART	Less 020%	1.00	2347.00	1,877.60
X	ABW5845298D NVB	SIDE WINDOW	Less 020%	1.00	548.50	432.40
X	ABW0821106A	FENDER	Less 020%	1.00	565.00	532.00
X	ABW5845501B NVB	REAR WINDOW	Less 020%	1.00	1014.00	811.20
X	ABW0807065C GRU	COVER	Less 020%	1.00	1849.00	1,479.20
X	ABW5807067A GRU	COVER	Less 020%	1.00	1907.00	1,525.60
X	ABW0821136C	SUPPORT	Less 020%	1.00	103.00	82.40
X	ABW0823746	COVER	Less 020%	1.00	19.20	15.36
X	ABW0821470	BRACKET	Less 020%	1.00	42.70	34.16
X	ABW0809906	INSERT	Less 020%	1.00	77.50	62.00
X	ABK9085673C	SPEED NUT	Less 020%	2.00	1.10	1.76
X	ABW0820582C	COVER	Less 020%	1.00	26.30	21.04
X	ABW0853824A 989	STONEGUARD	Less 020%	1.00	43.20	34.56
X	ABW0857528 GRU	CAP	Less 020%	1.00	217.00	173.60
X	ABW5807454	GUIDE	Less 020%	1.00	38.00	30.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2222
Main Telefax: 6471 3733
Page 4 15:35

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2222
Telefax: 6475 1025

Ubi Service Centre
55 Ubi Road 1
Singapore 408622
Telephone: 6386 2222
Telefax: 6475 1025

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2222
6626 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012952 Date : 18/09/2018 Order : SKQ3666P Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKQ3666P (V 35361) Regn Date: 11/12/2017 Mileage: 10110 WIP No.: 13377
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XJA041949 Engine: CVN 049863 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	AD 00920002	PRIMER (DG)	2.00	18.20	29.12
X	AN 91233601	NUT	4.00	1.00	3.20
X	AN 0161857	POP-RIVET	6.00	2.90	13.92

Parts	8,191.52	Sub-Total	21,843.52
Labour	0.00	7% GST	1,529.05
Sublet	14,252.00	Grand Total	23,372.57
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKQ3666P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0680/2018/TF
10 July 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI S tronic
Vehicle Chassis No. : WAUZZZF4XJA041949
Vehicle Regn No. : **SKQ 3666 P**
Vehicle Mileage : 10102KM
Vehicle Owner : Mr. Quah Tuang Kit
Certificate No : 1700087591
Policy Excess : \$642.00 (Inclusive GST)
Accident Date : 11 June 2018
Place : Upper Serangoon Viaduct Towards City
Repair Cost : \$ 23,372.57
WIP No. : 13377
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 10/7/18

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **S0197402E**

Name **TIANG LENG ING**

Birth Date **05 May 1950**
 Issue Date **23 May 2003**

000564016H



REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S0197402E**

Name **TIANG LENG ING**

程蓮英

Race **CHINESE**
 Date of Birth **05-05-1950** Sex **F**
 Country of Birth **SINGAPORE**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE **22 Jul 1977**

NP 428A

Licence No: **S0197402E**



1701056

NPIC No: **S0197402E**

Street Group **B+** Date of issue **19-02-1994**

APT BLK 234 HOUGANG AVENUE 1 #04-262
SINGAPORE 530234

NRIC No: **S0197402E** Date: **23/12/2012** No: **7154040**






CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : QUAH TUANG KIT @ LEE TUANG KIT
Period of Insurance : 11 Dec 2017 To 10 Dec 2018
Engine No. : CVN049863
Chassis No. : WAUZZZF4XJA041949

Vehicle No. : SKQ3666P
Policy No. : 1700087591
Endorsement No. :
Issued Date : 21 Dec 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

QUAH TUANG KIT @ LEE TUANG KIT - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 35 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 8338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0504125256

PREMIUM LEASING -LSYA

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. P. Loh

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Bartley Loh

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jun 2018 Edit Reg		14 Jun 2018 00:00 Edit Adj Rpt	S\$22,443.52 Edit Estimates	S\$22,443.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	QUAH TUANG KIT @ LEE TUANG KIT, ID: S0164076C, Tel: +6590628793								
Vehicle Reg. No.:	SKQ3666P	Date of Loss:	11/06/2018 12:00 - :59 [6 Months From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2463747590SG	Policy/Cover Note No.:	1700087591 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/06/2018]								
Driver/Custodian:	TIANG LENG ING (68)								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- AIG_SG_EXPRESS (11/09/2018): Alert - Adj Mandate Approved (S\$22443.52) - SKQ3666P - Claim Handler: Tr, Tinesh - AIG_SG_EXPRESS (19/06/2018): Alert - Adj Mandate Approved (S\$22251.00) - SKQ3666P - Claim Handler: Tr, Tinesh - AIG_SG (18/06/2018): SKQ3666P / OD / 11/06/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ3666P (2463747590SG)
OD

Jun 11 2018 12:00PM
[QUAH TUANG KIT @ LEE TUANG KIT]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☐	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	18/06/18 14:35	Adjuster Immediate Advice														Load HTM				
2	17/08/18 16:56	Adjuster Immediate Advice														Load HTM				
Photos/Images															3 per page		☐	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	18/06/18 14:12	General View														Load JPG	☒			
2	18/06/18 14:12	Chassis Number														Load JPG	☒			
3	18/06/18 14:12	General View														Load JPG	☒			
4	18/06/18 14:12	General View														Load JPG	☒			
5	18/06/18 14:12	General View														Load JPG	☒			
6	18/06/18 14:12	General View														Load JPG	☒			
7	18/06/18 14:12	General View														Load JPG	☒			
8	18/06/18 14:12	General View														Load JPG	☒			
9	18/06/18 14:12	General View														Load JPG	☒			
10	18/06/18 14:12	General View														Load JPG	☒			
11	18/06/18 14:12	General View														Load JPG	☒			
12	18/06/18 14:12	General View														Load JPG	☒			
13	18/06/18 14:12	General View														Load JPG	☒			
14	18/06/18 14:12	General View														Load JPG	☒			
15	18/06/18 14:12	General View														Load JPG	☒			
16	18/06/18 14:12	General View														Load JPG	☒			
17	18/06/18 14:12	General View														Load JPG	☒			
18	18/06/18 14:12	General View														Load JPG	☒			
19	18/06/18 14:12	General View														Load JPG	☒			
20	18/06/18 14:12	General View														Load JPG	☒			
21	18/06/18 14:12	General View														Load JPG	☒			
22	18/06/18 14:12	General View														Load JPG	☒			
23	18/06/18 14:12	General View														Load JPG	☒			
24	18/06/18 14:12	General View														Load JPG	☒			
25	18/06/18 14:12	General View														Load JPG	☒			
26	18/06/18 14:12	General View														Load JPG	☒			
27	18/06/18 14:12	General View														Load JPG	☒			
28	18/06/18 14:12	General View														Load JPG	☒			
29	18/06/18 14:12	General View														Load JPG	☒			
30	18/06/18 14:12	General View														Load JPG	☒			
31	18/06/18 14:12	General View														Load JPG	☒			
32	18/06/18 14:12	General View														Load JPG	☒			
33	18/06/18 14:12	General View														Load JPG	☒			
34	18/06/18 14:12	General View														Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	18/06/18 14:12	General View	 Load JPG	☒
36	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
37	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
38	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
39	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
40	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
41	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
42	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
43	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
44	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
45	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
46	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
47	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
48	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
49	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
50	17/08/18 15:52	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/18 14:12	Singapore Accident Statement	 Load PDF	
2	18/06/18 14:12	Certificate of Insurance	 Load PDF	
3	18/06/18 14:12	Driver's Driving License	 Load PDF	
4	18/06/18 14:12	ESTIMATE	 Load PDF	
5	17/08/18 16:51	REVISED ESTIMATE	 Load PDF	
6	28/09/18 11:56	Workshop Incoice	 Load PDF	
7	28/09/18 11:56	Discharge Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18010899/AQBE2

Date: 28/09/2018

REFERENCE

Insured/Claimant: QUAH TUANG KIT @ LEE TUANG KIT

Policy No: 1700087591

Date of Loss: 11/06/2018

Nature of Claim: OD

Claim No: 2463747590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ3666P

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN049863

Reg. Date: 11/12/2017 (Man. Year: 2017)

Chassis No: WAUZZZF4XJA041949

Colour: Black

Odometer: 10101 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$145,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,670.00	9,271.52	11,398.48	55.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,332.00	13,172.00	6,160.00	31.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,002.00	22,443.52	17,558.48	43.89
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	39,402.00	21,843.52	17,558.48	44.56
+ GST 7.00/7.00% (S\$)	2,758.14	1,529.05	1,229.09	44.56
Nett Amount (S\$)	42,160.14	23,372.57	18,787.57	44.56

INSPECTION

Date of Assignment: 14/06/2018

Date Inspected: 14/06/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 16.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	60.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	73.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	32.00 FS	*- FS
6	1		*FRONT FENDER-RH	Dented	665.00 FS	*532.00 FS
7	1		*FENDER ATTACHMENT PARTS	Not Necessary	45.00 FS	*- FS
8	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	44.00 FS	*- FS
9	1		*FRONT FENDER BRACKET-RH	Not Necessary	31.00 FS	*- FS
10	1		*FRONT FENDER BRACKET DEFORMATION-RH	Necessary	43.00 FS	*34.16 FS
11	1		*FRONT FENDER BRACE-RH	Bent	103.00 FS	*82.40 FS
12	1		*FRONT FENDER LEDGE COVER-RH	Necessary	20.00 FS	*15.36 FS
13	1		*FRONT FENDER COVER-RH	Necessary	27.00 FS	*21.04 FS
14	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	209.00 FS	*- FS
15	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
16	1		*FRONT SPOILER SPOILER-RH	Not Necessary	63.00 FS	*- FS
17	1		*FRONT STONE CHIP GUARD-RH	Necessary	44.00 FS	*34.56 FS
18	1		*FRONT DOOR-RH	Repair	1,860.00 FS	*- FS
19	1		*FRONT DOOR OUTER SEAL-RH	Not Necessary	176.00 FS	*- FS
20	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
21	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
22	1		*DOOR ATTACHMENT PARTS	Not Necessary	462.00 FS	*- FS
23	1		*FRONT DOOR CATCH-RH	Not Necessary	92.00 FS	*- FS
24	1		*FRONT EXTERIOR MIRROR-RH	Not Necessary	790.00 FS	*- FS
25	1		*FRONT MIRROR CAP-RH	Cut	217.00 FS	*173.60 FS
26	1		*TURN SIGNAL INDICATOR-RH	Not Necessary	93.00 FS	*- FS
27	1		*REAR DOOR-RH	Repair	1,928.00 FS	*- FS
28	1		*FRONT MIRROR GLASS-RH	Not Necessary	1,506.00 FS	*- FS
29	1		*REAR OUTER DOOR SEAL-RH	Not Necessary	176.00 FS	*- FS
30	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
31	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
32	1		*DOOR ATTACHMENT PARTS	Not Necessary	488.00 FS	*- FS
33	1		*REAR DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
34	1		*DATA PLATE FOR TYRE PRESSURE	Not Necessary	33.00 FS	*- FS
35	1		*REAR SECTIONAL PARTS	Distorted	2,347.00 FS	*1,877.60 FS
36	1		*REAR BUMPER UPPER GUIDE-RH	Not Necessary	38.00 FS	*- FS
37	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	38.00 FS	*- FS
38	1		*SIDE WINDOW-RH	Necessary	541.00 FS	*432.40 FS
39	1		*REAR WINDOW	Necessary	1,014.00 FS	*811.20 FS
40	2		*PRIMER	Necessary	37.00 FS	*29.12 FS
41	1		*REAR GUIDE SECTION-RH	Not Necessary	38.00 FS	*- FS
42	1		*REAR BUMPER COVER	Deformed	1,907.00 FS	*1,525.60 FS
43	1		*REAR BUMPER FIXING PARTS	Not Necessary	63.00 FS	*- FS
44	2		*ALUMINIUM RIM	Cut	1,290.00 FS	*1,032.00 FS
45	2		*RUBBER VALVE	Not Necessary	6.00 FS	*- FS
46	1		*PIRELLI P7 TYRES X2 (NPA)	Not Necessary	0.00 FS	*- FS
47	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
48	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
49	1		*ACYLIC SEALER	Necessary	180.00 FS	*180.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
51	1		*STONE CHIP GUARD	Necessary	180.00 FS	*180.00 FS
52	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
53	1		*SUNDRIES	Necessary	500.00 FS	*111.28 FS
				Total Parts (S\$)	20,670.00	9,271.52

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	-
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS,SEAT BELTS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
5	TO REMOVE AND RENEW RHS REAR 1/4 GLASS AND REAR WINDSCREEN	New	600.00	600.00
6	TO DISMANTLE FRONT BUMPER FRONT,RHS FRONT FENDER,RHS FRONT AND REAR DOORS,REAR BUMPER AND REAR LID.CUT OUT AND WELD RHS REAR FENDER.RENEW DAMAGED PANELS.REINSTALL ALL PARTS REMOVED	New	7,200.00	4,500.00
7	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,SILL PANEL,DOOR PANEL,DOOR ENTRANC,DRAIN PANEL,ROOF CHANNEL,END PANELLING AND REAR BUMPER.TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	7,300.00	4,400.00
8	TO RENEW RHS FRONT FENDER AND REAR RIMS WITH TYRES.CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			19,332.00	13,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >