

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 驗燭

SUPPLEMENTARY

Date : 05/07/2018
TP Vehicle No. : SH-6200-H
To : FIRST CAPITAL INSURANCE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : KOO BEE YONG (XU MEIRONG)
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5090561340-01
Vehicle No. : SKS-9761-Y
Make & Model : KIA FORTE K3 1.6A

Accident Date: 18/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	REAR BUMPER REINFORCEMENT <i>ADD</i>	<i>one</i> \$450.80	<i>389-30</i>
	Sub Total	\$450.80	
	Discount 10% on Parts	(\$45.08)	
		\$405.72	
	Sub Total	\$405.72	
	GST 7%	\$28.40	
	Total	\$434.12	