

(06/11/13) well
ASS. REC. BY: Marius

REF:

50/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 726321P

at Workshop m/s H.

of _____

Insured: SKW 522/4

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 19k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5 days

Res: Yes or No

Lum Sum: 20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 726321P

Yr Regn: 7 06

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Dyna

c.c. 2986

Colour: silver

A/C: Insured / Std / NI / NA

Sp. Reading: 281162

Ti/Radio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: JTFUF344503012071

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 185-R14

R: 155-R12 Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKO or

Front

Rear

R/Bal: 5 mm

R/Bal: 5/5 mm

L/Bal: 5 mm

L/Bal: 5/5 mm

D.O.A: 15/6/18

D.O.A: 18/6/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

June 6/18 4A13699 3yrs 1ml.

26/6/18 2/5 \$5000 cashed with other.

CR60: 45,893.30 (54%)

NU: \$19,000.00 (Cent)

LTA: \$13,699.00 (Cent)

NETT: \$5,801.00 (Cent)

Date/Time, File Pass to:

☐ : Prel. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to:

2) _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS: \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

(08/11/13) wef

ASS. REC. BY: MD/CLJ

REF:

50/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 926321Pat Workshop m/s H.of SKW522/4

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 19k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

17/7/2021

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 926321P Yr Regn: 7 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)Make: Toyota Dyna C.C. 2986Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 281162 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFUF344503012071

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185-R14R: 155-R12 Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5/5 mmL/Bal. 5 mm L/Bal. 5/5 mmD.O.A. 15/6/18 D.O.I. 18/6/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have GIA 4A13699 3yrs 1ml.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ118010963/Uhb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 18-06-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 5221U	Veh. Inspected	GZ 6321P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/06/2018	Inspection Date	18/06/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQI18010963/Uhb3

Date: 03.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GZ 6321P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.06.2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	10,893.30
Revised Estimate Amount	: S\$	6,282.55
"Check" Items Amount	: S\$	-
Market Value	: S\$	19,000.00
LTA Reimbursement Value	: S\$	13,699.00
Nett Value	: S\$	5,301.00

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHICLE NO: GZ 6321P

QTY	PARTICULAR	AMOUNT
1 PCS	TAILLAMP <i>1/3</i>	<i>320</i> \$282.10 ✓
1 PCS	TAILLAMP BRACKET O/S	<i>sent</i> \$185.90 ✓
1 PCS	REAR EXHAUST PIPE	<i>1</i> \$645.20 X
1PCS	REAR EXHAUST PIPE MOUNTING	<i>11</i> \$66.50 X
1 PCS	REAR LICENCE PLATE BRACKET	<i>sent</i> \$188.20 ✓
1PCS	REAR SPARE TYRE BRACKET & CHAIN	<i>sent</i> \$395.40 ✓
		\$1,763.30
		<i>1051.6</i>
		<i>788.70</i>
	S.NETT	
1 PCS	REAR CARGO BOX BACK DOOR O/S	<i>sent/cn</i> \$2,000.00 <i>1200</i>
1 PCS	REAR CARGO BOX BACK DOOR LOCK O/S	<i>1</i> \$600.00 X
1 PCS	REAR CARGO BOX REAR PILLAR O/S	<i>o/cn</i> \$1,200.00 <i>1000</i>
1 PCS	REAR CARGO BOX LOWER MEMBER	<i>sent/ds</i> \$1,020.00 <i>800</i>
1 PCS	REAR CARGO BOX LOWER O/S RAILING	<i>sent/ds</i> \$1,080.00 <i>1000</i>
1 PCS	REAR CARGO BOX INNER WOODEN	<i>11</i> \$800.00 X
1 PCS	REAR LICENCE PLATE	<i>sent</i> \$20.00 <i>14</i>
1 PCS	REAR 'DYNAL' STICKER	<i>NN</i> \$20.00 X
1 SET	REAR REVERSE SENSOR	<i>NT</i> \$300.00 X

LABOUR CHARGES:

TO CHECK WIRING	\$50.00 <i>20</i>
TO SPRAY RUST PROOFING	\$80.00 <i>50</i>
TO DISMENTLE & <i>REPLACING</i> REAR EXHAUST	\$80.00 <i>60</i>
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,000.00 <i>800</i>
TO PUTTY & SPRAY PAINTING	\$880.00 <i>550</i>
	\$10,893.30

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6212

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	4747H

Vehicle Details

Vehicle No.:	GZ6321P
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	5L5656657
Chassis No.:	JTFUF34Y503012071
Maximum Power Output:	-
Open Market Value:	\$23,681.00
Original Registration Date:	18 Jul 2006
First Registration Date:	18 Jul 2006
Transfer Count:	2
Actual ARF Paid:	\$1,185.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,247.00
COE Rebate Amount:	\$13,699.00
Total Rebate Amount:	\$13,699.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

Transfer of ownership or de-registration is not allowed for this vehicle.

The information contained herein is correct as at 18 Jun 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

Click here to start the hunt!

Toyota Dyna

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Bee Huat Credit > Toyota Dyna 150 (COE till 03/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

CL LEASING

YOUR FUTURE CAR OF CHOICE

6768 7117 8720 5000 8720 8000

Toyota Dyna 150 (COE till 03/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$20,000

Depreciation

\$7,360 /yr

Reg Date

07-Mar-2006

(2yrs 8mths 16days COE left)

Lifespan

06-Mar-2026

Manufactured

2006

Mileage

-

Transmission

Manual

Engine Cap

2,986 cc

Curb Weight

1,720 kg

Fuel type

Diesel

Features

-

Accessories

Factory Fitted Accessories.

Description

Eligible For ETS, Good Condition, High Trade In And Loan Available.

COE

\$22,724

OMV

\$23,681

ARF

\$1,185

Dereg Value

\$12,352 as of today (change)

No. of Owners

3

Type of Veh

Truck

Category

COE Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 15-Jun-2018 | Last Updated on: 15-Jun-2018

Tags: Toyota Dyna, 2006 Toyota Dyna, Toyota, Dyna, Used Toyota

Upfront Payment

Transfer Fee

\$25

Down Payment

\$2,000 (change)

Maximum 90% Loan

1st Instalment

\$630

Total Upfront Payment

\$2,655 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

Items for Toyota Dyna

View All

Seller Information

Company

Bee Huat Credit

• dealer's pricelist

• 23 vehs sold | 13 vehs available

Address

343 Jurong East Street 31 #01-61

Search cars nearby this location

Office No

65666885

Contact Person(s)

Peh

97266885

Guan Huat

96200068

Chin

93851234

Useful Services

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation

http://www.sgcarmart.com/used_cars/info.php?ID=741542&DL=2494

18-Jun-18

Shu Pei (LKKAUTO)

From: Francis Ng <francis.ng@eqinsurance.com.sg>
Sent: Wednesday, 20 June 2018 9:36 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SKW5221U (OI : EQI - TBA) AND GZ6321P (TP : LKK REF - CC6/EQI18010963/Uhb3) on 15.06.2018
Attachments: EQIC-MAR500002438-SKW5221U-GIA.PDF

Dear Shu Pei,

Our insured's report is attached.

Regards,
Francis Ng
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, June 19, 2018 5:59 PM
To: Francis Ng <francis.ng@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: Direct Settlement - Accident Involving SKW5221U (OI : EQI - TBA) AND GZ6321P (TP : LKK REF - CC6/EQI18010963/Uhb3) on 15.06.2018

WITHOUT PREJUDICE

Dear Francis,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle GZ 6321P at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vic (LKKAUTO)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Thursday, 22 November, 2018 5:46 PM
To: Vic (LKKAUTO)
Cc: Admin A; 'Nancy Lam'
Subject: RE: YOUR REF: GZ6321P MY REF: GZ6321P DOA:15/06/2018. LKK REF CC6/EQI18010963/Uhb3

Without Prejudice

Dear Vic,

We are pleased to accept your offer of global sum of \$5,900.00 all in (Property Only).

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Thursday, November 22, 2018 5:40 PM
To: jason@fastechauto.com.sg
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Nancy Lam <nancy.lam@fastechauto.com.sg>
Subject: RE: YOUR REF: GZ6321P MY REF: GZ6321P DOA:15/06/2018. LKK REF CC6/EQI18010963/Uhb3

WITHOUT PREJUDICE

Dear Jason,

We refer to the subject matter and we confirmed in receipt of your LOD.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal's mandate and we offer to settle your client's claim on a global sum of \$5,900.00 (all in).

Please confirm acceptance. Please note that no DV is required.

The above amount is to be made payable to **FASTECH AUTO PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Jason Fastech Auto [<mailto:jason@fastechauto.com.sg>]

Sent: Thursday, 22 November, 2018 5:22 PM

To: Vic (LKKAuto)

Subject: YOUR REF: GZ6321P MY REF: GZ6321P DOA:15/06/2018.

Without Prejudice

Dear Vic,

Please refer to our LOD dated 26/06/2018.

We await your offer.

Thank you.

Best Regards

Jason Tang

Fastech Auto Pte Ltd

1 Kaki Bukit Ave 6

#01-46/48/50 AutoBay

Singapore 417883

Tel: 67465405

Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date : 26.06.2018

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : GZ 6321P / SKW 5221U ON 15.06.2018

We are the authorized repair workshop for the owner of motor vehicle no: **GZ 6321P**, which was involved in the captioned accident with your insured vehicle no: **SKW 5221U**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	5,350.00
2) Loss of Use (5 days + 1 Sunday X S\$100)	\$	600.00
3) GIA Search Fee	\$	2.00
	\$	5,952.00

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|--------------------------|
| a) Final Repair Invoice | b) GIA Search Result |
| c) Letter of Authorisation, etc... | d) GIA Report |
| e) I/C & Driving Licence | f) Insurance Certificate |
| g) Vehicle Registration Log Card | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.
Yours faithfully,

Jason Tang (jason@fastechnauto.com.sg)
For Fastechn Auto Pte Ltd

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Friday, 3 August, 2018 11:14 AM
To: alstonng@live.com
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF : SKW 5221U_ACCIDENT INVOLVING SKW 5221U AND GZ 6321P ALONG CTE ANG MO KIO EXIT AVENUE 1 EXIT ON 15.06.2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 AUGUST 2018

ALSTON NG WEI JIE

Dear Sir/Madam,

OUR REF : CC6/EQI18010963/Uhb3

YOUR REF : SKW 5221U

ACCIDENT INVOLVING SKW 5221U AND GZ 6321P ALONG CTE ANG MO KIO EXIT AVENUE 1 EXIT ON 15.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ INSURANCE COMPANY LIMITED to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of GZ 6321P against your motor insurance policy.

Based on the accident report and pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

Please be informed that your No Claim Discount (NCD - if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at EQ's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without EQ's prior knowledge and consent.

This letter should **not** be regarded as a waiver by EQ of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), EQ shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us or email us at the below details.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

DATE : 16.06.2018

TO : EQ Insurance Company Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. GZ6321P / SKW 5221V

ALONG CTE > SLE Near Ang Mo Kio Ave 1 Exit

ON 15.06.2018

I/We, Kwang chun Pte Ltd

of (NRIC No./ROC No.) 201424747 H

of 21 Toh Guan Road East #01-03 Toh Guan Centre Singapore 608609

owner of vehicle no. GZ 6321 P in consideration of M/s FASTECH AUTO
PTE LTD repairing my/our vehicle GZ 6321 P at my/our instruction and hereby
authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever
amount settled/payable by the Insurance Company and/or third party or to commence legal
proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use,
etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and
all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost
which may arisen therewith.

Signature of Owner :



Name of Owner :

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Attn : Motor Claim Department

Tax Invoice : 20349

Date : 26.06.2018
Vehicle No : GZ 6321P
Make/Model : TOYOTA DYNA
Chassis/Eng# :
Accident Date : 15.06.2018
Claim No :
Reference : 0618 -20349
Policy No :

	Amount
To proceed on lump sum repair	S\$ 5000.00

E. & O. E.	Total : S\$	5000.00
	GST @ 7% : S\$	350.00
	Amount Due : S\$	5350.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-091812

Date of Request: 16/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 16/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SKW5221U
Accident Date 15/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKW5221U	EQ Insurance Company Ltd	31/10/2017-30/10/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-091812

Date of Request: 16/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 16/06/2018
Enquiry By: Tang Kok Wee, Allan
TP Vehicle No: SKW5221U
Accident Date: 15/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 12/12/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKW 5221U	(Insd Veh)	Your Ref. No. : DMPPHQ17-005279
	GZ 6321P	(TP Veh)	Our Ref. No. : CC6/EQI18010963/Uhb3q2
Date of Accident	15/6/2018		

Liability	100%	
Final Repair Cost	: \$ 5,350.00	
Loss of Use	: \$ 600.00	6 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	5,952.00	
Final Settlement Sum	: \$ 5,900.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	FASTECH AUTO PTE LTD	: \$ 5,900.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ118010963/Uhb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 12-12-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKW 5221U	Veh. Inspected	GZ 6321P
Policy No.	DMPPHQ17-005279	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JTFUF34Y503012071	Colour	SILVER
Odometer	281162	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14	YOKOHAMA	5 mm
L/H Front Tyre	185 R14	YOKOHAMA	5 mm
R/H Rear Tyre	155 R12 (D)	DUNLOP	5/5 mm
L/H Rear Tyre	155 R12 (D)	DUNLOP	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/06/2018	Inspection Date	18/06/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 6321P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILLAMP O/S	BROKEN	282.10	282.10
1	TAILLAMP BRACKET O/S	BENT	185.90	185.90
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	645.20	-
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	66.50	-
1	REAR LICENCE PLATE BRACKET	BENT	188.20	188.20
1	REAR SPARE TYRE BRACKET & CHAIN	TWISTED /JAMMED	395.40	395.40
	LESS 25% DISCOUNT		-	-262.90
			1,763.30	788.70
SPECIAL NETT ITEMS				
1	REAR CARGO BOX BACK DOOR O/S (SN)	BENT/ CRACKED	2,000.00	1,200.00
1	REAR CARGO BOX BACK DOOR LOCK O/S (SN)	TO REPAIR SEE LABOUR	600.00	-
1	REAR CARGO BOX REAR PILLAR O/S (SN)	DENTED / CRACKED	1,200.00	1,000.00
1	REAR CARGO BOX LOWER MEMBER (SN)	BENT / DISTORTED	1,020.00	800.00
1	REAR CARGO BOX LOWER O/S RAILING (SN)	BENT / DISTORTED	1,080.00	1,000.00
1	REAR CARGO BOX INNER WOODEN (SN)	NOT NECESSARY	800.00	-
1	REAR LICENCE PLATE (SN)	BENT	20.00	14.00
1	REAR 'DYNA' STICKER (SN)	NOT NECESSARY	20.00	-
1	SET REVERSE SENSOR (SN)	NOT FITTED	300.00	-
			7,040.00	4,014.00
LABOUR				
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING .		80.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST .		80.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE AND REAR CARGO BOX BACK DOOR LOCK O/S.		1,000.00	800.00
	TO PUTTY & SPRAY PAINTING.		880.00	550.00
			2,090.00	1,480.00

Report Ref No. CC6/EQ118010963/Uhb3q2



GRAND TOTAL		10,893.30	6,282.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CC6/EQ118010963/Uhb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.