

United SG Automobile Pte Ltd

"We are always in your journey"....

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

ESTIMATION QUOTE

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

ATTN: MOTOR CLAIMS DEPARTMENT

ACV 403127973

Veron.

VEHICLE NO : SFX8088Y

MAKE MODEL : TOYOTA CAMRY

REFERENCE : USG-201806-18

DOA : 6-Jun-18

CLAIM TYPE : TP CLAIM

PAGE 1 OF 1

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER <i>tom</i>	1	\$ 715.90	✓
REAR BUMPER SIDE RETAINER <i>RH 2nd</i>	2	\$ 82.60	<i>41.30</i>
REAR BUMPER SIDE BRACKET <i>3</i>	2	\$ 59.40	<i>x</i>
REAR BUMPER REINFORCEMENT <i>1st new</i>	1	\$ 535.50	<i>x</i>
REAR BUMPER SPONGE <i>1</i>	1	\$ 225.30	<i>x</i>
END PANEL - OUTER <i>2</i>	1	\$ 571.89	<i>x</i>
END PANEL - INNER <i>1st new</i>	1	\$ 189.50	<i>x</i>
END PANEL TOP GARNISH <i>1</i>	1	\$ 325.80	<i>x</i>
END PANEL KEY LOCK SENSOR <i>1</i>	1	\$ 613.61	<i>x</i>

Tailamp RH 1st

385

\$ 3,319.50

LESS 25% \$ 829.88

SUBTOTAL \$ 2,489.63

BALANCE C/F \$ 2,489.63

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 2,489.63	
REAR BUMPER CLIP <i>new</i>	1 SET	\$ 50.00	<i>30</i>
REAR REVERSE SENSOR <i>3 new</i>	1 SET	\$ 400.00	<i>+</i>
JOINT SEALANT <i>1</i>	1	\$ 150.00	<i>+</i>

30 SUBTOTAL \$ 600.00

BALANCE C/F \$ 3,089.63

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 3,089.63	
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	<i>30</i>
REMOVE AND RENEW REAR REVERSE SENSOR	2	\$ 120.00	<i>50</i>
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	3	\$ 200.00	<i>+</i>
PANEL BEATING ON AFFECTED AREAS	4	\$ 800.00	<i>200</i>
SPRAY PAINTING ON AFFECTED AREAS	5	\$ 800.00	<i>200</i>
APPLY ANTI RUST ON AFFECTED AREAS	6	\$ 150.00	<i>x</i>

SUBTOTAL \$ 2,130.00

GRAND TOTAL \$ 5,219.63

480

total: 1366.65
1/5: 1.1K,
02 days.

United SG Automobile Pte Ltd

"We are always in your journey"....

53 Ubi Ave 1, #01-56 Paya Ubi Industrial Park, Singapore 408934.
Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg
UEN No. 201729521C | GST No: 201729521C

ESTIMATION QUOTE

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLE5006H
MAKE MODEL : BMW 335I
REFERENCE : USG-201806-16
DOA : 08-Jun-18
CLAIM TYPE : 3P CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER RETAINER <i>me</i>	2	\$ 120.00	✓
REAR BUMPER LOWER BRACKET <i>me</i>	2	\$ 66.00	+
REAR BUMPER INNER GUIDE <i>me</i>	1	\$ 540.00	+
TOW COVER <i>not all</i>	1	\$ 54.00	+
REAR PDC SENSOR <i>2 pieces Damage</i>	4	\$ -840.00	420.
REAR BUMPER REINFORCEMENT <i>20mm</i>	1	\$ 540.00	X.

540
513.
\$ 2,160.00
LESS 5% \$ 108.00
SUBTOTAL \$ 2,052.00
BALANCE C/F \$ 2,052.00

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 2,052.00	
REAR BUMPER (AFTER MARKET) <i>Delid</i>	1	\$ 2,800.00	1300
REAR EXHAUST ASSY (AFTER MARKET) <i>Pepis</i>	1	\$ 3,500.00	200
REAR BUMPER CLIP <i>me</i>	1 SET	\$ 50.00	30

SUBTOTAL \$ 6,350.00
BALANCE C/F \$ 8,402.00

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 8,402.00	
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	30
PANEL BEATING ON AFFECTED AREAS	2	\$ 500.00	250
SPRAY PAINTING ON AFFECTED AREAS	3	\$ 500.00	250
APPLY ANTI RUST ON AFFECTED AREAS	4	\$ 150.00	X.

SUBTOTAL \$ 1,210.00

GRAND TOTAL \$ 9,612.00

Adrian King
L/S 19/06/18.
030mp

total: 2573
L/S: 2050.

1530

530