

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7953D

DATE 18/6/2018 9:58

MAKE :

MODEL : HYUNDAI i40

*LKK/pawan* *L/Sun*  
*Like* *AIG*

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>x repair</i>			\$ 603.60	
	Rear Bumper Clips 10 pcs <i>x</i>			\$ 22.00	
	Rear Fender (LH) <i>x repair</i>			\$ 2,020.10	
	Rear Fender Inner Lining (LH) <i>x</i>			\$ 164.40	
	Rear Windscreen Moulding <i>x</i>			\$ 60.00	
	Rear Door (LH) <i>x repair</i>			\$ 1,351.10	
	Rocker Panel Outer Garnish (LH) <i>x repair</i>			\$ 483.60	
	Rear Wheel Hup-Cap (LH) <i>-</i>			\$ 150.70	
	<i>Front Bumper (LH) x repair</i>				
	<b>SUB TOTAL</b>			<b>\$ 4,855.50</b>	
	<b>LESS 20% DISCOUNTED TOTAL</b>			<b>\$ 971.10</b>	
				<b>\$ 3,884.40</b>	
	Rear Bumper Rubber Mat <i>x</i>			\$ 50.00	Nett
	Rear Windscreen Sealant <i>x</i>			\$ 46.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>-</i>			\$ 80.00	Nett
				<b>\$ 176.00</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 1,000.00	<i>400</i>
	Spray Painting Charge			\$ 1,000.00	<i>900</i>
	Wiring Charge			\$ 50.00	<i>x</i>
	Tuff Kote			\$ 50.00	<i>x</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	<i>x</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00	<i>x</i>
	Transfer of Door			\$ 120.00	<i>x</i>
	Rear Wheel Alignment			\$ 120.00	<i>x</i>
	<b>TOTAL LABOUR</b>			<b>\$ 2,730.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 6,790.40</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Kalini (11/11/18)*  
*18/6/18 11:10hrs*  
*3 Days*  
*45 After Repair photo*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.