

6/16/2018

Repairer Estimates

4



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

TP INSURER: India International Insurance Pte Ltd (HQ)
NA

Singapore

Claimant Insurer: Auto & General Insurance (Singapore) Pte. Limited.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0618-5106
Policy No:		Date of Loss:	12/06/2018
Vehicle Reg. No.:	SJQ6571X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHEN SHAO WEI		
Make/Model:	NISSAN SYLPHY, 1.5 (A)	Vehicle Reg. Date:	21/05/2009
Vehicle Colour:	GREY		
Engine No:	HR15110661B	Chassis No:	JN1BAAG11Z0107568
Odometer:	114468 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE IS NOT IN WORKSHOP		
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)		

not Adhered
note
4/5/1900/2
3/7/18 take photo after repair

COST OF CLAIMS

		Amount
Parts	Repair of the following:	2,308.02
Miscellaneous Items	• resurvey before and after spray painting	1,002.50
Labour	• To display damaged part(s) during resurvey	900.00
Paintwork Labour	• Parts prices are subject to confirmation	800.00
Towing	• Third party survey is on a "Without Prejudice" basis	0.00
	• No illegal modification(s) is allowed	
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
	Gross Total (S\$)	5,010.52
	Acknowledged by Repairer + GST 7.00% (S\$)	350.74
	Signature:	
	Date:	
	Nett Amount (S\$)	5,361.26

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 16 Jun 2018)**Parts:** 143 NISSAN SYLPHY 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SJQ6571X/16/06/2018 10:25**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BOOT NISSAN LOGO 11	0.00	0.00	*59.70 F X
2	1	NA	*REAR BOOT SYLPHY WORDING 11	0.00	0.00	*88.50 F X
3	1	NA	*REAR BOOT CHROME MOULDING - TOP 11	0.00	0.00	*270.60 F X
4	1	NA	*REAR BOOT CHROME MOULDING - LOWER 11	0.00	0.00	*152.70 F X
5	1	NA	*REAR BUMPER TD	0.00	0.00	*660.60 F —
6	1	NA	*REAR BUMPER SIDE HOLDER - LH 34	0.00	0.00	*36.60 F —
7	1	NA	*REAR BUMPER SIDE HOLDER - RH 34	0.00	0.00	*36.60 F —
8	10	NA	*REAR BUMPER CLIPS 24	0.00	0.00	*44.00 F —
9	1	NA	*REAR BUMPER CHROME MOULDING 24	0.00	0.00	*162.80 F —
10	1	NA	*REAR BUMPER REFLECTOR - RH 4.5	0.00	0.00	*55.00 F —
11	1	NA	*REAR BUMPER REFLECTOR - LH 4.5	0.00	0.00	*55.00 F X
12	1	NA	*TAIL LAMP ASSY - RH 5.2	0.00	0.00	*241.80 F —
13	1	NA	*REAR FENDER UNDER COWLING; SMALL - RH 11	0.00	0.00	*19.40 F X
14	1	NA	*REAR PANEL 2	0.00	0.00	*438.37 F X
15	1	NA	*REAR PANEL TOP GARNISH 11	0.00	0.00	*242.80 F X

F=Franchise part.

Sub Total (\$\$)

2,564.47

- Add. Disc. on L,N Items 10.00% (\$\$)

256.45

Total Parts (\$\$)

2,308.02

Progressive Automotive Pte Ltd/SJQ6571X/16/06/2018 10:25. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

1237.4
1113.66

6/16/2018

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	1	REAR BUMPER LOWER SPOILER	NF	772.50 ✓
2	1	REAR BUMPER SENSOR	NN	220.00 ✓
3	1	OD/TP Case (Insurer)	NR	10.00 ✓
Sub Total (S\$)				1,002.50

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New 600	800.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; RH REAR FENDER INNER; OUTER; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS	New 600	800.00
3	TO TRANSFER REAR BUMPER SENSOR	New	50.00 ✓
4	TO CHECK WIRING	New	20.00 ✓
5	TO TUFF-KOTE	New 12	30.00 ✓
Gross Labour Cost (S\$)			1,700.00

Progressive Automotive Pte Ltd/SJQ6571X/16/06/2018 10:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

2393.66