

United SG Automobile Pte Ltd

"We are always in your journey"....

53 Ubi Ave 1, #01-56 Paya Ubi Industrial Park, Singapore 408934.

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST No: 201729521C

ESTIMATION QUOTE

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD #17-00

TOWER BLOCK MND COMPLEX

SINGAPORE 069110

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLE5006H

MAKE MODEL : BMW 335i

REFERENCE : USG-201806-16

DOA : 08-Jun-18

CLAIM TYPE : 3P CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER RETAINER <i>me</i>	2	\$ 120.00	✓
REAR BUMPER LOWER BRACKET <i>me</i>	2	\$ 66.00	+
REAR BUMPER INNER GUIDE <i>me</i>	1	\$ 540.00	+
TOW COVER <i>me</i>	1	\$ 54.00	+
REAR PDC SENSOR <i>2 pieces</i>	4	\$ 840.00	420.
REAR BUMPER REINFORCEMENT <i>2H me</i>	1	\$ 540.00	x.

540

513.

\$ 2,160.00

LESS 5% \$ 108.00

SUBTOTAL \$ 2,052.00

BALANCE C/F \$ 2,052.00

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 2,052.00	
REAR BUMPER (AFTER MARKET) <i>Deland</i>	1	\$ 2,800.00	1300
REAR EXHAUST ASSY (AFTER MARKET) <i>Penis</i>	1	\$ 3,500.00	200.
REAR BUMPER CLIP <i>me</i>	1 SET	\$ 50.00	30

SUBTOTAL \$ 6,350.00

BALANCE C/F \$ 8,402.00

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 8,402.00	
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	30
PANEL BEATING ON AFFECTED AREAS	2	\$ 500.00	250
SPRAY PAINTING ON AFFECTED AREAS	3	\$ 500.00	250
APPLY ANTI RUST ON AFFECTED AREAS	4	\$ 150.00	x.

SUBTOTAL \$ 1,210.00

GRAND TOTAL \$ 9,612.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
L/S 19/06/18.
030mp

total: 2573

L/S: 2050. ✓