

1400000

INS. CASE OWNER

CC 4/EQ1801 1070, T2 jbz

LKK

IDAC

Surveyor:

Tantren

DOI:

ASSIGNMENT

2/6/18

Date / Time:

18/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GW 8466H

Name of Insured:

GOM SWEET SENA

Insured Tel No.:

HP:

9220441

Excess See II :SS

D.O.A.:

19/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

0M18H000727/CT

Policy No.:

0M18H017-005471

Make / Model:

NISSAN

Place of Accident:

Tampines North Rd.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No

SFP 2403C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sport mode.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

25/6/18
Jing

SFP 2403C-2

GW 8466H-2

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call Of:

After call Itr to Of:

29-1-19 JY

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVISE

Date/Time:

25/6/18

Sent By:

Jing

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

19-6-19

Confirm with:

JEF

Email

Call

Final Liability:

SS

100

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1,200

Loss of Rental (LOR):

SS

300

(S60 x 5 days)

Loss of Use (LOU):

SS

300

(S60 x 5 days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

1,500

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,500

Name 1:

SPORT MODE

Payee 2 (Strike if N.A.):

SS

Name 2:

X

Payee 3 (Strike if N.A.):

SS

Name 3:

X

alc
4/17
aw

Taufiq

REF: EQ1

ASSIGNMENT

CoE 2024 at

From: Date 21062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFP 2403C

at Workshop m/s: Sport mode

of 25 Kaki Bukit Rd 4 #05-66

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X		
	N/S	O/S

Bal. or Market Value

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs 3 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No: SFP2403C Yr Regn: 2004 Nov

Type: ☒ M Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Mini Cooper S cc 1598

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 121942 T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No: WMWRE32090JK75613

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/48R17

R: 205/48R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 21/6/18 @ 1630

Survey held at: Sport mode

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/S \$1,200. x x

R (\$7,613.70/82?)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

N

Date/Time, File Return to?

D

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Y S + PL \$

1. Fleet

1. Other

1. Other

1. Other

1. Other

Report Format:

Lump Sum / I.B.I. / S

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech Insp \$☐ Weekend \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ18011070/T1jb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 19-06-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 8466H	Veh. Inspected	SFP 2403C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/03/2018	Inspection Date	21/06/2018	
Survey held at	SPORT MODE AUTO PTE LTD 8 KAKI BUKIT AVE 4 #05-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Monday, 18 June, 2018 4:49 PM
To: Catherine Chong (LKK Auto)
Cc: SUR
Subject: FW: DM18HO00737/JT-: Our Vehicle SFP2403C , Your Vehicle GW8466H
Attachments: img018.jpg; ATT00001.txt; img019.jpg; ATT00002.txt; img020.jpg; ATT00003.txt; img021.jpg; ATT00004.txt; img022.jpg; ATT00005.txt; img023.jpg; ATT00006.txt; img024.jpg; ATT00007.txt; img025.jpg; ATT00008.txt; img026.jpg; ATT00009.txt; img027.jpg; ATT00010.txt; GW8466H.PDF

Dear all,

Please arrange to attend to the PRS.

Liability is cleared, proceed to direct settle if possible.

Regards,

Janet Tan
Senior Executive | Claims

18062018 @ 5:24pm
Jeffrey veh not in.



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: JEFFERY SEET [mailto:sportmode0911@gmail.com]
Sent: Monday, June 18, 2018 4:16 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>; EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: Re: DM18HO00737/JT-: Our Vehicle SFP2403C , Your Vehicle GW8466H

Hi Ms Janet ,

Will like to have LKK Auto Consultants Pte Ltd.

Thanks
Jeffery 9389 7789
Sport Mode
25 Kaki Bukit Road 4 , Synergy @ KB #05-66 Spore 417800

Sent from my iPhone

On 18 Jun 2018, at 13:32, Janet Tan <janet.tan@eqinsurance.com.sg> wrote:

Without Prejudice
Save As To Costs

Dear Jeffrey

Liability is cleared.

For Pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
Senior Executive | Claims

<image001.png>

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

<image003.png>

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please

From: JEFFERY SEET [<mailto:sportmode0911@gmail.com>]
Sent: Saturday, June 16, 2018 1:14 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: Our Vehicle SFP2403C , Your Vehicle GW8466H

Dear Officer in charge ,

Please advise us the liability for this case , we have attach the related documents for your reference.

Best Regards,

Jeffery 9389 7789
Sport Mode
25 Kaki Bukit Road 4 , Synergy @ KB #05-66 Spore 417800

SPORT MODE



Date : 14/01/2019

MS Joy (Motor Claims Department)

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex
Singapore 069110

Our ref : SFP2403C/ 190318

Your ref : DM18HO00737/JT (GW8466H)

Dear Sir,

RE: SUBMISSION OF DOCUMENTS FOR SFP2403C

Kindly be informed that our customer, PANG HUI CHIN owner of vehicle registration no. SFP2403C (insured with NTUC INCOME) holds vehicle registration no. GW8466H which is insured with you EQ INSURANCE at the time of an accident liable and hereby submitting a claim against your insured for the cost incurred.

On behalf of our customer, we provide the following claim for your settlement below:

Repair cost	:	\$ 1200.00
Loss of use	:	\$ 300.00 (\$60 per day for 5 days)
Total	:	\$ 1500.00

Please contact Mr Jeffery Seet at 93897789 or email him at jefferyseet@yahoo.com.sg **within 7 working days** from the date of this letter should there be any missing documents or any other additional documents required. If we do not hear from you during these 7 days, we would take it that all documents submitted to you are complete and in order.

Cheque should be made payable to **SPORT MODE**

We look forward to receiving your early settlement of the invoice(s). Thank you.

Yours faithfully



SPORT MODE

25 Kaki Bukit Road 4 #05-66
Synergy @ KB Singapore 417800

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 29 January 2019 5:55 PM
To: 'gohsweeseng816@gmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING GW 8466H AND SFP 2403C ON 19/03/2018
Attachments: INSPECTION OF THIRD PARTY VEHICLE.pdf, ESTIMATED CLAIM WITH SURVEYORS MARKINGS.pdf

Our ref: CC4/EQI18011070/T1jb3

GOH SWEE SENG

Policy Holder

Dear Sir,

ACCIDENT INVOLVING GW 8466H AND SFP 2403C ON 19/03/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further clarifications.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF INDEMINITY AND AUTHORITY

To: Sport Mode of 25 Kaki Bukit Road 4 #05-66 Singapore 417800 (Synergy @ Kaki Bukit)


Re: Accident on 19/03/2018 involving vehicle number SFP2403C and GW8466H at TAMPINES GIANT SHELTERED CARPARK I/We PANG HUI CHIN of NRIC S2555974F, the Owner of vehicle no. SFP2403C hereby authorize Sport Mode (following sentence named as "you") to commence repairs of the said vehicle forthwith.

1. I/We authorize your instruct and deal with the surveyor/ experts and whoever else necessary on order for you to assist me/ us in my/ our claim.
2. I/We also authorize you to appoint solicitors on my behalf to process my/our claim against the third party driver for my/ our damages including. If necessary, to commence legal proceeding in court in my/ our name
3. If the third party claim is unsuccessful or if no payment is received. I/We hereby instruct and authorize you to make claim against my/ our insurance company on my/our behalf or pay by myself for shortage amount, for your repair costs and any other losses. In case, I/We understand the any "Excess" applicable under my/our insurance policy is to be borne by me/us.
4. I/We give you full authority to instruct my/our solicitors to negotiate settlement, to sue, to reject or accept any offer of settlement on such terms as you deem fit from third party driver and/ or his insurers and/or from my/our insurers.
5. I/We undertake to assign the whole process on my/ our third party and/ or own insurance claim to you and if applicable, my/ our solicitors shall accept this as my/ our irrevocable authority to pay the amount compensated direct to you after deduction of their costs on a solicitors and clients basis.
6. I/We undertake to cooperate fully with you and all parties concerned including attending Court (when necessary) to see the claim to successful conclusion.
7. For Third Party Claim (Direct settlement) all repair cost shall paid to Sport Mode
8. I/We also authorize your to sign all Discharge Voucher/ Indemnity forms and all necessary papers in connection with the above claim.
9. I/We authorized you to reimburse the loss-of-use received from insurance company to the Car Rental Company on our behalf and in the event of any shortfall we will bear the different.

Date this 20 day of 03 2018



Owner's Signature



Witness's Signature



SPORT MODE

BILL: EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

INVOICE NO. : 2019-0205
DATE: 5-Jan-19
TERMS: Cash

VEHICLE NO. : SFP2403C
MODEL: MINI COOPER

NO	DESCRIPTION	QTY	UNIT PRICE (S\$)	TOTAL (S\$)
1	BEING LUMP SUM REPAIR FOR VEHICLE SJP2403C	1	1,200.00	1,200.00
TOTAL PAYABLE:				1,200.00

All cheques should be crossed and made payable to "SPORT MODE"
This is system generated invoice. No Signature is required.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 17/07/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GW 8466H ✓ (Insd Veh)	Your Ref. No. : DM18HO00737/JT ✓
	SFP 2403C (TP Veh)	Our Ref. No. : CC4/EQI18011070/T1jb3q2
Date of Accident	19/3/2018 ✓	✓

Liability	100%	
Final Repair Cost	: \$ 1,200.00	
Loss of Use	: \$ 300.00	5 days
Rental (If any)	: \$ ✓	days
Others:	: \$	
	: \$	
	1,500.00 ✓	
Final Settlement Sum	: \$ 1,500.00	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	SPORT MODE ✓	: \$ 1,500.00
		: \$ ✓

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ118011070/T1jb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 17-07-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 8466H	Veh. Inspected	SFP 2403C	
Policy No.	DMCPHQ17-005431	Coverage (\$)	0.00	
Claim No.	DM18HO00737/JT	Excess (\$)	0.00	
Assign From	JANET	Assign Date	18/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER S	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	WMWRE32090TK75613	Colour	GREEN	
Odometer	121942	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	DUNLOP	6 mm	
L/H Front Tyre	205/45 R17	DUNLOP	6 mm	
R/H Rear Tyre	205/45 R17	DUNLOP	6 mm	
L/H Rear Tyre	205/45 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2018	Inspection Date	21/06/2018	
Survey held at	25 KAKI BUKIT RD 4 # 05-66			
Repairer	SPORT MODE AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFP 2403C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	CARRIER	NOT NECESSARY	520.00	-
1	MOUNT BRACKET LH	NOT NECESSARY	85.00	-
1	FOG LAMP COVER LH	NOT NECESSARY	38.00	-
1	FRONT PANEL	NOT NECESSARY	550.00	-
1	SPLASH WALL REINFORCEMENT LH	NOT NECESSARY	102.00	-
1	COVER PANEL WHEEL HOUSE	NOT NECESSARY	35.00	-
1	SUPPORTING STRUT	NOT NECESSARY	189.00	-
1	INTERIOR COLUMN A LH	NOT NECESSARY	110.00	-
1	LOWER APRON	NOT NECESSARY	145.00	-
1	GUIDE LEFT BOTTM	NECESSARY	33.00	33.00
1	GUIDE LEFT TOP	NECESSARY	11.00	11.00
1	FRONT BUMPER	DEFORMED	670.00	670.00
1	TRIM STRIP	NOT NECESSARY	99.00	-
1	CENTRE FINISHER	NOT NECESSARY	89.00	-
1	GRILLE	NOT NECESSARY	45.00	-
1	CENTRE SPOILER	NOT NECESSARY	97.00	-
1	LEFT SPOILER	NOT NECESSARY	42.00	-
1	TRIM PANEL	NOT NECESSARY	75.00	-
1	SPOILER LEFT	NOT NECESSARY	75.00	-
1	WHEEL ARCH LH	NOT NECESSARY	73.00	-
1	ENGINE HOOD	TO REPAIR SEE LABOUR	1,100.00	-
1	HEADLAMP LH	NOT NECESSARY	1,650.00	-
1	FOG LAMP LH	NOT NECESSARY	185.00	-
1	CONTROL UNIT XENON	NOT NECESSARY	630.00	-
1	XENON BULB	NOT NECESSARY	375.00	-
1	LEFT TURN INDICATOR	NOT NECESSARY	77.00	-
1	WHEEL HOUSING COVER LH	NOT NECESSARY	93.00	-
	LESS 10% DISCOUNT		-719.30	-71.40
			6,473.70	642.60

Report Ref No. CC4/EQ118011070/T1jb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	50.00	-
1	SUNDRY (SN)	NECESSARY	20.00	20.00
			70.00	20.00
	<u>LABOUR</u>			
	RENEW ACCIDENT DAMAGED PARTS ON FRT BUMPER ,BONNET.INCLUSIVE OF THE REPAIR OF ENGINE HOOD .		900.00	300.00
	RESPRAY PAINT ACCIDENT DAMAGED PORTION ON FRT BUMPER ,BONNET.		600.00	400.00
	CHECK WIRING AND ELECTRICAL SYSTEM.		30.00	30.00
	TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM.		200.00	100.00
	TO APPLY SEALANT FOR ACCIDENT AFFECTED AREA.	NOT NECESSARY	120.00	-
	TO RENEW FRT UNDER CARRIAGE.	NOT NECESSARY	300.00	-
	TO CONDUCT WHEELALIGNMENT.	NOT NECESSARY	120.00	-
			2,270.00	830.00
GRAND TOTAL			8,813.70	1,492.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CC4/EQ18011070/T1jb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Thursday, 18 July 2019 3:52 PM
To: 'janet.tan@eqinsurance.com.sg'
Cc: 'Joylrene@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving GW 8466H (OI) and SFP 2403C (TP) on 19/03/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933