				1- 110	
100000	Coutley	CC YAXA1801	1074	[ph h 4 1.K	
INS. CASE OWN	HE CONTRACTOR OF THE PERSON OF			1	1 1
Surveyor:	Kancth	DOI: ASSIGN	118	Date / Time :	(8/0/c8
Pre-assign / CC	U/FTE	V 1981 - 1291		Registered in Merimon	
-	SHIC	5(73R	Claim No.	104778	14
Insured Vehicle	No.	ARB SEPULPS VIL	Claim No.	. VPK	pibrozno
Name of Insured	(ENNS-0	HR ACLARON ALL	Policy No.	DENEL	
Insured Tel No.		HP: Watty	Make / Model	IM VI	ISMUN ST II LP
Excess Sec II :S	-	_ D.O.A: _ Y V V	Place of Accid	ient: 198 4	Cation of the
Is driver the own		Nature of Accident			ou francera
If NO. Driver N Driver T		(VIL (E)/NO)	Invured Liabili	RT: (E)/NO : TP GI/ ity: % Fin	al? Yes/No
60139					
WSP. Chu	N NS WS	SRS:	INSRS: WSP:		INSRS: WSP:
Tel:	Tel Tel	P-A	Tel:	B A	Tel : Liability
RMKS V	W -W	hility:	Liability: RMKS:		RMKS:
Date/ Time					
-1-/-	5年に カガモーメ			STAGE	DATE/PIC
M18/18	CHU VINNE - 1	United The Equal Cop	12000	Non-Reporting ltr (1st) Non-Reporting ltr (2nd)	
11.1	ditte at Ause-	1.6		Non-Reporting lir (Final)	
Wil				Notification ltr (if non-pic	1 2101
. 1.41.0	200		-	After rall fir to OE	a Chelinan
31/8/18	- 010 turns	el out own min	urnoul	Documentation Check I	
	who is	TYMEDI IMO MIN	or mach	Notification ltr (if non-pic After call ltr to Of-	xup)
- 31 MPH	Flegus 1 to 7	comete		Authorisation To Act.	
.21 .4 16	prient			Release Viriother	
(7) 17 -	7.444			Final Repair Bill: Car Reput Invoice	
22/1/19	- file -> St	who to close		Towing Invoice	
	1,,0			LTA/GIA	
,				Medical Bill PIR_	
				Mandate/Reject Instruc	tion:
				LOD	
PRELIMINARY ADVIC	Y DaveTime	Sent By:		Payment Breakdown F	om:
PRELISHNART ADVIC	A. Dister Fittie:	acts by:		Post-Repair Photos: Others:	
FINALIZATION	Date/Time:	Confirm with:		Confirm by:	
Repair Cost:	55 121341	days) Reduction:	56	- Em	ed Call
FINAL SETTLEMENT Final Liability: 15		d Assessed BOLA S/N No.	a(c)	If DO or B 28. Ass. Li	
Repair Cost WON	55 4912.76	Q	12-2	-	
Loss of Rental (LOR):	55 420.00 60	i days)		Carrellow for	20052
Loss of Use (LOU) Loss of Income (LOI):	55 720.00 1950	x days)		Ow A	F04
LOR only LOU or	The second second	LOR+LO [Tick only	one)	100	r- /III
GIA/LTA Search	ss -				in a second
Medical: Disbursement:	55 -	(e.g. Tow/ Independ	ent)	2) Report Formul:	PReject/Private Settle
Legal Cost	55		1112/8	3) Survey fee 4	35VW
Total:	ss 5332 .76	Global Sum S\$:			
FINAL PAYMENT Pasee 1	SS 5332 . H	Name 1: Cheny Ho	e Motor P	limail Call	1
Payee 1. Payee 2. (Strike if N.A.)	55 7532.46	Name 1: Creary Pro	(3.0 (0) (a roto.	
Payee 3: (Strike if N.A.)	SS	Name 3:			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

	HENTON WAY #24 A TOWERSINGAP		Date: 19-06-2018					
	A TOWERON ON E SOUD !!		Code: AXA2					
1.	Pol	icy Particulars :- TH	IRD PARTY (FOLLOW THROUGH	GH INSPECTION)				
	Insured Veh.	SHC 5173R	Veh. Inspected	SBL 39C				
	Policy No.		Coverage (\$)	0.00				
	Claim No.		Excess (\$)	0.00				
	Assign From		Assign Date	19/06/2018				
2.		Veh	icle Particulars & Condition					
	Make & Model		c.c	0				
	Engine No. HIDDEN		Year of Reg.					
	Chassis No.		Colour	Colour				
	Odometer		Steering	Steering				
	Brakes		Modification	Modification				
	General							
3.			Conditions of Tyres					
		Size	Make	Balance				
	R/H Front Tyre			mm				
	L/H Front Tyre			mm				
	R/H Rear Tyre			mm				
	L/H Rear Tyre			mm				
4.			Description of Damages					
5.			General Information					
	Accident Date	17/06/2018	Inspection Date	18/06/2018				
	Survey held at	CHENG HOE MOTOR	RPL					
		BLK 1019 YISHUN IN #01-374/382 SINGAPORE 768761	D. PARK A					
5a.			Remarks					

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

M/S: AXA INSURANCE (S) PTE LTD

> 8 SHENTON WAY #27-02 AXA TOWER

SINGAPORE 068811

TEL: 63387288

ATTN: Motor Claim Department

WS Ref:

TP/AXA/YS

Claim Type: Third Party 17/06/2018 Accident Date:

TP Veh Reg No: SHC5173R

KKK Auto Consultants hence notify

Not Nothern

FAX: 68804739

Rearry 84 paint Engine 1 Reg. Dat 4581.36

ES1890668/YISHUN Estimate No:

18 Jun 2018 Date:

DMPCSN3068021700 Policy No:

Veh Reg No: SBL39C

Make/Model: HONDA CITY 1.5 SV

CVT

Chassis No: MRHGM6660HP000194

Engine No: L15Z14111068 Reg. Date:

14/09/2016

	Estimate Repair Cost to	Vehicle No	SBL39C		PAGE:1/I
	Description	U/Price	Quantity	List Price S\$	Amount S\$
	List Price			- 22	22.00
1	REAR RH DOOR	653.00	1 PC	Ry 653.00	
2	REAR RH DOOR FRAME STICKER	15.40		May 15.40	-
3	REAR RH DOOR INNER RUBBER	63.60		63.60	X
4	REAR RH FENDER	A 1,134.80	1 PC	1,134.80	w-X
5	REAR RH FENDER TRIANGLE GLASS GARNISH	20.70		S 20.70	
6	REAR RH FENDER INNER SHIELD	35.10	7. 5.75	A 35.10	
7	REAR RH FENDER INNER SHIELD CLIPS	3.90	0.	Me 23.40	
8	REAR BUMPER	463.70		Bu 463.70	
g	REAR BUMPER RH SIDE RETAINER	13.50		017 13.50	_
10	REAR BUMPER CLIPS	3.90		Ac 23.40	_
11	REAR RH SPORT RIM	590.30		ne 590.30	
12	REAR RH WHEEL BEARING	281.50		ac 281.50	
13	REAR AXLE	40.00		987.50	
14	REAR WINDSCREEN GLASS MOULDING	7 987.30 119.20		119.20	
15	RH TAILLAMP	205.70		205.70	
18.45	RII TAILLAMI	203.70	1.1%	4,630.80	4
			Less 20%	926.16	3,704.64
	Special Net				
116	REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	X
17	REVERSE SENSOR	200.00	1 SET	Fin 200.00	× 1
	MET ERGE SERGOR	200.00	1 SEI	240.00	240.00
	Labour			100	
18	REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	I LA	120.00	X
19	REMOVE & REFIX TOP ROOF	120.00	1 LA	120.00	1001
	LINING, SEAT, CARPET, GARNISH, ETC				
20		R 1,200.00	1 LA	1,200.00	900
	RH DOOR,TRANSFER DOOR ATTACHMENT,CUT,WELD & RENEW REAR RH FENDER,KNOCK & REPAIR REAR PANEL & REALIGN THE SAME				V
21	DELLOUE & DEEDLOE A BULDOOD OL LOS	60.00	170.0	10.00	
21		60.00	1 LA	60.00	Q
22	PUTTY & RESPRAY ON REAR BUMPER, REAR BHOULS FENDER, REAR RH DOOR & ALL AFFECTED AREAS	800.00	1 LA	800.00	8001
23		250.00	1 LA	250.00	2001
24	TO CONDUCT COMPLITERIZED WHERE IM IGNMENT	60.00	1 PC	60.00	-
25	PLISTPROOFING	60.00	1 LA	60.00	301
	ATTACON TO CALL PROPERTY.			2,670,00	2,670.00
	THE RESERVE OF THE PROPERTY OF			Total	S\$ 6,614.64
			444.00	T @ 7%	
	Annual Control of the				463.02
	To resure; or the following:		Total Amoun	Payable	S\$ 7,077.66
	the Repairer of the feature nerice north	For C	heng Hoe Mot	or Pte Ltd	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Mortin 9BL 39C M rear RH door Bru Frame Sticker inner rubber In rear RIM fender BI-INNER shield 7 Inner shield Clip? In rear bumper Bu-R/4 side retainer clips se m rear R/4 Sport Ring Dd-

| pr rear RM wheel bearing? | pr rear axle.? | pr rear axle.? | pr rear mysceen moulding me. -| pr relit fail (amy?

m #40/W/ met revose sonson #120/ OR AR HEAR Mareen g/951 O) ROR top roof liney, seat, Carpet, \$120/1001 3 Rak rear brumper 9854 lail Comp, rear R/n close, transfer door affectment, Tenter, and real the say, # 1200/9001 took rear ponel #60/ -PRAR rear R/M door stay (8) Putty manymany on rear brimger, rev R/4 Dentor, rav A/4 door and all affected a rec \$ 800/ -(6) Rock pear under corrlage #250/ ? D to conduct computer wheel aligh A 60/ \$ 60/ 8 kinghoof

> Back to OneMotoring

SBL 39 C

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Singapore NRIC Owner ID Type:

6473F Owner ID:

Vehicle Details

SBL39C Vehicle No.:

Vehicle to be Exported: No

18 Jun 2018 Intended De-registration Date:

Vehicle Make: HONDA

Vehicle Model: CITY 1.5 SV CVT

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: L15Z14111068

Chassis No.: MRHGM6660HP000194

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$17,459.00

Original Registration Date: 14 Sep 2016

First Registration Date: 14 Sep 2016

Transfer Count: 1

Actual ARF Paid: \$12,459.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Sep 2026

PARF Rebate Amount: \$9,344.00

Intended COE Rebate Details

COE Expiry Date: 13 Sep 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

OP Paid: \$55,200.00 COE Rebate Amount: \$45,472.00

Total Rebate Amount: \$54.816.00

The information contained herein is correct as at 18 Jun 2018

OK

Hsiao Tong (LKKAuto)

From:

Shu Pei (LKKAuto)

Sent:

Thursday, 30 August 2018 10:46 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: TP settlement - C0473894/P1680520

Best Regards,

Shu Pel | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>shupei@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 30 August 2018 10:00 AM To: Admin A <admin-a@lkkauto.com>

Subject: FW: TP settlement - C0473894/P1680520

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Thursday, 30 August 2018 10:00 AM

To: sur@lkkauto.com; assignments@lkkauto.com Subject: TP settlement - C0473894/P1680520

This mail is associated with:

*SBL39C (C0473894) [SHC5173R]

TP

Jun 17 2018 7:00AM [TRANS-CAB SERVICES PTE LTD] Cheng Hoe Motor Pte Ltd

Dear KENNETH KONG,

Please proceed for direct settlement if damages consistent.

Regards,

Cynthia Loh

This is an auto-generated email. Do not reply to this email.

Sent by : Cynthia Loh (AXA Insurance Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com

Print Sent Message

This mail is associated with:

*SBL39C (C0473894) [SHC5173R] TP

Jun 17 2018 7:00AM [TRANS-CAB SERVICES PTE LTD] Cheng Hoe Motor Pte Ltd

From

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 08/02/2019 09:22 AM.

To

sawtheng.khor@axa.com.sg

CC

AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com

Subject

<Mandate IA> C0473894

Dear Sirs/Mdm,

We refer to the above matter.

Liability: 100%. Insured driver turned out from minor road and collided with third party who was turning into minor road. BOLA S9(c) is applicable. Inform OI about third party claim. Agreed to settle at best.

We seek your mandate at \$5,332.76(all-in). Mandate IA had been uploaded in Merimen.

Kindly let us have your approval/instruction.

Hsiao Tong



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date:08/02/2019

Survey Details:

Date of loss	17.06.2018
Date of appointment	18.06.2018
Date of survey	18.06.2018
Location of survey	CHENG HOE MOTOR PL

Vehicle Details:

Claim Type:	Third part	у	
Vehicle number	SBL 39C		
Make and Model	Honda City (1497cc)		
Date of registration	14.09.2016		
Excess	NIL		
Market Value/ Book Value	\$	72,000.00	(e
Parf/COE Rebate	\$	54,816.00	(e
Nett Value/ ERV	\$	17,184.00	(e

Repair details:

Initial Estimate	\$ 6,614.64

Proposed/Revised repair cost:

Lump Sum(if applicable)	NIL
Total	\$ 4,591.36
Supplementary	NIL
Labour	\$ 2,150.00
Check items (estimate)	NIL
Parts	\$ 2,441.36

Number of days for repair	6



51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 400933 TEL: 1065) 62563561 FAX: 1065) 62564315

	Rema	rks:		

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 4,912.76	
Loss of use	\$ 420.00	(7days x \$60.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	NIL	
Others	NIL	
Proposed Total	\$ 5,332.76	

Print Received Message

This mail is associated with:

*SBL39C (C0473894) [SHC5173R] TP

Jun 17 2018 7:00AM [TRANS-CAB SERVICES PTE LTD] Cheng Hoe Motor Pte Ltd

From

AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 10/02/2019 14:37 PM.

To

Subject

Alert - Adj Mandate Approved (S\$5332.76) - SBL39C - Claim Handler: Khor Saw Theng

Approved:5332.76.



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761 Tel: 67556142 Fax: 67557719

Email: chmotor@singnet.com.sg

Date:

2 4 JAN 2019

AXA Insurance (S) Pte Ltd C/O LKK Auto Consultants

Attn: THE MOTOR CLAIMS DEPT

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO. SBL39C & SHC5173R ON 17/06/2018 ALONG YISHUN ST.11 TURNING INTO HDB CAR PARK.

We are authorized by SBL39C for their above matter.

Record reveals that you are the insurer of SHC5173R. We therefore wish to seek compensation from you as below:-

1.	Cost of Repairs		S\$	4912.76
2.	Loss of Use (S\$60.00 /- x 7 days)		S\$	420.00
3.	Hire of Vehicle		S\$	0.00
4.	LTA Search Fee/GIA Reports		S\$	0.00
		TOTAL	S\$	5332.76

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Friday, 31 August 2018 12:10 PM

To:

claims@transcab.com.sg

Cc:

'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com';

'foonghon@ava-ins.com'

Subject:

ACCIDENT INVOLVING SHC 5173R AND SBL 39C ALONG/AT YISHUN ST 11

TURNING INTO HDB CARPARK ON 17/06/2018

31 AUG 2018

Transcab Taxi Singapore

Dear Sir,

OUR REF

: CC4/AXA18011074/Kpb3

YOUR REF : P1680520 (SHC 5173R)

ACCIDENT INVOLVING SHC 5173R AND SBL 39C ALONG/AT YISHUN ST 11 TURNING INTO HDB CARPARK ON 17/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer. AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from CHENG HOE MOTOR PL acting on behalf of the owner of SBL 39C against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

We also wish to advise that there is an excess of \$\sumset\$\$ \$\sumset\$\$ \$\sumset\$\$ \$\sumset\$\$ attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / chewht@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s). AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewhtielkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT

(FOR PROPERTY DAMAGE CLAIM ONLY) I. Cheong Siew Ting (Zhang Xiu Ting) ("the third party claimant") of 62 Goodlink Park S 759531 (address), owner of SBL39C (vehicle no.) hereby authorize CHENG HOE MOTOR PTE L'ID ("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my Vehicle No. SBL39C that was damaged pursuant to the accident which occurred on 17/6/2018 (date) along Yishun St 11 turning into HDB Car Park (location) involving Vehicle No/s SHC5173R ("The accident"). I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop. I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned. Dated this 18 day of June

Signed by "the workshop"

Signed by "the third party claimant"



This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement lerms should not be used as evidence in any related suits or claims arising from this accident.

CLAIM REF

:[C0473894

INSURED

: I TRANS-CAB SERVICES PTE LTb

DISCHARGE VOUCHER

We/I [CHEONG	SIEW	TING	(Zhar	ng Xiư	Ting)], NRIC	NO. S7	726473F)
	gree three hux	to ired thi	accep	ot & cts s	the seventy-	sum _\$2x[z-		of	dollars [) paid to
us/me by AXA including damage said AXA INSUR as a result of a which we/l were I SBL39C	INSURANC ges for per ANCE PTE an accident	E PTE L sonal in LTD or t along	TD as f juries ar heir Insu Yish	full and nd dama ared or to oun St.	final se ges to p he drive 11-to	oroperty or of mot	that we to vehicl carpar	laims of /I may ha le no. [Si k 17/0	ave against the HC5173R 1 of
We/I hereby de liable for any fi against the sai connection dire	urther clair d Insurer,	n(s) wha	atsoever and/or	and wh	nosoeve of vehic	r preser cle no.	t or futu SHC51	ure that v 73R	we/I may have 1_in
We/I hereby de hereby underta respect of this s	ke to inden								
It is understood on the part of th			Contract the second						ity whatsoever
Date	d this2	1st		_day of _	Fe	b		×2017	2019
Claimant's Signa	ture	:_	Ju	m Pa	NO4				
NRIC no./ Comp	any Stamp	1_	S77	726473	7				
Occupation/ Bus	iness	4_		sewife					
Address		3_		31k 101 in Ind			68761)		
Telephone No.			9879	5264					
Witness's Name		:	Phua	Lian	Hua				
Witness's Signat	ure	:_							
Witness's NRIC	No.	:	S172	23330j					

AXA Insurance Pte Ltd (Company Reg. No. 199903512M) B Sheriton Way, #24-01 AXA Tower, Singapore 068811 Customer Centre #B1-01

Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

FAX: 68804739

TAX INVOICE

M/S: AXA INSURANCE (S) PTE LTD

> 8 SHENTON WAY #27-02 AXA TOWER

SINGAPORE 068811

63387288 TEL:

ATTN: Motor Claim Department

WS Ref: Claim Type: TP/AXA/YS Third Party 17/06/2018

Accident Date: TP Veh Reg No: SHC5173R

NO:

CL8181376

Date:

21 Dec 2018

Policy No:

DMPCSN3068021700

Veh Reg No:

SBL39C

Make/Model: HONDA CITY 1.5 SV CVT

Job No:

JC1598868

Description	1	Quantity	List Price	PAGE:1
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.		1 PC	S\$ 4,591.36	S\$ 4,591.36

(As recommended by your appointed surveyor)

S\$ 4,591.36 Total Add GST @ 7% 321.40

S\$ 4,912.76 Total Amount payable

For Cheng Hoe Motor Pte Ltd

E. && O. E.

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report) Proceed Direct Settlement

Case	Notified	Est Submitted	Ad) Assigned	Adj Rpt	1	d) Submitted	Ins Auth ed	Status		
Main	18 Jun 2018		18 Jun 2018 15:02 Edit Adj Rpt	S\$4,591.	1	\$4,591.36 View Rpt		Pending for Survey Report Cancel Case		
	Main	R	eference	Cla	im Detai	is \	Documents		Show All	
CLAIM SU	BFOLDER DI	TAILS				[Created	by insurer]			
Insured:	TRANS-C	AB SERVICES PT	ELTD, Co. Reg. N	lo.: 20030387	8K.					
Main Claimant:	CHEONG	HEONG SIEW TING (ZHANG XIUTING), ID: S7726473F								
Vehicle Reg No.:	SBL39C			1	Date of Lo		3 07:00 - :59 and 3 Days From	LTA Reg Date	(Man Yr)]	
Claim Type	TP / C04	73894			Palicy/Cov Note No.:	P1680520	(Third Party Only)			
Vehicle Reg No. (Insured):	SHC5173R				olicy No. Claimant)	DMPCSN30	DMPCSN3068021700			
					xcess:	\$\$5,000.00				
Repairer:	Cheng Ho	e Motor Pte Ltd	(Yishun) Blk 1019	#01-374/382	, Yishun l	ndustrial Park A	, 768761 Yishun -	Tel: 6755 614	12	
Handling Insurer:	AXA Insu	rance Pte Ltd (H	Q) - Tel: 6338 728	8 [Handled	by Khor	Saw Theng - 6	880 4754]			
Claimant's Insurer:	China Tai	ping Insurance	(Singapore) Pte. L	td. (HQ) - T	el: 6389 6	111				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handled b	Y KENNETH KO	NG] [Final R	pt due 27/0	06/2018]	
Adj Asg. Remarks:	Non-repor	ting case. TP want	s either Kenneth Ko	ing/ Marcus C	hua/ Hen	try Ng to be the	SJE.			
ASSOCIAT	ED MAIL RE	CEIVED					View	All Comp	ose Case Ma	
AXA_SG AXA_SG AXA_SG	(22/12/2018) (30/08/2018) (21/08/2018) CIATED TAS	: C0473894 STA : TP settlement : C0473894 -PL!	- CO473894/P168	0520				eate New Task Created		

Claim Documents

*SBL39C (C0473894)

[SHC5173R]

TP

CHEONG SIEW TING (ZHANG XIUTING)

Jun 17 2018 7:00AM

[TRANS-CAB SERVICES PTE LTD]

Cheng Hoe Motor Pte Ltd

Let	ters/Corresponder	nces	1 per	page V	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1	Thumbnail	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	-
Do	cumentation		1 per	page V	V
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	18/06/18 13:52	EMAIL FROM WORKSHOP	0	Load PDF	
2	18/06/18 13:55	EMAIL TO WORKSHOP (LIST OF SURVEYOUR)	0	Load PDF	
3	18/06/18 14:51	REPLY FROM WORKSHOP	0	Load PDF	
4	18/06/18 15:01	TP appoint LKK	0	Load PDF	
5	20/06/18 14:17	reply to surveyour (non-report)	0	Load PDF	
6	02/07/18 10:58	EMAIL INSD REPORTED	0	Load PDF	
7	02/07/18 10:58	SHC5173R INSD GIA	0	Load PDF	
В	10/07/18 10:45	TP SAS Report	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/06/18 17:46	TP ESTIMATE- MARKED (INCOMPLETE)	0	Load POF	
2	08/02/19 09:15	TP ESTIMATE_MARKED	0	Load PDF	
3	08/02/19 09:15	PARF_COE REBATE	0	Load PDF	
4	08/02/19 09:15	LKK Survey Photos	0	Load PDF	
5	08/02/19 09:15	LKK Resurvey Photos 1	0	Load PDF	
6	08/02/19 09:15	LKK Resurvey Photos 2	0	Load POF	
7	08/02/19 09:20	Mandate IA dd 080219	0	Load POF	
8	26/02/19 10:16	WORKSHOP INVOICE	0	Load PDF	
9	26/02/19 10:16	AUTHORISATION TO ACT FORM	0	Load POF	
10	26/02/19 10:16	DISCHARGE VOUCHER	0	Load PDF	
11	26/02/19 10:16	LOD	0	Load PDF	
12	26/02/19 10:16	LETTER TO OI	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save	Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		^
		~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

NOTE: TO BE COMPLETED BY SURVEYO	PLETED BY SURVEYOR	COMPL	TO BE	NOTE:
----------------------------------	--------------------	-------	-------	-------

TEAM		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5173R (Insd veh)				Mo	del:	H	HONDA CITY 1.5 CVT (A)		
	SBL39C (TP veh)									
Date of Accident:	17/06/2018									
				_						
Global Sum Settlem	ent :	[]	Yes		[X]	No				
Repair Estimate				:\$		7,077.6	6			
Final Repair Cost				: \$		4,912.76	3			
Loss of Use				: \$		420.00	7	.00 day	ys at \$60.00 per day	
Rental (if any)				: \$		0.00)	day	ys	
LTA / GIA Search F	ee			: \$		0.00	0			
Others:				: \$		0.00	0			
				: \$						
Final Settlement Su	m			: \$		5,332.76	3			
Is Third Party Work					[x]	YES	[]	NO	(Kindly indicate	
A) For Non GIA R	egistere	d Work	(shop:			ed Liability			Uniform to the second s	
B) For GIA Regist	ered Wo	orksho	p:		BOL (c)_		ole: Yes/	No- E	BOLA Scenario No:	
BOLA Liability: * Assessed Liab				hain			And the second second		(%) OLA does not apply.	
Remarks										
CONTROL OF THE PARTY OF THE PAR										
Payment Instruction			akdown							
Cheng Hoe Mo	otor Pte I	.td				: \$			5,332.76	
2)						: \$				
JOANNE I	EE KHA	NG MI	N		-	Feb 019				
LKK Auto C	onsultan	ts Pte I	.td		D	ate				

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AXA18011074/KPB3Q2

Date:

26/02/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No :

le SBL39C

Insured Vehicle No :

SHC5173R

Date of Loss:

17/06/2018

Nature of Claim:

TO

Claim No:

C0473894

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SBL39C

Make & Model:

HONDA CITY, 1.5 CVT (A)

Engine No:

L15Z14111068

21800 km

Reg. Date: Colour: 14/09/2016 (Man. Year: 2016) Metallic Grey

Chassis No: Odometer: MRHGM6660HP000194

Engine Capacity:

Metallic Gre

1497 cc

Market Value/New Car Price: N/A

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Engine Modification: Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

185/55 R16

Rear Tyre Size:

185/55 R16

Front Left Side:

Bridgestone 5 mm

Rear Left Side:

Bridgestone 7 mm

Front Right Side: Bridgestone 5 mm
The above values represent the remaining tyre treads depth

Bridgestone 5 mm Rear Right Side:

Bridgestone 7 mm

The state of the s

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,944.64	2,441.36	1,503.28	38.11
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,670.00	2,150.00	520.00	19.48
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	6,614.64	4,591.36	2,023.28	30.59
	+ GST 7.00/7.00% (S\$)	463.02	321.40	141.62	30.59
	Nett Amount (S\$)	7,077.66	4,912.76	2,164.90	30.59
	+ Loss of Use (7.0 x 5	\$\$60.00/day) (\$\$)	420.00		
		Nett Liability (S\$)	5,332.76		

INSPECTION

Date of Assignment:

18/06/2018

Date Inspected:

18/06/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial

Park A

Singapore 768761

Estimated Period of Repair:

6.0 days

Adjuster Report

Page 2 of 4

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 25 Feb 2019)

Parts:

143

HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBL39C)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	653.00 FL	*653.00 FL
2	1		*REAR RH DOOR FRAME STICKER	Necessary	15.40 FL	*15.40 FL
3	1		*REAR RH DOOR INNER RUBBER	Serviceable	63.60 FL	*-FL
4	1		*REAR RH FENDER	Repair	1,134.80 FL	*-FL
5	1		*REAR RH FENDER TRIANGLE GLASS GARNISH	Serviceable	20.70 FL	*-FL
6	1		*REAR RH FENDER INNER SHIELD	Serviceable	35.10 FL	*-FL
7	6		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	23.40 FL	*23.40 FL
8	1		*REAR BUMPER	Buckled	463.70 FL	*463.70 FL
9	1		*REAR BUMPER RH SIDE RETAINER	Distorted	13.50 FL	*13.50 FL
10	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
11	1		*REAR RH SPORT RIM	Dented	590.30 FL	*590.30 FL
12	1		*REAR RH WHEEL BEARING	Necessary	281.50 FL	*281.50 FL
13	1		*REAR AXLE	Bent	987.50 FL	*987.50 FL
14	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	119.20 FL	*-FL
15	1		*RH TAILLAMP	Serviceable	205.70 FL	*-FL
16	1		*REAR WINDSCREEN GLASS GUM	Not Necessary	40.00FS	*-FS
17	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*-FS
F=Fra	nchise	part. S=Spci	Nett. L=ListItemDisc			
				Sub Total (S\$)	4,870.80	3,051.70
			- List Item Discount on L Items	20.00/20.00% (S\$)	926.16	610.34
				Total Parts (S\$)	3,944.64	2,441.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
2	REMOVE & REFIX TOP ROOF LINING ,SEAT ,CARPET ,GARNISH ,ETC	New	120.00	100.00
3	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMP ,REAR RH DOOR ,TRANSFER DOOR ATTACHMENT ,CUT ,WELD & RENEW REAR RH FENDER ,KNOCK & REPAIR REAR PANE & REALIGN THE SAME	New	1,200.00	900.00
4	REMOVE & REFIX REAR RH DOOR GLASS	New	60.00	60.00
5	PUTTY & RESPRAY ON REAR BUMPER ,REAR RH FENDER ,REAR RH DOOR & ALL AFFECTED AREAS	New	800.00	800.00
6	REMOVE & REFIX REAR UNDER CARRIAGE	New	250.00	200.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
8	RUSTPROOFING	New	60.00	30.00
	Gross Labo	our Cost (S\$)	2,670.00	2,150.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >