

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN POI HUAT
BLK 119C RIVERVALE DRIVE
#12-344
S 543119

TPAXA.
Joy.

Date :28.06.2018
Vehicle no :SJT 7083 R
Make/Model :KIA FORTE
Accident date :17.06.2018

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front RH fender <i>dent</i>	1	\$ 354.2 ✓
2	Front RH fender inner shield	1	\$ 65.8 X
3	Front RH fender inner shield clips (1set) <i>2 not new</i>	1	\$ 70 X
4	Front RH door <i>distorted</i>	1	\$ 1078 ✓
5	Front RH door top hinge <i>new</i>	1	\$ 46.2 X
6	Front RH door lower hinge <i>dent</i>	1	\$ 46.3 ✓
7	Front RH door stopper <i>new</i>	1	\$ 27.5 X
8	Front RH door power window motor <i>2 not new</i>	1	\$ 352.7 X
9	Front RH door power window regulator <i>new</i>	1	\$ 372.9 X
10	Front RH door inner board <i>cracked</i>	1	\$ 471.5 ✓
11	Front RH door inner lock <i>new</i>	1	\$ 209 X
12	Front RH door pillar <i>new</i>	1	\$ 858 X
13	Front RH lower arm <i>dent</i>	1	\$ 353.1 ✓
14	Front RH knuckle arm <i>dent</i>	1	\$ 387.2 ✓
15	Front RH knuckle arm bearing <i>new</i>	1	\$ 141.9 ✓
16	Front RH shock absorber <i>dent</i>	1	\$ 283.6 ✓
17	Front RH drive shaft <i>new</i>	1	\$ 1038.4 X
			\$ 6156.3
Less 10% Disc			\$ 615.63
Total			\$ 5540.67

Special Nett Items

1	Front RH sport rim <i>cut</i>	\$ 780 <i>480</i>
2	Front RH tyre <i>new</i>	\$ 280 X
Total		\$ 1060

Labour Cost

1	Remove & reinstall front windscreen	\$ 150 X
2	To check wheel alignment	\$ 100 <i>80</i>
3	Remove & reinstall front RH suspension	\$ 300 <i>220</i>
4	Remove & reinstall dashboard	\$ 380 X
5	Remove & reinstall door glass <i>ittings</i>	\$ 100 <i>80</i>
6	Remove, replace & repair consisten to the accident	\$ 1600 <i>600</i>
7	Respray painting	\$ 1200 <i>600</i>
8	Tuff kote	\$ 150 X
Total		\$ 3980

Grand Total

\$ 10580.67

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey the car after spray painting
- To display the car during a resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Total: 48422

h/s: 39K

050 days

3-9K