

SERVICE ESTIMATE

96279 - C00001 SL: SERVICE SALES - PC

Mr Ung Chuong Hing

Blk 311 Ang Mo Kio Avenue 3

#08-2116

Singapore 560311

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 18/06/2018

WIP No. : 11608

Veh.In/Out:

*Tel.No. : Mobile: 92381018

Reg.No. : SJN6199D

Reg.date : 29/03/2018

Mileage : 0

Chassis No: YV1LF10ACJ1340009

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Ung Chuong Hing

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802 TO REPLACE FRONT BONNET,FRT
BUMPER,FRT BRACKET,FRT GRILL,
FRT RH HEADLAMP,ETC

0

3200.00 0

~~3,200.00~~ S

2400

800 TO PUTTY SPRAY PAINT ON FRT
BONNET,FRT BUMPER,ETC

0

2100.00 0

~~2,100.00~~ S

1400

R06 TO INSTALL FRONT NUMBER PLATE
INCLUDE HOLDER

0

60.00 0

60.00 S

280 TO FOCUS HEADLAMP

0

150.00 0

150.00 S

280 TO CHECK WIRING INCLUDE

0

450.00 0

450.00 S

RESETTING OF ALL ELECTRICAL
MODULES

BUMPER COVER FRT XC9

1.0 EA

1714.40

1,714.40 S

at

PROTECTING PLATE FRT

1.0 EA

562.70

562.70 S

BUMPER BRACKET LHF X

1.0 EA

79.10

79.10 S

X

BUMPER BRACKET RH F X

1.0 EA

79.10

79.10 S

ne

BUMPER BRACKET LHF X

1.0 EA

79.10

79.10 S

X

BUMPER BRACKET RH F X

1.0 EA

79.10

79.10 S

ne

Paul

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X



WEARNES

SERVICE ESTIMATE

96279 - C00001 SL: SERVICE SALES - PC

Mr Ung Chuong Hing

Blk 311 Ang Mo Kio Avenue 3

#08-2116

Singapore 560311

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 18/06/2018

WIP No. : 11608

Veh.In/Out:

*Tel.No. : Mobile: 92381018

Reg.No. : SJN6199D

Reg.date. : 29/03/2018

Mileage : 0

Chassis No: YV1LF10ACJ1340009

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Ung Chuong Hing

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER FOAM FRT XC90	1.0 EA	337.30			337.30 S	?
	WIPER GRILLE CLIP XC	10.0 EA	7.10			71.00 S	new /
	BONNET FRT XC90 16-	1.0 EA	3338.00			3,338.00 S	PA /
	HEADLAMP RH XC90 16-	1.0 EA	2315.60			2,315.60 S	sch /
	HEADLAMP DRIVE UNIT	1.0 EA	235.90			235.90 S	new /
	HEADLAMP DRIVE UNIT	1.0 EA	250.50			250.50 S	new /
	BUMPER RAIL (BEAM) F	1.0 EA	1022.30			1,022.30 S	?
	RADIATOR GRILLE	1.0 EA	780.00			780.00 S	sch /
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00 S	new /
	BUMPER CLIP	10.0 EA	4.80			48.00 S	new /
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40 S	new /
	NOISE DEADENING PAD	1.0 EA	500.00			500.00 S	X
	D ADHESIVE SEALANT	1.0 EA	344.10			344.10 S	new /
	BUMPER LOWER GRILLE	1.0 EA	251.20			251.20 S	?

Reau
Hp 90000068

Gross Total. 18,160.80

Labour Total 5,960.00

Parts Total 12,200.80

Package Total 0.00

Net..... 18,160.80

GST @ 7.0% 1,271.26

Total..... 19,432.05

Paid..... 0.00

Please Pay.. 19,432.05

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

02/07/18 @ 1520
Reg 54 part

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X