



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18011102/K1pa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:RICHARD ANG

Date : 07-08-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKB 9729G	<b>Veh. Inspected</b>	SHB 3999T
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M00KZQ	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	18/06/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ	<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
<b>Chassis No.</b>	WDD2120022A671117	<b>Colour</b>	WHITE
<b>Odometer</b>	554941	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	WEST LAKE	7 mm
<b>L/H Front Tyre</b>	205/60 R16	WEST LAKE	7 mm
<b>R/H Rear Tyre</b>	205/60 R16	WEST LAKE	7 mm
<b>L/H Rear Tyre</b>	205/60 R16	WEST LAKE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	14/06/2018	<b>Inspection Date</b>	18/06/2018
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**