

REPAIR ESTIMATE*

CCPL

VEHICLE NO : SHB 3999T

DATE 18/6/2018 8:35

MAKE :

Like

AXA

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	Nett
	Rear Door Comfort Limo Cab Logo ✓			\$ 60.00	
	Rear Bumper x repair				
	Rear RH Fender x repair				
	Rear RH Door x repair				
	Labour Charge			200	
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 750.00	600
	Tuff Kote			\$ 50.00	x
	TOTAL LABOUR			\$ 1,150.00	
	ESTIMATE TOTAL			\$ 1,210.00	
1 Calm 1 Ucky 18/6/18 1505hrs. 2 Days 4/5 After Repair photo					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					