

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0812/2018
DATE : 16-JUN-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : TAN BOON PIN
ADDRESS : APT BLK 171 LORONG 1 TOA PAYOH
#20-1152
S(310171)
TELEPHONE NO : 91834438

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800050270
VEHICLE NO : SLZ5183T
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD37532
CHASSIS NO : JF1SJ5KC5JG107886
MILEAGE : 1 KM
DATE IN : 16/06/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 10/06/2018

Print Date : 20/06/2018
Print Time : 08:21:32

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ5183T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SKZ6913J - AXA		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION: AFTER MOUNT PLEASANT FLYOVER(PIE) DATE: 10/06/2018 TIME: 1555HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND PANEL	1680.00	2801
4	ZZ/003	RESPRAY REAR BUMPER AND PANEL	1260.00	4201
5	ZZ/004	TO SUPPLY&INSTALL REVERSE SENSOR-2 EYES	300.00	X
6	ZZ/005	SUNDRIES	100.00	X
TOTAL LABOUR CHARGES			3340.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ5183T

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
					S/LIST REMARKS
1	BUMPER FACE REAR FORESTER IL	57704SG012	<i>Buckin</i> 540.00	<i>✓</i>	
2	BRKT CORNER R RH	57707SG060	<i>Sm</i> 18.00	<i>X</i>	
3	BRKT CORNER R LH	57707SG070	<i>Sm</i> 18.00	<i>X</i>	
4	BRKT SD R RH	(1) 57707SG080	<i>M</i> 14.40	<i>X</i>	
5	BRKT SD R LH	57707SG090	<i>M</i> 14.40	<i>X</i>	
6	BEAM COMPL R EU	57711SG0219P	288.00	<i>7</i>	
7	COVER HOOK R	57731SG010NN	<i>Sm</i> 12.60	<i>X</i>	
SUB TOTAL			905.40	0.00	0.00
LESS DISCOUNT (NETT-20 %)			181.08	0.00	0.00
GRAND TOTAL			724.32	0.00	0.00
OVERALL TOTAL			724.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SL25183T

TOTAL LABOUR CHARGES	3340.00
TOTAL SPARE PARTS CHARGES	724.32
GRAND TOTAL	4064.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Not Anthony
Recovery B4 paint
2 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are on "market" quotation
- Third party survey done on "no dispute" basis
- No illegal modification is allowed
- Supplementary repair charges are allowed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: