



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/07/2019

Survey Details:

Date of loss	10-Jun-18
Date of appointment	19-Jun-18
Date of survey	15-Jul-19
Location of survey	MOTOR IMAGE ENTERPRISES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLZ 5183T
Make and Model	SUBARU FORESTER 2.0I-L CVT AWD SR
Date of registration	7/5/2018
Excess	
Market Value	\$89,000
Parf Rebate	\$42,796
Nett Loss	\$46,204

Repair details:

Initial Estimate	\$ 4,064.32
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 432.00
Check items (estimate)	\$ 230.40
Labour	\$ 700.00
Total	\$ 1,362.40
Lump Sum(if applicable)	\$ -
Number of days for repair	2



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. We will seek mandate after our surveyor have verify the check items.

Mandate:

Liability(TP)	%	
Proposed repair cost	TBA	
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
Proposed Total	TBA	