

Service Order Confirmation

SERVICE ORDER NO: 18IP1553

CUSTOMER NO.: CV034371

CUSTOMER NAME: LIM TOW NAN

TELEPHONE NO.:

ADDRESS: 480 SEMBAWANG DRIVE #07-457
Singapore

VEH No.: SLD9445C

Order Date: 06/18/18

Reg Date: 06/30/16

KM: 44,541

VIN NO.: VWWZZZAUZGW075252

ENGINE NO:

MODEL: GOLF A7 1.4 CL 92 (DSG) EQP

MODEL NO: 5G13HZ

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SA: Tang Shu Shi

Tan Shu 97495749 - WP
19/6/18 @ 3pm
Lamp Resurvey before repair
sur @ 18 auto co in
12 days

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P TOWING	B&P TOWING CHARGES	156	TU	1.25	195
2	B&P MECH	CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280	280
3	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	480	480
4	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
5	B&P MACP LABOUR	LABOUR FRT	4	UNIT	840	2520 3,360
6	B&P MACP PAINT	SPRAY PAINT FRT	6	UNIT	800	2400 4,800
7	B&P MACP LABOUR	LABOUR REAR	6	UNIT	840	2520 5,040
8	B&P MACP PAINT	SPRAY PAINT REAR	7	UNIT	844	2400 5,908
9	B&P MACP LABOUR	R&R REAR W/SCREEN	1	UNIT	840	840
10	B&P MACP LABOUR	TRANSFER BOOT LID MECHANISM	1	UNIT	840	420 840
11	B&P MACP LABOUR	R&R REAR SILENCER	1	UNIT	840	7 840
12	B&P MACP LABOUR	R&R FRT & REAR BODY KIT	2	UNIT	840	840 1,680
13	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	2	ST	80	64 160
Item						
14	5G0823031J	FRT BONNET	1	PCS	1,206.36	Rp 1,206.36
15	5G0807217BPGRU	FRT BUMPER	1	PCS	1,152.82	de 1,152.82
16	5G0998399 GRU	SENSOR BRACKET	1	PCS	32.19	net 32.19
17	5G0919493	SENSOR BRACKET	1	PCS	14.70	net 14.70
18	5G0919493A	SENSOR BRACKET	2	PCS	14.70	net 29.40
19	5G0919494	SENSOR BRACKET	1	PCS	14.70	net 14.70
20	D 180KU2A1	2KADHESIVE	1	PCS	103.66	net 103.66
21	D 822150A1	BONDAGENT	1	PCS	74.16	net 74.16
22	5G0805915 9B9	SPOILER	1	PCS	187.63	can 187.63
23	5G0807109AL	REINFORCEMENT	1	PCS	625.71	? 625.71
24	5G0807248F	FOAM INSERT	1	PCS	40.17	? 40.17
25	5G0807724D	BUMPER INNER BRACKET RH	1	PCS	27.60	net 27.60
26	5G0807049A	BUMPER SIDE BRACKET LH	1	PCS	19.54	x 19.54
27	5G0807050A	BUMPER SIDE BRACKET RH	1	PCS	19.54	net 19.54
28	5Q0919275B GRU	SENSOR	2	PCS	166.62	? 333.24

Service Order Confirmation

SERVICE ORDER NO: 18IP1553

CUSTOMER NO.: CV034371

CUSTOMER NAME: LIM TOW NAN

TELEPHONE NO.:

ADDRESS: 480 SEMBAWANG DRIVE #07-457
Singapore

VEH No.: SLD9445C

Order Date: 06/18/18

Reg Date: 06/30/16 KM: 44,541

VIN NO.: WWWZZZAUZGW075252 ENGINE NO:

SA: Tang Shu Shi

MODEL: GOLF A7 1.4 CL 92 (DSG) EQP MODEL NO.: 5G13HZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	5Q0919133 9B9	3	PCS	1.98		5.94
30	5G0955966	1	PCS	178.51		178.51
31	5G0955110 GRU	1	PCS	37.78		37.78
32	5G0853651A ZLL	1	PCS	509.37		509.37
33	5G0853677 9B9	1	PCS	134.01		134.01
34	5G0853212E 9B9	1	PCS	25.72		25.72
35	5G0853666 9B9	1	PCS	93.82		93.82
36	5G2941754	1	PCS	2,959.71		2,959.71
37	5G0941662	1	PCS	290.04		290.04
38	5G0805932	1	PCS	34.83		34.83
39	5G0805705G	1	PCS	40.21		40.21
40	D 004660M2	1	PCS	183.87		183.87
41	D 00940104	1	PCS	113.83		113.83
42	D 00920002	1	PCS	32.19		32.19
43	D 00950025	2	PCS	11.19		22.38
44	D 181802M1	1	PCS	29.46		29.46
45	5G6827025Q	1	PCS	1,355.49		1,355.49
46	5G6971829B	2	PCS	15.28		30.56
47	000979941	15	PCS	10.86		162.90
48	000979942	5	PCS	10.86		54.30
49	5G0853687 2ZZ	1	PCS	69.99		69.99
50	5G0853675A JZQ	1	PCS	61.93		61.93
51	5G0853675APCWB	1	PCS	57.75		57.75
52	5G0945087B	1	PCS	152.25		152.25
53	5G6807417APGRU	1	PCS	1,149.75		1,149.75
54	5G0998492 GRU	1	PCS	32.19		32.19
55	5G0919491	2	PCS	14.70		29.40
56	5G0919491A	1	PCS	14.70		14.70
57	5G0919492A	1	PCS	14.70		14.70
58	5G0807305B	1	PCS	725.80		725.80

Service Order Confirmation

SERVICE ORDER NO: 18IP1553

CUSTOMER NO.: CV034371

CUSTOMER NAME: LIM TOW NAN

TELEPHONE NO.:

ADDRESS: 480 SEMBAWANG DRIVE #07-457

Singapore

VEH No.: SLD9445C

Order Date: 06/18/18

Reg Date: 06/30/16 KM: 44,541

VIN NO.: WWWZZZAUZGW075252 ENGINE NO:

SA: Tang Shu Shi

MODEL: GOLF A7 1.4 CL 92 (DSG) EQP MODEL NO.: 5G13HZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	5G6807863A BUMPER CENTRE BRACKET	1	PCS	67.06		67.06 ?
60	5G6807393A TAILLIGHT LOWER BRACKET LH	1	PCS	36.45		36.45 ?
61	5G6807394A TAILLIGHT LOWER BRACKET RH	1	PCS	36.45		36.45 ?
62	5G6807393 BUMPER SIDE BRACKET LH	1	PCS	36.45		36.45 ?
63	5G6807394 BUMPER SIDE BRACKET RH	1	PCS	36.45		36.45 ?
64	WHT005263 POP-RIVET	6	PCS	1.69		10.14 ne
65	5G6253609P REAR SILENCER	1	PCS	1,351.17		1,351.17 ?
66	1K0253141R CLAMP	1	PCS	74.88		74.88 ?

Remarks : AIG DIRECT SETTLEMENT

DOA: 17/06/2018

TP VEHICLE: SDQ2777S

SURVEY BY:

TOTAL	38,556.85
GST AMOUNT	2,698.98
TOTAL AMOUNT	41,255.83

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT