




REP.

Special Instruction:

ASS REC BY:



ASSIGNMENT (Office)

Survivor:
MWS

From (Person):

Joanne Yong

of

FCT

Date/Time:

19/6/18 @ 5:07pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 1677Y

Insured:

SHB 6667G

at Workshop m/s

Cycle & Carriage Fulco Motor

Tel: 6594 9163 / 9179 2566

of

330 Ubi Road 3

Policy No:

Claim No:

D18004767MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

21.06.2018 @ 10am

H.O.D. Endorsement:

Date/Time:

5:14pm @ 19/6/18

Person Contacted:

Mars Jer

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (☒ Estimate

SLE 1677Y - X

SHB 6667G - CC3 / AIG 09022500 / Dn / k2

DOA: 21/06/2018

22/6/18

Revert thru email.

08/11/13 wel

ASS. REC. BY: MORIS

REF:

Ref

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 1677Y

at Workshop n/s C & C Wom

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 99k.

IPAC Accident Report: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lump Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE 1677Y Yr Regn: Y 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: mit outlander cc 2360

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 28841 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYXTGF3W67004194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 7 mm

L/Bal: 7 mm

D.O.A. 15/6/18

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A 63518

RECEIVED 25 JUL 2018

u/7/18 cont. work f. val by 10813 with moris-ker

Red: \$ 9563.00, 471.

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. \$ _____

Photos: 857

Others: 367/18

TOTAL

10x15 = 150

170 + 150

50

50 + 50

100

574

Report Format: TD

Lump Sum / I.B.I. (\$) 10813

MOTOR SURVEY ASSIGNMENT

Date	18-06-2018	Our Ref No. D18004767MFSH
Accident Date	15-06-2018	Claim Type. Third Party
Insured Vehicle	SHB6667G	Third Party Vehicle. SLE1677Y
Survey Location	330 UBI ROAD 3	
Contact Person.	MARS LER	
Contact No.	65949163/ 91792566	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE - FULCO MOTOR DEALER PTE LTD - (SERVICE)	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241494)



PRI Documents



Close



PRI Header Details

Claim No	D18004767MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYCLE & (DEALER PTE L
Workshop Name	CYCLE & CARRIAGE - FULCO MOTOR DEALER PTE LTD - (SERVICE) (Contact Person : MARS LER)	Survey Location & Contact Details	330 UBI ROAD 3 Mobile: 91792566 , Phone: 65949163 , Fax: 0 EmailId: MARS.LER@CCFULCO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHB6667G	TP Vehicle No	SLE1677Y
PRI Recieved Date	18-06-2018 03:23:21 PM	Surveyor Appointed Date	19-06-2018 05:06:14 PM	Surveyor Accept Date	19-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	19-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004767MFSH

Our Ref: CS/FCI18011132/Urd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 2344Y.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.06.2018 at the premises of M/s DING AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>20,305.00</u>
Revised Estimate Amount	: S\$ <u>7,296.00</u>
"Check" Items Amount	: S\$ <u>11,650.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
MARCUS
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/06/2018 11:15
Date Of Accident	15/06/2018 10:30
Exact Location Of Accident	ORCHARD ROAD TOWARDS GRANGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1677Y
Insured/Policyholder	
Name Of Registered Owner	CPJ ACCOUNTING SERVICES LLP
Co Reg No	T16LL0923A
Email Address	CINDYCHEW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96211938
Alternative Phone No	OFFICE-96211938

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	OUTLANDER-2.4 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100474494-01000
Cover Note Number	

Driver

Name of Driver	CHEW JUN JIE
NRIC No	S9431081D
Date Of Birth	02/09/1994
Occupation	OUTDOOR
Date Of Driving Pass	29/09/2015
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98629178
Fax Number	
Contact Number	HOME-64539746
Email Address	CHEWJJ@LIVE.COM.SG

Address 6 JALAN IKAN MERAH SINGAPORE
 Postcode 578037
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1
 NAME: : CHEW SOR HUA
 GENDER: : FEMALE
 Passenger 2
 NAME: : CHEW JUN XIANG
 GENDER: : MALE
 Passenger 3
 NAME: : ADAM TAN YUE YANG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name THOMSON NPP 25 SIN MING ROAD
 Police Station Address ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS I WAS TRAVELLING ALONG ORCHARD ROAD TOWARDS GRANGE ROAD, I STOPPED WHILE WAITING TO TURN RIGHT, WHEN I SUDDENLY FELT AN IMPACT FROM BEHIND AND REALISED THAT VEHICLE B SHB6667G KNOCKED ONTO MY CAR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB6667G
 Vehicle Make/Model/Colour MERCEDES-BENZ WHITE

Details Of Properties

Vehicle Category

TAXI

Name of Driver

CHOO GUAN ANN

NRIC/Passport Number

S0060841F

Contact Number

90673302

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was travelling along Orchard Road towards Grange Road, I stopped while waiting to turn right, when I suddenly felt an impact from behind and realised that vehicle B SHB 6667G knocked into my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Handwritten signature

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Handwritten signature



NOTICE OF REPORTING

This is to inform that Chew Jun Jie, S9431081D (Name/ NRIC) 6 Jalan Ikan Merah Singapore 578037 (Address) 98629178 (Tel) has reported to the police a non injury traffic accident which had occurred somewhere along Orchard Road towards Grange Road on 15/06/2018 (Date) be about 1036 hrs (Time) involving the following vehicles:

- V1. SLE1677Y (Informant's vehicle, Mitsubishi Outlander, Brown)
V2. SHB6667G (Defendant's vehicle, Mercedes Benz, White)

V2 Driver's Particulars as follows :

Name : Choo Guan Ann

NRIC : S0060841F

Rank/Name of issuing officer: SGT T150185 Cheng Xinliang

Date: 15/06/2018

Time: 1246 hours

eSD reference: 08

Police Post/ Police Centre: (Thomson NPP)

Original - To be issued to complainant

Duplicate- To be submitted to Traffic Police

THOMSON NPP
300-4500000
#01-30
SINGAPORE 370011
TEL: 300-4500000



CONFIDENTIAL

CPJ Accounting Services LLP

WRITER'S NAME : Cindy Chew Sor Hua

DIRECT TEL : +65 9621 1938

DIRECT E-MAIL : cindychewsh@gmail.com

OUR REF : CPJ/ccsh/internal/16072016-03

YOUR REF :

BY HAND AND E-MAIL

16 July 2016

Chew Jun Jie
6 Jalan Ikan Merah
Singapore 578037

Dear Jun Jie

Letter of Appointment and Authorisation


You are hereby appointed as one of the assigned drivers for CPJ Accounting Services LLP ("the firm").

I, Chew Sor Hua, holder of NRIC S1688526F, Director of CPJ Accounting Services LLP, hereby authorise you, Chew Jun Jie, holder of NRIC S9431081D to drive the firm's vehicle of registration number SLE1677Y. You will be allowed to drive the vehicle of the firm until you receive a formal notice by the firm which supersedes this letter of appointment.

Do note that this letter also serves as an official authorisation to use the firm's vehicle.

Please feel free to contact me should there be any queries regarding the contents of this letter.

Yours sincerely,



Cindy Chew Sor Hua (Ms)

Founding Partner and Director

CPJ Accounting Services LLP

CPJ Accounting Services LLP
6 Jalan Ikan Merah Singapore 578037

CPJ Accounting Services LLP (UEN/Registration No. T16LL0923A) is registered in Singapore under the Limited Liability Partnership Act (Chapter 163A) with limited liability. A list of the partners and their professional qualification may be inspected at the address specified above.



HOTLINE TEL: (65) 6419-1000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M 2 300

MITSUBISHI COMMERCIAL AUTO PROTECTOR

CERTIFICATE NO. 2100474484-01000

(The above excess is subject to GST)
OWN DAMAGE EXCESS S\$3000.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SLE1677Y

2) NAME OF INSURED

CPJ Accounting Services LLP

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

12 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

11 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person provided he is in the insured's employ and is driving on their order or with their permission.
A Young and/or Inexperienced Driver Excess ("YIDER") of S\$3,000.00, in addition to the
Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said
Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or
has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from
driving the Motor Vehicle.

6) LIMITATION AS TO USE*

- 1) Use in connection with the insured's business.
 - 2) Use for the carriage of passengers (other than for hire or reward) in connection with the insured's business.
 - 3) Use for social, domestic or pleasure purposes.
- The Policy does not cover: a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing.
b) Use whilst towing a trailer except the towing of any one disabled mechanically propelled vehicle.

APPROVED REPORTING CENTRES / MITSUBISHI AUTHORISED REPAIRERS:

1. Cycle & Carriage Pandan Gardens Service Centre - 209 Pandan Gdns (Tel: 6568 4555)
2. Approved Reporting Centres / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)
3. Gomen Daigro Singh - 205 Braddell Rd (Tel: 63837118) 3. Elnaz - 30 Bukit Batok Cres (Tel: 6547777)
4. Bliss-Fu - 32 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)
6. Lat Hooi (Jing Hoo) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Maya Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)
8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 5 Bk D (Tel: 67476106)

LOSS OF USE Not Included

* NAMED DRIVER Chew Sor Hua

HMF PURCHASE COMPANY Goldbell Financial Services Pte Ltd
EMPLOYER'S LOAN

Employers (other than those mentioned in Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and
Section 80 of the Road Transport Act, 1987 (Malaysia)), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 17 Jul 2017

AIG Asia Pacific Insurance Pte. Ltd.

500722-050
CSC FULCO-CORPORATE
22 UBI ROAD 4
FULCO BUILDING
SINGAPORE 408617
ANSP-MOTOR

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCGUR

4251793



NRIC No. S1688526F



Date of Issue

21-07-2008

FOR C&C USE ONLY

Address

5 JALAN IKAN MERAH
SINGAPORE 578037

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1688526F



Name

CHEW SOR HUA

FOR C&C USE ONLY



Race

CHINESE

Date of birth

08-09-1965

Sex

F

Country of birth

SINGAPORE



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9431081D



Name

CHEW JUN JIE

周 健 杰

Race

CHINESE

Date of birth

07-09-1964

Sex

M

Country of birth

SINGAPORE

FOR C&C USE ONLY

9431081D

9431081D



IDC NO. S9431081D



DATE OF ISSUE
24-08-2009

FOR C&C USE ONLY


ISSUED TO
G. JAYAKUMAR MESSIAH
OPERATION 075037

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 29 Sep 2015

FOR C&C USE ONLY



Licence No: S9431081D

NP 428A

REPUBLIC OF SINGAPORE DRIVING LICENCE

S9431081D




CHOW JIE

Date of Birth: 02 Sep 1954

Expiry Date: 29 Sep 2015

FOR C&C USE ONLY



002477983G

SG
50

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Limited Liability Partnership
Owner ID:	0923A

Vehicle Details

Vehicle No.:	SLE1677Y
Vehicle to be Exported:	No
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.4 CVT AWD S/R FACELIFT

Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	4B12RR1744
Chassis No.:	JMYXTGF3WGW004194
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$23,289.00
Original Registration Date:	12 Jul 2016
First Registration Date:	12 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$24,605.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jul 2026
PARF Rebate Amount:	\$18,453.00

Intended COE Rebate Details

COE Expiry Date:	11 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$45,105.00
Total Rebate Amount:	\$63,558.00

The information contained herein is correct as at 21 Jun 2018

OK

Trade Online

Start with \$30 Trading Bonus*

USAN BOLT

OFFICIAL SPONSOR

XM

WWW.XM.COM

*T&Cs apply. Forex and CFD trading is high risk and can result in the loss of all your invested capital.

Read More

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Porsche Cayman 2.7A Tip.



Low Mileage, Engine Oil & Gear Box Full Servicing, New LED Rear Lamp / Battery. Direct Owner - StarAd

ABWIN

ONE-STOP

VEHICLE SOLUTIONS



VIEW OUR RANGE

Browse by Category

Sort by Date Posted


20 results/page

7 vehicles

Mitsubishi Outlander

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Outlander		Any	Any	2016	Any	Any	Any	Available
	Mitsubishi Outlander	2.4A Sunroof	\$104,333	\$11,010 /yr	10-Oct-2016	2,360 cc	12,000 km	SUV	Available
Quartz Brown Metallic Colour, About 1 And A Half Years Old As Of March 2018. Also Added Chrome Trimmings For Rear Bumper, Lights And Fuel Tank Door. Stainless Steel Door Sill Protectors. Mat For Inter...									
Posted: 20-Jun-2018 Tags: 2016 Mitsubishi Outlander, Mitsubishi Outlander, Mitsubishi, Outlander, Used Mitsubishi									
	Mitsubishi Outlander	2.4A Sunroof	\$99,800	\$11,000 /yr	13-Jun-2016	2,360 cc	45,000 km	SUV	Available
2016 Facelift Model With Better Looking Grills, Under Agent (C&C) Still Have Factory Warranty. Full AGT Service Till Date. Impeccable Condition Inside/Out. High Loan Available With High Trade In. Why ...									
Posted: 13-Jun-2018 Tags: 2016 Mitsubishi Outlander, Mitsubishi Outlander, Mitsubishi, Outlander, Used Mitsubishi									
	Mitsubishi Outlander	2.4A Sunroof	\$108,800	\$11,690 /yr	05-Sep-2016	2,360 cc	38,000 km	SUV	Available
Hua Yang Group Since 1984 Iso9001:2000 Certified, Bank Loan, In House Loan, Balloon Scheme, 100% Loan Available! Attractive Interest Rate! Cheapest In The Market! 7 Seaters Sunroof Cavernous SUV. 5 Ye...									
Hua Yang Credit Pte Ltd									
Posted: 10-Jun-2018 Tags: 2016 Mitsubishi Outlander, Mitsubishi Outlander, Mitsubishi, Outlander, Used Mitsubishi									
	Mitsubishi Outlander	2.4A Sunroof	\$103,800	\$11,260 /yr	11-Aug-2016	2,360 cc	29,000 km	SUV	Available
Best 7 Seater SUV On The Market! 10 Year Engine Warranty And Fully Maintained By Agent Cycle & Carriage! 1 Owner Unit, Flexible In House Financing Package And Trade In Available, Price Negotiable, Vie...									
Supreme Cars Pte Ltd									
Posted: 08-Jun-2018 Tags: 2016 Mitsubishi Outlander, Mitsubishi Outlander, Mitsubishi, Outlander, Used Mitsubishi									
Car Buying	Car Selling	Car Ownership	Buying a pre-owned car, but Unsure of its Condition?						
Car Aftermarket	On The Move	Lifestyle	Get, STA Car Evaluation						
	Mitsubishi Outlander	2.4A Sunroof	\$97,822	\$11,120 /yr	30-Mar-2016	2,360 cc	40,000 km	SUV	Available
Latest Addition! 2016 Facelift Model With Better Looking Grills, Added Chrome Finishings Etc. Under Agent (C&C) 5Yrs Factory Warranty & 10Yrs Engine Warranty. Full AGT Service Till Date. Best Color Co...									
Posted: 26-May-2018 Tags: 2016 Mitsubishi Outlander, Mitsubishi Outlander, Mitsubishi, Outlander, Used Mitsubishi									
	Mitsubishi Outlander	2.4A Sunroof	\$100,888	\$10,630 /yr	04-Oct-2016	2,360 cc	50,000 km	SUV	Available
Sexy Pearl White Paintwork With Black Interior. 2016 Facelift Model With Better Looking Grills, Under Agent (C&C) Still Have Factory Warranty. Full Agent Service Till Date. Impeccable Condition Inside...									
Posted: 16-May-2018 Tags: 2016 Mitsubishi Outlander, Mitsubishi Outlander, Mitsubishi, Outlander, Used Mitsubishi									

Compare

PREMIUM AD

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CPJ ACCOUNTING SERVICES LLP 6 Jalan Ikan Merah Thomson Park Singapore 578037	Cust No/Name /Cpj Accounting Services Llp Reg No/Reg Date SLE1677Y*1F / 12/07/2016 Date In/Mileage 16/06/2018/ 0 Chassis No JMYXTGF3WGZ004194 Engine No 4B12RR1744 Make/Model MIT/GF3WG43 Colour/Trim C00 / BK
Contact No Mobile: 96211938	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/06/2018/ 13:42	DS	218 / MarsLer	59481
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	SUNDRY C & C LOGO			ner	35.00 ✓
M	SUNDRY MIVEC EMBLEM			ner	45.00 ✓
S	MIPNT88088 REVERSE SENSOR SET			shad	280.00 ✓
S	MIPNT88088 TO REPLACE REVERSE CAMARE LEN			11	350.00 X
S	MIPNT88088 REAR NUMBER PLATE WITH CASING			34	50.00 ✓
S	MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS			60	80.00 ✓
S	MIPNT88088 TO PERFORM COMPUTERIZE SCANNING & DIAGNOSTIC -RESET AUTO TAILGATE FUNCTION				250.00 ✓
S	MIPNT88088 TO REPLACE TAILGATE GLASS				300.00 ✓
S	MIPNT88088 SEALANT KIT ON TAILGATE GLASS			ner	100.00 ✓
S	MIPNT88088 TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS			AN	220.00 X
S	MIPNT88088 TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS			300	600.00
S	MIPNT88088 TO REPLACE REAR BUMPER, REINFORCEMENT, TAILGATE PANEL, ETC -CUT & RE-WELD REAR END PANEL -TO REPAIR FLOOR PAN STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS			3000.	3600.00
S	MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL			200	300.00
S	MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS			2100	2940.00

not authorized
Tel: 62563561
Take photo before party.
21/6/18
7dy.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE 330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CPJ ACCOUNTING SERVICES LLP 6 Jalan Ikan Merah Thomson Park Singapore 578037	Cust No/Name /Cpj Accounting Services Llp Reg No/Reg Date SLE1677Y*1F / 12/07/2016 Date In/Mileage 16/06/2018/ 0 Chassis No JMYXTGF3WGZ004194 Engine No 4B12RR1744 Make/Model MIT/GF3WG43 Colour/Trim C00 / BK
Contact No Mobile: 96211938	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSMO0001	Cash	16/06/2018/ 13:42	DS	218 / MarsLer	59481
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M JJ6410D243	FACE, RR BUMPER W/FL	1.00	873.00	0.00	873.00
P JJMU488006	CLIP,RR BUMPER	10.00	2.00	0.00	20.00
P JJMR200300	CLIP, RR BUMPER	10.00	2.00	0.00	20.00
M JJ6410D336	LH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
M JJ6410D337	RH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
M JJ6410B895	LH REINFORCEMENT,RR	1.00	78.00	0.00	78.00
M JJ6410B896	RH REINFORCEMENT,RR	1.00	78.00	0.00	78.00
M JJ6415A061	EXTENSION, RR BUMPER	1.00	230.00	0.00	230.00
M JJ6512A681	INNER CLIP, RR BUMPER	11.00	3.00	0.00	33.00
M JJ8336A153	LH REFLECTOR, TAIL L	1.00	99.00	0.00	99.00
M JJ8337A138	RH REFLECTOR, TAIL L	1.00	94.00	0.00	94.00
M JJ8330B173	LH LAMP ASSY, COMBIN	1.00	594.00	0.00	594.00
M JJ8330B174	RH LAMP ASSY, COMBIN	1.00	594.00	0.00	594.00
P JJ8331A179	LH TAIL LAMP ASSY	1.00	501.00	0.00	501.00
M JJ8331A180	RH TAIL LAMP ASSY	1.00	501.00	0.00	501.00
P JJ5801B675	PANEL ASSY, TAILGATE	1.00	924.00	0.00	924.00
M JJ5808A135	LATCH, TAILGATE	1.00	470.00	0.00	470.00
M JJ5813A149	MOTOR,POWER TAILGATE	1.00	1966.00	0.00	1966.00
M JJ5813A079	LH SENSOR, TAILGATE	1.00	422.00	0.00	422.00
M JJ5813A078	RH SENSOR, TAILGATE	1.00	422.00	0.00	422.00
M JJ8637A114	BUZZLER,WARNING	1.00	0.00	0.00	0.00
P JJ5802A601	LH GAS SPRING, TAILG	1.00	196.00	0.00	196.00
P JJ5802A602	RH GAS SPRING, TAILG	1.00	196.00	0.00	196.00
M JJ5815A067	WEATHERSTRIP, TAILGA	1.00	211.00	0.00	211.00
P JJ5805A306	GLASS,TAILGATE WINDO	1.00	743.00	0.00	743.00
M JJ5805A316	UPR DAM,TAILGATE	1.00	12.00	0.00	12.00
M JJ5805A317	LWR DAM,TAIL GATE	1.00	41.00	0.00	41.00
M JJ5805A315	SIDE DAM,TAILGATE	2.00	27.00	0.00	54.00
M JJMR462285	STOPPER,WINDSHIELD G	2.00	3.00	0.00	6.00
M JJMB814447	FASTENER,WINDSHIELD	4.00	6.00	0.00	24.00
M JJ5817A265YB	GARNISH,TAILGATE	1.00	489.00	0.00	489.00
M JJ7415A401	MARK,OUTLANDER	1.00	94.00	0.00	94.00
M JJ5257A879	PANEL,RR END	1.00	235.00	0.00	235.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CPJ ACCOUNTING SERVICES LLP 6 Jalan Ikan Merah Thomson Park Singapore 578037 Contact No Mobile: 96211938	<table> <tr> <td>Cust No/Name</td><td>/Cpj Accounting Services Llp</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLE1677Y*1F / 12/07/2016</td></tr> <tr> <td>Date In/Mileage</td><td>16/06/2018/ 0</td></tr> <tr> <td>Chassis No</td><td>JMYXTGF3WGZ004194</td></tr> <tr> <td>Engine No</td><td>4B12RR1744</td></tr> <tr> <td>Make/Model</td><td>MIT/GF3WG43</td></tr> <tr> <td>Colour/Trim</td><td>C00 / BK</td></tr> </table>	Cust No/Name	/Cpj Accounting Services Llp	Reg No/Reg Date	SLE1677Y*1F / 12/07/2016	Date In/Mileage	16/06/2018/ 0	Chassis No	JMYXTGF3WGZ004194	Engine No	4B12RR1744	Make/Model	MIT/GF3WG43	Colour/Trim	C00 / BK
Cust No/Name	/Cpj Accounting Services Llp														
Reg No/Reg Date	SLE1677Y*1F / 12/07/2016														
Date In/Mileage	16/06/2018/ 0														
Chassis No	JMYXTGF3WGZ004194														
Engine No	4B12RR1744														
Make/Model	MIT/GF3WG43														
Colour/Trim	C00 / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/06/2018/ 13:42	DS	218 / MarsLer	59481

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P JJ7407A318 RH MOULDING, RR BUMP	1.00	105.00	0.00	105.00
P JJ7407A317 LH MOULDING, RR BUMP	1.00	105.00	0.00	105.00
M JJ7407A303 LH MOULDING, RR WHEEL	1.00	197.00	0.00	197.00
M JJ7407A304 RH MOULDING, RR WHEEL	1.00	197.00	0.00	197.00
M JJ8637A176 BUZZER, KEYLESS OPER	1.00	90.00	0.00	90.00
P JJ8637B115 ANTENNA, KEYLESS OPE	1.00	95.00	0.00	95.00
M JJ7240A229XA TRIM, RR END	1.00	122.00	0.00	122.00

Z NOTES

ACCIDENT ON 15/06/2018 ALONG ORCHARD ROAD TOWARDS GRANGE ROAD

OWNER CLAIMING THIRD PARTY

REQUIRED REPLACEMENT CAR

TP # SHB6667G TP INS

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	11,155.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,070.00
Others(Lub,etc)	0.00
Sundry	80.00
Total(w/o GST)	20,305.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Cpj Accounting Services Llp
Contact No	Reg No/Reg Date SLE1677Y*1F / 12/07/2016
	Date In/Mileage 16/06/2018/ 0
	Chassis No JMYXTGF3WGZ004194
	Engine No 4B12RR1744
	Make/Model MIT/GF3WG43
	Colour/Trim C00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	02/07/2018/ 11:34	DS	218 / Marsler	59481

Description of Goods/ Services	Qty	Unit Price	Disc%	Amount
X JJMN170754 SWITCH,POWER TAILGAT	1.00	71.00	0.00	71.00
Z NOTES SUPPLEMENTARY ITEM				

Estimate

Confirm & accepted by

Supplementary

Authorized signatory and company stamp

Parts	71.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	71.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Cpj Accounting Services Llp Reg No/Reg Date SLE1677Y*1F / 12/07/2016 Date In/Mileage 16/06/2018/ 0 Chassis No JMYXTGF3WGZ004194 Engine No 4B12RR1744 Make/Model MIT/GF3WG43 Colour/Trim COO / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	10/07/2018/ 19:02	DS	218 / MarsLer	59481


Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY C & C LOGO				35.00
M SUNDRY MIVEC EMBLEM				45.00
S MIPNT88088 REVERSE SENSOR SET				280.00
S MIPNT88088 REAR NUMBER PLATE WITH CASING				50.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60.00
S MIPNT88088 TO PERFORM COMPUTERIZE SCANNING & DIAGNOSTIC -RESET AUTO TAILGATE FUNCTION				250.00
S MIPNT88088 TO REPLACE TAILGATE GLASS				300.00
S MIPNT88088 SEALANT KIT ON TAILGATE GLASS				100.00
S MIPNT88088 TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS				300.00
S MIPNT88088 TO REPLACE REAR BUMPER, REINFORCEMENT, TAILGATE PANEL, ETC -CUT & RE-WELD REAR END PANEL -TO REPAIR FLOOR PAN STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				3000.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				200.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				2100.00
X JJ6410D243 FACE, RR BUMPER W/FL	1.00	873.00	0.00	873.00
X JJMU48B006 CLIP, RR BUMPER	10.00	2.00	0.00	20.00
X JJMR200300 CLIP, RR BUMPER	10.00	2.00	0.00	20.00
X JJ6410D336 LH SIDE BRACKET, RR	1.00	12.00	0.00	12.00

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877		Cust No/Name	/Cpj Accounting Services Llp
Contact No		Reg No/Reg Date	SLE1677Y*1F / 12/07/2016
		Date In/Mileage	16/06/2018/ 0
		Chassis No	JMYXTGF3WGZ004194
		Engine No	4B12RR1744
		Make/Model	MIT/GF3WG43
		Colour/Trim	C00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	10/07/2018/ 19:02	DS	218 / MarsLer	59481

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X JJ64100337 RH SIDE BRACKET, RR	1.00	12.00	0.00	12.00
X JJ64108895 LH REINFORCEMENT, RR	1.00	78.00	0.00	78.00
X JJ64108896 RH REINFORCEMENT, RR	1.00	78.00	0.00	78.00
X JJ6415A061 EXTENSION, RR BUMPER	1.00	230.00	0.00	230.00
M JJ6512A681 INNER CLIP, RR BUMPER	11.00	3.00	0.00	33.00
M JJ8337A138 RH REFLECTOR, TAIL L	1.00	94.00	0.00	94.00
X JJ8331A179 LH TAIL LAMP ASSY	1.00	501.00	0.00	501.00
X JJ5808A135 LATCH, TAILGATE	1.00	470.00	0.00	470.00
M JJ5805A316 UPR DAM, TAILGATE	1.00	12.00	0.00	12.00
M JJ5805A317 LWR DAM, TAIL GATE	1.00	41.00	0.00	41.00
M JJ5805A315 SIDE DAM, TAILGATE	2.00	27.00	0.00	54.00
M JJMR462285 STOPPER, WINDSHIELD	2.00	3.00	0.00	6.00
M JJMB814447 FASTENER, WINDSHIELD	4.00	6.00	0.00	24.00
M JJ7415A401 MARK, OUTLANDER	1.00	94.00	0.00	94.00
X JJ5257A879 PANEL, RR END	1.00	235.00	0.00	235.00
M JJ5815A067 WEATHERSTRIP, TAILGA	1.00	211.00	0.00	211.00
X JJMN170754 SWITCH, POWER TAILGAT	1.00	71.00	0.00	71.00
M JJ5801B675 PANEL ASSY, TAILGATE	1.00	924.00	0.00	924.00

Z NOTES

ACCIDENT ON 15/06/2018 ALONG ORCHARD ROAD TOWARDS GRANGE ROAD
OWNER CLAIMING THIRD PARTY
LOSS OF USE 8DAYxS\$120.00 = S\$960.00
TP # SHB6667G TP INS :FIRST CAPITAL

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Parts	4,093.00
Labour	0.00
Standard Menu	0.00
Specialist Job	6,640.00
Others(Lub,etc)	0.00
Sundry	80.00
Total(w/o GST)	10,813.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011132/Urd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6667G	Veh. Inspected	SLE 1677Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004767MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI OUTLANDER (A)	c.c	2360	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JMYXTGF3WVGZ004194	Colour	BROWN	
Odometer	28841	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	DUNLOP	7 mm	
L/H Front Tyre	225/55 R18	DUNLOP	7 mm	
R/H Rear Tyre	225/55 R18	DUNLOP	7 mm	
L/H Rear Tyre	225/55 R18	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/06/2018	Inspection Date	21/06/2018	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1677Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	C&C LOGO (SN)	NECESSARY	35.00	35.00
1	MIVEC EMBLEM (SN)	NECESSARY	45.00	45.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	280.00
1	REAR NUMBER PLATE WITH CASING (SN)	BENT	50.00	50.00
1	SEALANT KIT ON TAILGATE GLASS (SN)	NECESSARY	100.00	100.00
1	FACE,RR BUMPER W/FL (SN)	DISTORTED	873.00	873.00
10	CLIP ,RR BUMPER (SN)	NECESSARY	20.00	20.00
10	CLIP,RR BUMPER (SN)	NECESSARY	20.00	20.00
1	LH SIDE BRACKET ,RR (SN)	BENT	12.00	12.00
1	RH SIDE BRACKET ,RR (SN)	BENT	12.00	12.00
1	LH REINFORCEMENT ,RR (SN)	BENT	78.00	78.00
1	RH REINFORCEMENT ,RR (SN)	BENT	78.00	78.00
1	EXTENSION ,RR BUMPER (SN)	DISTORTED	230.00	230.00
11	INNER CLIP, RR BUMPER (SN)	NECESSARY	33.00	33.00
1	LH REFLECTOR ,TAIL L (SN)	NOT NECESSARY	99.00	-
1	RH REFLECTOR ,TAIL L (SN)	SCRATCHED	94.00	94.00
1	LH LAMP ASSY ,COMBIN (SN)	NOT NECESSARY	594.00	-
1	RH LAMP ASSY ,COMBIN (SN)	NOT NECESSARY	594.00	-
1	LH TAIL LAMP ASSY (SN)	CRACKED	501.00	501.00
1	RH TAIL LAMP ASSY (SN)	NOT NECESSARY	501.00	-
1	PANEL ASSY ,TAILGATE (SN)	BADLY DENTED	924.00	924.00
1	LATCH ,TAILGATE (SN)	DENTED /JAMMED	470.00	470.00
1	MOTOR,POWER TAILGATE (SN)	NOT NECESSARY	1,966.00	-
1	LH SENSOR ,TAILGATE (SN)	NOT NECESSARY	422.00	-
1	RH SENSOR ,TAILGATE (SN)	NOT NECESSARY	422.00	-
1	BUZZER ,WARNING (SN) (NPA)	NOT NECESSARY	-	-
1	LH GAS SPRING ,TAILG (SN)	NOT NECESSARY	196.00	-
1	RH GAS SPRING ,TAILG (SN)	NOT NECESSARY	196.00	-
1	WEATHERSTRIP ,TAILGA (SN)	TWISTED	211.00	211.00
1	GLASS ,TAILGATE WINDO (SN)	NOT NECESSARY	743.00	-
1	UPR DAM ,TAILGATE (SN)	NECESSARY	12.00	12.00

Report Ref No. CS/FCI18011132/Urd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LWR DAM ,TAIL GATE (SN)	NECESSARY	41.00	41.00
2	SIDE DAM ,TAILGATE (SN)	NECESSARY	54.00	54.00
2	STOPPER ,WINDSHIELD G (SN)	NECESSARY	6.00	6.00
4	FASTENER ,WINDSHIELD (SN)	NECESSARY	24.00	24.00
1	GARNISH ,TAILGATE (SN)	NOT NECESSARY	489.00	-
1	MARK ,OUTLANDER (SN)	NECESSARY	94.00	94.00
1	PANEL ,RR END (SN)	BADLY DENTED	235.00	235.00
1	RH MOULDING ,RR BUMP (SN)	NOT NECESSARY	105.00	-
1	LH MOULDING ,RR BUMP (SN)	NOT NECESSARY	105.00	-
1	LH MOULDING ,RR WHEE (SN)	NOT NECESSARY	197.00	-
1	RH MOULDING ,RR WHEE (SN)	NOT NECESSARY	197.00	-
1	BUZZER ,KEYLESS OPER (SN)	NOT NECESSARY	90.00	-
1	ANTENNA,KEYLESS OPE (SN)	NOT NECESSARY	95.00	-
1	TRIM ,RR END (SN)	NOT NECESSARY	122.00	-
1	SWITCH ,POWER TAILGAT (ADDITIONAL) (SN)	CRACKED	71.00	71.00
			11,736.00	4,603.00
	LABOUR			
	TO REPLACE REVERSE CAMERA LEN .	NOT NECESSARY	350.00	-
	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.		80.00	60.00
	TO PERFORM COMPUTERIZE SCANNING & DIAGNOSTIC -RESET AUTO TAILGATE FUNCTION.		250.00	250.00
	TO REPLACE TAILGATE GLASS.		300.00	300.00
	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS.	NOT NECESSARY	220.00	-
	TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS .		600.00	300.00
	TO REPLACE REAR BUMPER ,REINFORCEMENT ,TAILGATE PANEL ,ETC-CUT & RE-WELD REAR END PANEL-TO REPAIR FLOOR PAN STRAIGHTEN ,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS.		3,600.00	3,000.00
	TO APPLY SEALANT KIT ON NEW PANEL .		300.00	200.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,940.00	2,100.00
			8,640.00	6,210.00

Report Ref No. CS/FCI18011132/Urd3q2



GRAND TOTAL		20,376.00	10,813.00
RECOMMENDED COST OF REPAIRS			10,813.00

Report Ref No. CS/FCI18011132/Urd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.