



FALCON-AIR

ONG CHEN HOON  
BLK335 CLEMENTI AVE2 #09-22  
SINGAPORE 120335

Attention : Motor Claim Department  
Contact : 91113963

Estimate : ES003204

Date : 19/06/2018  
Vehicle Num. : SGL2338S  
Make/Model : TOYOTA ALTIS  
Chassis/Eng# : MR053ZEC107130495  
Accident Date : 18/06/2018  
Claim No. :  
Reference : TP GE VS EQ  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOTLID		789.90 <i>bt</i>
2.	1	BOOTLID LOCK		61.20 <i>bt</i>
3.	1	BOOTLID WEATHERSTRIP		90.30 <i>cut</i>
4.	1	BOOTLID LOGO		30.30 <i>new</i>
5.	1	BOOTLID EMBLEM 1.6E		28.20 <i>new</i>
6.	1	BOOTLID EMBLEM VVTI		27.30 <i>new</i>
7.	1	BOOTLID EMBLEM COROLLA		28.20 <i>new</i>
8.	1	BOOTLID EMBLEM ALTIS		28.20 <i>new</i>
9.	2	BOOTLID LAMP LH/RH	85.60	171.20 <i>cut</i>
10.	1	BOOTLID CHROME		48.00 <i>cut</i>
11.	2	TAILLAMP LH/RH <i>- photo</i>	289.70	579.40 <i>cut</i>
12.	2	TAILLAMP LOWER PANEL LH/RH	88.30	176.60 <i>bt</i>
13.	1	REAR BUMPER		380.20 <i>de</i>
14.	2	REAR BUMPER BRACKET	37.30	74.60 <i>?</i>
15.	2	REAR BUMPER SIDE RETAINER LH/RH	86.60	173.20 <i>new</i>
16.	1	REAR END PANEL <i>- photo</i>		781.30 <i>bt</i>
17.	1	REAR END PANEL TOP GARNISH		85.00 <i>de</i>
List Total S\$ :				3,553.10
25.00% Discount S\$ :				888.28
				2,664.82

CONTINUE / ...

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

ONG CHEN HOON  
BLK335 CLEMENTI AVE2 #09-22  
SINGAPORE 120335

Attention : Motor Claim Department  
Contact : 91113963

Estimate : ES003204

Date : 19/06/2018  
Vehicle Num. : SGL2338S  
Make/Model : TOYOTA ALTIS  
Chassis/Eng# : MR053ZEC107130495  
Accident Date : 18/06/2018  
Claim No. :  
Reference : TP GE VS EQ  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	8	RIVETS	4.00	32.00 <i>3</i>
2.	1	REAR NUMBER PLATE		40.00 <i>30 cut.</i>
3.	1	REVERSE SENSOR		200.00 <i>mm</i>
Special Nett Total S\$ :				272.00
LABOUR :				
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				100.00 <i>40</i>
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS				150.00 <i>80</i>
TO TRANSFER BOOTLID PARTS/MECHANISMS				50.00 <i>40</i>
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS				1,300.00 <i>1000</i>
TO CUT/OUT REWELD REAR END PANEL, REPAIR SPARE TYRE PANEL, REAR CHASSIS, REAR FENDERS INCLUDES KNOCKING AND REPLACEMENT OF PARTS				950.00 <i>750</i>
Labour Total S\$ :				2,550.00

E. & O.E.

Total S\$ : 5,486.82



for FALCON AIR AUTO SERVICES PTE LTD

*Tanjin 97425749*  
*- WP*  
*20/6/18 @ 11am*  
*6-7 days*  
*Ready after repair.*  
*sur @ Ukanto.wm*

**FALCON-AIR AUTO SERVICES PTE LTD**

[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg