

Heng Sew Sow

From: Heng Sew Sow <woonmeng@singnet.com.sg>
Sent: Thursday, 12 July 2018 6:35 PM
To: 'Poh.Kin (LKKAUTO)'; 'SUR'
Cc: 'Hsiao Tong (LKKAUTO)'; 'Admin A'
Subject: RE: Our Ref: CC6/AIG18011146/fa3; Your Ref: YP 4160P

Dear Sir/madam

We refer to the above accident

Kindly arrange a surveyor to survey of vehicle YP4160P (13.07.18).

Location : 50, Bukit Batok St 23 # 01- 06 Midview Building (S) 659578

Thank you.

Woon Meng Motor Pte Ltd
Tel ; 63161131
Fax : 63167050

*cut rear corner panel (R)
R-4 U lamp in east (R)
cut U corner lamp (R)*

*labour — 150
wrap — X
today*

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Thursday, 28 June 2018 5:27 PM
To: Woon Meng <woonmeng@singnet.com.sg>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Our Ref: CC6/AIG18011146/fa3; Your Ref: YP 4160P

WITHOUT PREJUDICE

Our Ref: CC6/AIG18011146/fa3
Your Ref: YP 4160P

Dear Ms Heng,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SGS 8836U AND YP 4160P ON 19/03/2018

We refer to above matter and our tele-conversation on even date.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.