



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

|                         |                                                                                         |                     |                           |                           |                |
|-------------------------|-----------------------------------------------------------------------------------------|---------------------|---------------------------|---------------------------|----------------|
| <b>Customer</b>         | : AXA INSURANCE S'PORE PTE LTD<br>8 SHENTON WAY<br>#27-01 AXA TOWER<br>SINGAPORE 068811 | <b>Document No.</b> | : SQT18001935             | <b>Page</b>               | 1              |
| <b>Registration No</b>  | : SLE6412L                                                                              | <b>Date</b>         | : 11. May 2018            | <b>Customer No.</b>       | : WZA006       |
| <b>Chassis No</b>       | : JHMGK5850HX200110                                                                     | <b>Svc Advisor</b>  | : PATRICK MOK LIP KAY     | <b>Engine No</b>          | : L15B31190049 |
| <b>Model</b>            | : JAZZ 1.5VTIR CVT 17YM                                                                 | <b>Date   Time</b>  | : 11. May 2018 3:38:43 PM | <b>Surveyor Name</b>      | :              |
| <b>Owner's Name</b>     | : CHEAH PEI SHI                                                                         | <b>Survey Date</b>  | :                         | <b>Authorisation Date</b> | :              |
| <b>Ins Policy No.</b>   | :                                                                                       |                     |                           |                           |                |
| <b>Date of Accident</b> | : 2/5/2018                                                                              |                     |                           |                           |                |

| Item                   | Description                                                                                                                                                                                                  | Qty | Unit Price | Disc % | Amount         | 0% GST Amount | Amount incld GST |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|----------------|---------------|------------------|
|                        | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: CHEAH PEI SHI JENNIFER<br>OWNER INSURER: MSIG INSURANCE<br>ACC DATE: 02/05/2018<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: AXA INSURANCE<br>TP VEH: SHD9456T |     |            |        |                |               |                  |
| <b>BOSUN</b>           | SUNDRIES                                                                                                                                                                                                     | 1   | 50.00      |        | 50.00          | 3.50          | 53.50            |
| <b>BKBU01A</b>         | REMOVE & ALIGN FR BUMPER                                                                                                                                                                                     | 1   | 600.00     |        | 600.00         | 42.00         | 642.00           |
| <b>BP01R</b>           | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)                                                                                                                                                           | 1   | 500.00     |        | 500.00         | 35.00         | 535.00           |
| <b>Sum Labor</b>       |                                                                                                                                                                                                              |     |            |        | <b>1150.00</b> | <b>80.50</b>  | <b>1,230.50</b>  |
| <b>BO-NUM-COMP-L</b>   | NUMBER PLATE WITH CASING-L(N)                                                                                                                                                                                | 1   | 45.00      |        | 45.00          | 3.15          | 48.15            |
| <b>71145-T5A-000</b>   | BASEFR.LICENCE PLATE                                                                                                                                                                                         | 1   | 50.90      | 25     | 38.17          | 2.67          | 40.84            |
| <b>04711-T5A-000ZZ</b> | FACE,FR.BUMPER                                                                                                                                                                                               | 1   | 494.70     | 25     | 371.02         | 25.97         | 396.99           |
| <b>91505-TM8-003</b>   | CLIPBUMPER                                                                                                                                                                                                   | 17  | 2.00       | 25     | 25.50          | 1.79          | 27.29            |
| <b>Sum Item</b>        |                                                                                                                                                                                                              |     |            |        | <b>479.69</b>  | <b>33.58</b>  | <b>513.27</b>    |

Survey By

Date & Time

Excess

Status

Signature

**Total Amount** 1,629.69 114.08 1,743.77

**Total (Inclusive of GST)** 1,743.77

Printed on 11/5/2018 4:25:32 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from Individual line(s)