

REPAIR ESTIMATE

VEHICLE NO : SHD 7205P

19/6/2018 12:35

MAKE :

MODEL : TOYOTA PRIUS

Like/Kalvin phyP
Like AIG

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR BUMPER <i>x 1 pc</i>			\$ 458.60	
REAR BUMPER SIDE RETAINER <i>x</i>			\$ 112.70	
REAR BUMPER CLIPS <i>x</i>			\$ 22.00	
RETAINER, REAR BUMPER, SIDE, RH <i>x</i>			\$ 94.80	
SEAL, REAR BUMPER SIDE, RH <i>x</i>			\$ 148.40	
<i>rear RH Fender x 1 pc</i>				
SUB TOTAL			\$ 836.50	
LESS 25%			\$ 209.13	
DISCOUNTED TOTAL			\$ 627.38	
REAR BUMPER RUBBER MAT <i>x</i>			\$ 50.00	NETT
LABOUR CHARGE				
Panel Beating			\$ 350.00 ²⁰⁰	
Spray Painting Charge			\$ 500.00	<i>400</i>
Wiring Charge			\$ 50.00	<i>x</i>
Remove/Refix Reverse Sensor			\$ 120.00	<i>x</i>
TOTAL LABOUR			\$ 1,020.00	
ESTIMATE TOTAL			\$ 1,697.38	

Kalvin (K)
19/6/18 1345L.
2 B,
PIP
After Repair p Lt.

Like Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.