

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 765A**AAD1806-135**

Not Authored
Resurvey by painting @ 1854.78

Vehicle No.:	SHF 765A
Chassis No.:	VF1ABL15AUC283219
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	16.6.2018
Third Party Insurer :	AIG

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bulldozer</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>SL</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>SL</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>SL</i> 1,479.46
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	AIR CLEANER BOX	\$	<i>SL</i> 464.20
1	AIR CLEANER HOSE	\$	<i>SL</i> 175.85

Trans-cab Auto Services Pte Ltd

AAD1806-135

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 765A

1	LOWER ARM LH L70Y	\$	<i>Sm</i> 685.76 X
1	KUNCKLE ARM LH L70Y	\$	<i>Sm</i> 846.98 X
1	ABSORBER FRT LH L70Y	\$	<i>Sm</i> 360.54 X

TOTAL	\$	20,784.28
10%	\$	2,078.43
	\$	18,705.85

Specical Nett

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00
1SET	WHEELARCH CLIP FRT RH	\$	<i>Sm</i> 30.50
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nn</i> 80.00
1	FRONT DOOR STICKER 'Chassis'	\$	<i>nn</i> 50.00
1	FRONT RIGHT TYRE	\$	<i>Sm</i> 380.00

TOTAL	\$	818.00
--------------	-----------	---------------

TOTAL PARTS	\$	19,523.85
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,500.00 *4401*

Putty and spray painting of the affected portion.

\$ 3,000.00 *2001*

To rust-proofing of the affected areas.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 765A

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>15/</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 <i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 <i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	8,710.00
--------------	-----------	-----------------

Over All Total	\$	28,233.85
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: