

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : ET SOUND ENTERPRISE PTE LTD

Singapore

ATTN:

Your Ref No: 18/FC/TP-126 (06)

Claim Type: Third Party

Accident Date: 17/06/2018

TP Veh Reg No: SHC3348S

Estimate No: EST0004183

Date: 18 Jul 2018

Policy No: GA57308/1

Veh Reg No: SKQ1688P

Make/Model: LEXUS ES250

Chasis No: JTHBJ1GG402061725

Engine No: 2ARE896731

Reg. Date: 29/08/2014

Estimate Repair Cost to Vehicle No :SKQ1688P

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
List Price			
1 FRT LH DOOR TOP STICKER <i>see</i>	1 PC	80.00	<i>see</i>
2 REAR LH DOOT TOP STICKER <i>see</i>	1 PC	80.00	
		160.00	
	Less 10%	16.00	144.00
Total			S\$ 144.00
GST Amount			S\$ 10.08
Total Amount Payable			<u>S\$ 154.08</u>

For SME Motor Pte Ltd

AUTHORISED SIGNATURE