



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

ERGO INSURANCE PTE LTD

Ref: CS3/EGI18011289/Vz4d3e2

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER
FIVE SINGAPORE 038985

Date: 02-07-2018



Code: EGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 5814E	Veh. Inspected	XD 2918J
Policy No.		Coverage (\$)	0.00
Claim No.	XD2918/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	21/06/2018

2. Vehicle Particulars & Condition


Make & Model	ISUZU CYZ52L	c.c	15681
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JALCYZ52L87000079	Colour	YELLOW
Odometer	377425 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	AUFIN	6 mm
L/H Front Tyre	295/80 R22.5	AUFIN	6 mm
R/H Rear Tyre	295/80 R22.5	AUFIN	6 mm
L/H Rear Tyre	295/80 R22.5	AUFIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5. General Information

Accident Date	19/06/2018	Inspect Date / Time	27/06/2018 (03:28 PM)
Survey held at	SHINGDA GROUP - 10 KRANJI CRESCENT		
Repairer	-		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$10,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/EGI18011289/Vz4d3e2

Inspected By

SATHYA SAI KATHIRASEN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.