

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

20/06/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SGR8117S

Veh Model :- MERCEDES BENZ B170

Estimate# :- CK417591

Claim # :-

ACC. Date :- 17/06/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT BONNET	1 PC	1,550.00	bt 1,550.00
2.	FRONT BONNET LOGO CLIPS	2 PC	8.00	nei 16.00
3.	FRONT BONNET LOCK	1 PC	210.00	X 210.00
4.	FRONT GRILLE LOGO	1 PC	170.00	ave 170.00
5.	FRONT HEADLAMP L+R LH- ? 1 RH-cng ✓	2 PC	980.00	1,960.00
6.	FRONT BUMPER CLIPS	10 PC	5.00	nei 50.00
7.	FRONT BUMPER RIVET	10 PC	4.00	nei 40.00
8.	FRONT BUMPER	1 PC	1,140.00	ol 1,140.00
9.	FRONT BUMPER TOW COVER	1 PC	75.00	Ry 75.00
10.	FRONT BUMPER RETAINER RH	1 PC	38.00	nei 38.00
11.	FRONT BUMPER PROTECTOR CHROME L+R	2 PC	130.00	nei 260.00
12.	FRONT BUMPER INSERT CENTRE	1 PC	174.00	? 174.00
13.	FRONT BUMPER INSERT RH	1 PC	114.00	? 114.00
14.	FRONT FOG LAMP COVER WITH CHROME L+R	2 PC	125.00	X 250.00
15.	FRONT BUMPER GARNISH	1 PC	95.00	? 95.00
16.	FRONT REINFORCEMENT	1 PC	850.00	? 850.00
17.	FRONT REINFORCEMENT SPONGE	1 PC	110.00	? 110.00
18.	FRONT AIR BAFFLE	1 PC	270.00	? 270.00
19.	FRONT PLUG FASTENER L+R	2 PC	15.00	nei 30.00
20.	FRONT PLUG FASTENER RUBBER	2 PC	30.00	nei 60.00
21.	FRONT FENDER RH	1 PC	580.00	bt 580.00
22.	FRONT SUPPORT PANEL	1 PC	950.00	X 950.00
23.	REART BUMPER - REPAIR	1 PC		
24.	FRONT RADIATOR FAN GARNISH - CHECK	1 PC		
25.	FRONT RADIATOR FAN BLADE - CHECK	1 PC		
26.	FRONT RADIATOR FAN MOTOR - CHECK	1 PC		
27.	REAR REVERSE SENSOR - CHECK	1 PC		
28.	REAR REINFORCEMENT - CHECK	1 PC		
29.	REAR REINFORCEMENT SPONGE - CHECK	1 PC		
LIST TOTAL S\$				8,992.00
10% DISCOUNT S\$				-899.20
				8,092.80
SPECIAL NET ITEMS :				
1.	REAR BUMPER PROTECTOR STEEL BLADE	1 PC	220.00	X 220.00
2.	NUMBER PLATE	1 PC	60.00	bt 60.00 45
SPECIAL NET TOTAL S\$				280.00
LABOUR :				
TO REMOVE & REPLACE ACCIDENT AFFECTED AREAS AND REALIGN AND STRAIGHTEN ACCIDENT AFFECTED AREAS				700 850.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				700 950.00
TO RUST PROOF AFFECTED AREAS				30 60.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

20/06/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- **XA025**

Page # :- 1 131863
Veh # :- SGR8117S
Veh Model :- MERCEDES BENZ B170
Estimate# :- CK417591
Claim # :-
ACC. Date :- 17/06/18
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST			30 40.00
	LABOUR TOTAL S\$			1,900.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 10,272.80

GST @ 7 % 719.10

AMOUNT DUE S\$ 10,991.90

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tanjah 97495749
'wr'

26/6/18 1310.

Resurvey before paint
sur@lkkauto.com
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: