



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : RICHARD ANG			Ref: CS3/ASM18011300/Aes3e2 Date: 01/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 5984L	Veh. Inspected	SLV 3483L	
Policy No.	GA113215/1	Coverage (\$)	0.00	
Claim No.	S8M00KVS	Excess (\$)	0.00	
Assign From	RICHARD ANG	Assign Date	21/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	AGH300154151	Colour	BLACK	
Odometer	13788 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	TOYO	6 mm	
L/H Front Tyre	235/50 R18	TOYO	6 mm	
R/H Rear Tyre	235/50 R18	TOYO	6 mm	
L/H Rear Tyre	235/50 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.				
5. General Information				
Accident Date	13/06/2018	Inspect Date / Time	21/06/2018 (10:44 AM)	
Survey held at	UNITED SG AUTOMOBILE PTE LTD 53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Report Ref No. CS3/ASM18011300/Aes3e2

Inspected By

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.