

950000

INS. CASE OWNER:

Winnie

CC 4 ASM 1703, R1/Ph2
1801

LKK
IDAC

Surveyor:

Rasul

DOE:

ASSIGNMENT

10/9/18

Date / Time:

2/6/18

Registered in Meritmen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJM 3167X

Claim No.:

SBM00K16 / 5296

Name of Insured:

MOHAMED ABU BAKER MOHAMED ELYAS

Policy No.:

PM40528

Insured Tel No.:

HP: 96851056

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A: 11/6/18

Place of Accident:

LTE

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT (YES / NO) / TP GIA REPORT (YES / NO)

Insured Liability: %

Final? Yes / No

SJX 32618



INSRS: WSP: Tel: Liability: RMKS:

Charv's Customcraft



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time

2/6/18
LMT

SJX 3167X - 7
* amendment
28/6/18 @ 4:20pm Called OI, Mr Mohamed confirm accident. He changed lane & collided with TP. Inform TP claim & aware NCO issue.
28/6/18 - TP video uploaded in Smax
2/7/18 - AXA video PS.
24/6 - R - seek mandate of #2877.50 (pending approval) - approved.
24/6 - offer G/S \$2870.00 (pending acceptance).
24/6 - settle @ G/S \$2870.00. DV send (pending DV in)
13/19 - DV in (file pass admin. to close)

STAGE	DATE / PIC	
Non-Reporting Itr (1st)		
Non-Reporting Itr (2nd)		
Non-Reporting Itr (Final)		
Notification Itr (if non-pickup)		
Call OI	28/6/18	
After call Itr to OI		
Documentation Check List:	Handler Typist	
Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
After call Itr to OI	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LTA / GIA: Andatex	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PIR	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Others:	<input checked="" type="checkbox"/>	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with:

Repair Cost: \$5 1950.00 (5 days) Reduction: 2623.42 = 50

FINAL SETTLEMENT Date/Time: 25/6/17 10:38 Confirming with: Sharon

Final Liability: \$ 100 (Agreed / Assessed) BOLA S/N No.: 15.

Repair Cost: (W/AST) \$5 2026.50

Loss of Rental (LOR): \$5 249.00 (7 days) x 6107.00 (W/AST)

Loss of Use (LOU): \$5 - (5 days)

Loss of Income (LOI): \$5 - (5 days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5 42.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/Independent)

Legal Cost: \$5 -

Confirm by: Rasul

Email Call

If NO or B 28, Ass. Lia:

2/7/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 9P

3) Survey fee: \$350.00

Total: \$5 2822.50 Global Sum \$5: 2870.00

FINAL PAYMENT Date/Time: Confirm with:

Payee 1: \$5 2870.00 Name 1: Charv's Customcraft

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

Email Call

REF: 25740

REF: P


REF: 25740

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJX 3261X
 at Workshop m/s: CHARN'S CUSTOMCRAFT
 of: 1010, BUKIT MERAH #61-605
 Insured: AXA
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJX 32612 Yr Regn: 2010 / Jun
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HONDA CIVIC 1-6L cc: 1595
 Colour: GRN A/C: Insured / Std / NI / NA
 Sp Reading: 151773 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Cr/No: JHMP046209S200703
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Harder / Jammed / Leaked / Burnt or
 Brake: Harder / Jammed / Leaked / Burnt or
 Modi: Nil / R/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS: RUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 11/06/18 D.O.I: 10/07/18
 Survey held at: CHARN'S CUSTOMCRAFT
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
R/S FR & N/S CRASH
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition) 3pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 25K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lump Sum: 30 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>1/5 \$1950/- w/m 5 repair days-</u>
	<u>(Pod = \$2443 40 / 50%)</u>

* 5 repair days + 1 Sunday + 1 PRS = 7 days.

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 \$ + RS _____
 Photos: _____
 Other: _____
 TOTAL: _____

Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18011303/pb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 21-06-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 3167X	Veh. Inspected	SJX 3261Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/06/2018	Inspection Date	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Charn's Customcraft
1010 Bukit Merah Lane 3
Singapore 159724

Claim Reference:
Assessment Number: CC000002
Version: CHARNCUS/1
Date Calculated: 20/06/2018 08:18

Full Report - V1
Registration: SJX3261Z
Printed: 20/06/2018 15:19

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Sharon Lee	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SJX3261Z
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM MODEL 2010	AIR CONDITIONING
RADIATOR DENSO	FOG LAMPS
HEADLAMP WASHERS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	LEATHER STRG WHEEL
RR PARK DIST CONTROL	1.6 LTR 92KW VTEC
HYDRAULIC SERVO	TYRES 205/55 VR 16
WHEELS 6.5J X 16 ALU	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	20/06/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

Charn's Customcraft

Claim Reference:
 Assessment Number: CC000002
 Version: CHARNCUS/1
 Date Calculated: 20/06/2018 08:18

Full Report - V1
 Registration: SJX3261Z
 Printed: 20/06/2018 15:19



Primary Impact →
 Secondary Impact - - - - - →

Addresses

Cost Summary

Total Labour	\$1,827.00
Total Paint/Material	\$274.06
Total Parts	\$2,232.36
Total of Additional Costs	\$60.00
Excess:	TBA
Grand Total Exc GST:	\$4,393.42
7 % GST:	\$307.54
Grand Total Inc GST:	\$4,700.96

Repair Information

LABOUR

Time Basis 10 WU = 1 HR, Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
42700-SNA)	R + R LEFT FRONT WHEEL	2.0	9.00
42700-SNA)	FIT AND BALANCE LEFT FRONT TYRE (WHEEL REMOVED)	5.0	22.50
NN	FRONT BUMPER R&R / NEW PARTS	25.0*	112.50
NN	L/F HEADLAMP CPL R&R / NEW PARTS	9.0*	40.50
NN	L/F WING R&R / NEW PARTS	15.0*	67.50
NN	L/DOOR MIRROR R&R / NEW PARTS	10.0*	45.00
NN	REAR BUMPER R&R / NEW PARTS	10.0*	45.00
1481	REPAIR LEFT FRONT DOOR	30.0*	135.00
1781	REPAIR L/R DOOR	20.0*	90.00
3481	REPAIR L/R SIDE PANEL	50.0*	225.00

LABOUR COST

Total Work Units	176.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	17.6HRS	\$792.00
Paint Labour	23.0HRS	\$1,035.00
Total Labour	40.6HRS	\$1,827.00

PAINT WORK

Time Basis 10 WU = 1 HR, Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC - PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	30.0*	
283	FRONT BUMPER NEW PART PAINT K1R	25.0*	

Charn's Customcraft

Claim Reference:
 Assessment Number: CC000002
 Version: CHARNCUS/1
 Date Calculated: 20/06/2018 08:18

Full Report - V1
 Registration: SJX3261Z
 Printed: 20/06/2018 15:19

1737	L/DOOR MIRROR NEW PART PAINT K1R	10.0*	
2583	REAR BUMPER NEW PART PAINT K1R	30.0*	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	30.0*	
1781	L/R DOOR REPAIR PAINTING >50%	30.0*	
3481	L/R SIDE PANEL REPAIR PAINTING >50%	75.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	230.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	230.0	
	Total Paintwork Labour	23.0HRS	\$1,035.00
MATERIAL COST - PAINT			
	New Part Painting		Cost Price \$23.22
	New Part Painting - Plastic K1R		\$125.94
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$87.30
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$274.06
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$274.06

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER	71101SNBG50ZB		0%	scd 195.00*
1737	1	L/DOOR MIRROR	76250SNBY21ZA		0%	repair 345.00*
561	1	L/F HEADLAMP CPL	33151SNBD51		0%	scd 190.00*
319	1	L/F UPP BUMPER BRKT	71190SNB000		0%	scd 10.00*
7201	1	L/F WHEEL	08W16TR0604	s/n 300	0%	scd 750.00* 300*
741	1	L/F WING	60261SNB000ZZ		0%	repair 160.00*
2619	1	L/R BUMPER BRACKET	71598SNAA01		0%	scd 13.00*
841	1	L/WHEELHOUSE SHELL	74151SNAA10		0%	scd 50.00*
2583	1	REAR BUMPER	71501SNB010ZB		0%	repair 195.00*
f:		OEM Parts	Sub Total			\$1,908.00
g:		Original	Mark Up From Cost	(15 %)		\$286.20
h:		Secondhand	Sundry Parts	(2 %)		\$38.16
p:		Parallel	Total Parts			\$2,232.36
x:		Exchange				

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
ALIGNMENT	0%	\$60.00
SPECIALIST		
Total Extras		\$60.00

Final Calculation

Total Parts		\$2,232.36
Labour		
Total Panel/Mechanical	\$792.00	
Total Paintwork	\$1,035.00	
Total Labour		\$1,827.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$60.00	
Total of Additional Costs		\$60.00

Claim Reference:
Assessment Number: CC000002
Version: CHARNCUS/1
Date Calculated: 20/06/2018 08:18

Full Report - V1
Registration: SJX3261Z
Printed: 20/06/2018 15:19

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Sharon Lee	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SJX3261Z
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM MODEL 2010	AIR CONDITIONING
RADIATOR DENSO	FOG LAMPS
HEADLAMP WASHERS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	LEATHER STRG WHEEL
RR PARK DIST CONTROL	1.6 LTR 92KW VTEC
HYDRAULIC SERVO	TYRES 205/55 VR 16
WHEELS 6.5J X 16 ALU	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition



Vehicle Status

Pre-Accident Condition: Steering:	Severity of Impact: Vehicle Status on Inspection:
Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:	Date of Inspection: 20/06/2018
Tyres Condition: Tread Depth LHF: Tread Depth LHR:	Tread Depth RHF: Tread Depth RHR:
Damage Areas:	Direction of Impact:

Charn's Customcraft

Claim Reference:
Assessment Number: CC000002
Version: CHARNCUS/1
Date Calculated: 20/06/2018 08:18

Full Report - V1
Registration: SJX3261Z
Printed: 20/06/2018 15:19



Primary Impact
 Secondary Impact

Addresses

Cost Summary

Total Labour	\$1,827.00
Total Paint/Material	\$274.06
Total Parts	\$2,232.36
Total of Additional Costs	\$60.00
Excess:	TBA
Grand Total Exc GST:	\$4,393.42
7 % GST:	\$307.54
Grand Total Inc GST:	\$4,700.96

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
42700-SNA)	R + R LEFT FRONT WHEEL	2.0	9.00
42700-SNA)	FIT AND BALANCE LEFT FRONT TYRE (WHEEL REMOVED)	5.0	22.50
NN	FRONT BUMPER R&R / NEW PARTS	25.0*	112.50
NN	L/F HEADLAMP CPL R&R / NEW PARTS	9.0*	40.50
NN	L/F WING R&R / NEW PARTS	15.0*	67.50
NN	L/DOOR MIRROR R&R / NEW PARTS	10.0*	45.00
NN	REAR BUMPER R&R / NEW PARTS	10.0*	45.00
1481	REPAIR LEFT FRONT DOOR	30.0*	135.00
1781	REPAIR L/R DOOR	20.0*	90.00
3481	REPAIR L/R SIDE PANEL	50.0*	225.00

LABOUR COST

Total Work Units	176.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	17.6HRS	\$792.00
Paint Labour	23.0HRS	\$1,035.00
Total Labour	40.6HRS	\$1,827.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	30.0*	
283	FRONT BUMPER NEW PART PAINT K1R	25.0*	

Charn's Customcraft

Claim Reference:
Assessment Number: CC000002
Version: CHARNCUS/1
Date Calculated: 20/06/2018 08:18

Full Report - V1
Registration: SJX3261Z
Printed: 20/06/2018 15:19

1737	L/DOOR MIRROR NEW PART PAINT K1R	10.0*	
2583	REAR BUMPER NEW PART PAINT K1R	30.0*	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	30.0*	
1781	L/R DOOR REPAIR PAINTING >50%	30.0*	
3481	L/R SIDE PANEL REPAIR PAINTING >50%	75.0*	
LABOUR COST - PAINT			
	TIME(PAINT)	230.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	230.0	
	Total Paintwork Labour	23.0HRS	\$1,035.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$23.22
	New Part Painting - Plastic K1R		\$125.94
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$87.30
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$274.06
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$274.06

PARTS

				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER	71101SNBG50ZB		0%	scd 195.00*
1737	1	L/DOOR MIRROR	76250SNBY21ZA		0%	repair 345.00*
561	1	L/F HEADLAMP CPL	33151SNBD51		0%	scd 190.00*
319	1	L/F UPP BUMPER BRKT	71190SNB000		0%	new 10.00*
7201	1	L/F WHEEL	08W16TR0604	s/n 300	0%	scd 750.00* 720
741	1	L/F WING	60261SNB000ZZ		0%	repair 160.00*
2619	1	L/R BUMPER BRACKET	71598SNAA01		0%	new 13.00*
841	1	L/WHEELHOUSE SHELL	74151SNAA10		0%	? 50.00* new
2583	1	REAR BUMPER	71501SNB010ZB		0%	repair 195.00*
f: OEM Parts			Sub Total			\$1,908.00
g: Original			Mark Up From Cost	(15 %)		\$286.20
h: Secondhand			Sundry Parts	(2 %)		\$38.16
p: Parallel			Total Parts			\$2,232.36
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
ALIGNMENT	0%	\$60.00
SPECIALIST		
Total Extras		\$60.00

Final Calculation

Total Parts	\$2,232.36
Labour	
Total Panel/Mechanical	\$792.00
Total Paintwork	\$1,035.00
Total Labour	\$1,827.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$60.00
Total of Additional Costs	\$60.00

**Claim Reference: THIRD PARTY
Assessment Number: CC000002
Version: CHARNCUS/2
Date Calculated: 28/02/2019 04:24**

**Full Report - V1
Registration: SJX3261Z
Printed: 28/02/2019 12:25**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Sharon Lee	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	THIRD PARTY	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Civic
Sub Model:	BASE MODEL
Model Sheet Number:	H48 01
Registration:	SJX3261Z
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM MODEL 2010	AIR CONDITIONING
RADIATOR DENSO	FOG LAMPS
HEADLAMP WASHERS	PAINTED DOOR HANDLES
PAINTED DOOR MIRRORS	LEATHER STRG WHEEL
RR PARK DIST CONTROL	1.6 LTR 92KW VTEC
HYDRAULIC SERVO	TYRES 205/55 VR 16
WHEELS 6.5J X 16 ALU	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	20/06/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

Charn's Customcraft

Claim Reference: THIRD PARTY
Assessment Number: CC000002
Version: CHARNCUS/2
Date Calculated: 28/02/2019 04:24

Full Report - V1
Registration: SJX3261Z
Printed: 28/02/2019 12:25



Primary Impact →
 Secondary Impact - - - - - →

Addresses

Cost Summary

Total Labour	\$1,354.50
Total Paint/Material	\$230.55
Total Parts	\$814.20
Total of Additional Costs	\$60.00
Excess:	TBA
Grand Total Exc GST:	\$2,459.25
7 % GST:	\$172.15
Grand Total Inc GST:	\$2,631.40

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
8111D1	R + R REAR BUMPER	2.0	9.00
68500-SNB)	R + R BOOT LID	3.0	13.50
73211-SNB)	R + R REAR SCREEN	24.0	108.00
	INCLUDES: REAR TRAY COVER AND R + R ADDITIONAL BRAKE LAMP.		
84180-SNA	R + R L/UPPER C-PILLAR TRIM	3.0	13.50
84130-SNA	R + R R/UPPER C-PILLAR TRIM	3.0	13.50
42700-SNA)	R + R LEFT FRONT WHEEL	2.0	9.00
42700-SNA)	FIT AND BALANCE LEFT FRONT TYRE (WHEEL REMOVED)	5.0	22.50
NN	FRONT BUMPER R&R / NEW PARTS	25.0*	112.50
NN	L/F HEADLAMP CPL R&R / NEW PARTS	9.0*	40.50
0741	REPAIR L/F WING	8.0*	36.00
1481	REPAIR LEFT FRONT DOOR	30.0*	135.00
1781	REPAIR L/R DOOR	20.0*	90.00
2583	REPAIR REAR BUMPER	7.0*	31.50
LABOUR COST			
	Total Work Units	141.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	14.1HRS	\$634.50
	Paint Labour	16.0HRS	\$720.00
	Total Labour	30.1HRS	\$1,354.50

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Charn's Customcraft

Claim Reference: THIRD PARTY
Assessment Number: CC000002
Version: CHARNCUS/2
Date Calculated: 28/02/2019 04:24

Full Report - V1
Registration: SJX3261Z
Printed: 28/02/2019 12:25

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
283	FRONT BUMPER NEW PART PAINT K1R	25.0*	
1745	L/DOOR MIRROR COVER REPAIR PAINT PLASTIC	9.0	
2583	REAR BUMPER REPAIR PAINT PLASTIC	16.0	
741	L/F WING REPAIR PAINTING >50%	17.0	
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	30.0*	
1781	L/R DOOR REPAIR PAINTING >50%	30.0*	
LABOUR COST - PAINT			
	TIME(PAINT)		
	Preparation Main Work Plastic	127.0	
	Preparation Main Work Metal	8.0	
	Preparation Work Multi Layer Paint	25.0	
	Total Work Units (10WU/HR)	0.0	
	Total Paintwork Labour	160.0	
		16.0HRS	
	MATERIAL COST - PAINT		
	New Part Painting - Plastic K1R		\$720.00
	Material-Constant Main Work Metal		Cost Price
	Repair Painting		\$55.10
	Repair Painting Plastic		\$28.60
	Material-Const Main Work Plastic		\$76.64
	Total Excluding Pearlescent Uplift		\$57.51
	Pearlescent Uplift @ 0.0%		\$12.70
	Total Paint Material Cost		\$230.55
			\$0.00
			\$230.55

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
283	1	FRONT BUMPER	71101SNBG50ZB			0%	195.00F
561	1	L/F HEADLAMP CPL	33151SNBD51			0%	190.00*
319	1	L/F UPP BUMPER BRKT	71190SNB000			0%	10.00*
7201	1	L/F WHEEL	08W16TR0604			0%	300.00*
2619	1	L/R BUMPER BRACKET	71598SNAA01			0%	13.00*
3160	1	REAR SCREEN BOND KIT	08CRCX016N0	DEFAULT		0%	0.00F
3166	2	REAR SCREEN CLAMPS	91568SNA003	DEFAULT		0%	0.00F
3163	1	REAR SCREEN FIX SET		DEFAULT		0%	0.00
3161	1	REAR SCREEN SEAL	04733SNAA10	DEFAULT		0%	0.00F
3164	2	REAR SCREEN SPACER	91501S70003	DEFAULT		0%	0.00F
3165	2	REAR SCREEN SPACER	91536SS0J01	DEFAULT		0%	0.00F
f: OEM Parts							
g: Original							
h: Secondhand							
p: Parallel							
x: Exchange							
			Saving				\$369.31
			Sub Total				\$708.00
			Mark Up From Cost	(15 %)			\$106.20
			Total Parts				\$814.20

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	ALIGNMENT	0%	\$60.00
	SPECIALIST		
	Total Extras		\$60.00

Final Calculation

Total Parts	\$814.20
--------------------	-----------------

Charn's Customcraft

Claim Reference: THIRD PARTY
Assessment Number: CC000002
Version: CHARNCUS/2
Date Calculated: 28/02/2019 04:24

Full Report - V1
Registration: SJX3261Z
Printed: 28/02/2019 12:25

Labour		
Total Panel/Mechanical	\$634.50	
Total Paintwork	\$720.00	
Total Labour		\$1,354.50
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$60.00	
Total of Additional Costs		\$60.00
Total Paint/Material Costs		\$230.55
Grand Total Excludes GST		\$2,459.25
GST @ 7 %		\$172.15
Grand Total Includes GST		\$2,631.40

Assessment Notes

◀ Service Request Details

Claim
S8M00KIG

Reference
None ✎

Loss Date
June 11, 2018

Request Date
June 20, 2018

21062018 @ 925am
Shawn veh notin.

Due Date
June 27, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
SJX3261Z

Make
TPVD HONDA

Model

CIVIC-1.6 (A)

Service Address

...

Primary Contact/Insured

MOHAMED ELIYAS MOHAMED ABUBACKAR
BLK 143 JALAN BUKIT MERAH, #23-1140, 160143, Singapore

eliyas@zeatech.com.sg

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

 <Request for DS> S8M00KIG

Type

 Question

Message

Hi, We have uploaded a copy of third party video in Smartclaims for your easy reference. Insured changed lane and collided with third party who was driving on his own lane. Liability is not in our insured favour. Spoken to insured, inform TP claim, agreed to settle and aware NCD(if any) will be affected. Third party would like to know liability/ DS before arrange survey. Kindly advise if we may proceed DS on this matter. Thank you. Hsiao Tong - 30 June 2018

[Reply](#)

<< <Request for DS> S8M00KIG

Type

📍 Question

Message

Hi, pls proceed accordingly & be stringent on ON COR

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 2 July 2018 8:58 AM
To: Charn's Customcraft (charns@singnet.com.sg)
Cc: Admin A; assignments
Subject: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018]

Your Ref: **SJX 3261Z**
Our Ref: CC4/ASM18011303/pb3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 01/05/2019

Survey Details:

Date of loss	11.06.2018
Date of appointment	21.06.2018
Date of survey	10.07.2018
Location of survey	CHARN'S CUSTOMCRAFT

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJX3261Z
Make and Model	Honda Civic (1595cc)
Date of registration	02.06.2010
Excess	
Market Value/ Book Value	\$ 25,000.00 (est)
Parf/COE Rebate	\$ 19,466.00 (est)
Nett Value/ ERV	\$ 5,534.00 (est)

Repair details:

Initial Estimate	\$ 4,393.42
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 874.20
Check items (estimate)	NIL
Labour	\$ 1,585.05
Supplementary	NIL
Total	\$ 2,459.25
Lump Sum(if applicable)	

Number of days for repair	<u>5</u>
---------------------------	----------



Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 2,631.40	\$ 2,631.40
Loss of use (7days x \$60.00)	\$ 420.00	NIL
Loss of rental (7days x \$100.00)(w/GST)	NIL	\$ 749.00
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 3,058.85	\$ 3,387.85



<MANDATE IA> - S8M00KIG [ACCIDENT INVOLVING SJM 3167X(OI) & SJX 3261Z(TP) ON 11/06/2018]


Type

🔔 Question

Message

Liability: 100%. Insured changed lane and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,058.85(if claim LOU) - \$ 3,387.85(if claim LOR). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction.
Hsiao Tong - 01 May 2019

Reply



Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Friday, 3 May 2019 9:21 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 52796, vehicle number SJX3261Z

<input type="checkbox"/>	**INCOMPLETE TP MARKED EST(PG 4 MISSING)	CHT	1/5/2019 10:08:43 AM
<input type="checkbox"/>	Message Liability: 100%. Insured changed lane and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,058.85(if claim LOU) - \$ 3,387.85(if claim LOR). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 01 May 2019	CHT	1/5/2019 10:13:30 AM
<input type="checkbox"/>	2/5/19 11:03 AM HO Winnie—Hi Hsiao Tong, vehicle more than 3 yrs, check with workshop able to do LS. please proceed after confirmation. Tks	LSP	3/5/2019 9:08:14 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*TP Judge willing to do 10% - 15%
2200 + GST = 2357.00*

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Thursday, 2 May 2019 11:15 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 52796, vehicle number SJX3261Z

Best Regards,

G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: winnie.ho@axa.com.sg [mailto:winnie.ho@axa.com.sg]
Sent: Thursday, 2 May 2019 11:06 AM
To: admin-d@lkkauto.com
Subject: New message for service request 52796, vehicle number SJX3261Z

AXA Insurance has sent you a message for claim number S8M00KIG.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.

<https://www.avg.com>



RE: <MANDATE IA> - S8M00KIG [ACCIDENT INVOLVING SJM 3167X(OI) & SJX 3261Z(TP) ON 11/06/2018]

Type

🔍 Question

Message

Hi Winnie, we refer to your msg dated 02/05/2019. We were informed by third party repairer that the repair cost is adjusted in Audatex which is fair and reasonable. Nevertheless, for an amicable settlement, third party repairer proposed COR at L/sum \$2,200.00 to resolve the matter. In view of this, we seek your mandate at \$2,781.45(if claim LOU) - \$3,110.45(if claim LOR). Mandate IA dd 170519 had been uploaded in SC. Kindly let us have your approval/ instruction. Hsiao Tong - 17 May 2019

Reply



Immediate Advice

To : AXA Insurance Pte Ltd

17/5/2019

Survey Details:

Date of loss	11.06.2018
Date of appointment	21.06.2018
Date of survey	10.07.2018
Location of survey	CHARN'S CUSTOMCRAFT

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJX3261Z
Make and Model	Honda Civic (1595cc)
Date of registration	02.06.2010
Excess	
Market Value/ Book Value	\$ 25,000.00 (est)
Parf/COE Rebate	\$ 19,466.00 (est)
Nett Value/ ERV	\$ 5,534.00 (est)

Repair details:

Initial Estimate	\$ 4,393.42
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 874.20
Check items (estimate)	NIL
Labour	\$ 1,585.05
Supplementary	NIL
Total	\$ 2,459.25
Lump Sum(if applicable)	\$ 2,200.00

Number of days for repair	<u>5</u>
---------------------------	----------



Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 2,354.00	\$ 2,354.00
Loss of use (7days x \$60.00)	\$ 420.00	NIL
Loss of rental (w/GST)(7days x \$100.00)	NIL	\$ 749.00
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 2,781.45	\$ 3,110.45



<MANDATE IA> - S8M00KIG [ACCIDENT INVOLVING SJM 3167X(OI) & SJX 3261Z(TP) ON 11/06/2018]

Type

🔗 Question

Message

Hi Hsiao Tong, confirmed with Stacey, APW need to follow audatex and lump sum @ 20%. pls assist to inform APW accordingly. Tks

Reply



RE: <MANDATE IA> - S8M00KIG [ACCIDENT INVOLVING SJM 3167X(OI) & SJX 3261Z(TP) ON 11/06/2018]

Type

📍 Question

Message

Hi Winnie, Noted. We seek your mandate at \$2,513.95(if claim LOU) - \$ 2,842.95(if claim LOR). Mandate IA dd 180519 had been uploaded in SC. Kindly let us have your approval/ instruction. Hsiao Tong - 18 May 2019

Reply



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/5/2019

Survey Details:

Date of loss	11.06.2018
Date of appointment	21.06.2018
Date of survey	10.07.2018
Location of survey	CHARN'S CUSTOMCRAFT

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJX3261Z
Make and Model	Honda Civic (1595cc)
Date of registration	02.06.2010
Excess	
Market Value/ Book Value	\$ 25,000.00 (est)
Parf/COE Rebate	\$ 19,466.00 (est)
Nett Value/ ERV	\$ 5,534.00 (est)

Repair details:

Initial Estimate	\$ 4,393.42
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 874.20
Check items (estimate)	NIL
Labour	\$ 1,585.05
Supplementary	NIL
Total	\$ 2,459.25
Lump Sum(if applicable)	\$ 1,950.00

Number of days for repair	<u>5</u>
---------------------------	----------



Remarks:

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 2,086.50	\$ 2,086.50
Loss of use (7days x \$60.00)	\$ 420.00	NIL
Loss of rental (w/GST)(7days x \$100.00)	NIL	\$ 749.00
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 2,513.95	\$ 2,842.95

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Wednesday, 22 May 2019 10:25 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 52796, vehicle number SJX3261Z

<input type="checkbox"/>	let us have your approval/ instruction. Hsiao Tong - 17 May 2019		
<input type="checkbox"/>	5/17/19 10:45 AM HO Winnie—Hi Hsiao Tong, confirmed with Stacey, APW need to follow audatex and lump sum @ 20%. pls assist to inform APW accordingly. Tks	LSP	17/5/2019 4:59:41 PM
<input type="checkbox"/>	Message Hi Winnie, Noted. We seek your mandate at \$2,513.95(if claim LOU) - \$ 2,842.95 (if claim LOR). Mandate IA dd 180519 had been uploaded in SC. Kindly let us have your approval/ instruction. Hsiao Tong - 18 May 2019	CHT	18/5/2019 7:45:34 AM
<input type="checkbox"/>	5/21/19 11:45 AM HO Winnie—Hi Hsiao Tong, COR-proceed. LOU-propose @ \$50 per day. Tks	LSP	22/5/2019 10:11:52 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Tuesday, 21 May 2019 11:49 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 52796, vehicle number SJX3261Z

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: winnie.ho@axa.com.sg [mailto:winnie.ho@axa.com.sg]
Sent: Tuesday, 21 May, 2019 11:46 AM
To: admin-d@lkkauto.com
Subject: New message for service request 52796, vehicle number SJX3261Z

AXA Insurance has sent you a message for claim number S8M00KIG.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 5 June 2019 9:23 AM
To: Charn's Customcraft
Cc: Rasul (LKKAuto); Admin A
Subject: RE: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018]

Without Prejudice

Dear Sirs/Mdm,

Noted with thanks.

** Kindly forward your LOD with all the relevant documents (ie: final repair bill, authorisation to act, rental receipt) to us [LKK] for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Monday, 27 May 2019 2:06 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018]
Importance: High

Hi

Amount accepted.

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L

Company Reg No: 25151300M

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Saturday, 25 May, 2019 8:01 PM
To: Charn's Customcraft
Cc: Rasul (LKKAuto); Admin A
Subject: Re: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018]

Without Prejudice

Dear Sirs/Mdm,

For COR, we have our principal instruction to offer L/sum \$1,950.00(before GST) with 5 repair days.

Kindly confirm.

**Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us [LKK] for our necessary action.

Thank you.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Tuesday, 9 April 2019 3:26 PM
To: Rasul (LKKAuto); Hsiao Tong (LKKAuto)
Cc: SUR
Subject: FW: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018]

Hi Rasul

Kindly find attached for finalization.

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

From: Charn's Customcraft [mailto:charns@singnet.com.sg]
Sent: Thursday, 28 February, 2019 12:31 PM
To: Rasul (LKKAuto) (Rasul@lkkauto.com)
Cc: 'Admin A'; 'assignments'; 'Hsiao Tong (LKKAuto)'
Subject: RE: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND

SJX 3261Z ON 11/06/2018]

Importance: High

Hi Rasul

Kindly find attached for finalization.

Thanks & Regards,

Sharon Lee

Charn's Customcraft

Tel: 6272 5429 Fax: 6273 6676

Email: charns@singnet.com.sg

GST Reg. No: M90367863L

Company Reg No: 25151300M

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Monday, 2 July, 2018 8:58 AM

To: Charn's Customcraft (charns@singnet.com.sg)

Cc: Admin A; assignments

Subject: Your Ref: SJX 3261Z *Our Ref: CC4/ASM18011303/pb3 [ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018]

Your Ref: **SJX 3261Z**

Without Prejudice

Our Ref: CC4/ASM18011303/pb3

Dear Sirs,

ACCIDENT INVOLVING SJM 3167X(AXA) AND SJX 3261Z ON 11/06/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



<MANDATE IA> - S8M00KIG [ACCIDENT INVOLVING SJM 3167X(OI) & SJX 3261Z(TP) ON 11/06/2018]


Type

🔍 Question

Message

pls proceed. Tks

Reply



CHARN'S CUSTOMCRAFT

*Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars*

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: chams@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

19 June 2019

AXA Insurance Pte Ltd
The Motor Claim Dept
8 Shenton Way
#27-01, AXA Tower
Singapore 068811

Without Prejudices

Dear Sir

**ACCIDENT INVOLVING: SJX 3261 Z & SJM 3167 X on 11 JUNE 2018 at/along CTE
TWDS AYE BEFORE ORCHARD EXIT.**

We refer to the above matter.


We are helping the owner of vehicle no: SJX 3261 Z to claim against your vehicle no: SJM 3167 X, that the above accident was caused solely by the negligence of the driver of motor vehicle no: SJM 3167 X which was insured by you at the material time. As a result of the said accident, we are claiming as follows:

1. Cost of Repair:	\$2086.50
2. Rental Bill	\$ 898.80
3. Audatex Fee	\$ 42.00
TOTAL	<u>\$3027.30</u>

We forward copies of GIA reports, repair bill, certificate of insurance and driver's license for your attention. Please note that you should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter.

Thank You

Warmest Regards,


.....
Sharon Lee
Encl



Auto
Consultants
Pte Ltd

30 CUBA AVE, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 JULY 2018

MOHAMED ABUBACKAR MOHAMED ELIYAS
BLK 143 JALAN BUKIT MERAH
#23-1140
SINGAPORE 160143

Dear Sir/ Mdm

OUR REF : CC4/ASM18011303/pb3
YOUR REF : P2040528 (SJM 3167X)
ACCIDENT INVOLVING SJM 3167X AND SJX 3261Z ALONG/AT CTE ON 11/06/2018 /

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from CHARN'S CUSTOMCRAFT acting on behalf of the owner of SJX 3261Z against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to chewht@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.


This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

Cc *AXA Insurance Pte Ltd
(Motor Claims Dept)*

AXA INSURANCE PTE LTD

8 Shenton Way

#26-01, AXA Tower

Singapore 068811

Attn: The Motor Claims Dept

Without Prejudices

LETTER OF AUTHORITY

I, CHUANG KENG LIANG COLIN, owner of SJX 3261 Z hereby authorize CHARN'S CUSTOMCRAFT to act for me with respect to my claim for repair costs and/or rental and/or loss of use for my vehicle no: SJX 3261 Z that was damaged pursuant to the accident which occurred on 11 JUNE 2018 along CTE TWDS AYE BEFORE ORCHARD EXIT involving vehicle no/s: SJM 3167 X.

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis in so far as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 17 (day) of 07 (month) 18 (year)

Signature

Name: CHUANG KENG LIANG COLIN

NRIC: S7712574D



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJM 3167X (Insd veh)	Model: HONDA CIVIC
	SJX 3261Z (TP veh)	
Date of Accident/ Time:	11/06/2018 / 17:40	

Repair Estimate	: \$	4,613.57 ✓	
Final Repair Cost	: \$	2,088.50	(WIGST)
Loss of Use	: \$		days at \$ per day
Rental (if any) (WIGST)	: \$	748.00	07 days at \$107.00 per day
LTA / GIA Search Fee	: \$		
Others: (AUDADEX)	: \$	42.00	
	: \$		
Final Settlement Sum	: \$	2,870.00	(global sum)
Payee Name : CHARN'S CUSTOMCRAFT			
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: <u>15</u>	
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp		Signature of Witness / Workshop stamp (if applicable)
Name of Representative: <u>Sharon Lee</u>		Name of Witness: <u>Father</u>
Date: <u>25/6/18</u>		Date: <u>25/06/18</u>
Signature of AXA's surveyor/representative:		
Name of AXA's surveyor /Representative:		
Date:		



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

**TAX
INVOICE**
2019066332

AXA INSURANCE PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

M1

No.

TERM:

YOUR ORDER No.

OUR D/O No. 17/6/2019

DATE:

QUANTITY	DESCRIPTION			AMOUNT	
				\$	CTS.
	Vehicle No.	Make/Model	DOA	Reg. No.	
	SJX3261Z	HONDA CIVIC 1.6L SAT	11/06/2019@1740	50256	

Being Lump Sum repair for the above Vehicle

1,950.00

CHARN'S CUSTOMCRAFT

Subtotal \$1,950.00

GST 7% \$136.50

Total \$2,086.50

TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
CHUANG KENG LIANG COLIN BLK 17 TELOK BLANGAH CRESCENT #21-276 SINGAPORE 090017

DATE	INVOICE NO.
27-Jul-2018	A 38035

	VHA NO.	DUE DATE	VEH. NO.
	A 38035	27-Jul-2018	SKC 3907 T
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 10 JULY 2018 TO 17 JULY 2018 YOUR REF: SJX 3261 X	7	120.00	840.00
GST @ 7%			\$58.80
TOTAL			\$898.80

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.



INVOICE

CHARN'S CUSTOMCRAFT
Attention: Sharon
1010 Bukit Merah Lane 3,
SINGAPORE 159724

Invoice Date
16 Jul 2018

Invoice Number
AXSG-160718-009

Audatex Singapore Pte. Ltd.
7 Temasek Boulevard, Level
44 Suntec Tower 1, Singapore
038987
www.audatex.com.sg

Description	Quantity	Unit Price	Amount SGD
Monthly Usage Fee for AudaEnterpriseGold for June 2018	3.00	42.00	126.00
SLR2057L(CC000001) SKC3435M(CC000003) SJX3261Z(CC000002)			
Annual User Licence Fee (June. 2018- May.2019) for Access to Audatex Estimates Solution	1.00	13.00	13.00
Annual User Licence Fee (June. 2018- May.2019) for Access to Audatex Estimates	1.00	287.00	287.00
		Subtotal	426.00
		TOTAL SGD	426.00

Due Date: 15 Aug 2018

This is a computer-generated invoice and no signature is required.

Payment Details:

Payable : Payable 30 days from date of invoice

Payable to : Audatex Singapore Pte Ltd

Account no.:074-901961-1

Bank Name: DBS Bank Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18011303/R1gb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:WINNIE

Date : 12-07-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 3167X	Veh. Inspected	SJX 3261Z
Policy No.	P2040528	Coverage (\$)	0.00
Claim No.	S8M00KIG	Excess (\$)	0.00
Assign From		Assign Date	21/06/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.6L	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMF46209S200703	Colour	GREY
Odometer	151773	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	5 mm
L/H Front Tyre	205/55 R16	DUNLOP	5 mm
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND N/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/06/2018	Inspection Date	10/07/2018
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 3261Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT) (WCP)	SCRATCHED	195.00	195.00
1	L/DOOR MIRROR (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	345.00	-
1	L/F HEADLAMP CPL (CONSISTENT) (WCP)	SCRATCHED	190.00	190.00
1	L/F UPP BUMPER BRKT (CONSISTENT) (WCP)	NECESSARY	10.00	10.00
1	L/F WHEEK (CONSISTENT) (WCP)	SCRATCHED	750.00	300.00
1	L/F WING (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	160.00	-
1	L/R BUMPER BRACKET (CONSISTENT) (WCP)	NECESSARY	13.00	13.00
1	L/WEHELHOUSE SHELL (CONSISTENT) (WCP)	NOT NECESSARY	50.00	-
1	REAR BUMPER (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	195.00	-
	COST PLUS 15%		286.20	106.20
			2,194.20	814.20
LABOUR				
	ALIGNMENT .		60.00	60.00
	PANEL /MECHANICAL .INCLUSIVE OF THE REPAIR OF L/DOOR MIRROR,L/F WING AND REAR BUMPER.		792.00	634.50
	PAINTWORK.		1,035.00	720.00
	PAINT/MATERIAL COSTS.		230.55	230.55
			2,117.55	1,645.05
GRAND TOTAL			4,311.75	2,459.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CC4/ASM18011303/R1gb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	SAMODKIC
Reference	CC4JASM18011303/R1jpb3q2
Loss Date	11 June 2018
Report Date	12 Jun 2018 12:00:00 AM
Request Date	13 August 2018
Due Date	

Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

ADD INVOICE

Vehicle Information

Incident Vehicle Registration #	SDX2161Z
Make	TPVD HONDA
Model	CIVIC-1.6 (N)
Service Address	

Primary Contact/Insured

MOHAMED ELIYAS MOHAMMED ABUBACKAR
 BLK 143 JALAN BUKIT MERAH, #23-1140, 160143, Singapore
 eliyas@zeatstfh.com.sg

Claim Handler

HO Winnie
 6568804833
 winnie.ho@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
BENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
LK0Inspection.pdf	Forms / Claim Documents	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
LK0Adjustment1a.pdf	Forms / Claim Documents	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
AUDATEX.pdf	Forms / Claim Documents	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
WORKSHOP INVOICE.pdf	Invoice	Regular	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
LETTER TO OI.pdf	Letters and Correspondence	Part / Accessory Supplier	LAK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	24 June 2019
Mandate IA old 180519.pdf	Forms / Claim Documents	Assessment	LAK AUTO CONSULTANTS PTE LTD (TP)	18 May 2019
Mandate IA old 170519.pdf	Forms / Claim Documents	Assessment	LAK AUTO CONSULTANTS PTE LTD (TP)	17 May 2019
Mandate IA old 010519.pdf	Forms / Claim Documents	Assessment	LAK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019
LK0 Recovery Photos.pdf	Reports & Statement	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019
Audalox-5X3261Z.pdf	Reports & Statement	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
■ INRF_COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019
■ LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019
■ TP ESTIMATE- MAIBRED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	12 July 2018
■ SIX 3261Z vs SIX 3167X - TP VIDEO.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	30 June 2018
■ SIX3167X INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	20 June 2018
■ SIX3261Z TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	20 June 2018
■ TP PBI RECEIVED FROM WORKSHOP.mpg	Letters and Correspondence	Workshop	DHAKAL Raghav	20 June 2018